

## **ASBESTOS-CONTAINING BUILDING MATERIALS RE-ASSESSMENT REPORT**

### **Huntsville High School**

58 Brunel Road  
Huntsville, Ontario

#### **Presented to:**

### **Trillium Lakelands District School Board**

Box 420, County Road 36  
Lindsay, Ontario  
K9V 4S4

Attention: Daniel Whalen

September 2023

**Maple Project No. 21124-21**

# Executive Summary

## 2023 Asbestos-Containing Building Materials Re-Assessment Report

Maple Project	School Name	Address
21124-21	Huntsville High School	58 Brunel Rd, Huntsville, Ontario

Maple Environmental Inc. was retained by Trillium Lakelands District School Board to perform a re-assessment of known asbestos-containing building materials within the subject building.

The findings and recommendations of the current assessment are summarized below. Please refer to the main body of the report for details.

### FINDINGS

Asbestos-containing materials (ACM) identified within the building at the time of the assessment are as follows:

ASBESTOS BUILDING MATERIALS SUMMARY								
MATERIAL		ASBESTOS			FRIABILITY			Remedial Work Required
		Yes	No	Suspect	Friable	Non-Friable	Potentially	
Sprayed Fireproofing			X		X			NO
Textured Finish			X		X			NO
Mechanical Insulations	Pipe Fittings	X			X			YES
	Pipe Straight		X		X			NO
	Ductwork		X		X			NO
	Mechanical Equip.		X		X			NO
Ceiling Tiles			X				X	NO
Vinyl Sheet Flooring			X				X	NO
Vinyl Floor Tiles		X				X		NO
Asbestos Cement (Transite)		X				X		NO
Plaster		X		X			X	NO
Drywall Joint Compound		X		X		X		NO
Siporex Joint Compound		X				X		NO
Other (roofing, caulking, etc.)				X				NO

Please refer to Room by Room Inventory in Appendix I to view location, quantities, and condition of ACM observed within the building at the time of the assessment.

# **Executive Summary**

## **2023 Asbestos-Containing Building Materials Re-Assessment Report**

---

### **RECOMMENDATIONS**

As asbestos-containing materials were found to be present within the building, Ontario Regulation 278/05 requires that the Trillium Lakelands District School Board's Asbestos Management Plan must apply to this building. In addition, an annual re-assessment of all ACM must be performed.

Using Type 2 Asbestos Repair Procedures in accordance with Ontario Regulation 278/05, repair the following ACM pipe fitting insulations:

- One (1) fitting within Ebase 239 (Gym C), height restricted at roof hopper;
- Two (2) fittings within Ebase 339 (Mezzanine)

All remaining asbestos-containing materials identified within the building were observed to be in GOOD condition and therefore no additional recommendations are warranted.

### **General Statement**

The Executive Summary must be read in conjunction with the main body of this report.

## **TABLE OF CONTENTS**

<b>EXECUTIVE SUMMARY .....</b>	<b><i>i</i></b>
<b>1.0 INTRODUCTION .....</b>	<b>1</b>
<b>2.0 APPLICABLE ONTARIO REGULATIONS.....</b>	<b>1</b>
2.1 ONTARIO REGULATION 278/05 (ASBESTOS).....	1
2.2 ONTARIO REGULATION 347 .....	2
<b>3.0 SURVEY SCOPE AND METHODOLOGY.....</b>	<b>2</b>
3.1 INVENTORY METHODOLOGY.....	3
3.2 ASBESTOS ASSESSMENT CRITERIA .....	3
3.3 LIMITATIONS AND OMISSIONS FROM SCOPE .....	4
3.4 SAMPLING STRATEGY AND ANALYTICAL METHODS .....	5
3.5 DRAWINGS .....	6
<b>4.0 INVENTORY FINDINGS.....</b>	<b>6</b>
4.1 SPRAYED FIREPROOFING (FRIABLE) .....	7
4.2 THERMAL MECHANICAL INSULATION (FRIABLE).....	7
4.3 TEXTURE FINISH (FRIABLE) .....	7
4.4 ACOUSTIC CEILING TILES (POTENTIALLY FRIABLE) .....	8
4.5 VINYL SHEET FLOORING (POTENTIALLY FRIABLE) .....	8
4.6 VINYL FLOOR TILE (NON-FRIABLE).....	8
4.7 ASBESTOS CEMENT PRODUCTS "TRANSITE" (NON-FRIABLE) .....	8
4.8 DRYWALL JOINT COMPOUND (DJC) .....	8
4.9 PLASTER .....	8
4.10 SIPOREX JOINT COMPOUND .....	8
<b>5.0 RECOMMENDATIONS .....</b>	<b>9</b>
5.1 GENERAL RECOMMENDATIONS .....	9
5.2 SPECIFIC RECOMMENDATIONS .....	9
<b>6.0 LIMITATIONS.....</b>	<b>10</b>
 <b>APPENDIX I</b>	 ROOM-BY-ROOM ASBESTOS INVENTORY
<b>APPENDIX II</b>	DRAWINGS
<b>APPENDIX III</b>	POTENTIAL ASBESTOS-CONTAINING MATERIAL IDENTIFICATION SHEET

## **1.0 INTRODUCTION**

MAPLE Environmental Inc. ("MAPLE") was retained by the Trillium Lakelands District School Board (TLDSB) to perform a re-assessment of known asbestos-containing building materials within all TLDSB schools where asbestos was previously confirmed to be present (by others).

The assessment was completed in accordance with the requirement of Ontario Regulation 278/05 to complete a re-assessment on an annual basis.

The following report presents the findings and recommendations of the assessment for the specific building listed.

<b>SUMMARY OF BUILDING INFORMATION</b>	
<b>School Name:</b>	Huntsville High School
<b>Building Address:</b>	58 Brunel Rd, Huntsville, Ontario
<b>Number of Floors:</b>	3
<b>Approximate Square Footage:</b>	161,300
<b>Assessed by:</b>	Josh Prosser
<b>Assessment Date:</b>	July, 2023

## **2.0 APPLICABLE ONTARIO REGULATIONS**

Applicable Ontario Regulations for each of the materials included in the investigation are briefly described below.

### **2.1 Ontario Regulation 278/05 (Asbestos)**

The Ontario Ministry of Labour Regulation 278/05 requires a detailed asbestos inventory be performed in all buildings where friable and non-friable asbestos-containing materials (ACM) are present. The inventory must be available at the work place and must identify the type and location of asbestos-containing materials on a room-by-room basis, where necessary.

Each individual building report prepared by MAPLE meets or exceeds the requirements for an asbestos survey under Ontario Regulation 278/05.

Ontario Regulation 278/05 applies to buildings with regards to maintenance, renovation or demolition work where ACM is present and may be disturbed. The regulation requires all buildings where asbestos is known to be part of the building materials to implement an Asbestos Management Program (AMP). TLDSB has prepared and maintains an AMP of which the current Re-Assessment report is part of.

## **2.2 Ontario Regulation 347**

Ontario Regulation 347 applies to the transport of waste from the location of generation to a landfill site authorized to receive specific wastes. The regulation also prescribes procedures on how the specific wastes are to be handled at the landfill site.

The major requirements of the building owner and the person(s) removing the waste are to ensure that:

- The waste is appropriately packaged and labelled;
- The transport vehicle is appropriately placard; and
- The waste is to be transported as directly as possible to the landfill site once it leaves the site.

Some wastes require the Owner to register a Generator (of waste) number and many wastes require classification that can restrict or even prohibit their disposal in landfill.

It is important to note that the building owner can be held responsible for the waste until the waste disposal site accepts it.

## **3.0 SURVEY SCOPE AND METHODOLOGY**

The surveys were performed on a Room-by-Room basis within each building included in the scope of the assessment where asbestos was previously identified (by others).

The scope of the surveys included all friable and major non-friable materials suspected to contain asbestos. The term friable is applied to a material that can be readily reduced to dust or powder by hand or moderate pressure. Asbestos materials that are friable have a much greater potential to release airborne asbestos fibres when disturbed.

Typical friable asbestos materials include; sprayed fireproofing or thermal insulation, textured (stippled) plaster, and thermal mechanical insulation. Typical non-friable materials include: asbestos cement (transite) products, caulking, vinyl floor tiles, asbestos textiles and gaskets. Additional materials such as ceiling tiles and drywall joint compounds are classified as non-friable, but because of their ability to release dust when disturbed they are considered as "potentially friable" for the purpose of this report.

### **3.1 Inventory Methodology**

In order to determine the location of the materials included in the assessment, each room or area was entered where practical (i.e.: where access was possible without the demolition of walls, roof or ceilings or destruction of flooring) where asbestos materials were previously identified. An investigation of areas of the building where asbestos was not previously identified was not included in the scope of the current project.

Representative views were made above accessible suspended ceiling systems. Drywall or plaster ceilings were accessed via existing ceiling access panels only. The inventory did not include destructive testing of building systems or finishes to observe possible hidden conditions.

### **3.2 Asbestos Assessment Criteria**

The recommendations and suggestions made as part of this report with respect to asbestos have taken into consideration the condition and accessibility of the asbestos-containing material as well as other factors such as water damage, vibration, air movement, and general activities in the area.

Where ACM is found to be in GOOD condition and not likely to deteriorate or fall, the general recommendation would be to re-evaluate the condition of the material on an annual basis (required by Regulation 278/05). This recommendation can be subject to change if the material is located in a manner that persons untrained in asbestos awareness could physically damage it.

Where the ACM is found to be damaged (i.e. FAIR or POOR condition), a recommendation to have the material cleaned-up, repaired, removed, enclosed, or encapsulated is offered. The recommendation will also indicate which asbestos procedure should be used to perform the remedial work (i.e. Type 1, Type 2, Type 3, or Glove Bag Removal Methods).

In each area or room inventoried, the quantity, condition (GOOD, FAIR, or POOR) and accessibility (A, B, C, D or E) of each suspect material was recorded.

The definitions for condition and accessibility items are as follows:

**GOOD**      Material is intact with no visible signs of damage.

**FAIR**        Material is visibly damaged but can be repaired.

**POOR**        Material is damaged beyond repair and likely needs to be removed.

**Access A**    Accessible to all occupants of the building.

- |                 |  |
|-----------------|--|
| <b>Access B</b> | Accessible to Maintenance personnel without the use of a ladder (i.e. Mechanical Room, pipe chase etc.).   |
| <b>Access C</b> | Accessible to Maintenance personnel with the use of a ladder and is exposed to view without removing building components.                                |
| <b>Access D</b> | Accessible to Maintenance personnel with the use of a ladder and is concealed from viewing due to a building component (i.e. above a removable ceiling). |
| <b>Access E</b> | Not accessible without demolition of a building component (i.e. above a fixed ceiling system).   |

The asbestos related information collected during the previous assessments was confirmed and the room-by-room data updated to reflect the current information.

### **3.3 Limitations and Omissions from Scope**

Due to the nature of building construction, some limitations exist in regards to the possible thoroughness of any building materials inventory. The field observations, measurements, and analysis are considered sufficient in detail and scope to form a reasonable basis for the findings presented in this report. MAPLE warrants that the findings and conclusions contained herein have been made in accordance with generally accepted evaluation methods in the industry and applicable regulations at the time of the performance of the inventory.

It is possible that conditions may exist which could not be reasonably identified within the scope of the inventory or which were not apparent during the site investigation. MAPLE believes that the information collected during the inventory period concerning the property is reliable. No other warranties are implied or expressed.

In addition, during a standard asbestos assessment, performed for the purposes of regulatory compliance, it is industry practice to exclude some non-friable materials in the inventory. Examples of such assumptions include; elevator brakes, roofing felts and mastics, high voltage wiring, mechanical packing and gaskets, underground services or piping, fire-doors, window caulking, levelling compound, and/or materials used in operating equipment. As such, these materials were not sampled at the time of this survey and where present are assumed to be asbestos containing until proven otherwise.



### **3.4 Sampling Strategy and Analytical Methods**

As the majority of materials were previously sampled by others, the requirement for sampling during the current survey was limited. Where samples were collected, they conformed to the criteria outlined below and in compliance with O. Reg. 278/05.

A small volume of the material was removed either from a damaged section or cut out of intact material and then repaired by sealing with tape to prevent the release of fibres. The collected samples were placed in plastic bags, sealed and labelled and then sent to an independent laboratory for analysis. To ensure quality results, the independent laboratory chosen is NVLAP accredited and successfully participates in an "Asbestos Proficiency Analytical Testing Program" and as such, these laboratories are responsible for their findings.

The collection of samples was performed in accordance with regulatory sampling requirements and with sufficient frequency to obtain a general pattern of asbestos use within the building. Due to building renovations or modifications that have occurred, the consistency of the application of asbestos materials may not be uniform throughout the entire building. It is important to note that without sampling every wall, pipe section, ceiling tile etc. it is not possible to identify the possible asbestos content in every material present in the building. For this reason, materials similar in appearance to those sampled elsewhere in the building were visually identified as being homogeneous and thus are assumed to be composed of the same material, thus additional sampling is not required.

In accordance with Reg. 278/05, samples were collected at the following frequency.

<b>Material Type</b>	<b>No. Samples</b>
Sprayed Fireproofing	Up to 7
Texture Coat	Up to 7
Pipe Fitting Insulation	3
Pipe Straight Insulation	3
Ductwork Insulation	3
Ceiling Tiles	3
Vinyl Sheeting Flooring	3
Vinyl Floor Tile	3
Plaster Finishes	Up to 7
Drywall Compound	Up to 7

An independent NVLAP accredited laboratory, was used to analyse the collected samples. Analysis was performed following the Code of Practice for the identification of asbestos in bulk material, as detailed in Ontario Regulation 278/05. Bulk samples were analysed using the Polarized Light Microscopy ("PLM") Technique with Dispersion Staining. The identification of asbestos fibre in bulk material is based on a collective set of parameters dependent on the unique shape and crystallographic properties of each fibre as viewed through the microscope. This method is useful for the qualitative identification of asbestos and the semi-quantitative determination of asbestos content in bulk materials expressed as a percent of projected area. The method identifies types of asbestos and also measures percent of asbestos as perceived by the analyst in comparison to standard area projections or trained experience.

Given the composition of some vinyl floor products, the PLM analysis method is often prone to yielding false negative analysis results. Therefore it may be prudent that the Transmission Electron Microscopy (TEM) analysis method be used to determine the asbestos content in the vinyl floor products, if negative results are obtain from the laboratory analysis.

### **3.5 Drawings**

Drawings provided for each building indicate the following (where present):

- ◇ Location Numbers (reference to Room-by-Room asbestos data)
- ◇ Asbestos-Containing Sprayed Fireproofing
- ◇ Asbestos-Containing Texture Finishes
- ◇ Asbestos Containing Ceiling Tiles
- ◇ Asbestos-Containing Flooring Materials
- ◇ Presence of Asbestos-Containing Mechanical Insulations will not be specifically indicated on the drawings; however, a general statement regarding the presence of ACM mechanical insulations, where present, has been indicated on the drawings.
- ◇ Presence of asbestos-containing drywall joint compound and hard plaster will not be specifically identified on the drawings; however, a general statement regarding the presence of these ACM materials, where present, has been indicated on the drawings.

## **4.0 INVENTORY FINDINGS**

The following is a brief discussion of the extent to which Asbestos-Containing Materials (ACM) was identified in the building. The discussion is organized under the headings of materials that are generally suspected of containing asbestos. Refer to the Room-by-Room Survey Inventory in Appendix I for a detailed description and location of all ACM.

Destructive testing was not conducted and as such some areas within the building were not accessible for an assessment (i.e. above solid ceilings, behind walls). Access for viewing within wall and ceiling cavities was not always possible. Suspect asbestos materials may be present within ceiling and wall cavities that were not identified in this report. This comment is particularly important for materials such as mechanical insulation. Caution should be taken when demolishing solid wall finishes within the building.

#### **4.1 Sprayed Fireproofing (Friable)**

No sprayed fireproofing was observed in the building.

#### **4.2 Thermal Mechanical Insulation (Friable)**

Asbestos and non-asbestos mechanical insulations were identified in the building. A brief description of the insulations is provided below categorized by mechanical system type. Further, it is important to note that mechanical systems may be present within walls and ceiling cavities or pipe chases that were not accessible during this assessment. The presence of ACM mechanical insulations in these locations should be suspected.

##### **Pipe Systems:**

Pipe Fittings, including elbows, valves, tees, hangers, etc. where insulated are insulated with parging cement previously confirmed to contain Chrysotile asbestos or are insulated with non-asbestos materials (i.e. Fibreglass). All parging cement pipe fitting insulation were found to be in GOOD TO FAIR condition.

Pipe Straights, where insulated are insulated with non-asbestos fibreglass and/or armaflex materials.

##### **Ductwork:**

Duct systems were either insulated with non-asbestos fibreglass or were un-insulated.

##### **Mechanical Equipment:**

Mechanical equipment was observed to be externally un-insulated.

#### **4.3 Texture Finish (Friable)**

No asbestos-containing texture finishes were identified to be present within the building.

#### **4.4 Acoustic Ceiling Tiles (Potentially Friable)**

No asbestos-containing ceiling tiles were identified to be present within the building.

#### **4.5 Vinyl Sheet Flooring (Potentially Friable)**

No asbestos-containing vinyl sheet flooring was identified to be present within the building.

#### **4.6 Vinyl Floor Tile (Non-Friable)**

Vinyl floor tiles containing asbestos are present in various areas of the building. All tiles were found to be in GOOD condition. Refer to the Room-by-Room Inventory in Appendix I for details regarding location and quantity.

#### **4.7 Asbestos Cement Products "Transite" (Non-Friable)**

Asbestos-containing transite is present in the form of rain water leaders, roof drains, countertops and within fume hoods. All transite was found to be in GOOD condition. Refer to the Room-by-Room Inventory in Appendix I for details regarding location and quantity.

#### **4.8 Drywall Joint Compound (DJC)**

Previous sample results indicated drywall joint compound sampled at the Site contains asbestos. All drywall should be assumed to contain asbestos unless testing in specific areas indicates otherwise. The drywall was found to be in GOOD condition.

#### **4.9 Plaster**

Previous sample results indicated select plaster finishes sampled at the Site contains asbestos. All plaster should be assumed to contain asbestos unless testing in specific areas indicates otherwise. The plaster finishes were found to be in GOOD condition.

#### **4.10 Siporex Joint Compound**

During a project specific assessment in August of 2019, Siporex joint compound present in Gymnasium C (eBase 239) was identified as asbestos-containing. The material is applied to the seams of the deck and was observed to be in GOOD condition.

## **5.0 RECOMMENDATIONS**

### **5.1 General Recommendations**

Due to the presence of ACM within the building, TLDSB must maintain their existing Asbestos Management Program for this property.

A re-assessment of known ACM is to be conducted at least once annually.

It is important to note that due to the presence of solid walls and ceiling systems, ACM may be present in concealed locations not identified in this report.

The assessment confirmed the presence of ACM mechanical insulations within the building (Refer to room-by-room Inventory for condition and quantities). Should any proposed renovations likely cause disturbance of the mechanical insulations, the materials would require removal using Type 2, Type 3 or Glove Bag Asbestos procedures as appropriate for the work being performed.

If asbestos-containing vinyl floor tiles are likely to be disturbed, the tiles should be removed using Type 1 Asbestos procedures (provided no power tools are used and the material is wetted). The use of power tools would require Type 3 Asbestos procedures.

Removal or disturbance of transite cement products requires the use of Type 1 Asbestos procedures (provided no power tools are used and the material is wetted). If power tools are required Type 3 Asbestos procedures need be applied.

Asbestos-containing drywall joint compound is present within the building. Removal or disturbance of ACM drywall less than 1m<sup>2</sup> will require the use of Type 1 Asbestos procedures, greater than 1m<sup>2</sup> Type 2 Asbestos procedures.

Sample plaster finishes for asbestos content prior to disturbance. The removal or disturbance of asbestos-containing plaster finishes less than 1m<sup>2</sup> will require the use of Type 2 Asbestos procedures; greater than 1m<sup>2</sup> Type 3 Asbestos procedures apply.

Disturbance of siporex joint compound requires the use of Type 1 asbestos procedures (provided no power tools are used and the material is wetted). If power tools are required Type 3 Asbestos procedures need be applied.

### **5.2 Specific Recommendations**

Using Type 2 Asbestos Repair Procedures in accordance with Ontario Regulation 278/05, repair the following ACM pipe fitting insulations:

- One (1) fitting within Ebase 239 (Gym C), height restricted at roof hopper;

- Two (2) fittings within Ebase 339 (Mezzanine)

All remaining asbestos-containing materials identified within the building were observed to be in GOOD condition and therefore no additional recommendations are warranted.

## **6.0 LIMITATIONS**

Due to the nature of building construction some limitations exist as to the possible thoroughness of the subject investigation. The field observations are considered sufficient in detail and scope to form a reasonable basis for the findings presented in this report. MAPLE warrants that the findings and conclusions contained herein have been made in accordance with generally accepted evaluation methods in the industry and applicable regulations at the time of the performance of the assessment.

It is possible that conditions may exist which could not be reasonably identified within the scope of the investigation or which were not apparent during the site investigation. MAPLE believes that the information collected during the investigation period concerning the property is reliable. No other warranties are implied or expressed.

Information provided by Maple is intended for Client use only. Any use by a third party, of reports or documents authored by Maple, or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Maple accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted.

The liability of Maple or its staff will be limited to the lesser of the fees paid or actual damages incurred by the Client. Maple will not be responsible for any consequential or indirect damages. Maple will only be liable for damages resulting from negligence of Maple; all claims by the Client shall be deemed relinquished if not made within two years after last date of services provided.

Please contact Maple Environmental Inc. at (905) 257-4408 for inquiries regarding this project.

**Sincerely,**

**MAPLE ENVIRONMENTAL INC.**  
Environment, Health and Safety Consultants



**Josh Prosser**  
**Project Technologist**

**APPENDIX I**  
**ROOM-BY-ROOM ASBESTOS INVENTORY**



STRUCTURAL ELEMENT			ACCESSIBILITY				TERMINOLOGY																					
RF: Roof			B/J: Beams/Joists				A: All occupants of the facility										N/A: Not Applicable			PL: Plaster			TB: Transite Board			VSF: Vinyl Sheet Flooring		
WN: Window			CB: Chalkboard				B: Maintenance staff without a ladder										N/Anz: Not Analyzed			RM: Roofing Materials			TP: Transite Pipe			V/C: Visually Consistent w/ Other Sampled Material		
FL:Floor			PI: Pipe				C: Maintenance staff with a ladder, exposed to view without moving building components										N/D: None Detected			SFP: Sprayed Fireproofing			VI: Vermiculite Insulation			WC: Window Caulking		
CL:Ceiling			DT:Duct				D: Maintenance staff with a ladder, concealed from view by building components										PI-AC: Pipe Insulation - Aircell			SF: Square Feet			VFT: Vinyl Floor Tile					
WL:Wall			BL:Boiler				E: No access without demolition or removal of fixed building components or systems										LF: Linear Feet			PI-PC: Pipe Insulation-Parging Cement			TF: Texture Finish					
DK:Deck			MC:Mechanical														MA: Mastic			PI-CP: Pipe Insulation-Caposite								
							CONDITION										G: Good			F: Fair			P: Poor					
Floor #	Room #	Room name	Has ACM	Friable	Struct. Elem.	Application	Material	Type	Qty	Condition	Sample #	Action	Ref #	Comments 1	Comments 2	Comments 3	Notes											
2	202	HALLWAY 5	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-														
2	202	HALLWAY 5	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	203	201	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-														
2	203	201	No	No	WL	PL		N/D	-	-	16-BS-17A			-														
2	203	201	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	204	203	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-														
2	204	203	No	No	WL	PL		N/D	-	-	V/C 16-BS-16			-														
2	204	203	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	205	205	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-														
2	205	205	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-														
2	205	205	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	206	207	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-														
2	206	207	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-														
2	206	207	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	206	207	-	-	-	VFT	-	-	-	-	-			-														
2	206	211	Yes	No	WL	DJC		3% CHRYSOTILE	1	G	14398-21-PR9-04A-C			A			On Columns											
2	206	211	No	No	CL	DJC		N/D	-	-	14398-21-PR9-03A-E			-														
2	207	STUDENT CENTRE	No	No	FL	VFT	6	N/D	-	-	V/C 16-BS-07			-														
2	207	STUDENT CENTRE	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-														
2	207	STUDENT CENTRE	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	207	STUDENT CENTRE	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-														
2	208	HALLWAY 6	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-														
2	209	209	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-														
2	209	209	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-														
2	209	209	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	211	STAFF ROOM (246)	No	No	FL	VFT	6	N/D	-	-	V/C 16-BS-07			-														
2	211	STAFF ROOM (246)	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-														
2	211	STAFF ROOM (246)	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	212	LIBRARY	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	212	LIBRARY	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	212A	LIBRARY OFFICE	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	212A	LIBRARY OFFICE	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	212B	WORKROOM	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	212B	WORKROOM	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	212C	SEMINAR 1	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	212C	SEMINAR 1	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	212D	SEMINAR 2	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	212D	SEMINAR 2	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	212E	SEMINAR 3	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	212E	SEMINAR 3	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	213	HALLWAY 9	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-														
2	213	HALLWAY 9	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	214	221	No	No	FL	VFT	9	N/D	-	-	-			-														
2	214	221	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	214	221	Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			C			ABOVE CEILING											
2	214	221	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	216	BOYS WASHROOM 2N	No	No	CL	CT	1	N/D	-	-	-			-														
2	217	CUSTODIAN CLOSET 2N	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	218	GIRLS WASHROOM 2N	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	218	GIRLS WASHROOM 2N	Yes	No	WL	PL		0.6% CHRYSOTILE	1	G	14398-21-PR5-01A-C			A														
2	219	229	No	No	FL	VFT	12	3% CHRYSOTILE	-	-	16-BS-14A			-			VFT-12 REPLACED WITH NON ACM VFT-13											
2	219	229	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	219	229	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	220	231	No	No	FL	VFT	12	3% CHRYSOTILE	-	G	V/C 16-BS-14			-			VFT-12 REPLACED WITH NON ACM VFT-13											
2	220	231	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	220	231	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	221	233	No	No	FL	VFT	12	3% CHRYSOTILE	-	-	V/C 16-BS-14			-			VFT-12 REPLACED WITH NON ACM VFT-13											
2	221	233	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-														
2	221	233	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	222	235	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04			-														
2	222	235	No	No	CL	CT	1	N/D	-	-	16-BS-08C			-														
2	222	235	No	No	WL	PL		N/D	-	-	16-BS-17G			-														
2	223	HALLWAY 8	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-														
2	223	HALLWAY 8	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A														
2	224	237	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04			-														





STRUCTURAL ELEMENT				ACCESSIBILITY				TERMINOLOGY											
RF: Roof		B/J: Beams/Joists		A: All occupants of the facility				N/A: Not Applicable				PL: Plaster		TB: Transite Board		VSF: Vinyl Sheet Flooring			
WN: Window		CB: Chalkboard		B: Maintenance staff without a ladder				N/Anz: Not Analyzed				RM: Roofing Materials		TP: Transite Pipe		V/C: Visually Consistent w/ Other Sampled Material			
FL: Floor		PI: Pipe		C: Maintenance staff with a ladder, exposed to view without moving building components				N/D: None Detected				SFP: Sprayed Fireproofing		VI: Vermiculite Insulation		WC: Window Caulking			
CL: Ceiling		DT: Duct		D: Maintenance staff with a ladder, concealed from view by building components				PI-AC: Pipe Insulation - Aircell				SF: Square Feet		VFT: Vinyl Floor Tile					
WL: Wall		BL: Boiler		E: No access without demolition or removal of fixed building components or systems				LF: Linear Feet				PI-PC: Pipe Insulation-Parging Cement		TF: Texture Finish					
DK: Deck		MC: Mechanical						MA: Mastic				PI-CP: Pipe Insulation-Caposite							
				CONDITION				G: Good F: Fair P: Poor											
Floor #	Room #	Room name	Has ACM	Friable	Struct. Elem.	Application	Material	Type	Qty	Condition	Sample #	Action	Ref #	Comments 1	Comments 2	Comments 3	Notes		
2	224	237	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16		-	-					
2	225	239	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04		-	-					
2	225	239	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16		-	-					
2	225	239	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18		A	-					
2	226	241	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04		-	-					
2	226	241	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16		-	-					
2	226	241	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18		A	-					
2	227	243	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16		-	-					
2	227	243	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18		A	-					
2	228	ART ROOM	No	-	-	-	-	-	-	-	-		-	-			NO ACM		
2	230	247	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16		-	-					
2	230	247	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18		A	-					
2	231	HALLWAY 7	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18		A	-					
2	231	HALLWAY 7	No	No	WL	PL		N/D	-	-	16-BS-17E		-	-					
2	232	249	No	No	FL	VFT	6	N/D	-	-	V/C 16-BS-07		-	-					
2	232	249	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08		-	-					
2	232	249	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16		-	-					
2	232	249	No	No	CL	CT	3	N/D	-	-	V/C 12578-01		-	-			FIXTURES		
2	232	249	No	No	WL	PL		N/D	-	-	V/C 16-BS-17		-	-					
2	232	249	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18		A	-					
2	233	251	No	No	FL	VFT	6	N/D	-	-	V/C 16-BS-07		-	-					
2	233	251	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08		-	-					
2	233	251	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16		-	-					
2	233	251	No	No	CL	CT	3	N/D	-	-	V/C 12578-01		-	-					
2	233	251	No	No	WL	PL		N/D	-	-	V/C 16-BS-17		-	-					
2	233	251	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18		A	-					
2	235	GIRLS WASHROOM by	No	No	CL	PL		N/D	-	-	V/C 16-BS-17		-	-			HALLWAY 7		
2	235	GIRLS WASHROOM by	No	No	WL	PL		N/D	-	-	V/C 16-BS-17		-	-					
2	236	CUSTODIAN ROOM by	No	No	CL	DJC		N/A	-	-	-		-	-			All drywall removed during 2013 renovation.		
2	237	BOYS WASHROOM By	No	No	CL	PL		N/D	-	-	V/C 16-BS-17		-	-			HALLWAY 7		
2	237	BOYS WASHROOM By	No	No	WL	PL		N/D	-	-	V/C 16-BS-17		-	-					
2	239	GYM C	Yes	Yes	FTG	PI-PC		25% CHRYSOTILE	1	F	V/C 16-BS-01		D	-					
2	239	GYM C	Yes	No	DK	DK		0.5% CHRYSOTILE	100%	G	18133-S02						Siporex Joint Compound in seams of DECK. Sampled by Maple Aug 2019		
2	239A	GYM STORAGE	Yes	No	CL	DJC		5% CHRYSOTILE	1	G	16-BS-18E		C	-					
2	239A	GYM STORAGE	No	No	CL	CT	1	N/D	-	-	16-BS-08A		-	-					
2	239B	GIRLS PE OFFICE	Yes	No	FL	VFT	2	5% CHRYSOTILE	200 SF	G	16-BS-03B		A	-					
2	239B	GIRLS PE OFFICE	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16		-	-					
2	240	STAGE	No	No	FL	VFT (New)	13	N/A	-	-	N/S		-	-			REMOVED-Replaced with new VFT		
2	240	STAGE	No	No	FL	VFT (New)	13	N/A	-	-	N/S		-	-			REMOVED-Replaced with new VFT		
2	240	STAGE	Yes	No	CL	DJC		5% CHRYSOTILE	100 SF	G	V/C 16-BS-18		C	-					
2	240	STAGE	No	No	FTG	PI-PC		25% CHRYSOTILE	0	G	V/C 16-BS-01		D	-			REMOVED IN 2017		
2	240	STAGE	Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18		C	-					
2	240	STAGE	No	No	FTG	PI-PC		25% CHRYSOTILE	0	F	V/C 16-BS-01			-			REMOVED IN 2017		
2	242	GYM A B	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08		-	-					
2	242	GYM A B	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18		C	-					
2	242	GYM A B	Yes	No	PI	TP		VISUALLY ACM	6 LF	G	-		C	-			TOO HIGH TO CONFIRM TRANSITE		
2	243	ART STORAGE	-	-	-	-	-	-	-	-	-		-	-					
2	244	GIRLS CHANGEROOM	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16		-	-					
2	244	GIRLS CHANGEROOM	No	No	CL	DJC			-	-	-		-	-			All drywall removed during 2013 renovation.		
2	244	GIRLS CHANGEROOM	No	No	WL	PL		N/D	-	-	V/C 16-BS-17		-	-					
2	245	MEN'S WASHROOM By	No	No	FL	VFT (NEW)			-	-	-		-	-			All ACM VFT removed during 2013 renovation. Mastic analyzed and is non-asbestos.		
2	245	MEN'S WASHROOM By	No	No	CL	DJC			-	-	-		-	-			All drywall removed during 2013 renovation.		
2	245	MEN'S WASHROOM By	No	No	WL	PL		N/D	-	-	V/C 16-BS-17		-	-					
2	246	PE STORAGE	No	No	FL	VFT	4	N/D	-	-	V/C 16-BS-05		-	-					
2	246	PE STORAGE	No	No	CL	DJC			-	-	-		-	-			All drywall removed during 2013 renovation.		
2	246	PE STORAGE	No	No	WL	PL		N/D	-	-	V/C 16-BS-17		-	-					
2	246	PE STORAGE	No	No	WL	DJC			-	-	-		-	-			All ACM drywall removed during 2013 renovation.		
2	247	STUDENT STORAGE	No	No	FL	VFT	9	N/D	-	-	16-BS-11A-C		-	-					
2	247	STUDENT STORAGE	No	No	CL	DJC			-	-	-		-	-			All ACM drywall removed during 2013 renovation.		
2	247	STUDENT STORAGE	No	No	CL	PL			-	-	-		-	-			All ACM plaster removed during 2013 renovation.		
2	247	STUDENT STORAGE	No	No	WL	PL			-	-	-		-	-			All ACM plaster removed during 2013 renovation.		
2	247	STUDENT STORAGE	No	No	WL	DJC			-	-	-		-	-			All ACM drywall removed during 2013 renovation.		
2	248	BOYS CHANGEROOM	No	No	CL	PL		N/D	-	-	V/C 16-BS-17		-	-					



STRUCTURAL ELEMENT				ACCESSIBILITY				TERMINOLOGY															
RF: Roof				B/J: Beams/Joists				A: All occupants of the facility												N/A: Not Applicable			
WN: Window				CB: Chalkboard				B: Maintenance staff without a ladder												N/Anz: Not Analyzed			
FL: Floor				PI: Pipe				C: Maintenance staff with a ladder, exposed to view without moving building components												N/D: None Detected			
CL: Ceiling				DT: Duct				D: Maintenance staff with a ladder, concealed from view by building components												PI-AC: Pipe Insulation - Aircell			
WL: Wall				BL: Boiler				E: No access without demolition or removal of fixed building components or systems												PI-PC: Pipe Insulation-Parging Cement			
DK: Deck				MC: Mechanical																PI-CP: Pipe Insulation-Caposite			
								CONDITION												G: Good F: Fair P: Poor			
Floor #	Room #	Room name	Has ACM	Friable	Struct. Elem.	Application	Material	Type	Qty	Condition	Sample #	Action	Ref #	Comments 1	Comments 2	Comments 3	Notes						
2	248	BOYS CHANGEROOM	No	No	WL	PL			-	-				-			All ACM plaster removed during 2013 renovation. Renovated						
2	248	BOYS WASHROOM	No	No	CL	PL		N/D	-	-	V/C 16-BS-17			-									
2	248	BOYS WASHROOM	No	No	WL	PL			-	-				-			All ACM plaster removed during 2013 renovation. 4 FTG removed Summer 2013						
2	249	PE OFFICE BY GYM A&B	No	Yes	FTG	PI-PC		25% CHRYSOTILE	-	-	V/C 16-BS-01			-									
2	249	PE OFFICE BY GYM A&B	Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			C			20 SF of Drywall with DJC removed yesom rear storage area ceiling Summer 2013.						
2	250	PE OFFICE WASHROOM	No	No	FL	VFT			-	--				-			Removed July 2017						
2	250	PE OFFICE WASHROOM	No	No	FL	VFT			-	--				-			REMOVED JULY 2017						
2	251	BOYS CHANGEROOM	No	No	FL	VFT	12	3% CHRYSOTILE	-	-	V/C 16-BS-14			-			NOT PRESENT. APPEARS TO BE RENOVATED						
2	251	BOYS CHANGEROOM	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-									
2	251	BOYS CHANGEROOM	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
2	251	BOYS CHANGEROOM	Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			C									
2	252	GIRLS CHANGEROOM	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			APPEARS TO BE NEW						
2	252	GIRLS CHANGEROOM	No	No	CL	PL		N/D	-	-	V/C 16-BS-17			-									
2	252	GIRLS CHANGEROOM	Yes	No	WL	PL		2% CHRYSOTILE	1	G	14398-21-PR7-08A-C			A									
2	255	208	-	No	FL	VSF		-	-	G	-			A			VISUALLY NON-ACM						
2	255	208	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-									
2	255	208	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
2	255	208	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
2	256	206	-	No	FL	VSF		-	-	-	-			-			VISUALLY NON-ACM						
2	256	206	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-									
2	256	206	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
2	256	206	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
2	257	204	-	No	FL	VSF		-	-	-	-			-			VISUALLY NON-ACM						
2	257	204	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-									
2	257	204	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
2	257	204	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
2	258	202	No	No	CL	CT	2	N/D	-	-	16-BS-16A			-									
2	258	202	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
2	258	202	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	16-BS-18D			A									
2	299	245	No	No	FL	VFT	6	N/D	-	-	V/C 16-BS-07			-									
2	299	245	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-									
2	299	245	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	215	322	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04			-									
3	215	322	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	215	322	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	302	HALLWAY 12	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-									
3	302	HALLWAY 12	Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			D			ABOVE CEILING						
3	302	HALLWAY 12	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	303	MATH OFFICE	Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			C			ABOVE CEILING						
3	303	MATH OFFICE	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	303	MATH OFFICE	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	305	303	No	No	FL	VFT	10	N/D	-	-	V/C 16-BS-12			-									
3	305	303	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	305	303	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	305	303	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	307	305	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04			-									
3	307	305	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	307	305	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	308	307	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	308	307	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	308	307	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	309	309	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	309	309	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	309	309	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	310	HALLWAY 13	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-									
3	310	HALLWAY 13	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	313	324	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04			-									
3	313	324	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	313	324	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	313A	324 OFFICE	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	313A	324 OFFICE	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	313A	NETWORK ROOM	Yes	No	FL	VFT	2	5% CHRYSOTILE	50 SF	G	V/C 16-BS-03			A									
3	313A	NETWORK ROOM	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	314	CO-OP CENTRE	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									



STRUCTURAL ELEMENT			ACCESSIBILITY			TERMINOLOGY											
RF: Roof	B/J: Beams/Joists		A: All occupants of the facility			N/A: Not Applicable			PL: Plaster			TB: Transite Board			VSF: Vinyl Sheet Flooring		
WN: Window	CB: Chalkboard		B: Maintenance staff without a ladder			N/Anz: Not Analyzed			RM: Roofing Materials			TP: Transite Pipe			V/C: Visually Consistent w/ Other Sampled Material		
FL:Floor	PI: Pipe		C: Maintenance staff with a ladder, exposed to view without moving building components			N/D: None Detected			SFP: Sprayed Fireproofing			VI: Vermiculite Insulation			WC: Window Caulking		
CL:Ceiling	DT:Duct		D: Maintenance staff with a ladder, concealed from view by building components			PI-AC: Pipe Insulation - Aircell			SF: Square Feet			VFT: Vinyl Floor Tile					
WL:Wall	BL:Boiler		E: No access without demolition or removal of fixed building components or systems			LF: Linear Feet			PI-PC: Pipe Insulation-Parging Cement			TF: Texture Finish					
DK:Deck	MC:Mechanical					MA: Mastic			PI-CP: Pipe Insulation-Caposite								
						CONDITION			G: Good F: Fair P: Poor								
Floor #	Room #	Room name	Has ACM	Friable	Struct. Elem.	Application	Material	Type	Qty	Condition	Sample #	Action	Ref #	Comments 1	Comments 2	Comments 3	Notes
3	314	CO-OP CENTRE	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	314	CO-OP CENTRE	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-			
3	314A	CO-OP OFFICE	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	314A	CO-OP OFFICE	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	314A	CO-OP OFFICE	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-			
3	314A	CO-OP OFFICE	No	No	FL	VFT (New)	13	N/A	-	-	N/S			-			REMOVED-Replaced with new VFT
3	316	320	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04			-			
3	316	320	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	316	320	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	317	318	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04			-			
3	317	318	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	317	318	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	318	316	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04			-			
3	318	316	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	318	316	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	319	314	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04			-			
3	319	314	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	319	314	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	320	313	No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04			-			
3	320	313	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-			
3	320	313	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	322	CUSTODIAN CLOSET 1	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			ADJACENT TO ROOM 313
3	322	CUSTODIAN CLOSET 1	No	Yes	FTG	PI-PC		25% CHRYSOTILE	-	-	V/C 16-BS-01			-			ACM pipe fittings removed in 2016.
3	323	315	No	No	FL	VFT	2	5% CHRYSOTILE	-	-	V/C 16-BS-03			-			VFT-2 REPLACED WITH NON ACM VFT-13
3	323	315	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	323	315	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-			
3	323	315	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	323	315	Yes	No		TB		VISUALLY ACM	100 SF	G				A			COUNTERTOP+FUME HOODS
3	323	315	No	No	DT	TF		N/D	-	-	12578-02A-C			-			ON AIR VENTS ABOVE CEILING
																	2018-07 WAS PREVIOUSLY REPLACED
3	324	317	No	No	FL	VFT	2	5% CHRYSOTILE	0	G	V/C 16-BS-03			A			VFT-2 REPLACED WITH NON ACM VFT-13
3	324	317	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	324	317	Yes	No		TB		VISUALLY ACM	50 SF	G				A			COUNTERTOP+FUME HOODS
3	324	317	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-			
3	324	317	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	324	317	No	No	DT	TF		N/D	-	-	V/C 12578-02			-			ON AIR VENTS ABOVE CEILING
3	325	319	No	No	FL	VFT	2	N/A	-	-	V/C 16-BS-03			-			VFT-2 REPLACED WITH NON ACM VFT-13
3	325	319	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	325	319	Yes	No		TB		VISUALLY ACM	100 SF	G				A			COUNTERTOP+FUME HOODS
3	325	319	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-			
3	325	319	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	16-BS-18F			A			
3	325	319	No	No	DT	TF		N/D	-	-	V/C 12578-02			-			ON AIR VENTS ABOVE CEILING
3	326	321	No	No	FL	VFT	2	N/A	-	-	V/C 16-BS-03			-			VFT-2 REPLACED WITH NON ACM VFT-13
3	326	321	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	326	321	Yes	No		TB		VISUALLY ACM	50 SF	G				A			COUNTERTOP+FUME HOODS
3	326	321	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-			
3	326	321	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	326	321	No	No	DT	TF		N/D	-	-	V/C 12578-02			-			ON AIR VENTS ABOVE CEILING
3	327	323	No	No	FL	VFT			-	-				-			VFT-2 REPLACED WITH NON ACM VFT-13
3	327	323	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	327	323	Yes	No		TB		VISUALLY ACM	100 SF	G				A			COUNTERTOP+FUME HOODS
3	327	323	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-			
3	327	323	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	327	323	No	No	DT	TF		N/D	-	-	V/C 12578-02			-			ON AIR VENTS ABOVE CEILING
3	328	HALLWAY 11	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-			
3	328	HALLWAY 11	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A			
3	328	HALLWAY 11	Yes	Yes	FTG	PI-PC		25% CHRYSOTILE	1	G	V/C 16-BS-01			D			From previous survey - cannot locate.
3	329	SCIENCE OFFICE	No	No	FL	VFT	10	N/D	-	-	V/C 16-BS-12			-			
3	329	SCIENCE OFFICE	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	330	329	No	No	FL	VFT	10	N/D	-	-	V/C 16-BS-12			-			
3	330	329	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			
3	330	329	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-			
3	331	331	No	No	FL	VFT	10	N/D	-	-	V/C 16-BS-12			-			
3	331	331	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-			



STRUCTURAL ELEMENT				ACCESSIBILITY				TERMINOLOGY															
RF: Roof				B/J: Beams/Joists				A: All occupants of the facility												N/A: Not Applicable			
WN: Window				CB: Chalkboard				B: Maintenance staff without a ladder												N/Anz: Not Analyzed			
FL:Floor				PI: Pipe				C: Maintenance staff with a ladder, exposed to view without moving building components												N/D: None Detected			
CL:Ceiling				DT:Duct				D: Maintenance staff with a ladder, concealed from view by building components												PI-AC: Pipe Insulation - Aircell			
WL:Wall				BL:Boiler				E: No access without demolition or removal of fixed building components or systems												LF: Linear Feet			
DK:Deck				MC:Mechanical																PI-CP: Pipe Insulation-Caposite			
CONDITION																G: Good F: Fair P: Poor							
Floor #	Room #	Room name	Has ACM	Friable	Struct. Elem.	Application	Material	Type	Qty	Condition	Sample #	Action	Ref #	Comments 1	Comments 2	Comments 3	Notes						
3	331	331	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	332	333	No	No	FL	VFT	10	N/D	-	-	V/C 16-BS-12			-									
3	332	333	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	332	333	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	332	333	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	16-BS-18G			A									
3	333	335	No	No	FL	VFT	10	N/D	-	-	V/C 16-BS-12			-									
3	333	335	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	333	335	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	334	337	No	No	FL	VFT	10	N/D	-	-	V/C 16-BS-12			-									
3	334	337	No	No	CL	CT	2	N/D	-	-	16-BS-16C			-									
3	334	337	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	336	GIRLS WASHROOM 3R	No	No	CL	PL		N/D	-	-	V/C 16-BS-17			-									
3	336	GIRLS WASHROOM 3R	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	337	CUSTODIAN CLOSET 2	Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			C									
3	338	BOYS WASHROOM 3R	No	No	CL	PL		N/D	-	-	V/C 16-BS-17			-									
3	338	BOYS WASHROOM 3R	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	339	GYM C MEZZANINE	Yes	No	FL	VFT	12	3% CHRYSOTILE	200 SF	G	V/C 16-BS-14			A			On stairs only.						
3	339	GYM C MEZZANINE	Yes	Yes	FTG	PI-PC		25% CHRYSOTILE	4	G	V/C 16-BS-01			C									
3	339	GYM C MEZZANINE	Yes	Yes	FTG	PI-PC		25% CHRYSOTILE	2	F	V/C 16-BS-01			C									
3	339	THRESHOLD	No	No	FL	VFT			-	-				-									
3	339A	MECH ROOM SOUTH	No		NA	NO ACM		NA	NA	NA	NA			NA									
3	340	HALLWAY 10	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-									
3	340	HALLWAY 10	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	341	334	No	No	FL	VFT	10	N/D	-	-	V/C 16-BS-12			-									
3	341	334	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	341	334	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	342	332	No	No	FL	VFT	9	N/D	-	-	V/C 16-BS-11			-									
3	342	332	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	342	332	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	343	MAINTENANCE	-	-	-	-	-	-	-	-	-			-									
3	344	328	No	No	FL	VFT	4	N/D	-	-	V/C 16-BS-05			-									
3	344	328	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	344	328	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	345	326	No	No	FL	VFT	9	N/D	-	-	V/C 16-BS-11			-									
3	345	326	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	345	326	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	346	MECHANICAL OFFICE	-	-	-	-	-	-	-	-	-			-									
3	348	WEIGHT ROOM	-	-	-	-	-	-	-	-	-			-									
3	349	311	No	No	FL	VFT	10	N/D	-	-	V/C 16-BS-12			-									
3	349	311	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	350	CUSTODIAN ROOM	No	No	FL	VFT	10	N/D	-	-	V/C 16-BS-12			-									
3	350	CUSTODIAN ROOM	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	351	310	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	351	310	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	351	310	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	352	308	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	352	308	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	352	308	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	353	306	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	353	306	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	353	306	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	354	304	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	354	304	No	No	WL	PL		N/D	-	-	16-BS-17F			-									
3	354	304	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
3	355	302	Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			C			ABOVE CEILING						
3	355	302	No	No	CL	CT	1	N/D	-	-	V/C 16-BS-08			-									
3	355	302	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-									
3	355	302	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A									
G	101	LOBBY	No	No	CL	DJC		N/D	-	-	14398-21-PR15-ACM-01A-C			-									
G	101	LOBBY	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	16-BS-18A			A									
G	102	CAFETERIA	No	No	FL	VFT	1	N/D	-	-	16-BS-02A-C			-			Mastic analyzed and is non-asbestos						
G	102	CAFETERIA	No	No	FL	VFT	4	N/D	-	-	16-BS-05A-C			-			Mastic analyzed and is non-asbestos						
G	102	CAFETERIA	No	No	CL	CT	1	N/D	-	-	16-BS-08A			-									
G	102	CAFETERIA	Yes	No	WL	PL		1-2% CHRYSOTILE	-	-	15567-S01E			A			Plaster sample collected adjacent to elevator.						
G	102	CAFETERIA	No	No	WL	DJC		N/D	-	-	14398-21-PR6-05A-G			-									



STRUCTURAL ELEMENT				ACCESSIBILITY				TERMINOLOGY																			
RF: Roof		B/J: Beams/Joists		A: All occupants of the facility				N/A: Not Applicable												PL: Plaster		TB: Transite Board		VSF: Vinyl Sheet Flooring			
WN: Window		CB: Chalkboard		B: Maintenance staff without a ladder				N/Anz: Not Analyzed												RM: Roofing Materials		TP: Transite Pipe		V/C: Visually Consistent w/ Other Sampled Material			
FL: Floor		PI: Pipe		C: Maintenance staff with a ladder, exposed to view without moving building components				N/D: None Detected												SFP: Sprayed Fireproofing		VI: Vermiculite Insulation		WC: Window Caulking			
CL: Ceiling		DT: Duct		D: Maintenance staff with a ladder, concealed from view by building components				PI-AC: Pipe Insulation - Aircell												SF: Square Feet		VFT: Vinyl Floor Tile					
WL: Wall		BL: Boiler		E: No access without demolition or removal of fixed building components or systems				LF: Linear Feet												PI-PC: Pipe Insulation-Parging Cement		TF: Texture Finish					
DK: Deck		MC: Mechanical						MA: Mastic												PI-CP: Pipe Insulation-Caposite							
								CONDITION    G: Good    F: Fair    P: Poor																			
Floor #	Room #	Room name		Has ACM	Friable	Struct. Elem.	Application	Material	Type	Qty	Condition	Sample #	Action	Ref #	Comments 1	Comments 2	Comments 3	Notes									
G	103	KITCHEN		Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			C												
G	103	KITCHEN		No	No	WL	PL		N/D	-	-	16-BS-17C			-												
G	105	118		No	No	FL	VFT	1	N/D	-	-	V/C 16-BS-02			-												
G	105	118		No	No	FL	VFT	4	N/D	-	-	V/C 16-BS-05			-												
G	105	118		No	No	CL	CT	2	N/D	-	-	16-BS-16B			-												
G	105	118		Yes	No	WL	DJC		5% CHRYSOTILE	1	G	16-BS-18B			A												
G	106	116		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	106	116		Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A												
G	107	GIRLS WASHROOM		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	107	GIRLS WASHROOM		No	No	CL	PL		N/D	-	-	V/C 16-BS-17			-												
G	108	CUSTODIAN CLOSET		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	108	CUSTODIAN CLOSET		No	No	CL	PL		N/D	-	-	V/C 16-BS-17			-												
G	109	HALLWAY 2		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	109	HALLWAY 2		Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A												
G	110	STAFF WASHROOM		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	110	STAFF WASHROOM		No	No	CL	PL		N/D	-	-	V/C 16-BS-17			-												
G	111	BOYS WASHROOM		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	111	BOYS WASHROOM		No	No	CL	PL		N/D	-	-	V/C 16-BS-17			-												
G	112	HALLWAY 3		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	112	HALLWAY 3		Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A												
G	113	102		No	No	FL	VFT	5	N/D	-	-	16-BS-06A-B			-												
G	113	102		No	No	CL	CT	3	N/D	-	-	V/C 12578-01			-												
G	113	102		Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A												
G	114	103		No	No	FL	VFT	5	N/D	-	-	16-BS-06C			-												
G	114	103		No	No	CL	CT	3	N/D	-	-	V/C 12578-01			-												
G	114	103		Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A												
G	115	104		No	No	CL	CT	3	N/D	-	-	12578-01A-C			-												
G	115	104		Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A												
G	115	104		Yes	Yes	FTG	PI-PC		25% CHRYSOTILE	15 Fittings	G	V/C 16-BS-01			D			Fittings above 15 FT height-ACM by apperance only. 2018-07 Comment above is from previous assessments. Cannot locate.									
G	116	HALLWAY 4		No	No	CL	CT	3	N/D	-	-	V/C 12578-01			-												
G	116	HALLWAY 4		No	No	WL	PL		N/D	-	-	16-BS-17B			-												
G	116	HALLWAY 4		Yes	Yes	FTG	PI-PC		25% CHRYSOTILE	12	G	V/C 16-BS-01			D			Some fittings above 15 FT ceiling-ACM by appearance. 2018-07 Comment above is from previous assessments. Cannot locate.									
G	116	HALLWAY 4		No	Yes	FTG	PI-PC		25% CHRYSOTILE			V/C 16-BS-01						Removed - July 2017. Above Blue Guitar ceiling tile.									
G	118	BCT		No	No	CL	CT	3	N/D	-	-	V/C 12578-01			-												
G	118	BCT		Yes	Yes	FTG	PI-PC		25% CHRYSOTILE	2	G	V/C 16-BS-01			D			Fittings above 15 FT height-ACM by apperance above layin ceiling.									
G	118	BCT		Yes	No	PI	TP		VISUALLY ACM	6 LF	G	-			C												
G	120	107		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	120	107		Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			C			DJC in practise rooms sampled and is non-asbestos. (14398-20-PR2-01A-C & 02A-C)									
G	120D	MUSIC MEZZANINE		No	No	FL	VFT	3	N/D	-	-	16-BS-04A-C			-												
G	120D	MUSIC MEZZANINE		Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			C												
G	121	109		-	-	-	-	-	-	-	-	-			-												
G	122	111		No	No	FL	VFT (New)	13	N/A	-	-	N/S			-			REMOVED-Replaced with new VFT									
G	122	111		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	122	111		No	No	WL	DJC					V/C 16-BS-18			-			Removed from interior walls Summer 2019 Maple Project No 18074									
G	123	113		-	-	-	-	-	-	-	-	-			-												
G	124	115		-	-	-	-	-	-	-	-	-			-												
G	125	117 (NOW 101)		No	No	FL	VFT	3	N/D	-	-	V/C 16-BS-04			-												
G	125	117 (NOW 101)		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	126	GENERAL OFFICE		No	No	FL	VFT	6	N/D	-	-	16-BS-07C			-												
G	126	GENERAL OFFICE		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	126	GENERAL OFFICE		Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A												
G	127	VP OFFICE 1		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	127	VP OFFICE 1		Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A												
G	128	ATTENDANCE OFFICE		No	No	FL	VFT	6	N/D	-	-	V/C 16-BS-07			-												
G	128	ATTENDANCE OFFICE		No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-												
G	128	ATTENDANCE OFFICE		Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A												
G	129	KITCHEN 2		No	No	FL	VFT	6	N/D	-	-	16-BS-07B			-												



STRUCTURAL ELEMENT			ACCESSIBILITY				TERMINOLOGY												
RF: Roof	B/J: Beams/Joists		A: All occupants of the facility				N/A: Not Applicable				PL: Plaster			TB: Transite Board			VSF: Vinyl Sheet Flooring		
WN: Window	CB: Chalkboard		B: Maintenance staff without a ladder				N/Anz: Not Analyzed				RM: Roofing Materials			TP: Transite Pipe			V/C: Visually Consistent w/ Other Sampled Material		
FL: Floor	PI: Pipe		C: Maintenance staff with a ladder, exposed to view without moving building components				N/D: None Detected				SFP: Sprayed Fireproofing			VI: Vermiculite Insulation			WC: Window Caulking		
CL: Ceiling	DT: Duct		D: Maintenance staff with a ladder, concealed from view by building components				CT: Ceiling Tile				PI-AC: Pipe Insulation - Aircell			VFT: Vinyl Floor Tile					
WL: Wall	BL: Boiler						UJL: Drywall Joint Compound				FTG: Fitting								
DK: Deck	MC: Mechanical						LF: Linear Feet				PI-PC: Pipe Insulation-Parging Cement			TF: Texture Finish					
			E: No access without demolition or removal of fixed building components or systems				MA: Mastic				PI-CP: Pipe Insulation-Caposite								
							CONDITION				G: Good F: Fair P: Poor								
Floor #	Room #	Room name	Has ACM	Friable	Struct. Elem.	Application	Material	Type	Qty	Condition	Sample #	Action	Ref #	Comments 1	Comments 2	Comments 3	Notes		
G	129	KITCHEN 2	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-					
G	129	KITCHEN 2	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A					
G	130	VP OFFICE 2	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-					
G	130	VP OFFICE 2	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A					
G	131	OFFICE 1	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-					
G	131	OFFICE 1	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A					
G	132	PRINCIPALS OFFICE	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-					
G	132	PRINCIPALS OFFICE	Yes	No	CL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			C					
G	132	PRINCIPALS OFFICE	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A					
G	134	105	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A					
G	134	105	No	No	DBJ	SFP		N/D	-	-	16-BS-15A-E			-					
G	135	STORAGE	-	-	-	-	-	-	-	-	-			-					
G	136	BOILER ROOM	Yes	No	WL	DJC		3% CHRYSOTILE	-	-	14398-21-01A-C			-			NO DRYWALL IN ROOM		
G	137	STORAGE 1	-	-	-	-	-	-	-	-	-			-					
G	138	TRANSFORMER VAUL	-	-	-	-	-	-	-	-	-			-					
G	139	STORAGE 2	-	-	-	-	-	-	-	-	-			-					
G	140	MECHANICAL EQUIPM	-	-	-	-	-	-	-	-	-			-					
G	141	LUNCH ROOM	No	No	CL	CT	2	N/D	-	-	V/C 16-BS-16			-					
G	141	LUNCH ROOM	No	No	CL	PL		N/D	-	-	16-BS-17D			-					
G	141	LUNCH ROOM	No	No	WL	PL		N/D	-	-	V/C 16-BS-17			-					
G	141	LUNCH ROOM	Yes	No	WL	DJC		5% CHRYSOTILE	1	G	V/C 16-BS-18			A					
NA		EXTERIOR	Yes	No	RF	RM	NA	ACM ASSUMED	1	G	NS			C					
NA		EXTERIOR	No	No	WN	WC	NA	ACM ASSUMED	1	G	NS			A, C			sample prior to renovation		


# **APPENDIX II**

## **DRAWINGS**



Please Note:

- 1) Drywall Joint Compound (DJC) has been identified as ASBESTOS CONTAINING throughout the building.
- 2) Plaster walls and ceilings contain a mixture of ASBESTOS CONTAINING and NON ASBESTOS CONTAINING throughout the building.
- 3) Siporex Joint Compound (SJC) has been identified as ASBESTOS CONTAINING.



LEGEND

13491-XX-01A	2012 ECOH Sample Locations
14398-XX-01A	2013 ECOH Sample Locations
01-BS-01A	Jacques Whitford Sample Locations
#	Ebase Number

CONFIRMED ACM

SYMBOL	DESCRIPTION
	Friable Asbestos-Containing Material
	Non-Friable Asbestos-Containing Material
PI	Pipe Insulation (Friable Asbestos-Containing Material)
VFT	Vinyl Floor Tile (Non-Friable Asbestos-Containing Material)
TP	Transite Cement Pipe (Non-Friable Asbestos-Containing Material)
NOTE	Drywall Joint Compound
NOTE	Plaster
NOTE	Siporex Joint Compound

For Detailed Information as to Location, Type, Quantity, Condition and Access to ACM, Please Refer to the Room-by-Room Sheets Provided in the Report.

Huntsville High School

58 Brunel Road  
Huntsville, Ontario

Ground Floor Plan

Asbestos Materials Re-Assessment Survey

CLIENT: Trillium Lakelands District School Board

PROJECT NUMBER: 21124-21      DATE: September 2023      DRW BY: J. Prosser

SCALE: Not to Scale      CHK BY: K. Prosser




Please Note:

1) Drywall Joint Compound (DJC) has been identified as ASBESTOS CONTAINING throughout the building.

2) Plaster walls and ceilings contain a mixture of ASBESTOS CONTAINING and NON ASBESTOS CONTAINING throughout the building.

3) Siporex Joint Compound (SJC) has been identified as ASBESTOS CONTAINING.



## LEGEND

12578-XX-01A

ECOH Sample Locations

01-BS-01A

Jacques Whitford Sample Locations


#

Ebase Number


## CONFIRMED ACM

SYMBOL

DESCRIPTION



Friable Asbestos-Containing Material



Non-Friable  
Asbestos-Containing Material

PI

Pipe Insulation (Friable  
Asbestos-Containing Material)

VFT

Vinyl Floor Tile (Non-Friable  
Asbestos-Containing Material)

TP

Transite Cement Pipe (Non-Friable  
Asbestos-Containing Material)

NOTE

Drywall Joint Compound

NOTE

Plaster

NOTE

Siporex Joint Compound

For Detailed Information as to Location, Type, Quantity, Condition and Access to ACM, Please Refer to the Room-by-Room Sheets Provided in the Report.

## Huntsville High School

58 Brunel Road  
Huntsville, Ontario

## Second Floor Plan

Asbestos Materials Re-Assessment Survey

CLIENT:

Trillium Lakelands District School Board

PROJECT NUMBER:  
21124-21

DATE:  
September 2023

DRW BY:  
J. Prosser

SCALE:  
Not to Scale

CHK BY:  
K. Prosser



**MAPLE** ENVIRONMENTAL INC.


ENVIRONMENT, HEALTH & SAFETY CONSULTANTS

Please Note:

1) Drywall Joint Compound (DJC) has been identified as ASBESTOS CONTAINING throughout the building.

2) Plaster walls and ceilings contain a mixture of ASBESTOS CONTAINING and NON ASBESTOS CONTAINING throughout the building.

3) Siporex Joint Compound (SJC) has been identified as ASBESTOS CONTAINING.



**APPENDIX III**  
**POTENTIAL ASBESTOS-CONTAINING MATERIAL**  
**IDENTIFICATION SHEET**

### APPENDIX III - POTENTIAL ASBESTOS-CONTAINING MATERIALS INFORMATION SHEET

<i>MIN</i>	<i>Material</i>	<i>Material Description</i>	<i>Size</i>	<i>Sample Number</i>	<i>Sample Location</i>	<i>Asbestos Containing</i>
VFT-1	Vinyl Floor Tiles	White with blue specks	12 x 12	02A-C	Cafeteria	None
VFT-2	Vinyl Floor Tiles	Beige with white and black smears	12 x 12	03A-C	Room 111, Girl's PE Office, Room 323	5% Chrysotile
VFT-3	Vinyl Floor Tiles	Beige with dark smears	12 x 12	04A-C	Music Mezzanine	None
VFT-4	Vinyl Floor Tiles	Dark blue with white streaks	12 x 12	05A-C	Cafeteria	None
VFT-5	Vinyl Floor Tiles	Beige with red smears	12 x 12	06A-C	Room 102, 103	None
VFT-6	Vinyl Floor Tiles	Green with white smears	12 x 12	07A-C	Room 207, Kitchen, General Office	None
VFT-7	Vinyl Floor Tiles	Beige with streaks	9 x 9	09A-C	Hall by Stage	5% Chrysotile
VFT-8	Vinyl Floor Tiles	Light beige with red streaks	9 x 9	10A-C	Hall by Stage	12% Chrysotile
VFT-9	Vinyl Floor Tiles	White with blue smears	12 x 12	11A-C	Gym Storage Room	None
VFT-10	Vinyl Floor Tiles	Light beige with grey smears	12 x 12	12A-C	Co-op Centre	None
VFT-11	Vinyl Floor Tiles	White with green smears	12 x 12	13A-C	Staff Room	3% Chrysotile
VFT-12	Vinyl Floor Tiles	Brownish yellow with white streaks	12 x 12	14A-C	Room 229, PE Office	3% Chrysotile
VFT-13 (New)	Vinyl Floor Tiles	New Vinyl Floor Tiles	12 x 12	N/A	Multiple Areas	Non-ACM
VFT-14	Vinyl Floor Tiles	Beige with brown streaks	12 x 12	14398-21-PR7-11A-C	Men's W/C by Gym AB	Non-ACM
CT-1	Ceiling Tiles	Small fissure pin pattern with 8 square	2 x 4	08A-C	Cafeteria, Gym Equipment Room, Room 235	None
CT-2	Ceiling Tiles	Pinhole	2 x 4	16A-C	Room 202, 118, 337	None
CT-3	Ceiling Tiles	Pinhole Long Fissure	2 x 4	12578-21-01A-C	Room 104	None