

DESIGNATED SUBSTANCES AND HAZARDOUS BUILDING MATERIALS ASSESSMENT REPORT

**P00801 Window Replacements and Hollow Doors Repainting
St. Mary's Catholic School
340 Leacock Drive
Barrie, Ontario**

Prepared for:

**Paul Gignac
Capital Projects Officer**

**Simcoe Muskoka Catholic District School Board
49 Alliance Boulevard
Barrie, Ontario
L4M 5K3**

Prepared by:

Safetech Environmental Limited

A handwritten signature in black ink, appearing to read "Luke Guldemeester", written over a horizontal line.

**Luke Guldemeester, BA
OH&S Technician**

Reviewed by:

A handwritten signature in black ink, appearing to read "Larry Ramtahal", written over a horizontal line.

**Larry Ramtahal, CIH, ROH, CRSP
Sr. Occupational Hygienist**

Safetech Project Number: 4-4250091

Date of Site Work: April 11, 2025

Date of Issue: April 22, 2025

TABLE OF CONTENTS

EXECUTIVE SUMMARY	i
1.0 Introduction	1
1.1 Background and Objectives	1
1.2 Scope of Work.....	2
1.3 Description of Area(s) Assessed	3
2.0 Results	3
2.1 Designated Substances	3
2.1.1 Asbestos.....	3
2.1.2 Lead.....	7
2.1.3 Mercury.....	8
2.1.4 Silica	8
2.1.5 Other Designated Substances.....	8
2.2 Other Hazardous Materials	9
2.2.1 Chemical Hazards	9
2.2.2 Biological Hazards.....	9
2.2.3 Environmental Hazards	9
3.0 Conclusions and Recommendations.....	9
3.1 Designated Substances	9
3.1.1 Asbestos.....	9
3.1.2 Lead.....	10
3.1.3 Mercury.....	10
3.1.4 Silica	11
3.1.5 Other Designated Substances.....	12
3.2 Other Hazardous Materials	12
3.2.1 Chemical Hazards	12
3.2.2 Biological Hazards.....	12
3.2.3 Environmental Hazards	13
4.0 Limitations	13

LIST OF TABLES

Table 1: Summary of Hazardous Materials and Designated Substances

Table 2: Bulk Sample Analytical Results for Determination of Asbestos Content

Table 3: Results of Assessment for Asbestos-Containing Materials

Table 4: Results of Paint Condition and Lead Content Assessment

LIST OF APPENDICES

Appendix A: Summary of ACM Occurrences

Appendix B: Laboratory Certificate of Analysis – Asbestos

Appendix C: Laboratory Certificate of Analysis – Lead

Appendix D: Drawing

Appendix E: Methodology

EXECUTIVE SUMMARY

Safetech Environmental Limited (Safetech) was commissioned by Simcoe Muskoka Catholic District School Board to conduct a designated substances and hazardous materials assessment at St. Mary's Catholic School located at 340 Leacock Drive Barrie, Ontario.

The objective of the assessment was to determine the presence, location, condition and quantities of designated substances and other hazardous materials that have the potential to be disturbed as part of planned construction activities (i.e. P00801 Window Replacements and Hollow Doors Repainting) so that appropriate control measures can be implemented to protect workers during the work.

A summary of the assessment results and general recommendations based on our findings are provided in the following table. This table should be considered a summary only. Please refer to the Results (Section 2.0), Conclusions and Recommendations (Section 3.0) and Summary of ACM Occurrences (Appendix A) of our report for additional details.

Table 1: Summary of Hazardous Materials and Designated Substances


Designated Substance	Findings	Recommendations
Asbestos	<p>The following asbestos-containing materials were identified and sampled from the areas assessed that would be impacted during the proposed project.</p> <ul style="list-style-type: none"> - Door Threshold Caulking (Vestibule(s)) <p>The following presumed asbestos-containing materials were identified from the areas assessed that would be impacted during the proposed project.</p> <ul style="list-style-type: none"> - none identified 	<p>Disturbance of asbestos-containing materials must be conducted in accordance with Ontario Regulation 278/05 Designated Substance – Asbestos on Construction Projects and in Building and Repair Operations. Refer to Table 4 (Results of Assessment for Asbestos-Containing Materials), Section 3.1.1 (Conclusions and Recommendations) and Appendix A: Summary of ACM Occurrences. Asbestos-containing waste must be disposed of in accordance with R.R.O. 1990, Regulation 347, General - Waste Management.</p>
Lead	<p>Teal door casement and cream block wall surface coatings were found to be non-lead-containing paints (<0.0064% lead content).</p>	<p>Disturbance of lead-containing materials must be conducted in accordance with the Ontario Ministry of Labour, Immigration, Training and</p>

	<p>The following materials are assumed to be lead-containing:</p> <ul style="list-style-type: none"> - paints and surface coatings (not sampled) - glazing associated with ceramic tiles - solder in electrical components 	<p>Skills Development (MLITSD) <i>Lead on Construction Projects</i> guideline (2011) and/or the Environmental Abatement Council of Canada (EACC) <i>Lead Guideline</i> (October 2014). For additional details, refer to Section 3.1.2 (Conclusions and Recommendations). Lead-containing wastes should be recycled if practicable or handled and disposed of according to R.R.O. 1990, Regulation 347, <i>General- Waste Management</i>.</p>
Mercury	<p>Sources of mercury were observed in the subject area and include the following:</p> <ul style="list-style-type: none"> - vapour in fluorescent lamps - mechanical thermostat control panel(s) 	<p>Mercury-containing equipment is not expected to be impacted during the construction project.</p>
Silica	<p>Building materials identified that are suspected to contain crystalline silica and may be disturbed as part of the planned construction project include:</p> <ul style="list-style-type: none"> - concrete - mortar - grout - thinset 	<p>Any work involving the disturbance of silica-containing materials should follow the procedures outlined in the Ontario MLITSD <i>"Silica on Construction Projects"</i> guideline. For additional information, refer to Section 2.1.4 (Results) and Section 3.1.4 (Conclusions and Recommendations).</p>
Other Designated Substances	<p>No other designated substances are expected to be present in any significant quantities or in a form that would represent an exposure concern.</p>	<p>No protective measures or procedures specific to acrylonitrile, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates, and vinyl chloride are considered necessary.</p>
Other Hazardous Materials	Findings	Recommendations
Urea Formaldehyde Foam Insulation	<p>No UFFI was identified or is suspected in the subject area.</p>	<p>No action required.</p>
Mould Contamination	<p>No suspect mould contamination was observed on building finishes in the subject area.</p>	<p>No action required.</p>
Pest Infestation	<p>No pest infestations were observed in the areas assessed.</p>	<p>No action required.</p>
Polychlorinated Biphenyls	<p>No equipment was observed that is suspected to contain PCBs.</p>	<p>No action required.</p>
Ozone Depleting and Global Warming Substances	<p>No equipment was observed that is suspected to contain ozone depleting and/or global warming substances</p>	<p>No action required.</p>

This assessment satisfies the Owner's requirements under Section 30 of the Ontario Occupational Health and Safety Act (OHSA), Revised Statutes of Ontario 1990, as amended.

Should you have any questions regarding the information contained in the report, please contact our office.

Safetech Environmental Limited

A handwritten signature in black ink, appearing to read 'Luke Guldemeester', is written over a horizontal line.

**Luke Guldemeester, BA
OH&S Technician**

April 22, 2025

Simcoe Muskoka Catholic District School Board
49 Alliance Boulevard
Barrie, Ontario
L4M 5K3

Attention: Paul Gignac
Capital Projects Officer

**RE: Designated Substances and Hazardous Materials Assessment
P00801 Window Replacements and Hollow Doors Repainting
St. Mary's Catholic School
340 Leacock Drive, Barrie, Ontario**

1.0 INTRODUCTION

1.1 Background and Objectives

Safetech Environmental Limited (Safetech) was commissioned by Simcoe Muskoka Catholic District School Board to conduct a designated substances and hazardous materials assessment at St. Mary's Catholic School located at 340 Leacock Drive, Barrie, Ontario (subject areas). The objective of the assessment was to determine the presence, location, condition and quantities of designated substances and other hazardous materials in the subject areas that have the potential to be disturbed as part of planned construction activities (i.e. P00801 Window Replacements and Hollow Doors Repainting) so that appropriate control measures can be implemented to protect workers during the work.

This assessment satisfies the Owner's requirements under Section 30 of the Ontario Occupational Health and Safety Act (OHSA), Revised Statutes of Ontario 1990, as amended. Section 30(1) requires a building owner to determine if there are any designated substances present at a project site prior to construction or demolition activities. Sections 30(2), (3) and (4) require the Owner and constructors for a project to provide the findings in this report as part of the tendering information for any tendered project or to prospective contractors (and subcontractors) of a project before entering into a binding contract.

This report documents findings of our on-site inspection that was conducted on April 11, 2025 and provides conclusions and recommendations based on our findings and knowledge of the planned construction project.

1.2 Scope of Work

In accordance with our fee proposal document, our scope of work included the following activities:

- A review of existing documents, including renovation documents and drawings, floor plans and existing environmental assessment reports, etc., where available;
- A visual assessment of accessible area(s) in the subject areas to identify the presence, location, condition and quantities of designated substances and other hazardous materials;
- Collection, analysis and interpretation of representative bulk samples of suspect asbestos-containing building materials for the determination of asbestos content and material classification;
- Collection, analysis and interpretation of representative paint chip samples for the determination of lead content; and
- Preparation of a report to document findings and provide recommendations regarding control measures and/or special handling procedures for designated substances or specific hazardous materials that may be disturbed as part of planned construction activities.

Documents reviewed to aid in the assessment included the following:

- IFC drawing titled “*St. Mary’s School, Barrie, Ontario, for the Simcoe County Roman Catholic Separate School Board*”, prepared by Nesbitt Handy Architects Limited, dated August 15, 1990.
- IFC drawing titled “St Mary Window Replacement, 340 Leacock Dr, Barrie, ON, L4N 6J8”, not dated, prepared by Salterpilon Architecture.

This assessment only identified designated substances and hazardous materials that were deemed to be part of the building or somehow otherwise incorporated into the building structure and its finishes. **The following items were not included in our scope of work:**

- Assessing occupant items such as stored products, furnishings, items and materials used or produced as part of a manufacturing process;
- Investigating underground materials or equipment (vessels, drums, underground storage tanks, duct-banks, pipes, or cables);
- Assessing enclosed wall or ceiling cavities; and
- Assessing risers, pipe chases or elevator shafts.

1.3 Description of Area(s) Assessed

The area(s) investigated included all accessible locations of the subject areas. The areas investigated and findings are further illustrated in Appendix D: Drawing.

2.0 RESULTS

Results of our visual assessment and bulk sample analytical findings are summarized in the sections below.

2.1 Designated Substances

2.1.1 Asbestos

Results of bulk sample analysis for the determination of asbestos content are summarized in the following table. Materials have been classified as “ACM”, “Non-ACM”, “Suspected ACM” or “Presumed Non-ACM” based on analytical results. Materials classified as Suspected ACM or Presumed Non-ACM may require further analysis (depending on site-specific conditions) to verify whether the material should be classified as ACM or Non-ACM. Please refer to the Limitations section of this report (Section 4.0) for additional details. The Laboratory Certificate of Analysis is included in Appendix B.


Table 2: Bulk Sample Analytical Results for Determination of Asbestos Content





Sample No.	Material Description	Sample Location	Asbestos Content	Material Classification
S01A	Drywall Joint Compound	Room 201	None Detected	Non-ACM
S01B				
S01C				
S02A	Drywall Joint Compound	Room 123	None Detected	Non-ACM
S02B				
S02C				
S03A	Drywall Joint Compound	Room 134	None Detected	Non-ACM
S03B				
S03C				
S04A	Joint Compound 1	West Vestibule Stairwell	None Detected	Non-ACM
	Joint Compound 2			
S04B	Joint Compound 1			
	Joint Compound 2			
S04C	Joint Compound 1			
	Joint Compound 2			
S05A	Casement Caulking	Exterior Window Casement / Block – West Vestibule	None Detected	Non-ACM
S05B				
S05C				
S06A	Casement Caulking	Exterior Window Casement / Block – East Vestibule	None Detected	Non-ACM
S06B				
S06C				
S07A	Casement Caulking	Interior Window Casement / Block – East Vestibule	None Detected	Non-ACM
S07B				
S07C				



Sample No.	Material Description	Sample Location	Asbestos Content	Material Classification
S08A	Casement Caulking	Interior Window Casement / Block – West Vestibule	None Detected	Non-ACM
S08B				
S08C				
S09A	Window Glazing	Main Entrance Exterior Door	None Detected	Non-ACM
S09B	Cementitious Material			
S09C	Window Glazing			
S10A	Window Glazing	Kindergarten Exterior Window	None Detected	Non-ACM
S10B				
S10C				
S11A	Window Glazing	Room 134 Interior Window	0.32% Chrysotile	Non-ACM
S11B			<0.25% Chrysotile	
S11C			<0.25% Chrysotile	
S12A	Window Glazing	West Vestibule Exterior Window	None Detected	Non-ACM
S12B				
S12C				
S13A	Window Glazing	Room 202 Exterior Window	None Detected	Non-ACM
S13B				
S13C				
S14A	Door Threshold Caulking	Kindergarten Adjacent Vestibule Door Casement	1% Chrysotile	ACM
S14B				
S14C				
S15A	Block Mortar	Ground Floor Mechanical	None Detected	Non-ACM
S15B				
S15C				



Materials assessed for asbestos content are summarized in the following table based on the type/use of the material.

Table 3: Results of Assessment for Asbestos-Containing Materials

Sprayed and Loose Fill Insulating Materials	Location/Description	
Sprayed Fireproofing	None identified in subject areas.	
Sprayed Insulation	None identified in subject areas.	
Loose Fill / Vermiculite Insulation	None identified in subject areas. Inspections were performed via existing openings along the exterior stone block walls and representative inspections of interior block walls were performed via drilling. No loose fill / vermiculite insulation was discovered during these inspections. Should loose fill / vermiculite insulation be identified during the course of upcoming works, sampling should be performed prior to the recommencement of work.	

Thermal System Insulation	Location/Description	
Mechanical Pipe Insulation – Straights	None identified in subject areas.	
HVAC Duct Insulation	None identified in subject areas.	
HVAC Flex-Duct Connection	None identified in subject areas.	
Boiler Insulation	None identified in subject areas.	
Tank Insulation	None identified in subject areas.	
Window Glazing	Putty-like window glazing was observed in the subject areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is between <0.25% and 0.32% <i>chrysotile asbestos</i> , and as such is not considered to be an asbestos containing material. Refer to sample set S11 in Table 2.	
Window Glazing	Manufactured strip-like window glazing was observed in the subject areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample set S04 in Table 2.	
Casement Caulking	Window casement caulking was observed in the subject areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample sets S05-S08 in Table 2.	
Casement Caulking	Window casement caulking was observed in the subject areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample sets S05-S08 in Table 2.	

Other Mechanical Equipment Insulation	None identified in subject areas.	
Architectural Finishes & Finishing Materials	Location/Description	
Sprayed Texture / Stucco Finishes	None identified in subject areas.	
Firestop	None identified in subject areas.	
Plaster Finishes	None identified in subject areas.	
Drywall Joint Compound	Drywall joint compound was observed in the subject areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample sets S01-S04 in Table 2.	
Drywall Joint Compound	Drywall joint compound was observed in the subject areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample sets S01-S04 in Table 2.	
Mastic	None identified in subject areas.	
Ceiling Tiles	Location/Description	
Lay-in Acoustic Ceiling Tiles	None identified in subject areas.	
Glued-on Acoustic Ceiling Tiles	None identified in subject areas.	
Cement Ceiling Panels	None identified in subject areas.	
Flooring	Location/Description	
Vinyl Floor Tiles	None identified in subject areas.	
Mastic	None identified in subject areas.	

Vinyl Sheet Flooring	
Asbestos Cement Products	Location/Description
Piping	None identified in subject area.
Roofing, Siding, Wallboard	None identified in subject areas.
Ceramic Tile Grout	None identified in subject areas.
Ceramic Tile Thinset	None identified in subject areas.
Parging Cement	
Door Caulking	<p>Door threshold / vestibule casement caulking was observed in the subject areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material contains 1% chrysotile-asbestos and as such is to be considered an asbestos containing material. Refer to sample set S14 in Table 2</p> 
Block Mortar	<p>Block mortar was observed in the subject areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample set S15 in Table 2</p> 
Exterior Building Materials	Location/Description
Roofing Membrane	None identified in subject areas.
Shingles	None identified in subject areas.

2.1.2 Lead

Laboratory analytical results for paints tested to determine lead content are summarized in the following table. The Laboratory Certificate of Analysis is included in Appendix C. Refer to Section 3.1.2 of this report for recommended lead abatement procedures (if any) that correspond to the type of proposed construction, renovation, or demolition work.

Table 4: Results of Paint Condition and Lead Content Assessment

Sample No.	Location	Surface	Paint Colour	Condition	Lead Conc. (% by wt.)	Material Classification
LP1	Vestibule Door	Door Casement	Teal	Poor	<0.0064	Not Lead-Containing
LP2	Corridor	Block Wall	Cream	Good	<0.0064	Not Lead-Containing

Lead-Containing Material: $\geq 0.1\%$ Lead Content
 Low-Level Lead-Containing Materials: 0.009 to 0.1% Lead Content
 Not Lead-Containing: <0.009% Lead Content

Suspect lead-containing materials observed in the subject areas included the following:

- paints and surface coatings (not sampled)
- glazing associated with ceramic tiles
- solder in electrical components

2.1.3 Mercury

Mercury is present in the subject areas in the form of:

- vapour in fluorescent lamps
- mechanical thermostat control panel(s)

2.1.4 Silica

A number of building materials were identified in the subject areas that are **suspected to contain crystalline silica**. This includes the following materials:

- concrete
- mortar
- grout
- thinset

2.1.5 Other Designated Substances

Acrylonitrile, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates, and vinyl chloride were not included in the assessment as these substances are not expected to be a significant component of building materials or present in a form that would represent an exposure concern. Additionally, no specific information regarding their use was provided to us.

2.2 Other Hazardous Materials

2.2.1 Chemical Hazards

No visible evidence of UFFI installation (i.e. injection openings) or overspray of foam insulation at wall/ceiling joints was identified in the subject areas.

2.2.2 Biological Hazards

2.2.2.1 Mould Contamination

There was no visible evidence of obvious mould growth on building finishes in the subject areas at the time of the assessment. In addition, there was no visible evidence of any significant water staining or discolouration to building finishes in the subject areas that would suggest the potential for hidden mould growth behind these finishes.

2.2.2.2 Pest Infestation

There was no visible evidence of a pest infestation in the subject areas.

2.2.3 Environmental Hazards

2.2.3.1 Polychlorinated Biphenyls (PCBs)

No sources of polychlorinated biphenyls (PCBs) were observed in the subject areas.

2.2.3.2 Ozone Depleting and Global Warming Substances

No fixed equipment suspected to contain ODS/GWS was observed in the subject areas.

3.0 CONCLUSIONS AND RECOMMENDATIONS

3.1 Designated Substances

3.1.1 Asbestos

As results summarized in Table 2 indicate, no asbestos was detected in any of the bulk samples of caulking materials, block mortar or drywall joint compound retrieved for analysis. Therefore, these building materials are considered to be Non-ACM and there are no requirements for management, disturbance or removal of these materials under O. Reg. 278/05. No other suspect asbestos-containing materials were observed in the subject area.

Putty-like window glazing was determined to be between <0.25 to 0.32% Chrysotile asbestos, and as such is below the regulatory minimum threshold of 0.5% by weight and therefore does not meet the legal definition for an asbestos containing material.

Door threshold caulking (Vestibule(s)): is considered to be a non-friable ACM. As per O. Reg. 278/05, removal of non-friable ACM can be conducted following Type 1 operations; as long as the material can be removed without being broken, cut, drilled or

otherwise similarly disturbed. If the material cannot be removed without it breaking or being similarly disturbed then the work should be conducted using non-powered hand tools and the material should be wetted to control the spread of dust. If the material cannot be wetted or if power tools attached to dust-collecting devices equipped with HEPA (high efficiency particulate aerosol) filters are used during removal or disturbance, then work should be performed following Type 2 operations. If non-friable materials are removed or disturbed using power tools that are not attached to dust-collecting devices that are equipped with HEPA filters then work should be conducted following Type 3 operations.

3.1.2 Lead

Teal surface coatings associated with the vestibule door and exterior window casements, and cream surface coatings associated with interior block walls were found to be non-lead-containing paints (<0.0064% lead content) and as such require no additional measures for physical manipulation.

Paints and surface coatings not sampled are assumed to be lead-containing (>0.1% lead content) in the subject area.

Any disturbance of the lead-containing paints or surface coatings should be conducted in accordance with the procedures outlined in the Environmental Abatement Council of Canada (EACC) "Lead Guideline" (October 2014) and/or the Ontario Ministry of Labour, Training and Skills Development (MLTSD) "Lead on Construction Projects" guideline (April 2011). The extent of procedures required depends on the type of work to be conducted.

3.1.3 Mercury

Fluorescent lamps that require removal should be handled with care and kept intact to avoid potential exposure to mercury vapour present within the lamps. Under Reg. 347, waste mercury produced in amounts less than 5 kilograms (kg) in any month or otherwise accumulated in an amount less than 5 kg are exempt from hazardous waste registration, treatment and disposal requirements and can be disposed of in landfill as regular waste. Larger quantities of waste mercury must be treated and disposed of in accordance with the requirements of Reg. 347. Although it is anticipated that less than 5 kg of waste lamps will be produced as part of the P00801 Window Replacements and Hollow Doors Repainting, to prevent the release of mercury into the environment, Safetech recommends that all waste lamps be sent to a lamp recycling facility and not disposed of in landfill.

Although no mercury was visibly identified in other equipment, dismantling of equipment was not conducted to verify the presence/absence of mercury. It is cautioned that thermometers, barometers and other measuring devices (pressure gauges/sensors, vacuum gauges, manometers, etc.), thermostats and a variety of other electrical switches (temperature sensitive, tilt switches, float switches, etc.) may contain mercury that may not be visible without dismantling the equipment. Such devices should be assumed to

contain mercury until proven otherwise and similar precautions to those outlined above should be taken if any of these items are to be disturbed or taken out of service in the future.

3.1.4 Silica

Suspect silica-containing materials were identified to be present in the subject areas. In their current state, building materials containing silica do not represent a risk to building occupants or construction workers. Risks associated with exposure to silica arise during demolition activities that cause silica dust to be created (particularly grinding, drilling or cutting operations and during major demolition), resulting in a crystalline silica inhalation hazard.

If any materials suspected to contain silica are to be removed or otherwise disturbed as a result of renovation/demolition activities it is recommended that procedures be put in place to control the generation of dust (such as routine water misting) and thus reduce the potential for worker exposure. Workers that have the potential to be exposed to airborne silica should also wear appropriate protective clothing and respiratory protection. Any work involving the disturbance of silica-containing materials should follow the procedures outlined in the Ontario MLITSD “Silica on Construction Projects” guideline (April 2011). The appropriate engineering controls, work practices, hygiene practices, personal protective measures and training necessary to conduct the work in a safe manner are provided in this guideline. The general measures and procedures (or Type of operation) necessary depends on the type of work to be conducted. The following table outlines the classification of silica disturbance based on the Ontario MLITSD guideline.

Operation	Description
Type 1	<ol style="list-style-type: none"> 1. The drilling of holes in concrete or rock that is not part of a tunneling operation or road construction. 2. Milling of asphalt from concrete highway pavement 3. Charging mixers and hoppers with silica sand (sand consisting of at least 95% silica) or silica flour (finely ground sand consisting of at least 95% silica) 4. Any other operation at a project that requires the handling of silica-containing material in a way that may results in a worker being exposed to airborne silica. 5. Entry into a dry mortar removal or abrasive blasting area while airborne dust is visible for less than 15 minutes for inspection and/or sampling. 6. Working within 25 metres of an area where compressed air is being used to remove silica-containing dust outdoors.

Operation	Description
Type 2	<ol style="list-style-type: none"> 1. Removal of silica containing refractory materials with a jackhammer 2. The drilling of holes in concrete or rock that is part of a tunneling or road construction. 3. The use of a power tool to cut, grind, or polish concrete, masonry, terrazzo or refractory materials. 4. The use of a power tool to remove silica containing materials. 5. Tunneling (operation of the tunnel boring machine, tunnel drilling, and tunnel mesh installation). 6. Tuckpoint and surface grinding 7. Dry mortar removal with an electric or pneumatic cutting device 8. Dry method dust cleanup from abrasive blasting operations 9. The use of compress air outdoors for removing silica dust 10. Entry into area where abrasive blasting is being carried out for more than 15 minutes
Type 3	<ol style="list-style-type: none"> 1. Abrasive blasting with an abrasive that contains >1% silica 2. Abrasive blasting of a material that contains >1% silica

3.1.5 Other Designated Substances

No other designated substances are expected to be a component of building materials in the subject areas in a form that would represent an exposure concern. Therefore, no protective measures or procedures specific to acrylonitrile, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates, and vinyl chloride are considered necessary.

3.2 Other Hazardous Materials

3.2.1 Chemical Hazards

As no UFFI was identified or is suspected to be present in the subject areas, no further action is required. However, given that no destructive testing was conducted, there is a remote possibility that UFFI could be hidden within locations such as exterior wall cavities. If suspect foam insulation is identified during renovation/demolition activities work should be stopped and the area should be re-assessed to evaluate conditions and determine appropriate control measures and worker protection, if necessary.

3.2.2 Biological Hazards

3.2.2.1 Mould Contamination

No mould contamination was identified in the subject areas and no further action is required at this time. Although no obvious mould contamination or evidence to suggest possible hidden mould contamination was identified in the subject areas, there is still a potential for hidden mould growth to exist behind or underneath building finishes. Should suspect mould growth be discovered during the course of renovation or demolition work, Safetech recommends that all work stop so that the area can be assessed to evaluate proper control measures and remediation protocols in order to avoid worker exposure to mould and possible contamination of adjacent areas.

3.2.2.2 Pest Infestation

No visual evidence of any significant pest infestation was observed in the subject areas. Therefore, no additional precautionary measures are deemed necessary for protection against biological contaminants potentially associated with pest infestation.

3.2.3 Environmental Hazards

3.2.3.1 Polychlorinated Biphenyls (PCBs)

Given that the building is known to be constructed after 1980, no light fixtures are expected to have PCB-containing ballasts as the manufacture of PCBs in the U.S. was banned in 1979 and Canada banned the import, manufacture and sale of PCBs in 1977. Similarly, no other electrical equipment (such as transformers and capacitors) present in the subject area(s) is expected to contain PCBs based on the age of building construction.

3.2.3.2 Ozone Depleting and Global Warming Substances

No equipment was identified in the subject areas that is expected to contain ozone depleting or global warming substances. As such, no recommendations are considered necessary at this time.

4.0 LIMITATIONS

The information and recommendations detailed in this report were carried out by trained professional and technical staff in accordance with generally accepted environmental and industrial hygiene work practices and procedures. Recommendations provided in this report have been generated in accordance with accepted industry guidelines and practices. These guidelines and practices are considered acceptable as of the date of this report.

In preparation of this report, Safetech relied on information supplied by others, including without limitation, information pertaining to the history and operation of the site, test results and reports of other consultants and testing services provided by independent laboratories. Except as expressly set out in this report, Safetech has not made any independent verification of information provided by independent entities.

The collection of samples at the location noted was consistent with the scope of work agreed-upon with the person or entity to whom this report is addressed and the information obtained concerning prior site investigations. As conditions between samples may vary, the potential remains for the presence of unknown additional contaminants for which there were no known indicators.

The analytical method used for determination of asbestos content meets the requirements of O. Reg. 278/05. However, small asbestos fibres may be missed by PLM due to resolution limitations of the optical microscope. Interfering binder/matrix and/or low asbestos content may also hinder positive identification by PLM. These conditions are

common for vermiculite attic insulation (VAI) and non-friable organically bound (NOB) materials such as vinyl floor tiles, roofing materials, mastics and caulking and can lead to “false negative” results. If PLM analytical results for these types of materials indicate no asbestos detected they have been reported as “Presumed Non-ACM”. Due to limitations of the analytical method we cannot confirm that low quantities of asbestos are not present in these samples using solely PLM analysis. Additional analytical procedures should be considered for such materials to rule out false negative results.

Conclusions are based on site conditions at the time of inspection and can only be extrapolated to an undefined limited area around inspected locations. The extent of the limited area depends on building construction and conditions. Building materials that are not detailed within this survey due to inaccessibility during the time of survey and/or are uncovered during renovation/demolition activities should be properly assessed by a qualified person prior to their disturbance. Safetech cannot warrant against undiscovered environmental liabilities. If any information becomes available that differs from the findings in this report, we request that we be notified immediately to reassess the conclusions provided herein.

No other person or entity is entitled to use or rely upon this report without the express written consent of Safetech and the person or entity to who it is addressed. Any use that a third party makes of this report, or any reliance based on conclusions and recommendations made, are the responsibility of such third parties. Safetech accepts no responsibility for damages suffered by third parties as a result of actions based on this report.

Appendix A: Summary of ACM Occurrences

Floor	Location	System	Material	Description	Classification	Friable/Non-Friable	Condition	Est. Quantity	Unit	Access	Action
N/A	Vestibule(s)	Door	Caulking	Threshold Caulking (Grey)	ACM	Non-Friable	Good	50	LF	D	7

Appendix B: Laboratory Certificate of Analysis – Asbestos



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552506778
Customer ID: 55SELI62D
Customer PO: 4-4250091
Project ID:

Attn: Luke Guldemeester
Safetech Environmental Limited
130 Saunders Rd Unit 13
Barrie, ON L4N 9A8

Proj: 4-4250091/ St. Marys CS, Barrie, ON

Phone: (905) 624-2722
Fax:
Collected: 4/ 8/2025
Received: 4/15/2025
Analyzed: 4/17/2025

Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

Client Sample ID: S01A **Lab Sample ID:** 552506778-0001
Sample Description: Drywall Joint Compound/ Room 201

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: S01B **Lab Sample ID:** 552506778-0002
Sample Description: Drywall Joint Compound/ Room 201

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: S01C **Lab Sample ID:** 552506778-0003
Sample Description: Drywall Joint Compound/ Room 201

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: S02A **Lab Sample ID:** 552506778-0004
Sample Description: Drywall Joint Compound/ Room 123

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: S02B **Lab Sample ID:** 552506778-0005
Sample Description: Drywall Joint Compound/ Room 123

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: S02C **Lab Sample ID:** 552506778-0006
Sample Description: Drywall Joint Compound/ Room 123

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: S03A **Lab Sample ID:** 552506778-0007
Sample Description: Drywall Joint Compound/ Room 134

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552506778
Customer ID: 55SELI62D
Customer PO: 4-4250091
Project ID:

Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

Client Sample ID: S03B

Lab Sample ID: 552506778-0008

Sample Description: Drywall Joint Compound/ Room 134

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: S03C

Lab Sample ID: 552506778-0009

Sample Description: Drywall Joint Compound/ Room 134

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: S04A-Joint Compound 1

Lab Sample ID: 552506778-0010

Sample Description: Drywall Joint Compound/ West Vestibule Stairwell

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: S04A-Joint Compound 2

Lab Sample ID: 552506778-0010A

Sample Description: Drywall Joint Compound/ West Vestibule Stairwell

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Beige	0.0%	100.0%	None Detected	

Client Sample ID: S04B-Joint Compound 1

Lab Sample ID: 552506778-0011

Sample Description: Drywall Joint Compound/ West Vestibule Stairwell

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: S04B-Joint Compound 2

Lab Sample ID: 552506778-0011A

Sample Description: Drywall Joint Compound/ West Vestibule Stairwell

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Beige	0.0%	100.0%	None Detected	

Client Sample ID: S04C-Joint Compound 1

Lab Sample ID: 552506778-0012

Sample Description: Drywall Joint Compound/ West Vestibule Stairwell

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	White	0.0%	100.0%	None Detected	

Client Sample ID: S04C-Joint Compound 2

Lab Sample ID: 552506778-0012A

Sample Description: Drywall Joint Compound/ West Vestibule Stairwell

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Beige	0.0%	100.0%	None Detected	



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552506778
Customer ID: 55SELI62D
Customer PO: 4-4250091
Project ID:

Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

Client Sample ID: S05A **Lab Sample ID:** 552506778-0013

Sample Description: Casement Caulking/ Exterior Window Casement/ Block - West Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	Green	0.0%	100%	None Detected	

Client Sample ID: S05B **Lab Sample ID:** 552506778-0014

Sample Description: Casement Caulking/ Exterior Window Casement/ Block - West Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	Green	0.0%	100%	None Detected	

Client Sample ID: S05C **Lab Sample ID:** 552506778-0015

Sample Description: Casement Caulking/ Exterior Window Casement/ Block - West Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	Green	0.0%	100%	None Detected	

Client Sample ID: S06A **Lab Sample ID:** 552506778-0016

Sample Description: Casement Caulking/ Exterior Window Casement/ Block - East Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	Green	0.0%	100%	None Detected	

Client Sample ID: S06B **Lab Sample ID:** 552506778-0017

Sample Description: Casement Caulking/ Exterior Window Casement/ Block - East Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	Green	0.0%	100%	None Detected	

Client Sample ID: S06C **Lab Sample ID:** 552506778-0018

Sample Description: Casement Caulking/ Exterior Window Casement/ Block - East Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	Green	0.0%	100%	None Detected	

Client Sample ID: S07A **Lab Sample ID:** 552506778-0019

Sample Description: Casement Caulking/ Interior Window Casement/ Block - East Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	White	0.0%	100%	None Detected	

Client Sample ID: S07B **Lab Sample ID:** 552506778-0020

Sample Description: Casement Caulking/ Interior Window Casement/ Block - East Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	White	0.0%	100%	None Detected	



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552506778
Customer ID: 55SELI62D
Customer PO: 4-4250091
Project ID:

Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

Client Sample ID: S07C **Lab Sample ID:** 552506778-0021

Sample Description: Casement Caulking/ Interior Window Casement/ Block - East Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	White	0.0%	100%	None Detected	

Client Sample ID: S08A **Lab Sample ID:** 552506778-0022

Sample Description: Casement Caulking/ Interior Window Casement/ Block - West Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	White	0.0%	100%	None Detected	

Client Sample ID: S08B **Lab Sample ID:** 552506778-0023

Sample Description: Casement Caulking/ Interior Window Casement/ Block - West Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	White	0.0%	100%	None Detected	

Client Sample ID: S08C **Lab Sample ID:** 552506778-0024

Sample Description: Casement Caulking/ Interior Window Casement/ Block - West Vestibule

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	4/16/2025	White	0.0%	100%	None Detected	

Client Sample ID: S09A-Glazing **Lab Sample ID:** 552506778-0025

Sample Description: Window Glazing/ Main Entrance Exterior Door

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Gray	0.0%	100.0%	None Detected	

Client Sample ID: S09A-Cementitious Material **Lab Sample ID:** 552506778-0025A

Sample Description: Window Glazing/ Main Entrance Exterior Door

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Brown/Gray	0.0%	100.0%	None Detected	

Client Sample ID: S09B **Lab Sample ID:** 552506778-0026

Sample Description: Window Glazing/ Main Entrance Exterior Door

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Gray	0.0%	100.0%	None Detected	

Client Sample ID: S09C **Lab Sample ID:** 552506778-0027

Sample Description: Window Glazing/ Main Entrance Exterior Door

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Gray	0.0%	100.0%	None Detected	



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552506778
Customer ID: 55SELI62D
Customer PO: 4-4250091
Project ID:

Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

Client Sample ID: S10A

Lab Sample ID: 552506778-0028

Sample Description: Window Glazing/ Kindergarten Exterior Window

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM	4/16/2025	Black	0.0%	100.0%	None Detected	

Client Sample ID: S10B

Lab Sample ID: 552506778-0029

Sample Description: Window Glazing/ Kindergarten Exterior Window

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM	4/16/2025	Black	0.0%	100.0%	None Detected	

Client Sample ID: S10C

Lab Sample ID: 552506778-0030

Sample Description: Window Glazing/ Kindergarten Exterior Window

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM	4/16/2025	Black	0.0%	100.0%	None Detected	

Client Sample ID: S11A

Lab Sample ID: 552506778-0031

Sample Description: Window Glazing/ Room 134 Interior Window

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM	4/16/2025	Black	0.0%	100.0%	<1% Chrysotile	
PLM Grav. Reduction	4/17/2025	Black	0.0%	99.7%	0.32% Chrysotile	

Client Sample ID: S11B

Lab Sample ID: 552506778-0032

Sample Description: Window Glazing/ Room 134 Interior Window

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM	4/16/2025	Black	0.0%	100.0%	<1% Chrysotile	
PLM Grav. Reduction	4/17/2025	Black	0.0%	100%	<0.25% Chrysotile	

Client Sample ID: S11C

Lab Sample ID: 552506778-0033

Sample Description: Window Glazing/ Room 134 Interior Window

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM	4/16/2025	Gray	0.0%	100.0%	<1% Chrysotile	
PLM Grav. Reduction	4/17/2025	Gray	0.0%	100%	<0.25% Chrysotile	

Client Sample ID: S12A

Lab Sample ID: 552506778-0034

Sample Description: Window Glazing/ West Vestibule Exterior Window

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM	4/16/2025	Black	0.0%	100.0%	None Detected	

Client Sample ID: S12B

Lab Sample ID: 552506778-0035

Sample Description: Window Glazing/ West Vestibule Exterior Window

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM	4/16/2025	Black	0.0%	100.0%	None Detected	



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552506778
Customer ID: 55SELI62D
Customer PO: 4-4250091
Project ID:

Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

Client Sample ID: S12C **Lab Sample ID:** 552506778-0036

Sample Description: Window Glazing/ West Vestibule Exterior Window

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Gray/Black	0.0%	100.0%	None Detected	

Client Sample ID: S13A **Lab Sample ID:** 552506778-0037

Sample Description: Window Glazing/ Room 202 Exterior Window

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Black	0.0%	100.0%	None Detected	

Client Sample ID: S13B **Lab Sample ID:** 552506778-0038

Sample Description: Window Glazing/ Room 202 Exterior Window

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Black	0.0%	100.0%	None Detected	

Client Sample ID: S13C **Lab Sample ID:** 552506778-0039

Sample Description: Window Glazing/ Room 202 Exterior Window

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Black	0.0%	100.0%	None Detected	

Client Sample ID: S14A **Lab Sample ID:** 552506778-0040

Sample Description: Leveling Compound/ Kindergarten Adjacent Vestibule Door Casement

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Gray	0.0%	99.0%	1% Chrysotile	

Client Sample ID: S14B **Lab Sample ID:** 552506778-0041

Sample Description: Leveling Compound/ Kindergarten Adjacent Vestibule Door Casement

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025					Positive Stop (Not Analyzed)

Client Sample ID: S14C **Lab Sample ID:** 552506778-0042

Sample Description: Leveling Compound/ Kindergarten Adjacent Vestibule Door Casement

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025					Positive Stop (Not Analyzed)

Client Sample ID: S15A **Lab Sample ID:** 552506778-0043

Sample Description: Block Mortar/ Ground Floor Mechanical

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Gray	0.0%	100.0%	None Detected	



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552506778
Customer ID: 55SELI62D
Customer PO: 4-4250091
Project ID:

Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

Client Sample ID: S15B

Lab Sample ID: 552506778-0044

Sample Description: Block Mortar/ Ground Floor Mechanical

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Gray	0.0%	100.0%	None Detected	

Client Sample ID: S15C

Lab Sample ID: 552506778-0045

Sample Description: Block Mortar/ Ground Floor Mechanical

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/16/2025	Gray	0.0%	100.0%	None Detected	

Analyst(s):

Ashley Brito PLM (13)
Diana Costantino PLM Grav. Reduction (4)
PLM (3)
Hassan Moez PLM Grav. Reduction (1)
Kira Ramphal PLM Grav. Reduction (2)
Nickesh Mistry PLM Grav. Reduction (8)
PLM (2)
Stephanie Achaiya PLM (17)

Reviewed and approved by:

Matthew Davis or other approved signatory
or Other Approved Signatory

None Detected = <0.1%. EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This is a summary report; official reports are available on LabConnect or upon request and relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Canada Inc. Mississauga, ON NVLAP Lab Code 200877-0

Initial report from: 04/17/2025 10:51:46

Appendix C: Laboratory Certificate of Analysis – Lead

**EMSL Canada Inc.**

2756 Slough Street, Mississauga, ON L4T 1G3

Phone/Fax: (289) 997-4602 / (289) 997-4607

<http://www.EMSL.com>torontolab@emsl.com

EMSL Canada Or 552506762

CustomerID: 55SELI62D

CustomerPO: 4-4250091

ProjectID:

Attn: **Luke Guldemeester**
Safetech Environmental Limited
130 Saunders Rd Unit 13
Barrie, ON L4N 9A8

Phone: (905) 624-2722
Fax:
Received: 4/15/2025 09:00 AM
Collected: 4/8/2025

Project: 4-4250091 / St. Marys CS, Barrie, ON

Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample</i>	<i>Description</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Weight</i>	<i>RDL</i>	<i>Lead Concentration</i>
LP1		4/8/2025	4/16/2025	0.2508 g	0.0064 % wt	<0.0064 % wt
552506762-0001	Site: Teal Exterior Casement / Door Paint					
LP2		4/8/2025	4/16/2025	0.2501 g	0.0064 % wt	<0.0064 % wt
552506762-0002	Site: Interior Cream Block Wall Paint					

Rowena Fanto, Lead Supervisor
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. * Analysis following Lead in Paint by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 0.0064% wt based on the minimum sample weight per our SOP. "<" (less than) result signifies the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. Definitions of modifications are available upon request.


Samples analyzed by EMSL Canada Inc. Mississauga, ON AIHA LAP, LLC-ELLAP Accredited #196142

Initial report from 04/17/2025 09:03:06

Appendix D: Drawing

LEGEND

- AREA(S) ASSESSED
- THRESHOLD DOOR CAULKING (ACM)



NOTES:

- i. Base drawing provided to Safetech
- ii. Not to scale. For illustrative purposes only.
- iii. Contractor to confirm quantities and measurements.
- iv. Must be read in conjunction with report.

NOTES:

1) THIS FLOOR PLAN MUST BE READ IN CONJUNCTION WITH THE DESIGNATED SUBSTANCE AND HAZARDOUS MATERIALS ASSESSMENT REPORT.

2) NOT ALL ASBESTOS-CONTAINING MATERIALS ARE INDICATED IN THE FLOOR PLAN. REFER TO THE DESIGNATED SUBSTANCE AND HAZARDOUS MATERIALS REPORT FOR FURTHER DETAILS.

3) REMOVAL OR DISTURBANCE OF ASBESTOS-CONTAINING BUILDING MATERIALS MUST BE CONDUCTED IN ACCORDANCE WITH ONTARIO REGULATION 278/05 "DESIGNATED SUBSTANCE - ASBESTOS ON CONSTRUCTION PROJECTS AND IN BUILDINGS AND REPAIR OPERATIONS".

LOWER LEVEL	DRAWING NO.
WINDOW REPLACEMENT	WD-1
340 LEACOCK DRIVE BARRIE, ON	DATE: APRIL 21, 2025
	SAFETECH PROJECT NO. 4-4250091




safetech
ENVIRONMENTAL LTD.

130 Saunders Rd.,
Suite # 13
Barrie, Ontario, L4N 9A8

LEGEND

- AREA(S) ASSESSED
- THRESHOLD DOOR CAULKING (ACM)



NOTES:
i. Base drawing provided to Safetech
ii. Not to scale. For illustrative purposes only.
iii. Contractor to confirm quantities and measurements.
iv. Must be read in conjunction with report.

NOTES:
1) THIS FLOOR PLAN MUST BE READ IN CONJUNCTION WITH THE DESIGNATED SUBSTANCE AND HAZARDOUS MATERIALS ASSESSMENT REPORT.
2) NOT ALL ASBESTOS-CONTAINING MATERIALS ARE INDICATED IN THE FLOOR PLAN. REFER TO THE DESIGNATED SUBSTANCE AND HAZARDOUS MATERIALS REPORT FOR FURTHER DETAILS.
3) REMOVAL OR DISTURBANCE OF ASBESTOS-CONTAINING BUILDING MATERIALS MUST BE CONDUCTED IN ACCORDANCE WITH ONTARIO REGULATION 278/05 "DESIGNATED SUBSTANCE - ASBESTOS ON CONSTRUCTION PROJECTS AND IN BUILDINGS AND REPAIR OPERATIONS".

MAIN LEVEL	DRAWING NO.
WINDOW REPLACEMENT	WD-1
340 LEACOCK DRIVE BARRIE, ON	DATE: APRIL 21, 2025
	SAFETECH PROJECT NO. 4-4250091



safetech
ENVIRONMENTAL LTD.

130 Saunders Rd.,
Suite # 13
Barrie, Ontario, L4N 9A8

Appendix E: Methodology

A. METHODOLOGY

The presence of hazardous materials was assessed by visual inspection. For the purpose of this assessment and this document, hazardous materials include designated substances as well as other chemical, biological and environmental hazards as defined below:

- Designated Substances (as prescribed by Ontario Regulation 490/09):
 - Acrylonitrile, Arsenic, Asbestos, Benzene, Coke Oven Emissions, Ethylene Oxide, Isocyanates, Lead, Mercury, Silica and Vinyl Chloride.
- Other Hazardous Materials:
 - **Chemical Hazards** – Urea Formaldehyde Foam Insulation (UFFI)
 - **Biological Hazards** – Mould Contamination and Pest Infestation
 - **Environmental Hazards** – Polychlorinated Biphenyls (PCBs) and Ozone Depleting & Global Warming Substances

Concealed locations such as above solid plaster or drywall ceilings, within plaster or drywall wall cavities, enclosed mechanical/pipe shafts and bulkheads, etc. were not investigated, unless otherwise stated in Section 1.3. Similarly, motors, blowers, electrical panels, etc., were not de-energized or disassembled to examine concealed conditions. Building materials that are not detailed within this assessment due to inaccessibility at the time of our site visit and/or uncovered during renovation/demolition activities should be assessed by a qualified person prior to their disturbance.

Bulk sampling followed by laboratory analysis was also conducted to confirm the presence/absence of select hazardous materials. Bulk sampling was limited to asbestos in building materials and lead in paint on building finishes (if flaking paint was present). All other hazardous materials were identified by visual inspection only. Where possible, observations regarding the location, quantity and condition of the hazardous materials identified were made in order to determine the potential for exposure and provide appropriate recommendations for remedial action, if necessary. Specific methodology for each individual hazardous material assessed is further detailed below.

A.1 Designated Substances

A.1.1 Asbestos

A visual inspection for the presence of both friable and non-friable asbestos-containing material (ACM) was performed in the subject area.

If an existing asbestos survey was available for review, Safetech relied on the information present. Building materials that were visually similar to materials previously tested and that were confirmed to be either ACM or non-ACM were considered to have consistent content and were not re-sampled. Additional sampling was only conducted where the investigator believed a need existed.

Bulk samples of building materials suspected to contain asbestos were retrieved by Safetech only for materials that were deemed to have a potential to be disturbed as part

of the construction project. Some suspect materials may not have been sampled during our investigation. Bulk samples were retrieved in accordance with Section 3 and Table 1 of Ontario Regulation 278/05, "Designated Substance – Asbestos on Construction Projects and in Buildings and Repair Operations". The number of samples collected for each material was based on the type and quantity of the material present in the subject area. Each individual sample was placed in a labeled zip-lock bag for transportation to an independent laboratory (EMSL). EMSL is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) for bulk asbestos fiber analysis.

Analysis for asbestos content was performed by the independent laboratory in accordance with the U.S. Environmental Protection Agency (EPA) Test Method *EPA/600/R-93-116: Method for the Determination of Asbestos in Bulk Building Materials (June 1993)*. This method identifies the asbestos fibre content of building materials using polarized light microscopy (PLM) analytical techniques, with confirmation of presence and type of asbestos made by dispersion staining optical microscopy. This analytical method meets the requirements set forth in Section 3 of O. Reg. 278/05.

In accordance with O. Reg. 278/05, an asbestos-containing material is defined as material that contains 0.5 per cent or more asbestos by dry weight. The laboratory was instructed to conduct "stop-positive" analysis for all materials. If a sample was found to be asbestos-containing no further analysis was conducted for samples taken from the same homogeneous material.

Locations where ACM have been identified are detailed in this report. Recommendations pertaining to ACM were made based on the friability, accessibility and condition of the material in conjunction with the potential for the planned renovation work to disturb the ACM.

A.1.2 Assessment of Asbestos-Containing Building Materials

Accessibility, Condition and Action (Priority) ratings for individual items, or defined areas were developed by Safetech to determine remedial action plans specific to the facility's needs.

A.1.2.1 Accessibility

Accessibility has been assessed as: (A) Accessible to all non-maintenance occupants of the building; (B) Accessible to maintenance staff without a ladder; (C) Accessible to maintenance staff with a ladder and exposed to view without moving a building component; (D) Accessible to maintenance staff with a ladder and concealed from view due to a building component; (E) Not accessible without demolition or removal of fixed building components or building systems

A.1.2.2 Condition

The condition of asbestos-containing materials identified in the subject area was assessed as Good (G), Fair (F) or Poor (P). The assessment criteria used to determine condition is dependent on material characteristics, such as friability. The following table summarizes the criteria used by Safetech to evaluate the condition of ACM.

Sprayed Fireproofing, Sprayed Insulation and Sprayed Texture Finishes	
Good	<ul style="list-style-type: none"> Surface shows no significant signs of damage, deterioration, or delamination (i.e. <1%). Unencapsulated or unpainted fireproofing or texture finishes, where no delamination or damage is observed. Encapsulated fireproofing or texture finishes where encapsulation applied after damage or fallout.
Fair	<ul style="list-style-type: none"> Not utilized as part of condition assessment for these materials.
Poor	<ul style="list-style-type: none"> Greater than 1% damage, delamination, or deterioration to surface.
In areas where damage exists in isolated locations, both Good and Poor may be applicable.	
Mechanical Insulation (boilers, breeching, ductwork, piping, tanks, equipment, etc.)	
Good	<ul style="list-style-type: none"> Insulation completely covered in jacketing and exhibits no evidence of damage or deterioration. Jacketing may have minor damage (i.e. scuffs or stains), but is not penetrated.
Fair	<ul style="list-style-type: none"> Minor penetrating damage to jacketed insulation (cuts, tears, nicks, deterioration or delamination). Undamaged insulation that had never been jacketed. Insulation is exposed but not showing surface disintegration. Extent of missing insulation ranges from minor to none. Damage that can be repaired.
Poor	<ul style="list-style-type: none"> Original insulation jacket is missing, damaged, deteriorated, or delaminated. Insulation is exposed and significant areas have been dislodged. Damage that cannot be easily repaired.
Non-Friable and Potentially Friable Materials (includes materials such as plaster finishes, drywall compound, ceiling tiles, asbestos cement products, vinyl asbestos tile and asbestos paper backed vinyl sheet flooring, etc., which have the potential to become friable when handled)	
Good	<ul style="list-style-type: none"> No significant damage. Material may be cracked or broken but is stable and not likely to become friable upon casual contact. No friable debris present
Fair	<ul style="list-style-type: none"> Not utilized as part of condition assessment for these materials.
Poor	<ul style="list-style-type: none"> Material is severely damaged. Debris is present or binder has disintegrated to the point where the material has become friable.
Asbestos-Containing Debris (noted separately from the presumed source material)	
Poor	<ul style="list-style-type: none"> Debris is always considered to be in Poor condition.

A.1.2.3 Action

Recommended ACTION for compliance and for management of identified asbestos-containing materials has been provided for each condition and component outlined in the above table. Recommendations have been classified under the following 8 ACTIONS:

1. Action dealing with the immediate clean-up of fallen ACM likely to be disturbed.

2. Action dealing with the need to use Type 2 asbestos procedures to enter an area (other than a ceiling space).
3. Action dealing with performing asbestos removal for compliance with regulations.
4. Action dealing with Type 2 asbestos procedures for ceiling entry where friable ACM debris is present on the top side of a ceiling system.
5. Action dealing with the removal of asbestos that goes beyond compliance requirements but simplifies the asbestos management.
6. Action dealing with the repair of asbestos.
7. Action dealing with ACM surveillance requirements of the regulation.
8. Action for dealing with material that may contain asbestos but was not conclusively identified in the survey.

A.1.2.4 Quantity

The approximate quantity and the units of measure related to the quantity (i.e.: linear feet (LF), square feet (SF) or each (EACH) as appropriate to the item) have only been provided for materials requiring remedial or corrective action (i.e. materials in Fair or Poor condition). In such circumstances any quantities provided should be considered rough estimates only and should not be solely relied upon for bidding purposes. It is the responsibility of the selected Contractor to obtain actual quantities.

A.2 Lead

If paint samples were collected, they would be collected by scraping the paint down to the base material substrate to ensure collection of all layers of paint. Care would be taken to avoid collection of the underlying substrate to reduce analytical substrate matrix interference.

If collected, paint samples would be submitted to an independent laboratory for the determination of lead content. The laboratory would participate in and accredited by the EPA (U.S. Environmental Protection Agency) for analysis of lead in paint chips through the American Industrial Hygiene Association (AIHA) Environmental Lead Laboratory Accreditation Program (ELLAP). Analysis would be conducted by the laboratory following the EPA "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods" (SW-846), Method 7000B "Flame Atomic Absorption Spectrophotometry". Result of analysis would be reported by the laboratory as the percentage of lead by weight of the total sample (% by wt.).

The presence of lead in other materials, such as lead sheeting, pigmented mortar, lead piping, lead solder, etc. would be noted where observed but not sampled to verify lead content. Lead can be present in these materials to varying degrees, depending on their age of application and should be considered lead-containing until proven otherwise.

A.3 Mercury

The type, quantity and location of mercury-containing equipment and devices in the subject area were determined by visual inspection based on appearance, age and knowledge of historical uses. Sampling for mercury-containing building materials and dismantling of suspect mercury-containing equipment was not performed. Where possible, attempts were made to verify the presence/absence of mercury by gathering additional information such as equipment model number, serial number, etc.

A.4 Silica

The presence of crystalline silica in building materials was determined through visual inspection of building materials only, based on knowledge of the historic use of silica-containing materials in certain building materials. Sampling to verify the presence/absence of silica in building materials was not performed.

A.5 Other Designated Substances

Other designated substances (i.e. acrylonitrile, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates, and vinyl chloride) are typically not expected to be encountered in building materials as significant constituents or in a form that would represent an exposure concern. These substances were not included in the assessment unless specific information regarding their use (e.g. in a manufacturing process) was provided to us. No sampling for these designated substances was performed.

A.6 Other Hazardous Materials

A.6.1 Chemical Hazards

A.6.1.1 Urea Formaldehyde Foam Insulation (UFFI)

A visual inspection to evaluate the possible presence of Urea Formaldehyde Foam Insulation (UFFI) was conducted in the subject area. Our visual inspection was limited to identifying evidence of possible UFFI installation (i.e. repaired nozzle holes in walls) and overspray at wall/ceiling joints, etc. No destructive testing or material sampling was conducted as part of the assessment.

A.7 Biological Hazards

A.7.1.1 Mould Contamination

A visual inspection to determine the possibility of mould growth was conducted in the subject area. The assessment was limited to identifying evidence of mould growth and water damage (staining, material deterioration, efflorescence, etc.) on the surface of building materials, which may be an indicator of hidden mould growth. No moisture content readings of building materials were taken to determine their current condition. Additionally, destructive testing to confirm the presence/absence of hidden mould growth and material sampling to verify the presence/absence of mould on suspect surfaces was beyond the scope of this assessment.

A.7.1.2 Pest Infestation

The presence and extent of pest infestation in the subject area was based on visually inspecting for evidence of significant pest activity, including signs of nesting, droppings/fecal accumulation, dead insects/carcass accumulation, etc. Evidence of minor pest presence was not considered to be indicative of pest infestation.

A.8 Environmental Hazards

A.8.1 Polychlorinated Biphenyls (PCBs)

The presence of PCB-containing electrical equipment in the subject area was identified through visual inspection and knowledge of the timeline of historical use.

For stand-alone transformers and capacitors, information from the manufacturer nameplate (such as the date of manufacture, dielectric fluid trade name or “Type Number”, etc.) was gathered, where possible, to further evaluate if the equipment may contain PCBs. This information was then compared to the information provided in the Environment Canada document entitled “Handbook on PCB’s in Electrical Equipment” (Third Edition, April 1988) to aid in identification. Transformers and capacitors confirmed to be manufactured after 1979 were assumed to not contain PCBs. If appropriate information could not be obtained it was assumed that the transformer or capacitor contained PCBs.

For fluorescent light ballasts, a representative number of fixtures were inspected, if possible, for assessment areas that were constructed prior to 1980 and where there was no history or evidence of a complete lighting retrofit. The light fixtures were examined by removing any lenses and ballast covers to expose the ballast and identify information such as ballast make, model number, serial number, and date code. This information was then compared to the information provided in the Environment Canada document entitled “Identification of Lamp Ballasts Containing PCBs” (Report EPS 2/CC/2 (revised) August 1991) to aid in identification. Ballasts that could not be confirmed Non-PCB-containing were assumed to contain PCBs. The light fixtures were not de-energized and ballasts were not removed to obtain manufacturer information that may be on the back of the ballast. If visual confirmation of ballast type could not be made it was assumed that light fixtures in areas constructed prior to 1980 that have not undergone a complete lighting retrofit have PCB-containing ballasts until proven otherwise.

No sampling of materials or fluids within equipment was conducted to verify the presence/absence of PCBs. Inspection and testing of other materials for PCB content, including (but not limited to) caulking, asphalt, oil-based paint, plastics, switches, electric cables and hydraulic fluids was beyond the scope of the assessment.

A.8.2 Ozone Depleting and Global Warming Substances

The presence of fixed equipment likely to contain ozone-depleting substances (ODS) and/or global-warming substances (GWS) was identified through visual inspection and

knowledge of the timeline of historical use. This included equipment such as chillers, air-conditioners, walk-in refrigeration and freezer units and fixed dry-chemical fire extinguishers, where chemicals such as hydrochlorofluorocarbons (HCFCs), hydrofluorocarbons (HFCs) or halons may be present. Where possible, information regarding the type and quantity of refrigerant present was obtained from the manufacturer nameplate. Our visual assessment was limited to fixed equipment in the subject area and did not include portable equipment such as stand-alone refrigerators, freezers, water coolers, air-conditioners and fire extinguishers, etc.