

EASTDALE CVI

MINOR OFFICE ALTERATIONS

265 HARMONY RD. NORTH, OSHAWA, L1G 6L5

PROJECT# Q25-22

DATE: JUNE 20, 2025

DRAWING LIST

ARCHITECTURAL (INCLUDES MECHANICAL & ELECTRICAL SCOPE)

- A0 - GENERAL NOTES & SPECIFICATIONS
- A1 - CONSTRUCTION KEY PLAN
- A2 - DEMOLITION FLOOR PLAN - LAN TECH OFFICE
- A3 - NEW FLOOR PLAN - LAN TECH OFFICE
- A4 - DEMOLITION FLOOR PLAN - VP OFFICE
- A5 - NEW FLOOR PLAN - VP OFFICE
- A6 - MILLWORK ELEVATIONS AT STAFF ROOM

DESIGNATED SUBSTANCES SURVEY

PARASOL ENVIRONMENTAL REPORT NO.13307
DATED JUNE 6, 2025

STRUCTURAL DRAWINGS

ENGINEERING LINK - 25-2529 - DATED JUNE 17, 2025

NEW DOORS & HARDWARE SCHEDULE

RIVETT ARCHITECTURAL HARDWARE LTD







SPECIFICATIONS FOR MATERIALS

ARCHITECTURAL SPECIFICATIONS
NEW ACOUSTIC CEILINGS - ARMSTRONG OR APPROVED EQUIVALENT:
MAIN TEE 7300, CROSS TEE XL 7340, WALL MOULDING JS 25-U SHADOW MOULD
CEILING TILES - CERTAINTEED PBT-197 OR APPROVED EQUIVALENT

MECHANICAL SPECIFICATIONS
NEW MECHANICAL DIFFUSERS - SCD - 31 - 33, WHITE IN COLOUR, PRICE INDUSTRIES
AIR RETURN GRILLE - EGG CRATE STYLE

ELECTRICAL SPECIFICATIONS (ALL LIGHTS INDEPENDENTLY SUPPORTED ABOVE CEILING)
2X4 LIGHTS - 2TG8214 - 12 -120 - 1/2EB, PHILLIPS
1X4 LIGHTS - 5000K, LED, 1X4, WHITE, LITHONIA LIGHTING


LEGEND

- NEW DUPLEX RECEPTACLE
- NEW QUAD RECEPTACLE
- NEW DATA
- NEW LIGHTS
- PAGING SYSTEM SPEAKER
- NEW SINGLE POLE LIGHT SWITCH

CONSTRUCTION WORKING TIMES AND WORKING RESTRICTIONS DURING SCHOOL YEAR (APPLICABLE TO WORK UP UNTIL JUNE 30, 2025):

1. DAYTIME HOURS OF WORK: 7:30AM - 4PM
2. AFTER-HOURS WORK (ALL NOISY, DISRUPTIVE, AND HOT WORK): 4PM - 7:30AM
3. SITE ACCESS / EGRESS TIMES FOR TRADES TO BE COORDINATED CLOSELY WITH DDSB'S PROJECT SUPERVISOR AS TO AVOID CLOSE CONTACT WITH SCHOOL STAFF AND STUDENTS. (PRECAUTIONARY MEASURE TO INCREASE SOCIAL DISTANCING AND FOLLOW COVID 19 PROCTOCOLS)
- SITE SAFETY REQUIREMENTS:
4. ALL CONTRACTORS SHALL SIGN-IN AT SCHOOL ENTRY PRIOR TO ATTENDING THE CONSTRUCTION SITE.
5. THE PRIME CONTRACTOR SHALL SET UP A SITE SAFETY BOARD AT THE CONSTRUCTION SITE AT AN AGREED UPON LOCATION.
6. INTERRUPTION TO ANY MECHANICAL OR ELECTRICAL SYSTEMS WILL BE COORDINATED WITH THE PROJECT SUPERVISOR A MINIMUM OF 48 HOURS IN ADVANCE.
7. PERSONAL PROTECTIVE EQUIPMENT (PPE) SHALL BE WORN BY ALL PERSONNEL ENTERING THE CONSTRUCTION SITE.
8. HOT WORK PERMITS SHALL BE POSTED WHEN HOT WORK IS TO TAKE PLACE (SEE DDSB FRONT END FOR DETAILS). ALL HOT WORK SHALL TAKE PLACE AFTER HOURS.
9. COORDINATE SMOKE ALARM BY-PASS WITH DDSB PROJECT SUPERVISOR WHERE WORK MAY GENERATE SMOKE.
10. CONCRETE CUTTING SHALL BE WET-CUT ONLY, NOT DRY CUTTING WILL BE PERMITTED. SCAN SLAB AS REQUIRED PRIOR TO REMOVALS TO ENSURE CLEARANCES.

0	ISSUED FOR TENDER	JUNE 20, 2025
REV	REASON FOR ISSUANCE	DATE
LEGEND & GENERAL NOTES		
Address 265 Harmony Road North, Oshawa, ON L1G 6L5		
School EASTDALE CVI		Date: JUNE 20, 2025
		Drawn By: MK/NT
		Scale: N.T.S.
		Checked By: RR
		Project Number Q25-22
	A0	



1

EXISTING VCT FLOORING TO REMAIN

2


EXISTING DRYWALL CEILING TO REMAIN
CUT NEW OPENING IN EXISTING BLOCK WALL FOR NEW DOOR. SEE STRUCTURAL & DOOR HARDWARE SCHEDULE FOR SIZING INFORMATION. REFER TO PARASOL DESIGNATED SUBSTANCE REPORT FOR ABATMEENT REQUIREMENTS


3

EXISTING GYPSUM BOARD CEILING TO BE DEMOLISHED - REWORK EXISTING ABOVE CEILING MECHANICAL & ELECTRICAL TO SUIT NEW ACT CEILING. REFER TO PARASOL DESIGNATED SUBSTANCE REPORT FOR ABATEMENT REQUIREMENTS. ABATEMENT OF EXISTING GYPSUM BOARD CEILING BY OTHERS.

4


EXISTING DRYWALL CEILING TO REMAIN

0	ISSUED FOR TENDER	JUNE 20, 2025
REV	REASON FOR ISSUANCE	DATE
TITLE DEMO PLAN - LAN TECH		
Address 265 Harmony Road North, Oshawa, ON L1G 6L5		
School EASTDALE CVI		Date: JUNE 20, 2025
Drawn By: MK/NT		Scale: N.T.S.
Checked By: RR		Project Number Q25-22
<div><div>DDSB</div><div>Ignite Learning</div></div>		A2




- 1 EXISTING VCT FLOORING TO REMAIN
- 2 PATCH & PAINT ALL WALLS, DOORS, FRAMES
- 3 SUPPLY & INSTALL NEW FIRE RATED DOOR & FRAME PER DOOR HARDWARE SCHEDULE. SUPPLY & INSTALL NEW STEEL LINTEL PER STRUCTURAL.
- 4 NEW RUBBER BASE TO BE INSTALLED ON ALL WALLS
- 5 NEW ACT CEILING
- 6 EXISTING GYPSUM BOARD CEILING TO REMAIN - MAKE GOOD AS REQUIRED AT NEW WALL FOR LAN-TECH ROOM. INCLUDE TO PRIME & PAINT.

0	ISSUED FOR TENDER	JUNE 20, 2025
REV	REASON FOR ISSUANCE	DATE
TITLE NEW PLAN - LAN TECH		
Address 265 Harmony Road North, Oshawa, ON L1G 6L5		
School EASTDALE CVI		Date: JUNE 20, 2025
		Drawn By: MK/NT
		Scale: N.T.S.
		Checked By: RR
		Project Number Q25-22
		A3



1
A3

DEMO FLOOR PLAN - NEW VP OFFICE



1
A3


DEMO CEILING PLAN - NEW VP OFFICE

ALL EX. WALLS
ARE CONCRETE
BLOCK UNLESS
NOTED OTHERWISE


1 MODIFY EXISTING ACT CEILING TO SUIT
NEW BLOCK WALLS THAT ARE TO
EXTEND TO UNDERSIDE OF DECK.

0	ISSUED FOR TENDER	JUNE 20, 2025
REV	REASON FOR ISSUANCE	DATE
TITLE DEMO PLAN - VP OFFICE		
Address 265 Harmony Road North, Oshawa, ON L1G 6L5		
School EASTDALE CVI		Date: JUNE 20, 2025
		Drawn By: MK/NT
		Scale: N.T.S.
		Checked By: RR
		Project Number Q25-22
		A4





1
A4
NEW FLOOR PLAN - NEW VP OFFICE





1
A4
NEW CEILING PLAN - NEW VP OFFICE

ALL EX. WALLS
ARE CONCRETE
BLOCK U.N.O.

- 1 EXISTING VCT FLOORING TO REMAIN
- 2 PATCH & PAINT ALL WALLS, DOORS, FRAMES
- 3 SUPPLY & INSTALL NEW DOOR & FRAME PER HARDWARE SCHEDULE. SUPPLY & INSTALL STEEL LINTEL OVER DOOR PER STRUCTURAL.
- 4 NEW 4" RUBBER BASE TO BE INSTALLED ON ALL WALLS
- 5 EXISTING ACT CEILING TO REMAIN. REMOVE & REINSTATE AS REQUIRED TO PERMIT NEW BLOCK WALLS TO EXTEND TO UNDERSIDE OF DECK.
- 6 PROVIDE NEW LIGHTING CIRCUIT TIED INTO NEW LIGHT SWITCH AND EXISTING/NEW LIGHTS WITHIN OFFICE

0	ISSUED FOR TENDER	JUNE 20, 2025
REV	REASON FOR ISSUANCE	DATE
TITLE NEW PLAN - VP OFFICE		
Address 265 Harmony Road North, Oshawa, ON L1G 6L5		
School EASTDALE CVI		Date: JUNE 20, 2025
		Drawn By: MK/NT
		Scale: N.T.S.
		Checked By: RR
		Project Number Q25-22
		A5



1 TYPICAL NOTE - ALL MILLWORK SURFACES TO BE PLAM FINISH WITH $\frac{3}{4}$ " PLYWOOD SUBSTRATE

1 MILLWORK ELEVATION
A6

2 MILLWORK SECTION
A6

ALL EX. WALLS
ARE CONCRETE
BLOCK UNLESS
NOTED OTHERWISE

0	ISSUED FOR TENDER	JUNE 20, 2025
REV	REASON FOR ISSUANCE	DATE
TITLE MILLWORK ELEVATION AT STAFF ROOM		
Address 265 Harmony Road North, Oshawa, ON L1G 6L5		
School EASTDALE CVI		Date: JUNE 20, 2025
		Drawn By: MK/NT
		Scale: N.T.S.
		Checked By: RR
		Project Number Q25-22
		A6





125-1860 Appleby Line, Unit # 14,
Burlington, Ontario L7L 7H7

Limited Designated Substance Survey Report

Eastdale Collegiate and Vocational Institute

265 Harmony Road North, Oshawa, Ontario

Prepared for

Durham District School Board
400 Taunton Road East, Whitby, Ontario

June 6, 2025
Parasol Project No: 13307

Executive Summary

Parasol Environmental Inc. (Parasol) was retained by the Durham District School Board to conduct a Limited Designated Substance Survey within Eastdale Collegiate and Vocational Institute located at 265 Harmony Road North, Oshawa, Ontario. The purpose of the survey was to record the presence, location, condition and quantities of Designated Substances and Hazardous Materials within the surveyed area that may be disturbed during the planned renovation. Additional information is provided to document corrective measures necessary to ensure that remedial action occurs applying the proper abatement procedures, if necessary.

The survey was completed by Brad Panzer of Parasol on June 2, 2025.

The following table summarizes the Designated Substances and Hazardous Materials observed within the surveyed area.

Designated Substance or Hazardous Material	Findings	Recommendation
Asbestos	<p>Confirmed and suspected asbestos-containing materials were identified as follows:</p> <p>Friable Asbestos</p> <ul style="list-style-type: none"> Mechanical Insulations (Parging Cement) <p>Non-Friable Asbestos</p> <ul style="list-style-type: none"> Vinyl Floor Tiles Vinyl Floor Tile Mastic Primer (Applied to Masonry Block Finishes) Light Fixture Heat Shield Paper <p>Distinctive Asbestos</p> <ul style="list-style-type: none"> Drywall Finishes 	<p>The following remedial work is necessary to comply with Ontario Regulation 278/05:</p> <ul style="list-style-type: none"> Repair drywall ceiling finishes using Type 2 abatement procedures.
Benzene	No major sources were identified.	No recommendations are warranted as no benzene products were observed.
Lead	<p>Low-level lead concentrations were found to be present in the following materials:</p> <ul style="list-style-type: none"> White Paint Beige Paint Masonry Block Mortar <p>Lead-containing concentrations were found to be present in the following materials:</p> <ul style="list-style-type: none"> Yellow Paint <p>Lead of varying concentrations is also suspected to be present in the following items:</p> <ul style="list-style-type: none"> Ceramic Floor Tile Glazing Solder on pipe fittings 	<p>All paint and masonry mortar was observed in GOOD condition. If disturbed, remove using lead abatement procedures as per EACC <i>“Lead Guideline for Construction, Renovation, Maintenance or Repair”</i>.</p>

Designated Substance or Hazardous Material	Findings	Recommendation
Mercury	Mercury vapour is presumed to be present within all fluorescent light tubes.	If removed, the fluorescent lights are to be kept sealed and intact, which will prevent direct skin contact and the inhalation of mercury vapour.
Silica	Crystalline silica is suspected to be present within: <ul style="list-style-type: none"> • Ceramic tiles and grout, • Masonry and mortar, • Concrete (poured or pre-cast) 	The removal or disturbance of material suspected to contain crystalline silica are to follow procedures outlined in the MOL document <i>“Guideline - Silica on Construction Projects”</i> , dated September 2004.
Polychlorinated Biphenyls (PCBs)	T8 light fixtures observed contain non-PCB electronic ballasts.	If disturbed, compare fluorescent light fixture’s ballast to the Environment Canada Document, <i>“PCB Identification of Lamp Ballasts Containing PCBs”</i> dated August 1991. If the ballast does not contain a label that states “PCB Free” or the serial code that does not identify it as “PCB Free” then the ballast should be presumed to contain PCBs and disposed of accordingly.
Mould	No major sources were identified.	No recommendations are warranted as no mould or water-damaged building materials were observed.
Other Designated Substances	The following Designated Substances are not likely to be found in the area assessed: <ul style="list-style-type: none"> • Acrylonitrile • Arsenic • Coke Oven Emission • Ethylene Oxide • Isocyanates • Vinyl Chloride 	No recommendations are warranted as none were observed.

Before any renovation activities, perform an intrusive investigation for concealed Designated Substances and sample building materials that were not previously tested and may be disturbed as part of the renovation. In addition, consideration should be given to mechanical, electrical and structural components that pass beyond the rooftop into the building and may be impacted by the project. Further, consideration of the known or suspected asbestos-containing materials within the building should be assessed that may be disrupted during the renovation.

This executive summary is to be read in conjunction with the remainder of the report.

TABLE OF CONTENTS

1.0	INTRODUCTION	1
1.1	Background.....	1
2.0	REGULATORY FRAMEWORK	1
3.0	METHODOLOGY AND SCOPE	2
3.1	Scope of Assessment	2
3.2	Methodology	3
3.3	Asbestos	3
3.4	Excluded Asbestos-Containing Building Materials	4
3.5	Benzene.....	4
3.6	Lead	4
3.7	Mercury	4
3.8	Silica.....	4
3.9	Mould Contamination	4
3.10	Polychlorinated Biphenyls	5
3.11	Inaccessible Locations	5
4.0	EXISTING REPORTS AND DRAWINGS	5
5.0	FINDINGS.....	5
5.1	Building Information.....	5
5.2	Asbestos	6
5.3	Benzene.....	8
5.4	Lead	8
5.5	Mercury.....	8
5.6	Silica.....	9
5.7	PCBs.....	9
5.8	Mould	9
6.0	CONCLUSIONS AND RECOMMENDATIONS.....	9
6.1	General Recommendations	9
6.2	Remedial Recommendations	11
7.0	STATEMENT OF LIMITATIONS	11

Appendix A – Laboratory Certificate of Analysis

Appendix B – Drawings

1.0 Introduction

1.1 Background

Parasol Environmental Inc. (Parasol) was retained by the Durham District School Board to conduct a Limited Designated Substance Survey within Eastdale Collegiate and Vocational Institute located at 265 Harmony Road North, Oshawa, Ontario. The purpose of the survey was to record the presence, location, condition and quantities of Designated Substances and Hazardous Materials within the surveyed area that may be disturbed during the planned renovation. Additional information is provided to document corrective measures necessary to ensure that remedial action occurs using the proper abatement procedures, if necessary.

The survey was completed by Brad Panzer of Parasol on June 2, 2025.

2.0 Regulatory Framework

The following Acts, Regulations, Guidelines and documents were utilized for the survey and the preparation of this report:

1. *Occupational Health and Safety Act R.S.O. 1990, c. O.1.*
 - I. *Ontario Regulation 278/05- Designated Substances – Asbestos on Construction Projects and in Buildings and Repair Operations.*
 - II. *Ontario Regulation 490/09- Designated Substances.*
 - III. *Ontario Regulation 833 – Control of Exposure to Biological or Chemical Agents.*
 - IV. *Ontario Regulation 213/91 – Construction Projects*
2. Ministry of Labour (MOL) Document, “*Guideline - Lead on Construction Projects*”, September 2004.
3. Environmental Abatement Council of Canada (EACC) “*Lead Guideline for Construction, Renovation, Maintenance or Repair*”, October 2014.
4. Ministry of Labour (MOL) Document, “*Guideline - Silica on Construction Projects*”, September 2004.
5. Environment Canada Document, “*PCB Identification of Lamp Ballasts Containing PCBs*” August 1991.
6. Canadian Construction Association (CCA), “*Mould Guidelines for the Canadian Construction Industry*”, 2018.
7. Environmental Abatement Council of Canada (EACC) “*Mould Abatement Guidelines - Edition 3*”, 2015.
8. Ontario Ministry of Labour (MOL), *Alert: Mould in Workplace Buildings*, ISSN: 1195-5228, December 2000.
9. Environmental Abatement Council of Canada (EACC) “*Pre-Construction Designated Substances and Hazardous Materials Assessments Guideline for Construction, Renovation and Demolition Projects*” 2021.

Ontario Regulation 490/09 – *Designated Substances* defines the eleven (11) Designated Substances, establishes the requirements for workplaces containing these materials, which include the health and safety responsibilities, control programs to minimize worker’s exposures, and sets out the maximum exposure concentrations.

The control and management of asbestos in Ontario are further prescribed by Ontario Regulation 278/05- *Designated Substances – Asbestos on Construction Projects and in Buildings and Repair Operations*.

The major components of O. Reg 278/05 require that an asbestos survey record be completed for buildings or private residences with more than four units, and an asbestos management program be established for the asbestos-containing materials present within these buildings. The regulation also states the frequency in which a building material must be sampled, and defines an asbestos-containing material. The current definition of asbestos-containing material in Ontario is having 0.5% or greater fibrous silicate asbestos content by dry weight. Further, the Regulation divides asbestos-containing material into friable material (a

material, when dry, can be crumbled, pulverized, or powdered by hand pressure, or is crumbled, pulverized, or powdered) and non-friable material. In addition, the Regulation also defines the minimum measures and procedures for the repair or removal of asbestos-containing materials. Due to the limited scope of this survey, this report does not meet all the requirements of O. Reg. 278/05 and additional asbestos-containing materials may be present within the building that are not noted within this report. Within this report, building materials are separated into the typical applications of asbestos-containing materials.

Section 30 of the Occupational Health and Safety Act requires an Owner to determine and list Designated Substances present at a project site before beginning work. Further, this information must be included in tender documents, and the Owner and Constructor must ensure that each prospective contractor and subcontractor receive a copy of the information before entering into a binding contract. Otherwise, the Owner is liable to the constructor and every contractor and subcontractor who suffers any loss or damage as a result of the failure. The same liability applies to the Constructor regarding their contractors and subcontractors. This report meets the requirements of Section 30 of the Act.

Section 6, subsection 3 of O. Reg 213/91 requires that a Notice of Project be filed with the Ministry of Labour before beginning a project and the document requires the constructor to remark if any Designated Substance will be used, handled, or disturbed on the project. The information provided in this report can be used for the Notice of Project.

Based on the Environmental Abatement Council of Canada (EACC) *“Lead Guideline for Construction, Renovation, Maintenance or Repair”*, dated October 2014, and for this report, paints, mortar, or surface coatings containing less than or equal to 0.1% lead by weight (1000 µg/g or 1000 mg/kg or 1000 ppm lead) are considered low-level lead paints, mortars, or surface coatings. Paints, mortars, or surface coatings containing greater than 0.1% lead by weight (1000 µg/g, or 1000 mg/kg, or 1000 ppm) but less than 0.5% lead by weight (5000 µg/g, or 5000 mg/kg, or 5000 ppm lead) are considered lead-containing paints, mortars, or surface coatings. Paints, mortars, or surface coatings containing equal to or greater than 0.5% lead by weight (5000 µg/g, or 5000 mg/kg, or 5000 ppm lead) are considered lead-based paints, mortars, or surface coatings.

3.0 Methodology and Scope

3.1 Scope of Assessment

The survey was limited to the select portions of the main office area as illustrated on the architectural drawings provided by the client. The scope of the assessment was carried out in all accessible areas on a non-intrusive basis. Areas that were inaccessible at the time of the survey are listed in Section 3.11.

For this assessment, the following Designated Substances, as defined under *Ontario Regulation 490/09-Designated Substances* made under the *Occupational Health and Safety Act R.S.O. 1990, c. O.1* were assessed for as they are typically found in buildings and building material:

1. Asbestos
2. Benzene
3. Lead
4. Mercury
5. Silica

In addition to the above-noted Designated Substances, Parasol personnel also documented the presence of the following hazardous materials, which have similar Regulations that outline the management, handling and disposal of the material.

1. Polychlorinated Biphenyls
2. Mould

For this assessment, the following Designated Substances, as defined under *Ontario Regulation 490/09-Designated Substances* made under the *Occupational Health and Safety Act R.S.O. 1990, c. O.1*, were not assessed as they would not be found in building materials that may be disturbed as part of this project and typically only found in industrial or manufacturing settings.

1. Acrylonitrile
2. Arsenic
3. Coke Oven Emission
4. Ethylene Oxide
5. Isocyanates
6. Vinyl Chloride

No additional comments will be made regarding these materials within this report unless the Owner or the Owner Representative notifies Parasol of the use of these materials within the building.

3.2 Methodology

The assessment was completed largely on a visual basis at ground level and representative checks were made above ceilings with the aid of a six-foot (6FT) step ladder. Locations and building materials present above this height were considered to be inaccessible. In addition, due to the non-intrusive nature of the assessment, materials concealed above solid ceiling finishes, within wall cavities, and below floor grade may be present that are not documented within this report. Designated Substances should be presumed to be present within these locations and all necessary precautions should be followed when accessing these spaces.

3.3 Asbestos

Representative bulk samples of building materials were collected in the frequency required under Table 1, Subsection 3(3) of *Ontario Regulation 278/05- Designated Substances – Asbestos on Construction Projects and in Buildings and Repair Operations*. Samples were submitted to EMC Scientific Inc., an independent, NVLAP accredited laboratory for analysis. The bulk samples were analyzed using Polarized Light Microscopy (PLM) and dispersion staining techniques in accordance with the EPA 600/R-93/116 *Method for the Determination of Asbestos in Bulk Building Materials*. If a material was determined to be asbestos-containing, the laboratory was instructed to cease analysis of the remaining samples in the Sample Set.

The locations and conditions of the asbestos-containing materials identified within the building are detailed in this report. The condition criteria were evaluated using The Public Works and Government Services Canada (PWGSC) document *Public Services and Procurement Canada Asbestos Management Standard* updated June 1, 2019, which were then used to form recommendations for the asbestos-containing material present within the surveyed area.

The condition of the asbestos-containing material was assessed as follows:

Condition	Non-Friable	Friable
GOOD	<ul style="list-style-type: none"> Material intact and stable Minor cracks may be present on the surface 	<ul style="list-style-type: none"> Material is intact, with no signs of damage or delamination. Up to 1% of sprayed fireproofing has visible damage. Mechanical insulation is completely covered in jacketing, with no penetrations or exposed insulation.
FAIR	<ul style="list-style-type: none"> Criteria not used 	<ul style="list-style-type: none"> Jacket insulation is missing Minor damage (cuts, tears, or nicks) to jacketed insulation. Insulation is exposed but not showing surface disintegration. Missing insulation ranges from minor to none.
POOR	<ul style="list-style-type: none"> Material is broken, lifted, damaged, or deteriorated 	<ul style="list-style-type: none"> Damage cannot be easily repaired More than 1% of sprayed fireproofing is damaged, delaminated, or deteriorated.

Condition	Non-Friable	Friable
		<ul style="list-style-type: none"> The original insulation jacket is missing, damaged, deteriorated, or delaminated. Insulation is exposed and significant areas have been dislodged.

3.4 Excluded Asbestos-Containing Building Materials

Due to the non-intrusive basis of the survey, the following building materials, if present, were excluded from the survey but should be considered asbestos-containing until proven otherwise: roofing materials, refractory brick in boilers and incinerators, fire door core insulation, elevator brakes, mastics, high voltage wiring, heat shields within light fixtures, mechanical packing and gaskets, insulation or vermiculite inside wall cavities or concealed spaces, insulations within mechanical units or ducts, wall finishes concealed behind visible wall finishes, window and door glazing/caulking compounds, flooring material concealed beneath visible flooring and/or concealed beneath existing sub-floors, ceramic tile grout and mortar/adhesive concealed behind ceramic tiles, and sub-grade materials.

3.5 Benzene

No samples of building materials suspected of containing benzene were collected. If above or below grade fuel tanks were present within the assessed area, they were noted within the appropriate findings section.

3.6 Lead

Representative bulk samples of the most prevalent painted finishes and/or masonry mortar suspected of containing lead that is to be disturbed as part of the project were collected at the time of the assessment. A small area of the mortar or paint and subsurface layers were collected by scraping the material down to the substrate to which they are applied. Paint finishes of limited applications were not collected. Samples were submitted to EMSL Canada Inc. (EMSL), an ELLAP accredited laboratory. The paint or mortar samples were analyzed using Flame Atomic Absorption Spectrometry in accordance with EPA Method SW 846 3050B/7000B *Flame Atomic Absorption Spectrophotometry*. Results of the analysis were reported by the laboratory as the percentage of lead by weight of the total sample (% by wt.) or the mass of lead by the mass of the total sample (mg/kg).

The condition of painted surfaces and/or masonry mortar is also detailed in this report. A visual assessment of the mortar or paint for signs of cracking, chipping, flaking, bubbling and deterioration due to friction were noted and were assessed as GOOD, FAIR or POOR based on the degree and extent of deterioration.

The remainder of the suspect lead-containing material (lead piping, copper pipes soldering joints, wiring connectors, electric cable sheathing, batteries, and lead sheeting) were noted if present.

3.7 Mercury

A visual inspection was completed based on the age, appearance, and historical uses of suspect mercury-containing equipment, building materials, or products to identify their locations and quantities. Suspect mercury-containing equipment was not dismantled nor were samples collected for the determination of mercury content.

3.8 Silica

A visual inspection of building materials suspected of containing crystalline silica (e.g., concrete, cement, tile, brick, masonry, mortar) was completed based on the historical use of suspect silica-containing materials in certain materials. Samples of building material were not collected for the determination of the presence or absence of crystalline silica.

3.9 Mould Contamination

A visual inspection to note the extent of surface mould growth and water-damaged building materials was completed within the assessed areas. No sampling for mould spore concentration, or destructive testing

to identify concealed mould growth or water damage, was completed. Surface discolouration, material degradation, or suspect mould growth were noted.

3.10 Polychlorinated Biphenyls

A visual inspection for polychlorinated biphenyls (PCBs) was completed on a select number of accessible fluorescent light ballasts present within the assessed areas. If available, information was collected from the ballasts' label and compared to the information in the Environment Canada Document, "*PCB Identification of Lamp Ballasts Containing PCBs*", dated August 1991. It is important to note that due to safety precautions, the light fixtures were not opened to obtain the manufacturer's details as the fixtures were not de-energized. If visual confirmation of PCB content within the ballast could not be made, it was assumed that light fixtures in areas constructed before 1980 and did not have T8 style fluorescent light fixtures are PCB-containing until proven otherwise.

Information from electrical equipment, transformers specifically, was limited to the exterior labels, or nameplates, a review of maintenance records, and the age of the building to determine PCB content. No dielectric fluids were collected at the time of the assessment.

Caulking and sealants were not sampled or analyzed for PCB content. It should be assumed that if the material was installed before 1980, it contains PCBs until proven otherwise.

Dry-type transformers and fluorescent light ballasts with T8 style lights are presumed to be free of PCBs.

3.11 Inaccessible Locations

At the time of the survey the following locations were inaccessible:

1. 1138-Vault

It should be presumed that asbestos-containing materials are present within these locations until proven otherwise.

4.0 Existing Reports and Drawings

The following reports were provided to Parasol and the information presented within these reports was utilized in the preparation of this report.

1. Detailed Asbestos-Containing Building Materials Survey Report. Maple Environmental Inc. January 2018 (Maple Project No: 16312-119)

Detailed drawings were provided by the client and can be found in Appendix B.

5.0 Findings

The results of the visual identification and the bulk sampling completed during the duration of the survey are summarized below. The materials are divided into typical building material applications. The Laboratory Certificate of Analysis for the bulk samples collected while on site are presented in Appendix A.

5.1 Building Information

A summary of pertinent building details specific to the surveyed area is provided in the table below. Information is based on onsite observations, and interviews conducted as well as the provided prior reports.

Building Element	Details
Date of Construction & Additions	1967-Original Building, 2018-Building Addition
Number of Floors	2
Total Area	172,332 SF
Roof Type	Modified Bitumen
Floors	Vinyl Floor Tiles, Ceramic
Walls	Masonry Block, Brick, Drywall, Wood Panel

Building Element	Details
Ceilings	Lay-in Ceiling Tiles, Drywall
HVAC	Forced Air, Radiators
Structure	Steel, Concrete

The following section summarizes the findings of the assessment and provides a general description of the hazardous materials identified and their locations.

5.2 Asbestos

5.2.1 Building Materials Not Observed

At the time of the survey, the following building materials, which are known to historically contain asbestos were not observed and therefore are not discussed further within the report.

1. Sprayed Fireproofing
2. Texture Coat Finishes
3. Plaster Finishes
4. Vermiculite
5. Vinyl Sheet Flooring
6. Transite Cement Products
7. Caulking

5.2.2 Sprayed Fireproofing

Sprayed fireproofing was not observed within the surveyed area. However, it should be noted that asbestos-containing sprayed fireproofing is present within adjacent areas of the building. It is recommended to exercise caution when removing solid building systems, as the potential presence for concealed asbestos-containing fireproofing exists.

5.2.3 Acoustic Ceiling Tiles

The following acoustic ceiling tiles were observed to be present at the time of the survey:

Tile Number	Sample Number	Description	Locations	Asbestos Content	Notes
AT-01	NA	2'x4' Pinhole and Random Flecks	1136, 1139	NA	Date Stamped (06/21/2006) non-ACM

ND= None Detected, NA= Not Applicable, CH= Chrysotile Asbestos, AM= Amosite Asbestos

5.2.4 Drywall Finishes

Drywall with joint compound applied to gypsum board was observed throughout the surveyed area as wall and ceiling finishes. Analysis of Sample Set S03A-C determined that sample S03A was found to contain **2% Chrysotile asbestos**. The remaining samples within the sample set were not analyzed due to the stop positive confirmation. Ontario Regulation 278/05, requires a material to be considered as asbestos-containing if one or more of the samples within the set is determined to contain asbestos. Therefore, all drywall with joint compound applied is considered to be asbestos-containing until additional sampling proves otherwise. The drywall was observed in FAIR to GOOD condition at the time of the assessment.

5.2.5 Insulations

Friable asbestos-containing insulations and non-asbestos-containing insulations were observed to be present on mechanical systems throughout the surveyed area.

5.2.5.1 Fitting Insulation

Parging cement applied to pipe fittings was observed to be present within the surveyed area. Previous sampling performed by others determined that the material contains **25-50% Chrysotile asbestos**. At the time of the assessment, all visible parging cement applied to pipe fittings was observed in GOOD condition. Parging cement is likely to be concealed above solid ceilings throughout the surveyed area.

The remaining fitting insulation present within the surveyed area was observed to be fibreglass; a material not suspected to contain asbestos.

5.2.5.2 Straight Insulation

Cellulose insulation applied to pipe straights was observed to be present within the surveyed area. Analysis of Sample Set S05A-C determined that the cellulose pipe insulation does not contain asbestos.

The remaining pipe straight insulation present within the surveyed area was observed to be fibreglass; a material not suspected to contain asbestos.

5.2.5.3 Duct Insulation

Ducts present within the surveyed area were observed to be externally insulated with fibreglass; a building material not suspected to contain asbestos, or were not insulated.

5.2.5.4 Mechanical Equipment Insulation

Mechanical equipment (radiators) within the surveyed area was observed to not be externally insulated.

5.2.6 Vermiculite

No loose-fill vermiculite was observed to be present within the surveyed area at the time of the assessment. However, as the survey was non-destructive, loose-fill vermiculite may be present within the voids of the masonry blocks, which is a historical application of vermiculite. Precaution should be taken if the masonry block is to be disturbed.

5.2.7 Vinyl Floor Tiles

The following vinyl floor tiles were observed to be present at the time of the survey:

Tile Number	Sample Number	Description	Locations	Asbestos Content	Notes
VFT-01	S01A-C	12"x12" White with Black Spots	1136, 1137, 1137A, 1139	ND	GOOD Condition
		Black Mastic		1% CH	

ND= None Detected, NA= Not Applicable, CH= Chrysotile Asbestos, AM= Amosite Asbestos

As VFT-01 cannot be removed without disturbing or effectively separated from the associated asbestos-containing mastic, the tiles are deemed asbestos-containing and if removed, applicable asbestos abatement procedures apply.

5.2.8 Other

- Mortar associated with masonry block finishes was observed throughout the surveyed area. Analysis of Sample Set S02A-E determined that the mortar does not contain asbestos. However, a layer of primer applied to the surface of the masonry block mortar sample (Sample S02A) was analyzed as a separate sample layer and was determined to contain **1% Chrysotile asbestos**. As the material is applied directly to the surface of the masonry block, all painted masonry block finishes should be considered as asbestos-containing. Masonry Block finishes were observed in GOOD condition at the time of the assessment.
- Mortar associated with brick finishes was observed within the surveyed area. Analysis of Sample Set S08A-C determined that the samples do not contain asbestos.
- Ceramic tile grout and mortar was observed within the surveyed area. Analysis of Sample Set S06A-C determined that the samples do not contain asbestos.

- Heat shield paper associated with a light fixture was observed within the surveyed area and is limited to location #1136A-Washroom. Analysis of Sample Set S07A-C determined that the material contains **70% Chrysotile asbestos**. Heat shield paper was observed in GOOD condition at the time of the assessment.
- Ceiling tile mastic remnants were observed on the drywall second ceiling within the surveyed area. Analysis of Sample Set S04A-C determined that the samples do not contain asbestos.

5.3 Benzene

No products suspected of containing benzene were identified within the surveyed area.

5.4 Lead

Results of the lead in paint chips and/or masonry mortar are presented in the table below. The Certificate of Analysis is attached in Appendix A.

Sample No	Sample Location	Description	Substrate	Result	Lead Class	Condition
Pb-01	1139-Office	White Paint	Walls	0.013%	Low-Level Lead	GOOD
Pb-02	1137A-Storage	Beige Paint	Walls	0.020%	Low-Level Lead	GOOD
Pb-03	1137A-Storage	Mortar	Masonry Block	46 mg/Kg	Low-level Lead	GOOD
Pb-04	1136A-Washroom	Yellow Paint	Walls	0.20%	Lead-Containing	GOOD

As noted in the EACC guidelines, results above 0.1% are considered elevated and specific procedures apply to the removal or disturbance of these materials.

The following building materials were observed to be present within the assessed area and are suspected to contain lead:

- Ceramic Floor Tile Glazing
- Solder on pipe fittings

5.5 Mercury

5.5.1 Lamps

Mercury vapour is presumed to be present within all fluorescent light tubes.

5.5.2 Devices and Equipment

Thermostatic switches within the assessed areas were not observed to have liquid mercury present.

It is important to note that equipment present within the assessed area was not dismantled to verify the presence or absence of mercury within. As such, concealed mercury-containing devices may be present that are not noted within this report. Caution should be taken when dismantling this equipment as mercury-containing components should be assumed to be present.

5.6 Silica

The following building materials were observed to be present within the assessed area and are presumed to contain crystalline silica:

1. Ceramic tiles and grout
2. Masonry and mortar
3. Concrete (poured or pre-cast)

5.7 PCBs

5.7.1 Light Fixtures

Light fixtures observed within the surveyed area were observed to contain T8 lights, which contain electronic ballast and do not contain PCBs.

5.7.2 Transformers

Transformers were not observed to be present within the surveyed area.

5.8 Mould

No obvious visible mould growth and water damage were observed to be present within the surveyed area.

6.0 Conclusions and Recommendations

Based on the results of the bulk sampling and visual identification, the following Designated Substances and Hazardous Materials are known and/or assumed to be present within the surveyed area:

1. Asbestos
2. Lead
3. Mercury
4. Silica
5. PCBs

Parasol proposes the following recommendations:

6.1 General Recommendations

6.1.1 Asbestos

Based on the results of the bulk sampling and visual identification, the following asbestos-containing building materials were identified:

1. Mechanical Insulations (Parging Cement)
2. Drywall Finishes
3. Vinyl Floor Tiles
4. Vinyl Floor Tile Mastic
5. Primer (Applied to masonry block finishes)
6. Light Fixture Heat Shield Paper

Due to the presence of asbestos-containing materials within the building, the Asbestos Management Program must be updated and maintained for the building.

Perform a reassessment survey of asbestos-containing materials on an annual basis (minimum requirement).

Before any renovation activities, perform an intrusive investigation for concealed asbestos-containing materials and sample building materials that were not previously tested and may be disturbed as part of the renovation.

Before completing any renovation or alteration, all asbestos-containing material that may be disturbed as part of the project should be removed following Ontario Regulation 278/05.

6.1.2 Asbestos Abatement Procedures

The removal of non-friable asbestos-containing material (vinyl floor tiles, vinyl floor tile mastic, primer applied to masonry block finishes and light fixture heat shield paper) is to be completed using Type 1

asbestos abatement procedures provided that the material is wetted and non-powered hand tools are used. Type 2 asbestos abatement procedures apply if the non-friable material is disturbed with power tools equipped with dust collecting HEPA filters. If power tools are required that are not equipped with a HEPA attachment, then Type 3 asbestos abatement procedures apply.

Additional Type 2 and Type 3 asbestos abatement procedures apply to a building that has asbestos-containing sprayed fireproofing present within the building. These include the use of Type 2 asbestos abatement procedures when replacing HVAC filters, and Type 3 asbestos abatement procedures when cleaning or removing components associated with the HVAC system.

Removal of less than one square meter (1m²) of drywall is to be completed using Type 1 asbestos abatement procedures. If greater than one square meter (1m²) of drywall is to be disturbed then Type 2 asbestos abatement procedures apply.

Depending on the condition, geometry and size, the removal of mechanical insulations are to be completed using Type 2, Glove Bag or Type 3 asbestos abatement procedures.

6.1.3 Lead

Based on the results of the bulk sampling and the visual identification, low-level lead concentrations (less than or equal to 0.1% lead by weight (1000 µg/g or 1000 mg/kg or 1000 ppm lead)) were found to be present in the following building materials: white paint, beige paint and masonry block mortar.

Low-level lead guidelines only apply if they meet the following criteria:

1. The paint and substrate are not disturbed in an aggressive manner (grinding, cutting or blasting) or not heated where fumes are produced (welding or torching),
2. Dust control and suppression procedures are utilized so that the TWA (10 mg/m³) for particulates not otherwise specified (PNOS) is not exceeded and airborne lead concentrations are kept below 0.05 mg/m³, and,
3. Washing facilities are available for workers to wash hands and faces.

Based on the results of the bulk sampling and the visual identification, lead-containing concentrations (greater than 0.1% lead by weight (1000 µg/g, or 1000 mg/kg, or 1000 ppm) but less than 0.5% lead by weight (5000 µg/g, or 5000 mg/kg, or 5000 ppm lead) were found to be present in the following building materials: yellow paint.

Removal or disturbance of paints and brick mortar is to follow the procedures outlined in the EACC document *“Lead Guideline for Construction, Renovation, Maintenance or Repair”*, October 2014.

6.1.4 Mercury

Mercury vapour is present within fluorescent lights.

When removing the fluorescent lights, the materials are to be handled carefully to ensure they are kept sealed and intact, which will prevent direct skin contact and the inhalation of mercury vapour. Mercury is to be disposed of per Ontario Regulation 347 if greater than five kilograms (5 kg) is produced within a month.

6.1.5 Silica

Crystalline silica is suspected to be present within the ceramic tiles and grout, masonry and mortar, and concrete (poured or pre-cast) within the assessed area.

The removal or disturbance of material suspected to contain crystalline silica should follow procedures outlined in the MOL document *“Guideline - Silica on Construction Projects”*, dated September 2004.

6.1.6 PCBs

The light fixtures observed at the time of the assessment contain T8 lights, which are known to contain non-PCB electronic ballasts.

If the fluorescent light fixtures are to be disturbed as part of the project, they should be disassembled and the information on the ballast compared to the Environment Canada Document, *“PCB Identification of Lamp Ballasts Containing PCBs”* dated August 1991. If the ballast does not contain a label that states “PCB Free”

or the serial code that does not identify it as “PCB Free” then the ballast should be presumed to contain PCBs and disposed of accordingly.

6.1.7 Mould

No visible mould growth or water-damaged building materials were observed within the assessed area. If mould growth is discovered as part of the renovation project, then the material should be removed following the Environmental Abatement Council of Canada (EACC) “*Mould Abatement Guidelines - Edition 3*”, dated 2015. Further, a qualified Health and Safety professional should be consulted to inspect and verify the proper removal of the building materials.

6.2 Remedial Recommendations

The following remedial work should be completed regardless of the planned renovation.

6.2.1 Asbestos

The following remedial work is necessary if the asbestos-containing building materials are to remain:

Location	Description and Quantity	Remedial Recommendations
1137-Work Room	2 SF of Drywall in FAIR Condition	Repair drywall ceiling using Type 2 Asbestos Abatement Procedures

7.0 Statement of Limitations

The information and recommendations detailed in this report were carried out by trained professional and technical staff following generally accepted engineering and scientific work practices and procedures. Recommendations provided in this report have been generated in accordance with accepted industry guidelines and practices. These guidelines and practices are considered acceptable as of the date of this report.

During the preparation of this report, Parasol relied on information provided by the client, which includes reports and test results prepared by other consultants, the history and use of the site supplied by on-site personnel, and testing services provided by independent laboratories. Parasol has not made any independent verification of the provided information.

The collection of samples at the location noted was consistent with the scope of work agreed upon with the person or entity to whom this report is addressed and the information obtained concerning prior site investigations. As conditions between samples may vary, the potential remains for the presence of unknown additional contaminants for which there were no known indicators.

Information provided in this report by Parasol is intended for the client’s use only. Parasol will not provide results or information to any party unless disclosure by Parasol is required by law. Any use by a third party of reports or documents authored by Parasol or any reliance by a third party on or decisions made by a third party based on the findings described in said documents is the sole responsibility of such third parties. Parasol accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

Please contact the undersigned regarding the information presented within this report.

Sincerely,



Brad Panzer, Senior Project Manager
Parasol Environmental Inc.

Appendix A
Laboratory Certificate of Analysis

Laboratory Analysis Report

To:

Brad Panzer
Parasol Environmental
125–1860 Appleby Line, Unit #14
Burlington, Ontario
L7L 7H7

EMC LAB REPORT NUMBER: A120688

Job/Project Name: Eastdale CVI

Analysis Method: Polarized Light Microscopy – EPA 600

Date Received: Jun 3/25

Date Analyzed: Jun 5/25

Analyst: Jayoda Perera

Reviewed By: Malgorzata Sybydlo

Job No: 13307

Number of Samples: 26

Date Reported: Jun 5/25

Client's Sample ID	Lab Sample No.	Description/Location	Sample Appearance	SAMPLE COMPONENTS (%)			
				Asbestos Fibres		Non-asbestos Fibres	Non-fibrous Material
S-01A	A120688-1	VFT-01/ 1139 – office	2 Phases: a) White, vinyl floor tile b) Black, mastic	ND Chrysotile	1		100 99
S-01B	A120688-2	VFT-01/ 1137 – work room	2 Phases: a) White, vinyl floor tile b) NA	ND NA			100
S-01C	A120688-3	VFT-01/ 1137A – storage	2 Phases: a) White, vinyl floor tile b) NA	ND NA			100
S-02A	A120688-4	Masonry block mortar/ 1139 – office	2 Phases: a) Off white, primer b) Grey, cementitious material	Chrysotile ND	<0.5		100 100
S-02B	A120688-5	Masonry block mortar/ 1139 – office	2 Phases: a) White and blue, primer b) Grey, cementitious material	Chrysotile ND	1		99 100
S-02C	A120688-6	Masonry block mortar/ 1139 – office	2 Phases: a) NA b) Grey, cementitious material	NA ND			100
S-02D	A120688-7	Masonry block mortar/ 1137 – work room	2 Phases: a) NA b) Grey, cementitious material	NA ND			100
S-02E	A120688-8	Masonry block mortar/ 1137A – storage	2 Phases: a) NA b) Grey, cementitious material	NA ND			100

EMC LAB REPORT NUMBER: A120688

Client's Job/Project Name/No.: 13307

Analyst: Jayoda Perera

Client's Sample ID	Lab Sample No.	Description/Location	Sample Appearance	SAMPLE COMPONENTS (%)			
				Asbestos Fibres		Non-asbestos Fibres	Non-fibrous Material
S-03A	A120688-9	DJC/ 1137 – work room	Off white, joint compound	Chrysotile	2		98
S-03B	A120688-10	DJC/ 1137A – storage	NA	NA			
S-03C	A120688-11	DJC/ 1139 – office	NA	NA			
S-04A	A120688-12	Ceiling tile mastic/ 1139 – office	Brown, mastic	ND			100
S-04B	A120688-13	Ceiling tile mastic/ 1139 – office	Brown, mastic	ND			100
S-04C	A120688-14	Ceiling tile mastic/ 1139 – office	Brown, mastic	ND			100
S-05A	A120688-15	Pipe insulation/ 1139 – office	2 Phases: a) Black, paper with tar b) Brown, layered paper	ND ND		80 90	20 10
S-05B	A120688-16	Pipe insulation/ 1139 – office	2 Phases: a) Black, paper with tar b) Brown, layered paper	ND ND		80 90	20 10
S-05C	A120688-17	Pipe insulation/ 1139 – office	2 Phases: a) Black, paper with tar b) Brown, layered paper	ND ND		80 90	20 10
S-06A	A120688-18	Grout + mortar/ 1139 – office	Grey, cementitious material	ND			100
S-06B	A120688-19	Grout + mortar/ 1139 – office	Grey, cementitious material	ND			100
S-06C	A120688-20	Grout + mortar/ 1139 – office	Grey, cementitious material	ND			100
S-07A	A120688-21	Heat shield/ 1136A – washroom	Off white, paper	Chrysotile	70	10	20
S-07B	A120688-22	Heat shield/ 1136A – washroom	NA	NA			

EMC LAB REPORT NUMBER: A120688

Client's Job/Project Name/No.: 13307

Analyst: Jayoda Perera

Client's Sample ID	Lab Sample No.	Description/Location	Sample Appearance	SAMPLE COMPONENTS (%)			
				Asbestos Fibres		Non-asbestos Fibres	Non-fibrous Material
S-07C	A120688-23	Heat shield/ 1136A – washroom	NA	NA			
S-08A	A120688-24	Brick mortar/ 1136 – principal	Grey, cementitious material	ND			100
S-08B	A120688-25	Brick mortar/ 1136 – principal	Grey, cementitious material	ND			100
S-08C	A120688-26	Brick mortar/ 1136 – principal	Grey, cementitious material	ND			100

Note:

1. Bulk samples are analyzed using Polarized Light Microscopy (PLM) and dispersion staining techniques. The analytical procedures are in accordance with EPA 600/R-93/116 method.
2. The results are only related to the samples analyzed. **ND** = None Detected (no asbestos fibres were observed), **NA** = Not Analyzed (analysis stopped due to a previous positive result).
3. This report may not be reproduced, except in full without the written approval of EMC Scientific Inc. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. Government.
4. The Ontario Regulatory Threshold for asbestos is 0.5%. The limit of quantification (LOQ) is 0.5%.
5. Vinyl floor tiles may contain very fine asbestos fibres which the PLM method cannot detect. TEM analysis may be necessary to confirm the absence of asbestos.

**EMSL Canada Inc.**

2756 Slough Street, Mississauga, ON L4T 1G3

Phone/Fax: (289) 997-4602 / (289) 997-4607

<http://www.EMSL.com>torontolab@emsl.com

EMSL Canada Or 552509799

CustomerID: 55PAEN75

CustomerPO: 13307

ProjectID:

Attn: **Brad Panzer**
Parasol Environmental Inc.
125-1860 Appleby Line
Unit 14
Burlington, ON L7L 7H7

Phone: (416) 579-1284
Fax:
Received: 6/3/2025 09:00 AM
Collected: 6/2/2025

Project: 13307/ Eastdale CVI

Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample</i>	<i>Description</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Weight</i>	<i>RDL</i>	<i>Lead Concentration</i>
Pb-01		6/2/2025	6/3/2025	0.2518 g	0.0064 % wt	0.013 % wt
552509799-0001		Site: 1139-Office/White Paint				
Pb-02		6/2/2025	6/3/2025	0.2547 g	0.0064 % wt	0.020 % wt
552509799-0002		Site: 1137A-Storage/Beige Paint				
Pb-04		6/2/2025	6/3/2025	0.2541 g	0.0064 % wt	0.20 % wt
552509799-0004		Site: 1136A- Washroom/ Yellow Paint				

Rowena Fanto, Lead Supervisor
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. * Analysis following Lead in Paint by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 0.0064% wt based on the minimum sample weight per our SOP. "<" (less than) result signifies the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. Definitions of modifications are available upon request.

Samples analyzed by EMSL Canada Inc. Mississauga, ON AIHA LAP, LLC-ELLAP Accredited #196142

Initial report from 06/06/2025 08:36:13

**EMSL Canada Inc.**

2756 Slough Street, Mississauga, ON L4T 1G3

Phone/Fax: (289) 997-4602 / (289) 997-4607

<http://www.EMSL.com>torontolab@emsl.com

EMSL Canada Or 552509799

CustomerID: 55PAEN75

CustomerPO: 13307

ProjectID:

Attn: **Brad Panzer**
Parasol Environmental Inc.
125-1860 Appleby Line
Unit 14
Burlington, ON L7L 7H7

Phone: (416) 579-1284
Fax:
Received: 6/3/2025 09:00 AM
Collected: 6/2/2025

Project: 13307/ Eastdale CVI

Test Report: Lead by Flame AAS (SW 846 3050B/7000B)*

<i>Client SampleDescription</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Weight (g)</i>	<i>RDL</i>	<i>Lead Concentration</i>
Pb-03 552509799-0003	6/2/2025 Site: 1137A-Storage/Masonry Block Mortar	6/3/2025	0.5063 g	32 mg/Kg	46 mg/Kg

Rowena Fanto, Lead Supervisor
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted.


* Analysis following Lead in Soil/Solids by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 40 mg/kg based on the minimum sample weight per our SOP. Unless noted, results in this report are not blank corrected. "<" (less than) result signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. Definitions of modifications are available upon request.

Samples analyzed by EMSL Canada Inc. Mississauga, ON

Initial report from 06/06/2025 08:36:13

Appendix B


Site Drawing












NOTE:

- 1) Drywall finishes with drywall joint compound applied are confirmed to contain Chrysotile asbestos.
- 2) Primer applied to masonry block finishes is confirmed to contain Chrysotile asbestos.

Refer to Main Report.



TITLE		LEGEND		CONFIRMED & SUSPECTED ACM		DRAWING NO		DRAWN BY:		
Limited Designated Substance Survey First Floor Plan		   	NO ACCESS ASBESTOS SAMPLE LOCATION LEAD SAMPLE LOCATION SURVEY AREA	   NOTE NOTE	VINYL FLOOR TILES AND ASSOCIATED MASTIC LIGHT FIXTURE HEAT SHIELD PAPER MECHANICAL INSULATIONS (PARGING CEMENT) DRYWALL FINISHES PRIMER (APPLIED TO MASONRY BLOCK FINISHES)	DSR-01		B. PANZER		
CLIENT						SCALE		PARASOL PROJECT NO		
Durham District School Board						NTS		13307		
LOCATION						DATE				
Eastdale Collegiate and Vocational Institute 265 Harmony Road North Oshawa, Ontario		June 6, 2025								

A. GENERAL INFORMATION

1. READ STRUCTURAL DOCUMENTS IN CONJUNCTION WITH CONTRACT DOCUMENTS, WHICH INCLUDE, BUT ARE NOT LIMITED TO, ARCHITECTURAL, MECHANICAL, AND ELECTRICAL DOCUMENTS.
2. CONTRACTOR TO BE RESPONSIBLE FOR CHECKING SITE CONDITIONS AGAINST DOCUMENTS, BEFORE PROCEEDING WITH THE WORK, AND REPORT DISCREPANCIES TO THE CONSULTANT.
3. CONTRACTOR TO PROVIDE LABOUR, MATERIALS, AND EQUIPMENT TO COMPLETE ALL STRUCTURAL WORK INDICATED.
4. CARRY OUT CONSTRUCTION OPERATIONS, INCLUDING THE INSTALLATION OF TEMPORARY GUYING AND SHORING REQUIRED, ENSURING THAT THE EXISTING STRUCTURE OR MEMBERS ALREADY ERECTED ARE NOT LOADED IN EXCESS OF THEIR SAFE LOAD CARRYING CAPACITY.
5. STRUCTURAL DOCUMENTS DO NOT NECESSARILY SHOW ALL OPENINGS AND SLAB VARIATIONS REQUIRED. THE CONTRACTOR SHALL REFER TO ARCHITECTURAL, MECHANICAL, AND ELECTRICAL DRAWINGS FOR THE EXACT LOCATION, NUMBER, AND SIZE OF OPENINGS, TRENCHES, PITS, SUMPS, SLEEVES, AND DEPRESSIONS. PROVIDE STRUCTURAL FRAMING AT THESE LOCATIONS IN ACCORDANCE WITH THE APPLICABLE TYPICAL DETAIL.

B. REFERENCE STANDARDS/CODES AND ACTS

1. THIS STRUCTURE HAS BEEN DESIGNED IN ACCORDANCE WITH AND SHALL BE CONSTRUCTED TO CONFORM WITH THE 2024 ONTARIO BUILDING CODE, ONTARIO REGULATION 203/24 (REFERRED TO AS "THE BUILDING CODE"), ANY APPLICABLE ACTS OF ANY AUTHORITY HAVING JURISDICTION, AND THE FOLLOWING:

TABLE B.1: REFERENCE STANDARDS

REF	CODE	TITLE
a)	CAN/CSA A23.1	CONCRETE MATERIALS AND METHODS OF CONCRETE CONSTRUCTION.
b)	CAN/CSA A23.2	METHODS OF TEST FOR CONCRETE.
c)	CAN/CSA A23.3	DESIGN OF CONCRETE STRUCTURES.
d)	CAN/CSA-S16	LIMIT STATES DESIGN OF STEEL STRUCTURES.
e)	CAN/CSA G40.20/G40.21	STRUCTURAL QUALITY STEEL.
f)	CAN/CSA-A370	CONNECTORS FOR MASONRY
g)	CSA-A371	MASONRY CONSTRUCTION FOR BUILDINGS.
h)	S304.1	DESIGN OF MASONRY STRUCTURES
i)	CSA G30.18	CARBON STEEL BARS FOR CONCRETE REINFORCING

2. ALL STANDARDS AND PUBLICATIONS REFERENCED BY THE STANDARDS NOTED ABOVE ARE TO APPLY.
3. WHERE THERE ARE DIFFERENCES BETWEEN THE DOCUMENTS AND THE STANDARDS, CODES AND ACTS, THE MOST STRINGENT SHALL GOVERN.

C. MATERIALS

1. PROVIDE ONLY NEW STRUCTURAL MATERIALS IN ACCORDANCE WITH THE REFERENCE STANDARDS AND THE FOLLOWING, UNLESS OTHERWISE NOTED.
 - 1.1 STRUCTURAL STEEL:
 - (a) ANGLES AND CHANNELS (L, C) AND PLATES TO CONFORM TO CAN/CSA-G40.20/G40.21 GRADE 300W.
 - 1.2 PRIME PAINT: CONFORM TO CISC/CPMA STANDARD 2-75.

- | | |
|-----|---|
| 1.3 | NON-SHRINK GROUT = COMPRESSIVE STRENGTH OF 35 MPa AT 24 HOURS. |
| 1.4 | BLOCK: CONFORM TO CAN3-A165 SERIES, MINIMUM COMPRESSIVE STRENGTH = 15.0 MPa (MIN.) BASED ON NET AREA. |
| 1.5 | MORTAR: CONFORM TO CSA A179 TYPE S FOR LOADBEARING WALLS UNLESS NOTED. |
| 1.6 | MASONRY GROUT: CONFORM TO CSA A179, 15 MPa MINIMUM COMPRESSIVE STRENGTH AT 28 DAYS, 250 mm (10") SLUMP, MAXIMUM AGGREGATE SIZE 10 mm (3/8") |

D. EXECUTION

1. STRUCTURAL STEEL
 - 1.1. PAINT ALL STRUCTURAL STEEL TO REQUIREMENTS OF CISC/CPMA 2-75. TOUCH UP ALL FIELD WELDS.
 - 1.2. ALL STRUCTURAL STEEL EXPOSED TO WEATHER SHALL BE GALVANIZED IN ACCORDANCE WITH CSA G164.
 - 1.3. ALL WELDS SHALL CONFORM TO CSA STANDARD W59.
 - 1.4. ALL WELDS EXPOSED TO VIEW SHALL BE GROUND SMOOTH.
 - 1.5. ANY ORGANIZATION UNDERTAKING TO WELD UNDER THIS CONTRACT SHALL BE CERTIFIED BY THE CANADIAN WELDING BUREAU UNDER REQUIREMENTS OF DIVISION 1 OR DIVISION 2.1 OF W47.1.
 - 1.6. UNLESS A REINFORCED MASONRY OR CONCRETE LINTEL IS SHOWN, IN MASONRY WALLS OR MASONRY PARTITIONS PROVIDE LOOSE STEEL LINTELS IN ACCORDANCE WITH REQUIREMENTS OF DOCUMENTS OVER ALL DOORWAYS, OTHER OPENINGS, AND RECESSES, INCLUDING THOSE FOR MECHANICAL OR ELECTRICAL SERVICES. IT IS THE RESPONSIBILITY OF THE CONTRACTOR TO COORDINATE THE LOCATION, SIZE AND NUMBER OF OPENINGS REQUIRED BY THE MECHANICAL AND ELECTRICAL CONSULTANT.

FOR CONTINUATION, SEE DRAWING NO. SK-S1.2

LIST OF STRUCTURAL DRAWINGS

<u>DRAWING NO.</u>	<u>DRAWING TITLE</u>
SK-S1.1	GENERAL NOTES
SK-S1.2	GENERAL NOTES
SK-S1.3	TYPICAL DETAILS
SK-S1.4	TYPICAL DETAILS
S2.1	KEY PLAN AND PART FOUNDATION PLAN
S2.2	PART SECOND FLOOR FRAMING PLAN
S2.3	PART FOUNDATION PLAN
S2.4	PART SECOND FLOOR FRAMING PLAN



375 University Ave., Suite 901
Toronto, ON M5G 2J5
416-599-(LINK) 5465
www.engineeringlink.ca

Project No. 25-2529

All reproduction & intellectual property rights reserved © 2013

Professional Seal



No.	Issue Description	YYYY-MM-DD
01	ISSUED FOR TENDER	2025-06-13

North

Project Title:

265 HARMONY RD. N., OSHAWA
EASTDALE CVI

Designed by:	MH	Scale:	AS NOTED
Drawn by:	MH	Date:	JUN. 13, 2025

Drawing Title

GENERAL NOTES

Drawing Number

SK-S1.1

- 1.7.

DO NOT SPLICE STRUCTURAL STEEL SECTIONS WITHOUT PRIOR APPROVAL OF THE CONSULTANT. ALL SPLICES SHALL DEVELOP THE FULL CAPACITY OF THE SECTION AND ARE TO BE TESTED BY NON DESTRUCTIVE METHODS, BY AN INDEPENDENT INSPECTION AND TESTING COMPANY, AT THE CONTRACTOR'S EXPENSE.
- 1.8.

COMPLETELY FILL VOIDS BENEATH STEEL BASES ON CONCRETE WITH AN APPROVED NON-SHRINK 36MPa (5ksi) GROUT
- 1.9.

SEE ARCHITECTURAL DRAWINGS FOR FIREPROOFING REQUIREMENTS. CONFIRM COMPATIBILITY OF FIREPROOFING MATERIAL WITH STEEL PAINT.
2.

MASONRY
- 2.1.

PROVIDE A MINIMUM LENGTH OF 200 mm (8") OF 100% SOLID MASONRY UNITS FOR BEARING OF STEEL, CONCRETE OR REINFORCED MASONRY LINTELS.
- 2.2.

SUPPLY AND PLACE REINFORCEMENT AND CONCRETE FOR REINFORCED MASONRY LINTELS IN ACCORDANCE WITH TYPICAL DETAILS SHOWN.
3.

ALTERATIONS AND/OR CONNECTIONS TO EXISTING STRUCTURE
- 3.1.

INSPECT THE EXISTING BUILDING AND BECOME THOROUGHLY FAMILIAR WITH THE EXISTING CONDITIONS.
- 3.2.

PRIOR TO FABRICATION OF STRUCTURAL STEEL, OPEN UP ALL AREAS WHERE CONNECTIONS ARE TO BE MADE TO EXISTING WORK AND TAKE FIELD MEASUREMENTS. MODIFY METHODS FOR CONNECTING TO SUIT SITE CONDITIONS FOUND AND TO THE APPROVAL OF THE CONSULTANT. CARRY OUT LOCAL REPAIRS TO THE EXISTING WORK AS NECESSARY AND AS DIRECTED BY THE CONSULTANT.
- 3.3.

SHORE EXISTING WORK AS REQUIRED UNTIL ALL NEW WORK HAS BEEN COMPLETED AND REVIEWED BY THE CONSULTANT.
- 3.4.

MAKE GOOD THE EXISTING WORK.

E. QUALITY CONTROL

1.

GENERAL
- 1.1

IMPLEMENT A SYSTEM OF QUALITY CONTROL TO ENSURE THAT THE MINIMUM STANDARDS SPECIFIED HEREIN ARE ATTAINED.
- 1.2

BRING TO THE ATTENTION OF THE CONSULTANT ANY DEFECTS IN THE WORK OR DEPARTURES FROM THE CONTRACT DOCUMENTS, WHICH MAY OCCUR DURING CONSTRUCTION. THE CONSULTANT WILL DECIDE UPON CORRECTIVE ACTION AND GIVE RECOMMENDATIONS IN WRITING.
- 1.3

THE CONSULTANT'S GENERAL REVIEW DURING CONSTRUCTION AND INSPECTION AND TESTING BY INDEPENDENT INSPECTION AND TESTING AGENCIES REPORTING TO THE CONSULTANT ARE BOTH UNDERTAKEN TO INFORM THE OWNER/CLIENT OF THE CONTRACTOR'S PERFORMANCE AND SHALL IN NO WAY AUGMENT THE CONTRACTOR'S QUALITY CONTROL OR RELIEVE THE CONTRACTOR OF CONTRACTUAL RESPONSIBILITY.
2.

NOTIFICATION
- 2.1

PRIOR TO COMMENCING SIGNIFICANT SEGMENTS OF THE WORK, GIVE THE CONSULTANT AND INDEPENDENT INSPECTION AND TESTING COMPANIES APPROPRIATE NOTIFICATION (MINIMUM 24 HOURS) SO AS TO AFFORD THEM REASONABLE OPPORTUNITY TO REVIEW THE WORK. FAILURE TO MEET THIS REQUIREMENT MAY BE CAUSE FOR THE CONSULTANT TO CLASSIFY THE WORK AS DEFECTIVE.

3.

DEFECTIVE MATERIALS AND WORK
- 3.1

WHERE EVIDENCE EXISTS THAT DEFECTIVE WORK HAS OCCURRED OR THAT WORK HAS BEEN CARRIED OUT INCORPORATING DEFECTIVE MATERIALS, THE CONSULTANT MAY HAVE TESTS, INSPECTIONS OR SURVEYS PERFORMED, ANALYTICAL CALCULATIONS OF STRUCTURAL STRENGTH MADE, AND THE LIKE, IN ORDER TO HELP DETERMINE WHETHER THE WORK MUST BE CORRECTED OR REPLACED. TESTS, INSPECTIONS OR SURVEYS OR CALCULATIONS CARRIED OUT UNDER THESE CIRCUMSTANCES WILL BE MADE AT THE CONTRACTOR'S EXPENSE, REGARDLESS OF THEIR RESULTS, WHICH MAY BE SUCH THAT, IN THE CONSULTANT'S OPINION, THE WORK MAY BE ACCEPTABLE.
- 3.2

ALL TESTING SHALL BE CONDUCTED IN ACCORDANCE WITH THE REQUIREMENTS OF THE BUILDING CODE, EXCEPT WHERE THIS WOULD, IN THE CONSULTANT'S OPINION, CAUSE UNDUE DELAY OR GIVE RESULTS NOT REPRESENTATIVE OF THE REJECTED MATERIAL IN PLACE. IN THIS CASE, THE TESTS SHALL BE CONDUCTED IN ACCORDANCE WITH THE STANDARDS GIVEN BY THE CONSULTANT.
- 3.3

MATERIALS OR WORK, WHICH FAIL TO MEET SPECIFIED REQUIREMENTS, MAY BE REJECTED BY THE CONSULTANT WHENEVER FOUND AT ANY TIME PRIOR TO FINAL ACCEPTANCE OF THE WORK REGARDLESS OF PREVIOUS INSPECTION. IF REJECTED, DEFECTIVE MATERIALS OR WORK SHALL BE PROMPTLY REMOVED AND REPLACED OR REPAIRED TO THE SATISFACTION OF THE CONSULTANT, AT NO EXPENSE TO THE OWNER.



No.	Issue Description	YYYY-MM-DD
01	ISSUED FOR TENDER	2025-06-13

North

Project Title:

265 HARMONY RD. N., OSHAWA

EASTDALE CVI

Designed by:	MH	Scale:	AS NOTED
Drawn by:	MH	Date:	JUN. 13, 2025
Drawing Title			

GENERAL NOTES

Drawing Number

SK-S1.2

NEW SLAB ON GRADE, MATCH EXISTING SLAB THICKNESS

100 mm (4") EMBED

IF WIDTH OF TRENCH GREATER THAN 600 mm (2'-0") PROVIDE 1 - LAYER WWF 152x152 MW 18.7x18.7 REINF. LOCATE MESH 2" FROM TOP OF SLAB. PROVIDE CONCRETE BRICK SUPPORT AS REQUIRED TO SUPPORT MESH.

EXISTING 100 mm (4") SLAB ON GRADE


PROVIDE DOWELS 250 mm (10") LG @ 600 mm (2'-0") c/c (STAGGERED). DRILL AND EPOXY INTO EXISTING SLAB EDGE.

NEW MECHANICAL SERVICE

BACKFILL TRENCH WITH COMPACTED GRANULAR MATERIAL

LATERAL SUPPORT FOR TOP OF MASONRY WALL
AT UNDERSIDE OF CONCRETE SLAB ON STEEL PAN


TD-M17



TYPICAL CONNECTION OF NEW CONCRETE
BLOCK WALL TO EXISTING CONCRETE
CONCRETE SLAB ON PAN

STEEL LINTELS FOR NON-LOAD BEARING
MASONRY WALLS

TD-S01



CLEAR SPAN	WALL THICKNESS				
	90 (3 1/2") VENEER	140 (5 1/2")	190 (7 1/2")	240 (9 1/2")	290 (11 1/2")
UP TO 1200 (4'-0")	L89x89x6.4	2-L64x64x6.4	2-L76x89x6.4 (LLH)	L76x102x6.4 + L76x127x6.4 (LLH)	3-L76x89x6.4 (LLH)
1200 (4'-0") TO 1800 (6'-0")	L127x89x6.4 (LLV)	2-L89x64x6.4 (LLV)	2-L89x89x6.4	L102x102x6.4 + L76x127x6.4 (LLH)	3-L89x89x6.4
1800 (6'-0") TO 2400 (8'-0")	L127x89x6.4 (LLV)	2-L89x64x7.9 (LLV)	2-L102x89x7.9 (LLV)	L102x102x9.5 + L89x127x7.9 (LLH)	3-L102x89x6.4 (LLV)
2400 (8'-0") TO 3000 (10'-0")	L127x89x9.5 (LLV)	2-L89x64x9.5 (LLV)	2-L152x89x7.9 (LLV)	L152x102x7.9 (LLV) + L127x127x7.9	3-L127x89x6.4 (LLV)
DETAIL					

- NOTES:
- CONNECT BACK TO BACK DOUBLE ANGLE LINTELS USING 16 mm (5/8") Ø BOLTS AT 450 mm (18") c/c MAX OR BY WELDING AT TOP AND BOTTOM USING 6 mm (1/4") WELDS x 50 mm (2") LONG AT 450 mm (18") c/c MAX. FIRST BOLT OR WELD TO BE A MAX OF 75 mm (3") FROM END OF LINTEL
 - FULLY PACK LINTEL ENDS WITH STEEL SHIMS TO ENSURE EVEN BEARING.
 - LINTELS AS COVERED UNDER THIS DETAIL ARE NOT NECESSARILY SHOWN ON THE STRUCTURAL DRAWINGS. REFER TO ARCHITECTURAL, MECHANICAL AND ELECTRICAL DRAWINGS FOR OPENING LOCATIONS AND SIZES.



No.	Issue Description	YYYY-MM-DD
01	ISSUED FOR TENDER	2025-06-13

North

Project Title:



265 HARMONY RD. N., OSHAWA
EASTDALE CVI

Designed by:	MH	Scale:	AS NOTED
Drawn by:	MH	Date:	JUN. 13, 2025
Drawing Title			

TYPICAL DETAILS

Drawing Number

SK-S1.4



EXISTING THICKENED SLAB
AT EXISTING MASONRY WALL
LOCATIONS, SITE VERIFY.

EXISTING CONCRETE SPREAD
FOOTING AT COLUMN
LOCATIONS, TYP.


EXISTING CONCRETE PIER AT
COLUMN LOCATIONS, TYP.

EXISTING 6"x6" STEEL
COLUMNS, TYP.

EXISTING 4" BLOCK + 4" BRICK
NON-LOAD BEARING MASONRY
WALL, CONTRACTOR TO SITE
VERIFY CONSTRUCTION PRIOR
TO INSTALLATION OF
STRUCTURAL STEEL

NEW DOOR OPENING IN
EXISTING NON-LOAD
BEARING MASONRY WALL

NEW NON-LOAD BEARING 4" MASONRY
BLOCK WALL, REFER TO ARCHITECTURAL
DRAWINGS FOR ADDITIONAL
INFORMATION. AT BASE OF WALL PROVIDE
1 COURSE TALL BOND BEAM, TYP @ ALL
NEW 4" MASONRY WALL LOCATIONS




KEY PLAN
A
S2.1 N.T.S.


PART FOUNDATION PLAN
B
S2.1 1/4"=1'-0"

NOTES:

1. TOP OF SLAB ON GRADE TO BE 0'-0" BELOW FINISHED GROUND FLOOR ELEVATION 0, EXCEPT AS CROSSED AND NOTED. AREAS CROSSED AND NOTED TO BE READ FROM GROUND FLOOR ELEVATION 0.
2. PROVIDE SLAB DEPRESSIONS AND SLOPES, OTHER THAN THOSE SHOWN ON THE STRUCTURAL DRAWINGS, AS REQUIRED BY THE ARCHITECTURAL AND MECHANICAL DRAWINGS AND SPECIFICATIONS.
3. SEE ARCHITECTURAL DRAWINGS FOR SLOPES TO DRAIN. MAINTAIN SLAB THICKNESSES SHOWN.



0	ISSUED FOR TENDER	2025/06/13
REV	REASON FOR ISSUANCE	DATE
TITLE KEY PLAN AND PART FOUNDATION PLAN		
Address 265 Harmony Road North, Oshawa, ON L1G 6L5		
School EASTDALE CVI		Date: JUNE 13, 2025
		Drawn By: MH
		Scale: 1/4" = 1'-0"
		Checked By: MH
		Project Number S2.1



PART SECOND FLOOR FRAMING PLAN

A
S2.2
1/4"=1'-0"

- NOTES:
- 1.TOP OF CONCRETE SLAB IS 0'-0" BELOW SECOND FLOOR ELEVATION +14'-6", EXCEPT AS CROSSED AND NOTED. AREAS CROSSED AND NOTED TO BE READ FROM SECOND FLOOR ELEVATION +14'-6".
 - 3.TOP OF STEEL BEAMS ARE 0'-5" BELOW SECOND FLOOR ELEVATION +14'-6", UNLESS NOTED +/- 0'-0" ON PLAN. BEAM ELEVATIONS NOTED ON PLAN ARE TO BE READ FROM SECOND FLOOR ELEVATION +14'-6".
 - 4.EXISTING STRUCTURE HAS BEEN CHECKED FOR NEW LOADS (INCL. WIND LOADS) AND WAS FOUND TO BE ACCEPTABLE.
 - 5.LIVE LOADS ARE AS FOLLOWS, UNLESS NOTED OTHERWISE ON PLAN:
- | | |
|----------------------|---------|
| CLASSROOM | 50 psf |
| STAIRS AND CORRIDORS | 100 psf |
- 6.SUPERIMPOSED DEAD LOADS ARE:

CLASSROOM	50 psf
STAIRS AND CORRIDORS	100 psf
PARTITION ALLOWANCE	20 psf
CONCRETE TOPPING	20 psf
FLOOR FINISH	15 psf
CEILING FINISHES	5 psf
MECHANICAL & ELECTRICAL	5 psf

L89x89x6.4 STEEL ANGLE (FOR 4" BLOCK) + L89x89x6.4 STEEL ANGLE (FOR 4" BRICK) BACK-TO-BACK TO SUPPORT MASONRY ABOVE PROPOSED DOOR OPENING.


NEW DOOR OPENING IN EXISTING NON-LOAD BEARING MASONRY WALL BELOW

PROVIDE LATERAL SUPPORT CLIPS AT TOP OF NEW NON-LOAD BEARING MASONRY WALL AS REQUIRED.

L89x89x6.4 STEEL ANGLE (FOR 4" BLOCK) + L89x89x6.4 STEEL ANGLE (FOR 4" BRICK) TOE-TO-TOE TO SUPPORT MASONRY ABOVE PROPOSED DOOR OPENING.

0	ISSUED FOR TENDER	2025/06/13
REV	REASON FOR ISSUANCE	DATE
TITLE PART SECOND FLOOR FRAMING PLAN		
Address 265 Harmony Road North, Oshawa, ON L1G 6L5		
School EASTDALE CVI		Date: JUNE 13, 2025
		Drawn By: MH
		Scale: 1/4" = 1'-0"
		Checked By: MH
		Project Number S2.2





- EXISTING 4" NON-LOAD BEARING MASONRY WALL, CONTRACTOR TO SITE VERIFY CONSTRUCTION PRIOR TO INSTALLATION OF STRUCTURAL STEEL
- TOOTH NEW MASONRY INTO EXISTING MASONRY BLOCK WALL. NOT ACCEPTABLE TO DOWEL INTO EXISTING MASONRY.
- EXISTING CONCRETE SPREAD FOOTING AT COLUMN LOCATIONS, TYP.
- EXISTING CONCRETE PIER AT COLUMN LOCATIONS, TYP.
- EXISTING 6"x6" STEEL COLUMNS, TYP.
- NEW DOOR OPENING IN NEW NON-LOAD BEARING MASONRY WALL
- NEW NON-LOAD BEARING 4" MASONRY BLOCK WALL, REFER TO ARCHITECTURAL DRAWINGS FOR ADDITIONAL INFORMATION, TYP @ ALL NEW 4" MASONRY WALL LOCATIONS.

A

S2.3


PART FOUNDATION PLAN


1/4"=1'-0"

NOTES:

1. SEE B/S2.1 FOR ADDITIONAL NOTES




0	ISSUED FOR TENDER	2025/06/13
REV	REASON FOR ISSUANCE	DATE
TITLE PART FOUNDATION PLAN		
Address 265 Harmony Road North, Oshawa, ON L1G 6L5		
School EASTDALE CVI		Date: JUNE 13, 2025
		Drawn By: MH
		Scale: 1/4" = 1'-0"
		Checked By: MH
		Project Number
		S2.3


$$1/4" = 1'-0"$$

1. SEE A/S2.2 FOR ADDITIONAL NOTES.


PROVIDE LATERAL
SUPPORT CLIPS AT TOP OF
NEW NON-LOAD BEARING
MASONRY WALL AS
REQUIRED.

Ⓜ


0	ISSUED FOR TENDER	2025/06/13
REV	REASON FOR ISSUANCE	DATE
TITLE		
PART SECOND FLOOR FRAMING PLAN		
Address		
265 Harmony Road North, Oshawa, ON L1G 6L5		
School		
EASTDALE CVI		
		Date: JUNE 13, 2025
		Drawn By: MH
		Scale: 1/4" = 1'-0"
		Checked By: MH
		Project Number
		S2.4

NOTES :

FRAME ELEVATION



FRAME ANCHORS




#4 = 7-3/4" #5 = 8-3/4"

RIVETT ARCHITECTURAL HARDWARE LTD.


PRESSED STEEL FRAME SECTIONS AND ANCHOR TYPES

ELEVATIONS




A = REBATE OPENING	C = HINGE SPACING	E = HINGE SPACING	G = DOOR UNDERCUT
B = REBATE HEIGHT	D = HINGE SPECING	F = HINGE SPACING	H = HINGE SIZE

FRAME SECTIONS



SECTION	A	B	C	D	E	F	G
V.P OFFICE 1	4-3/4"	1-15/16"	1-9/16"	1-1/4"	5/8"	2"	1/2"
	121MM	49MM	40MM	32MM	16MM	51MM	13MM
2	5-3/4"	1-15/16"	1-9/16"	2-1/4"	5/8"	2"	3/8"
	146MM	49MM	40MM	57MM	16MM	51MM	10MM
3	6-3/4"	1-15/16"	1-9/16"	3-1/4"	5/8"	2"	1/2"
	172MM	49MM	40MM	83MM	16MM	51MM	13MM
4	7-3/4"	1-15/16"	1-9/16"	4-1/4"	5/8"	2"	1/2"
	197MM	49MM	40MM	108MM	16MM	51MM	13MM
LAN/TECH OFFICE	8-3/4"	1-15/16"	1-9/16"	5-1/4"	5/8"	2"	1/2"
	222MM	49MM	40MM	133MM	16MM	51MM	13MM

ANCHOR TYPES




RIVETT ARCHITECTURAL HARDWARE LTD.

PRESSED STEEL TRANSUM FRAME ELEVATIONS

JOB:

DOOR #: LAN TECH OFFICE




ELEV. "A"

RIVETT ARCHITECTURAL HARDWARE LTD.

PRESSED STEEL TRANSUM FRAME ELEVATIONS

JOB:

DOOR #: V.P OFFICE



ELEV. "A"

Rivett Architectural Hardware Ltd.

Door Listing

EASTDALE C.V.I - MAIN OFF. ALT - 265 Harmony Rd N, Oshawa

Schedule 200766
Date Jun 20/25

Door Number	Set Number
LAN/TECH	2
VP OFFICE	1

Rivett Architectural Hardware Ltd.
Hardware Schedule
EASTDALE C.V.I - MAIN OFF. ALT - 265 Harmony Rd N, Oshawa

Schedule 200766
Date Jun 20/25

Set # 1

1 SGLE. DR. # VP OFFICE GENERAL OFFICE TO NEW V.P OFFICE RH
1 -2'8" x 7'0" x 1-3/4" x PSF x WD DR

Qty

:	:	3 EA	HINGE	BB1279-114 X 101- 626
:	:	1 EA	OFFICE LOCK	L9050P X 03B X 626
:	:	1 EA	WALL STOP	232W X 626
:	:	1 EA	KICKPLATE	190S X 203 X 762 X 630

Set # 2

1 SGLE. DR. # LAN/TECH EXISTING CORRIDOR TO NEW LAN/TECH OFFICE RH
1 -3'0" x 7'0" x 1-3/4" x PSF x WD DR x 45 MIN RATED

Qty

:	:	3 EA	HINGE	BB1279-114 X 101- 626
:	:	1 EA	OFFICE LOCK	L9050P X 03B X 626
:	:	1 EA	CLOSER	4040XP X 689
:	:	1 EA	WALL STOP	232W X 626
:	:	1 EA	KICKPLATE	190S X 203 X 863 X 630

WHITBY, ONT.

TEL-905-668-4455 FAX-905-668-4433

PART __

Baillargeon		ELEVATION FOR PRE-MACHINED DOOR							
Doors Inc.	DR CONST. #	AF	45	SPECIES	PS. WHITE MAPLE		FACTORY FINISH	BC-00-25 CLEAR COAT	
	DOOR EDGE	ME	GLAZING TYPE		"M" FOR FIRE RATED STEEL		PACKAGING - SHRINK WRAP	YES	
DATE:	BEVEL-1/8" in 2"	BOTH EDGES		LOCK MANUFACTURER		SCHLAGE			
	FUNCTION	SINGLE		LOCK FUNCTION #		L9050P X 03B X 626		DOOR #	HAND
ORDER #	PLEASE FILL IN DETAILS AND SIGN HAND OF DOOR		NOMINAL (IN INCHES)	WIDTH "	HEIGHT "	THICKNESS	LAN/TECH OFFICE		RH
BILL #			CLEARANCE"	36	84	1.75			
TAG #			UNDERCUT "	0.25	0.125	EXACT WIDTH "			
ELEV. #				0.75	35.750				
RESERVED FOR MACH. DEPT.	LH	0				LOCK C/LINE TO TOP OF DOOR			
C/C (1-2) _____ (2-3) _____	LHR	0				43.937			
DOOR STOP L.H. _____	RH	1							
C/L CYLINDER L.H. _____	RHR	0							
C/L D/L/ L.H. _____	TOTAL COUNT	1		EXACT HEIGHT "				LEEDS CERTIFICATION	
C/L MORTISE L.H. _____	HINGES	3		83.125				FSC NO	
	HEIGHT	4.5		39 5/16				UFF NO	
	GAUGE	.134S		71 1/4				AGRIFIBER CORE NO	
	DEPTH	1 1/2 "						FACEPLATE	
		X SQUARE						DRIVE-IN 1" 1" X 1-1/4" SAME FOR D/LOCKS	
		RADIUS 1/4"						1-1/8" X 2-1/4"	
		RADIUS 5/8"						1-1/4" X 8" X OTHER → SEE NOTES	

NOTES:

PART # _____

NOTES:

PART #