



COLBOURNE & KEMBEL , ARCHITECTS INC.

739D ARLINGTON PARK PLACE KINGSTON ONTARIO K7M 8M8
E-MAIL Info@ckai.ca

TEL 613-384-2240

ADDENDUM #2

PROJECT: Aesthetics Lab and Classroom
Renovation at Centennial Secondary
School RFQ-VOR 2526-102

PROJ. NO.: 25045

DATE: December 8, 2025

of pages: 1

The following information supplements and/or supersedes the documents issued on Thursday, November 20, 2025.

This addendum forms part of the contract documents and is to be read, interpreted, and coordinated with all other parts. The cost of all contained herein is to be included in the contract sum. The following revisions supersede the information contained in the original drawings and specifications issued for the above-named project to the extent referenced and shall become part thereof. Acknowledging receipt of this Addendum will be requested on the Bidding System. Failure to do so may subject bidder to disqualification.

1.0 Drawings

- .1 Drawing 301 Note C10 Revise note C10 to read: Install smart board projector to be supplied by owner.

2.0 Questions and Clarifications

- .1 Question: Note C10 says supply and install new smart board wall projector.
Is there a spec for this equipment?
Answer: Revise note C10 to read: Install smart board projector to be supplied by owner.

End of Addendum



December 3, 2025

Hastings And Prince Edward District School Board
224 Palmer Road
Belleville, ON K8P 4E1

Re: Hazardous Building Materials Assessment (Preconstruction)
Centennial Secondary School, 160 Palmer Road, Belleville, ON
Pinchin File: 200584.110

Hastings And Prince Edward District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct a hazardous building materials assessment of Centennial Secondary School located at 160 Palmer Road, Belleville, ON.

Pinchin performed the assessment on November 20, 2025. The assessor was unaccompanied during the assessment. The assessed area was unoccupied at the time of the assessment.

The objective of the assessment was to identify specified hazardous building materials in preparation for building renovation. The proposed work includes renovations to convert the existing classroom 204 into an aesthetics lab, as identified in the drawings provided by the Client entitled "*Centennial SS*", dated October 2025, prepared by Colborne & Kembel Architects Inc., Project No. 25045.

The **assessed area** is limited to the portion(s) of the building to be renovated, as described by the Client, and identified in the drawings in Appendix I.

1.0 SUMMARY OF FINDINGS

- Asbestos-Containing Materials (ACM) are present as follows:
 - Vinyl floor tiles
- Lead is present in paints and coatings.
- Crystalline silica is present in concrete and other materials such as masonry and mortar.
- Mercury vapour is present in lamp tubes.
- No PCB-containing items were identified.
- No mould or water damage was identified.



2.0 RECOMMENDATIONS

2.1 General

If suspected hazardous building materials are discovered during the planned work, which are not identified in this report, do not disturb, and arrange for further testing and evaluation.

Provide this report to the contractor prior to bidding or commencing work.

Retain a qualified consultant to specify, observe and document the successful removal of hazardous materials.

Update the asbestos inventory upon completion of the abatement and removal of asbestos-containing materials and any other relevant findings.

2.2 Project Work

The following recommendations are made regarding renovation involving the hazardous materials identified.

2.2.1 Asbestos

Remove asbestos-containing materials (ACM) prior to renovation, alteration, or maintenance if ACM may be disturbed by the work.

If the identified ACM will not be removed prior to commencement of the work, any potential disturbance of ACM must follow asbestos precautions appropriate for the type of work being performed.

Asbestos-containing materials must be disposed of at a landfill approved to accept asbestos waste.

2.2.2 Lead

For lead-containing or lead-based paints (i.e., greater than the EACC guideline of 0.1% (1,000 mg/kg) for lead-containing paints, and 0.5% (5,000 mg/kg) for lead-based), construction disturbance may result in over-exposure to lead dust or fumes. The need for work procedures, engineering controls and personal protective equipment should be assessed on a site-specific basis to comply with applicable regulations, and/or guidelines.

For paints identified as having low levels of lead (i.e., equal to or above 0.009% (90 mg/kg) but less than or equal to the EACC guideline of 0.1% (1,000 mg/kg) for lead-containing paints) special precautions are not recommended unless aggressive disturbance (grinding, blasting, torching) is planned.

Exposure from construction disturbance of paints containing lead less than 0.009% (90 mg/kg) is assumed to be insignificant.



Items painted with paints containing elevated levels of lead may be a hazardous waste. Test lead-painted materials for leachable lead and other metals prior to disposal. Metallic components coated with lead paint do not require leachate testing and can be disposed of as non-hazardous construction and demolition (C&D) waste.

2.2.3 Silica

Construction disturbance of silica-containing products may result in excessive exposures to airborne silica, especially if performed indoors and dry. Cutting, grinding, drilling or demolition of materials containing silica should be completed only with proper respiratory protection and other worker safety precautions that comply with applicable regulations and guidelines.

2.2.4 Mercury

Do not break lamps. Recycle and reclaim mercury from fluorescent lamps when taken out of service. Mercury is classified as a hazardous waste and must be disposed of in accordance with applicable regulations.

3.0 BACKGROUND INFORMATION

3.1 Assessed Area Description Summary

Description Item	Details
Building Use	Secondary School
Floors Above Grade	2 (assessed area limited to portion of the ground floor)
Floors Below Grade	0
Total Area (assessed area)	1,200 square feet
Year of Construction	1967
Structure	Poured concrete foundation, Structural steel, Precast concrete panels/slabs, Concrete block
Exterior Cladding	Brick, Precast concrete panels, Metal cladding
HVAC	Mechanical Room Air Handling Units, Boiler with radiators
Roof	Flat, Unknown (Not assessed)
Flooring	Vinyl floor tile
Wall and Ceiling Finishes	Drywall, Concrete block, Lay-in ceiling tiles



3.2 Existing Reports

3.2.1 Review of Previous Reports

Pinchin reviewed the following reports and included relevant results as appropriate:

- “Asbestos Reassessment, Centennial Secondary School, 160 Palmer Road, Belleville, Ontario” dated May 31, 2024, prepared by Pinchin Ltd., Pinchin File No.: 200584.085.
- “Hazardous Building Materials Assessment (Preconstruction), Centennial Secondary School, 160 Palmer Road, Belleville, Ontario” dated January 13, 2025, prepared by Pinchin Ltd., Pinchin File No.: 200584.095.

4.0 FINDINGS

Any quantities listed in this report or data tables are estimated based on visual approximations only and are subject to variation.

4.1 Asbestos

The following table summarizes the materials evaluated for asbestos in the assessed area. For details on approximate quantities, condition, friability, accessibility, and locations of hazardous building materials; refer to the Hazardous Material Summary / Sample Log and All Data Report in Appendices V and VI.

Sample Number	Material Description	Type of Asbestos	Confirmed Hazard	Total Quantity Present	Material Specific Notes
V0015	Wall Paint I on Concrete Block	None Detected	No	2,000 SF	
V0016	Structure Paint I on Concrete Column	None Detected	No	200 SF	
S0021 ABC	Floor Vinyl Floor Tile and Mastic 12"x12" beige with pink streaks	None Detected	No	145 SF	
S0023 ABC	Other Conduit I Firestopping (mastic) Yellow	None Detected	No	4 SF	
V9000	Floor Vinyl Floor Tile 12x12 pale green, 12x12 off-white and 12x12 grey	Confirmed Asbestos	Yes	975 SF	Previous samples ASB-125.1-3
V0000	Ceiling Ceiling Tiles (lay-in) 2'x4' lay-in, fissures across length and 2'x4' lay-in, fissures across width	None	No	1,200 SF	Previous samples: ASB-103. 1-3, ASB-104. 1-3,



Sample Number	Material Description	Type of Asbestos	Confirmed Hazard	Total Quantity Present	Material Specific Notes
V0000	Floor Mastic Under Vinyl Floor Tiles	None	No	1,200 SF	Previous samples ASB-125.1-3, A0012A-C and A0013A-C
V0000	Floor Vinyl Floor Tile and Mastic 12"x12" light brown with dark brown and white smears	None	No	80 SF	Installed post 2017

General Notes:

Materials identified as Sample Number V9000 were observed to be present and were determined to contain asbestos based on previous analytical results.

Materials identified as Sample Number V0000 were determined to be non-asbestos based on the manufacture date and known end of use of asbestos in these products or previous analytical results.

Destructive testing was conducted of a representative selection of masonry walls, including creating penetrations at 6 locations. The locations of destructive testing have been indicated on the drawings in Appendix I. Loose fill vermiculite was not observed within the cavities.

4.1.1 Excluded Asbestos Materials

The following is a list of materials which may contain asbestos and were excluded from the assessment. These materials are presumed to contain asbestos until otherwise proven to be non-asbestos by sampling and analysis:

- Roofing felts and tar, mastics
- Electrical components
- Adhesives and duct mastics
- Vibration dampers on HVAC equipment
- Sealants on pipe threads
- Inaccessible/concealed materials
- Materials outside of the assessed area

4.2 Lead

Refer to the Hazardous Material Summary / Sample Log and All Data Report in Appendices V and VI for details on locations, condition and approximate quantities on paints sampled and their locations.

The following table summarizes the analytical results of paints sampled.

Sample Number	Material Description	Concentration	Confirmed Hazard	Total Quantity Present	Material Specific Notes
V0002	Wall Concrete (precast) Various colours	0.0095%	Yes	2200 SF	
L0009	Ceiling Drywall (no compound) Off-White on bulkhead	0.0034 %	No	150 SF	
L0010	Wall Metal Red and white on metal door and frame	1.26 %	No	20 SF	

General Notes:

Results above 0.1% (1,000 mg/kg) are considered lead-containing, and over 0.5% (5,000 mg/kg) are considered lead-based.

Results less than or equal to 0.1% (1,000 mg/kg), but equal to or greater than 0.009% (90 mg/kg), are considered low-level lead paints or surface coatings in accordance with the EACC guideline.

Paints containing lead less than 0.009% (90 mg/kg) are assumed to be insignificant relating to potential exposure from construction disturbance.

4.2.1 Lead Products and Applications

Lead products and applications were not identified during the assessment.

4.2.2 Excluded Lead Materials

Lead may be present in a number of materials which were not assessed and/or sampled. The following materials, where found, should be considered to contain lead:

- Electrical components, including wiring connectors, grounding conductors, and solder
- Solder on pipe connections

4.3 Silica

Crystalline silica is a presumed component of the following materials:

- Poured and pre-cast concrete

- Masonry and mortar

4.4 Mercury

Refer to the Hazardous Material Summary / Sample Log and All Data Report in Appendices V and VI for details on mercury-containing products including their locations and quantities.

Sample Number	Material Description	Confirmed Hazard	Total Quantity Present	Material Specific Notes
V9000	Light Fixture	Yes	100 %	

General Notes:

Items identified as Sample Number V9000 were observed to be present and were determined to contain mercury based on visual observation (e.g., labelled lamps and ampules in thermostats).

4.5 Polychlorinated Biphenyls

Refer to the Hazardous Material Summary / Sample Log and All Data Report in Appendices V and VI for details on PCB-products including their locations and quantities.

Sample Number	Material Description	Concentration	Confirmed Hazard	Total Quantity Present	Material Specific Notes
V0000	Light Ballasts		No	100 %	T8

General Notes:

Materials identified as Sample Number V0000 were determined to be non-PCB based on the manufacture date and regulated restrictions of PCBs. It can also include items that historically may have contained PCBs; however, have been visually identified as non-PCB types (e.g., fluorescent fixtures with T5 or T8 tubes, LED light fixtures).

4.6 Mould and Water Damage

Visible mould growth and water damage was not found during the assessment.

5.0 METHODOLOGY

For the purpose of the assessment and this report, hazardous building materials are defined as follows:

- Asbestos
- Lead
- Silica

- Mercury
- Polychlorinated Biphenyls (PCBs)
- Mould and Water Damage

Arsenic, acrylonitrile, benzene, coke oven emissions, ethylene oxide, isocyanates and vinyl chloride monomer are not typically found in building materials in a composition/state that is hazardous and were not included in this assessment.

Pinchin conducted a room-by-room assessment to identify the hazardous building materials as defined in the scope.

The assessment was performed to establish the type of specified hazardous building materials, locations and approximate quantities incorporated in the structure(s) and its finishes.

The assessment included limited demolition of wall and ceiling finishes (drywall or plaster) to view concealed conditions at representative areas as permitted by the current building use. Limited destructive testing of flooring was conducted where possible (under ceramic tiles, carpets, or multiple layers of flooring). Demolition of exterior building finishes, masonry walls (chases, shafts etc.), and structural surrounds was not conducted.

Limited demolition of masonry block walls (core holes) was conducted to investigate for loose fill vermiculite insulation. Sampling of roofing materials was not conducted.

For further details on the methodology including test methods and evaluation criteria, refer to Appendix III.

6.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.
3. Lead on Construction Projects, Ministry of Labour Guidance Document.
4. The Environmental Abatement Council of Canada (EACC) Lead Guideline for Construction, Renovation, Maintenance or Repair.
5. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 347 as amended.
6. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 362 as amended.
7. Silica on Construction Projects, Ministry of Labour Guidance Document.
8. Alert – Mould in Workplace Buildings, Ontario Ministry of Labour.



9. PCB Regulations, SOR/2008-273, Canadian Environmental Protection Act.
10. Surface Coating Materials Regulations, SOR/2016-193, Canada Consumer Product Safety Act.

7.0 LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.

8.0 CLOSURE

The data presented in the appendices is prepared by Pinchin's Hazardous Materials Inventory System (HMIS). The information can be made available for your real-time access through our secure web-based platform. Please contact your Pinchin representative to discuss HMIS solutions for management of your asbestos (and other hazardous materials) inventory.

Contact the Project Manager, Halie MacKillican at 613.541.1013 or hmackillican@pinchin.com should you have any questions.

Sincerely,

Pinchin Ltd.

Prepared by:

Reviewed by:

Nic Page, M.A.Sc
Project Technologist

Halie MacKillican
Team Leader, Hazardous Materials




Encl:	APPENDIX I	Drawings
	APPENDIX II-A	Asbestos Analytical Certificates
	APPENDIX II-B	Lead Analytical Certificates
	APPENDIX III	Methodology
	APPENDIX IV	Location Summary Report
	APPENDIX V	Hazardous Materials Summary Report / Sample Log
	APPENDIX VI	All Data Report
	APPENDIX VII	Photographs

\\PIN-KGN-FS01\job\200000s\0200584.000 HPEDSB,various,BellevilleON,HAZ,DSS\0200584.110 HPEDSB,CentennialSS,HAZ,HBMA\Deliverables\200584.110 HBMA CentennialSS 160PalmerRdBellevilleON HPEDSB.docx

Template: Master Template HBMA PreConstruction, HMIS, HAZ, August 15, 2024

APPENDIX I
Drawings



N

LEGEND

X

PINCHIN LOCATION NUMBER

XXX

ROOM NUMBER

SURVEY BOUNDARY/ASSESSED AREA

OUTSIDE ASSESSMENT SCOPE

ASBESTOS BULK SAMPLE

LEAD BULK SAMPLE

X

INTRUSIVE INSPECTION

ASBESTOS-CONTAINING MATERIALS:

VINYL FLOOR TILES

NOT ALL KNOWN OR SUSPECTED HAZARDOUS BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE HAZARDOUS BUILDING MATERIALS ASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED HAZARDOUS BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.

PROJECT NAME:
HAZARDOUS BUILDING MATERIALS ASSESSMENT

CLIENT NAME:
HASTINGS AND PRINCE EDWARD DISTRICT SCHOOL BOARD

PROJECT LOCATION:
CENTENNIAL SS
160 PALMER ROAD
BELLEVILLE, ONTARIO

FIGURE NAME:
SECOND FLOOR

PROJECT NUMBER:
200584.110

SCALE:
NOT TO SCALE

DRAWN BY:
SG

REVIEWED BY:
HM

DATE:
DECEMBER 2025

FIGURE NUMBER:
1 of 1

APPENDIX II-A
Asbestos Analytical Certificates



Your Project #: 200584.110
Your C.O.C. #: N/A

Attention: Nicolas Page

Pinchin Ltd
1456 Centennial Drive
Suite 2
Kingston, ON
CANADA K7P 0K4

Report Date: 2025/11/28
Report #: R8659821
Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C5E9289

Received: 2025/11/24, 14:30

Sample Matrix: Solid
Samples Received: 6

Analyses	Quantity	Date Extracted	Date Analyzed	Laboratory Method	Analytical Method
Asbestos by PLM - 0.5 RDL (1)	6	N/A	2025/11/28	COR3SOP-00002	EPA 600R-93/116

Remarks:

Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, EPA, APHA or the Quebec Ministry of Environment.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested.

This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

This report may not be reproduced, except in full, without the written approval of Bureau Veritas. This report may not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any other agency of the U.S. Government.

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.

(1) P.O.B. - Percent of Bulk

When Asbestos data is reported with other data, this report contains data that are not covered by the NVLAP accreditation.



Your Project #: 200584.110
Your C.O.C. #: N/A

Attention: Nicolas Page

Pinchin Ltd
1456 Centennial Drive
Suite 2
Kingston, ON
CANADA K7P 0K4

Report Date: 2025/11/28
Report #: R8659821
Version: 1 - Final

CERTIFICATE OF ANALYSIS

BUREAU VERITAS JOB #: C5E9289

Received: 2025/11/24, 14:30

Encryption Key



**AUTHORIZED REPORT
RAPPORT AUTORISÉ**

Bureau Veritas

28 Nov 2025 15:07:21

Please direct all questions regarding this Certificate of Analysis to:

Nilushi Mahathantila, Project Manager

Email: Nilushi.Mahathantila@bureauveritas.com

Phone# (905) 817-5700

=====

This report has been generated and distributed using a secure automated process.

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0021A FLOOR, VINYL FLOOR TILE AND MASTIC, 12"X12" BEIGE WITH PINK STREAKS, LOC:2040,204					
Bureau Veritas ID: AXRX82		Date Analyzed: 2025/11/28			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	97	Homogeneous beige vinyl floor tile	Not Detected		Non-Fibrous
Layer 2	3	Homogeneous black mastic	Not Detected		Non-Fibrous

S0021B FLOOR, VINYL FLOOR TILE AND MASTIC, 12"X12" BEIGE WITH PINK STREAKS, LOC:2040,204					
Bureau Veritas ID: AXRX83		Date Analyzed: 2025/11/28			
	P.O.B	Sample Morphology	Asbestos	Other Fibres	Particulate
Layer 1	97	Homogeneous beige vinyl floor tile	Not Detected		Non-Fibrous
Layer 2	3	Homogeneous black mastic	Not Detected		Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C5E9289
Report Date: 2025/11/28

Pinchin Ltd
Client Project #: 200584.110
Sampler Initials: NC

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0021C FLOOR, VINYL FLOOR TILE AND MASTIC, 12"X12" BEIGE WITH PINK STREAKS, LOC:2040,204						
Bureau Veritas ID:		AXRX84		Date Analyzed:		2025/11/28
	P.O.B	Sample Morphology	Asbestos	Other Fibres		Particulate
Layer 1	97	Homogeneous beige vinyl floor tile	Not Detected			Non-Fibrous
Layer 2	3	Homogeneous black mastic	Not Detected			Non-Fibrous

S0023A FIRESTOPPING (MASTIC), YELLOW, LOC:2040,204						
Bureau Veritas ID:		AXRX85		Date Analyzed:		2025/11/28
	P.O.B	Sample Morphology	Asbestos	Other Fibres		Particulate
Layer 1	100	Homogeneous yellow mastic	Not Detected	Glass Fibres	3%	Non-Fibrous

S0023B FIRESTOPPING (MASTIC), YELLOW, LOC: 2040,204						
Bureau Veritas ID:		AXRX86		Date Analyzed:		2025/11/28
	P.O.B	Sample Morphology	Asbestos	Other Fibres		Particulate
Layer 1	100	Homogeneous yellow mastic	Not Detected	Glass Fibres	3%	Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C5E9289
Report Date: 2025/11/28

Pinchin Ltd
Client Project #: 200584.110
Sampler Initials: NC

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

S0023C FIRESTOPPING (MASTIC), YELLOW, LOC:2040,204						
Bureau Veritas ID: AXRX87		Date Analyzed: 2025/11/28				
	<u>P.O.B</u>	<u>Sample Morphology</u>	<u>Asbestos</u>	<u>Other Fibres</u>		<u>Particulate</u>
Layer 1	100	Homogeneous yellow mastic	Not Detected	Glass Fibres	3%	Non-Fibrous

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, “<0.50%”. “Not Detected” indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



TEST SUMMARY

Bureau Veritas ID: AXRX82
Sample ID: S0021A FLOOR, VINYL FLOOR TILE AND MASTIC, 12"X12" BEIGE WITH PINK STREAKS, LOC:2040,204
Matrix: Solid
Collected: 2025/11/21
Shipped: 2025/11/21
Received: 2025/11/24

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	A063774	N/A	2025/11/28	Rayana De Oliveira Cardoso

Bureau Veritas ID: AXRX83
Sample ID: S0021B FLOOR, VINYL FLOOR TILE AND MASTIC, 12"X12" BEIGE WITH PINK STREAKS, LOC:2040,204
Matrix: Solid
Collected: 2025/11/21
Shipped: 2025/11/21
Received: 2025/11/24

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	A063774	N/A	2025/11/28	Rayana De Oliveira Cardoso

Bureau Veritas ID: AXRX84
Sample ID: S0021C FLOOR, VINYL FLOOR TILE AND MASTIC, 12"X12" BEIGE WITH PINK STREAKS, LOC:2040,204
Matrix: Solid
Collected: 2025/11/21
Shipped: 2025/11/21
Received: 2025/11/24

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	A063774	N/A	2025/11/28	Rayana De Oliveira Cardoso

Bureau Veritas ID: AXRX85
Sample ID: S0023A FIRESTOPPING (MASTIC), YELLOW, LOC:2040,204
Matrix: Solid
Collected: 2025/11/21
Shipped: 2025/11/21
Received: 2025/11/24

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	A063774	N/A	2025/11/28	Rayana De Oliveira Cardoso

Bureau Veritas ID: AXRX86
Sample ID: S0023B FIRESTOPPING (MASTIC), YELLOW, LOC: 2040,204
Matrix: Solid
Collected: 2025/11/21
Shipped: 2025/11/21
Received: 2025/11/24

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	A063774	N/A	2025/11/28	Rayana De Oliveira Cardoso

Bureau Veritas ID: AXRX87
Sample ID: S0023C FIRESTOPPING (MASTIC), YELLOW, LOC:2040,204
Matrix: Solid
Collected: 2025/11/21
Shipped: 2025/11/21
Received: 2025/11/24

Test Description	Instrumentation	Batch	Extracted	Date Analyzed	Analyst
Asbestos by PLM - 0.5 RDL	MIC	A063774	N/A	2025/11/28	Rayana De Oliveira Cardoso



**BUREAU
VERITAS**

Bureau Veritas Job #: C5E9289
Report Date: 2025/11/28

Pinchin Ltd
Client Project #: 200584.110
Sampler Initials: NC

GENERAL COMMENTS

Results relate only to the items tested.



BUREAU
VERITAS

Bureau Veritas Job #: C5E9289

Report Date: 2025/11/28

Pinchin Ltd

Client Project #: 200584.110

Sampler Initials: NC

VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

Dina Yousif, Analyst 2

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

APPENDIX II-B
Lead Analytical Certificates

Certificate of Analysis

Pinchin Ltd. (Kingston)

1456 Centennial Drive, Suite 2

Kingston, ON K7P 0K4

Attn: Nicolas Page

Client PO: 200584.110

Project: 200584.110

Custody:

Report Date: 26-Nov-2025

Order Date: 24-Nov-2025

Order #: 2548067

This Certificate of Analysis contains analytical data applicable to the following samples as submitted:

Paracel ID	Client ID
2548067-01	L0009 - Off-white on Drywall, Loc. 2040
2548067-02	L0010 - Red and white on metal door and frame, Loc.2040

Approved By:

A. Tirca

Adriana Tirca, B.Eng (Chem)
Supervisor

Any use of these results implies your agreement that our total liability in connection with this work, however arising shall be limited to the amount paid by you for this work, and that our employees or agents shall not under circumstances be liable to you in connection with this work

Certificate of Analysis

Client: Pinchin Ltd. (Kingston)

Client PO: 200584.110

Report Date: 26-Nov-2025

Order Date: 24-Nov-2025

Project Description: 200584.110

Analysis Summary Table

Analysis	Method Reference/Description	Extraction Date	Analysis Date
Metals, ICP-MS	EPA 6020 - Digestion - ICP-MS	25-Nov-25	26-Nov-25

Qualifier Notes:*Sample Qualifiers :*

- 1 : Complete separation of paint from substrate not possible for this sample and a small amount of substrate has been included in the paint digestion.

Sample Data Revisions

None

Work Order Revisions/Comments:

None

Other Report Notes:

n/a: not applicable

ND: Not Detected

MDL: Method Detection Limit

Source Result: Data used as source for matrix and duplicate samples

%REC: Percent recovery.

RPD: Relative percent difference.

Certificate of Analysis

Report Date: 26-Nov-2025

Client: Pinchin Ltd. (Kingston)

Order Date: 24-Nov-2025

Client PO: 200584.110

Project Description: 200584.110

Sample Results

Lead					Matrix: Paint
Parcel ID	Client ID	Sample Date	Units	MDL	Result
2548067-01	L0009 - Off-white on Drywall, Loc. 2040	20-Nov-25	% by Wt.	0.0005	0.0034 [1]
2548067-02	L0010 - Red and white on metal door and frame, Loc.20	20-Nov-25	% by Wt.	0.0005	1.26

Laboratory Internal QA/QC

Analyte	Result	Reporting Limit	Units	Source Result	%REC	%REC Limit	RPD	RPD Limit	Notes
Matrix Blank									
Lead	ND	0.0005	% by Wt.						
Matrix Duplicate									
Lead	0.00127	0.0005	% by Wt.	0.00091			33.50	50	
Matrix Spike									
Lead	42.4	5.00	% by Wt.	0.4	84.0	70-130			



Parcel ID: 2548067



Parcel Order Number
(Lab Use Only)

Chain Of Custody
(Lab Use Only)

Client Name: Pinchin Ltd.	Project Ref: 200584.110	Page 1 of 1
Contact Name: Nic Page	Quote #: 200584.110	Turnaround Time
Address: 1456 Centennial Drive, Suite 2, Kingston	PO #: 200584.110	<input type="checkbox"/> 1 day <input type="checkbox"/> 3 day
Telephone: 613.541.1013	Email: npage@pinchin.com	<input type="checkbox"/> 2 day <input checked="" type="checkbox"/> Regular
	skoblenick@pinchin.com	Date Required: Nov 26, 2025

<input type="checkbox"/> REG 103/04 <input type="checkbox"/> REG 406/23	Other Regulation	Matrix Type: S (Soil/Sed), GW (Ground Water) SW (Surface Water) SS (Storm/Sanitary Sewer) P (Paint) A (Air) Q (Other)	Required Analysis
<input type="checkbox"/> Table 1 <input type="checkbox"/> Res/Park <input type="checkbox"/> Med/Pine <input type="checkbox"/> REG 55A <input type="checkbox"/> PWQO	<input type="checkbox"/> COM1 <input type="checkbox"/> MSA		
<input type="checkbox"/> Table 2 <input type="checkbox"/> Ind/Comm <input type="checkbox"/> Gravel <input type="checkbox"/> SW - Sand <input type="checkbox"/> SW - Storm	Mun: _____		
<input type="checkbox"/> Table 3 <input type="checkbox"/> Agri/Other	<input type="checkbox"/> Other: _____		
<input type="checkbox"/> Table _____			
For RSC: <input type="checkbox"/> Yes <input type="checkbox"/> No			
Sample ID/Location Name	Matrix	Vol/Volume	# of Containers
1 L0009 - Off-white on Drywall, Loc. 2040	P	1	Nov 20, 2025 PM
2 L0010 - Red and white on metal door and frame, Loc. 2040	P	1	Nov 20, 2025 PM
3			
4			
5			
6			
7			
8			
9			
10			

Comments: cc: skoblenick@pinchin.com with results
Please report results in percent

Relinquished By (Sign):	Received By (Driver/Depot):	Received at Lab:	Method of Delivery:
Relinquished By (Print): Nic Page	Date/Time:	Date/Time: Nov 21 17:00	Verified by: [Signature]
Date/Time: Nov 21, 2025	Temperature: °C	Temperature:	Date/Time: Nov 24/2025 3:00pm
Chain of Custody (Blank Label)			Signature: [Signature]

Revision 4.0

APPENDIX III

Methodology



1.0 GENERAL

An investigation was conducted to identify the type of Hazardous Building Materials incorporated in the structure and its finishes.

Information regarding the location and condition of hazardous building materials encountered and visually estimated quantities were recorded. The locations of any samples collected were recorded on small-scale plans. As-built drawings and previous reports were referenced where provided.

Sample collection was conducted in accordance with our Standard Operating Procedures.

1.1 Asbestos

The investigation for asbestos included friable and non-friable asbestos-containing materials (ACM). A friable material is a material that when dry can be crumbled, pulverized or powdered by hand pressure, or a material that has already become crushed, pulverized, or powdered.

A separate set of samples was collected of each type of homogenous material suspected to contain asbestos. A homogenous material is defined by the US EPA as material that is uniform in texture and appearance, was installed at one time, and is unlikely to consist of more than one type or formulation of material. The homogeneous materials were determined by visual examination and available information on the phases of construction and prior renovations.

Samples were collected at a rate that is in compliance with the requirements of local regulations and guidelines. The sampling strategy was also based on known ban dates and phase out dates of the use of asbestos; sampling of certain building materials is not conducted after specific construction dates. In addition, to be conservative, several years past these dates are added to account for some uncertainty in the exact start / finish date of construction and associated usage of ACM. In some cases, manufactured products such as asbestos cement pipe were visually identified without sample confirmation.

The asbestos analysis of select materials was completed using a stop-positive approach. Only one result meeting the regulated criteria was required to determine that a material is asbestos-containing, but all samples must be analyzed to conclusively determine that a material is non-asbestos. The laboratory stopped analyzing samples from a homogeneous material once a result equal to or greater than the regulated criteria is detected in any of the samples of that material. All samples of a homogeneous material were analyzed if no asbestos is detected. In some cases, all samples were analyzed in the sample set regardless of result.

The analysis was performed in accordance with Test Method EPA/600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials, July 1993.

Analytical results were compared to the following criteria:

Jurisdiction	Friable	Non-Friable
Ontario	0.5%	0.5%

Where building materials are described in the report as “non-asbestos” or “does not contain asbestos”, this means that either no asbestos was detected by the analytical method utilized in any of the multiple samples or, if detected, it is below the lower limit of an asbestos-containing material in the applicable regulation. Additionally, these terms are used for materials which historically are known to not include asbestos in their manufacturing.

Asbestos materials were evaluated in order to make recommendations regarding any remedial work. The priority for remedial action was based on several factors:

- Friability (friable or non-friable)
- Condition (good, fair, poor, debris)
- Accessibility (ranking from accessible to all building users to inaccessible)
- Visibility (whether the material is obscured by other building components)
- Efficiency of the work (for example, if damaged ACM is being removed in an area, it may be most practical to remove all ACM in the area even if it is in good condition)

1.2 Lead

Samples of distinctive paint finishes, and surface coatings present in more than a limited application, where removal of the paint is possible were collected. The samples were collected by scraping the painted finish to include base and covering applications.

Analysis for lead in paints or surface coatings was performed in accordance with EPA Method No. 3050B/EPA SW-846-6020B0B, inductively coupled plasma – mass spectrometry.

Analytical results were compared to the following criteria.

Jurisdiction	Units (%)	Units (ppm) / (mg/kg)
Ontario	0.009	90

Other lead building products (e.g. batteries, lead sheeting, flashing) were identified by visual observation only.

1.3 Silica

Building materials known to contain crystalline silica (e.g. concrete, cement, tile, brick, masonry, mortar) were identified by visual inspection only. Pinchin did not perform sampling of these materials for laboratory analysis of crystalline silica content.

1.4 Mercury

Building materials, products or equipment (e.g. thermostats, barometers, pressure gauges, lamp tubes), suspected to contain mercury were identified by visual inspection only. Dismantling of equipment suspected of containing mercury was not performed. Sampling of these materials for laboratory analysis of mercury content was not performed.

1.5 Polychlorinated Biphenyls

The potential for light ballast and oil filled transformers to contain PCBs was based on the age of the building, a review of maintenance records, and examination of labels or nameplates on equipment, where present and accessible. The information was compared to known ban dates of PCBs and Environment Canada publications.

Dry type transformers were presumed to be free of dielectric fluids and hence non-PCB.

Fluids (mineral oil, hydraulic, Aroclor or Askarel) in transformers or other equipment were not sampled for PCB content.

1.6 Visible Mould

The presence of mould or water damage was determined by visual inspection of exposed building surfaces. If any mould growth or water damage was concealed within building cavities it was not addressed in this assessment.

Template: Methodology for Hazardous Building Materials Assessment, HAZ, May 16, 2025

APPENDIX IV
Location Summary Report

Client:Hastings And Prince Edward District School Board

Site: 160 Palmer Road, Belleville, ON

Building Name: Centennial Secondary School

Survey Date:

Last Re-Assessment:

Building Phases: A: 1967

Location No.	Name or Description	Area ft ²	Floor No.	Bldg. Phase	Notes
2040	204, room no. 204	1200	2	A	

APPENDIX V
Hazardous Materials Summary Report / Sample Log

Client:Hastings And Prince Edward District School Board

Site: 160 Palmer Road, Belleville, ON

Building Name: Centennial Secondary School

Survey Date: 2025-11-20

HAZMAT	Sample No	System/Component/Material/Sample Description	Locations	Bldg. Phase	LF	SF	EA	%	Type	Positive	Friability
Asbestos	V0015	Wall Paint	2040	A	0	2000	0	0	None Detected	No	
Asbestos	V0016	Structure Column Paint	2040	A	0	200	0	0	None Detected	No	
Asbestos	S0021 ABC	Floor Vinyl Floor Tile And Mastic 12"x12" Beige With Pink Streaks	2040	A	0	145	0	0	None Detected	No	
Asbestos	S0023 ABC	Other Firestopping (mastic) Yellow	2040	A	0	4	0	0	None Detected	No	
Asbestos	V9000	Floor Vinyl Floor Tile Vt-10, 12x12, Grey, Vt-5, 12x12 Pale Green, Vt-9, 12x12 Off-white	2040	A	0	975	0	0	Confirmed Asbestos	Yes	NF
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2'x4' Lay-in, Fissures Across Length	2040	A	0	1000	0	0	Non Asbestos	No	
Asbestos	V0000	Ceiling Ceiling Tiles (lay-in) 2'x4' Lay-in, Fissures Across Width	2040	A	0	200	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Mastic	2040	A	0	1200	0	0	Non Asbestos	No	
Asbestos	V0000	Floor Vinyl Floor Tile And Mastic 12"x12" Light Brown With Dark Brown And White Smears, Installed Post 2017	2040	A	0	80	0	0	Non Asbestos	No	
Paint	V0002	Wall Concrete (precast) Various Colours	2040	A	0	2200	0	0	Lead (Low)	Yes	-
Paint	L0009	Ceiling Drywall (no Compound) Off-white On Bulkhead	2040	A	0	150	0	0		No	-
Paint	L0010	Wall Metal Red And White On Metal Door And Frame	2040	A	0	20	0	0	Lead (High)	Yes	-
PCB	V0000	Light Ballasts	2040	A	0	0	0	100	-	No	-
Hg	V9000	Light Fixture	2040	A	0	0	0	100	Hg	Yes	-

Legend:

Sample number		Units		
S####	Asbestos sample collected	SF	Square feet	NF Non Friable material.
L####	Paint sample collected	LF	Linear feet	F Friable material
P####	PCB sample collected	EA	Each	PF Potentially Friable material
M####	Mould sample collected	%	Percentage	
V####	Material visually similar to numbered sample collected			
V0000	Known non Hazardous Material			
V9000	Material is visually identified as Hazardous Material			
V9500	Material is presumed to be Hazardous Material			
[Loc. No.]	Abated Material			

APPENDIX VI
All Data Report

ALL DATA REPORT

Client: Hastings And Prince Edward District School Board
Location: #2040 : 204
Survey Date: 2025-11-20

Site: 160 Palmer Road, Belleville, ON
Floor: 2

Building Name: Centennial Secondary School
Room #: 204
Last Re-Assessment: 0000-00-00

Area (sqft): 1200

ASBESTOS																
System	Component	Material	Item	Covering	A*	V*	AP*	Good	Fair	Poor	Unit	Sample	Asbestos Type	Amount	Hazard	Friable
Ceiling ¹		Ceiling Tiles (lay-in), 2'x4' lay-in, fissures across length			C	Y		1000			SF	V0000	Non-Asbestos		None	
Ceiling ²		Ceiling Tiles (lay-in), 2'x4' lay-in, fissures across width			C	Y		200			SF	V0000	Non-Asbestos		None	
Ceiling	Bulkhead	Drywall (no compound)			C	Y		150			SF					
Duct	All	Not Insulated			C	N										
Floor		Vinyl Floor Tile and Mastic, 12"x12" light brown with dark brown and white smears, installed post 2017			A	Y		80			SF	V0000	Non-Asbestos		None	
Floor		Vinyl Floor Tile and Mastic, 12"x12" beige with pink streaks			A	Y		145			SF	S0021ABC	None Detected	N.D.	None	
Floor ³		Mastic		Vinyl Floor Tile	D	N		1200			SF	V0000	Non-Asbestos		None	
Floor ⁴		Vinyl Floor Tile, VT-5, 12x12 pale green			A	Y		225(7)			SF	V9000	Confirmed Asbestos		Confirmed Asbestos	NF
Floor ⁵		Vinyl Floor Tile, VT-9, 12x12 off-white			A	Y		525(7)			SF	V9000	Confirmed Asbestos		Confirmed Asbestos	NF
Floor ⁶		Vinyl Floor Tile, VT-10, 12x12, grey			A	Y		225(7)			SF	V9000	Confirmed Asbestos		Confirmed Asbestos	NF
Mechanical Equipment	Radiator	Not Insulated														
Other	Conduit	Firestopping (mastic), Yellow			C	N		4			SF	S0023ABC	None Detected	N.D.	None	
Piping		Not Insulated														
Structure	Column	Concrete (poured)		Paint	A	Y		200			SF					
Structure	Column	Paint			A	Y		200			SF	V0016	None Detected	N.D.	None	
Structure	Deck	Steel			C	N										
Structure	Deck	Concrete (poured)			C	N		1200			SF					
Wall		Paint			A	Y		2000			SF	V0015	None Detected	N.D.	None	
Wall	All	Concrete (precast)		Paint	A	Y										
Wall	Door Frame	Metal		Paint	A	Y		20			LF					

- 1 - Previous samples ASB-103.1-3
- 2 - Previous samples ASB-104.1-3
- 3 - Previous samples ASB-125.1-3, A0012A-C and A0013A-C
- 4 - Previous samples ASB-125.1-3
- 5 - Historic data
- 6 - Historic Data

Client: Hastings And Prince Edward District School Board
Location: #2040 : 204
Survey Date: 2025-11-20

Site: 160 Palmer Road, Belleville, ON
Floor: 2

Building Name: Centennial Secondary School
Room #: 204
Last Re-Assessment: 0000-00-00

Area (sqft): 1200

PAINT

System	Item	Good	Poor	Unit	Sample	Sample Description	Amount	Hazard
Wall	Concrete (precast)	2000		SF	V0002	Various colours	Pb: 0.0095 %	Lead (Low)
Structure	Concrete (poured)	200		SF	V0002	Various colours	Pb: 0.0095 %	Lead (Low)
Ceiling	Drywall (no compound)	150		SF	L0009	Off-White on bulkhead	Pb: 0.0034 %	No
Wall	Metal	20		SF	L0010	Red and white on metal door and frame	Pb: 1.26 %	Lead (High)

Client: Hastings And Prince Edward District School Board

Site: 160 Palmer Road, Belleville, ON

Building Name: Centennial Secondary School

Location: #2040 : 204

Floor: 2

Room #: 204

Area (sqft): 1200

Survey Date: 2025-11-20

Last Re-Assessment: 0000-00-00

MERCURY				
Component	Quantity	Unit	Sample	Hazard
Light Fixture ¹	100	%	V9000	Yes

1 - T8

Client: Hastings And Prince Edward District School Board

Site: 160 Palmer Road, Belleville, ON

Building Name: Centennial Secondary School

Location: #2040 : 204

Floor: 2

Room #: 204

Area (sqft): 1200

Survey Date: 2025-11-20

Last Re-Assessment: 0000-00-00

PCB							
Component	Good	Poor	Unit	Sample	Sample Description	Amount	PCB
Light Ballasts	100		%	V0000	T8		No

Legend:



Sample number		Units		Other	
S####	Asbestos sample collected	SF	Square feet	A	Access
L####	Paint sample collected	LF	Linear feet	V	Visible
P####	PCB sample collected	EA	Each	AP	Air Plenum
M####	Mould sample collected	%	Percentage	F	Friable material
V####	Material is visually identified to be identical to S####	LF	Linear feet	NF	Non Friable material
V0000	Known non hazardous material			PF	Potentially Friable material
V9000	Material visually identified as a Hazardous Material			Pb	Lead
V9500	Material is presumed to be a hazardous material			Hg	Mercury
				As	Arsenic
				Cr	Chromium

Access	
A	Accessible to all building occupants
B	Accessible to maintenance and operations staff without a ladder
C	Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas
D	Not normally accessible

Condition	
Good	No visible damage or deterioration
Fair	Minor, repairable damage, cracking, delamination or deterioration
Poor	Irreparable damage or deterioration with exposed and missing material


Visible	
Y	The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels).
N	The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points.
L	The material is partially visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceiling system or access panels) to view completely and access. Includes partially viewed access points to crawlspaces, attic spaces, etc. without entering. Observations are limited to the extent visible from the access points.

Air Plenum	
Yes or No	The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation.

Colour Coding	
	The material is a hazardous material, either by analytical results or by visible identification.
	The material is presumed to be a hazardous material, based on visual appearance, and was not sampled due to limited access or the non-destructive nature of sampling.

Action					
(1)	Clean up of ACM Debris	(2)	Precautions for Access Which may Disturb ACM Debris	(3)	ACM removal
(4)	Precautions for Work Which may Disturb ACM in Poor Condition	(5)	Proactive ACM removal (Minimum repair required for fair condition)	(6)	ACM repair
(7)	Management program and surveillance				


APPENDIX VII
Photographs



V0015 (None), Wall, Paint, on Concrete Block, 204 (Location #: 2040)



V0016 (None), Structure, Column, Paint, on Concrete column, 204 (Location #: 2040)




S0021A (None), Floor, Vinyl Floor Tile and Mastic, 12"x12" beige with pink streaks, 204 (Location #: 2040)



S0023A (None), Other, Firestopping (mastic), Yellow, 204 (Location #: 2040)



V9000 (**Confirmed Asbestos**), , Vinyl Floor Tile, VT-5, 12x12 pale green, Floor 204 (Location #: 2040)
Previous samples ASB-125.1-3



V9000 (**Confirmed Asbestos**), Floor, Vinyl Floor Tile, VT-9, 12x12 off-white, 204 (Location #: 2040)
Historic data



V9000 (Confirmed Asbestos), Floor, Vinyl Floor Tile, VT-10, 12x12 grey, 204 (Location #: 2040)
Historic Data




V0000 (None), Floor, Mastic, Under vinyl floor tiles, 204 (Location #: 2040)
Previous samples ASB-125.1-3, A0012A-C and A0013A-C




V0000 (None), Ceiling, Ceiling Tiles (lay-in), 2'x4' lay-in, fissures across length, 204 (Location #: 2040)
Previous samples ASB-103.1-3



V0000 (None), Ceiling, Ceiling Tiles (lay-in), 2'x4' lay-in, fissures across width, 204 (Location #: 2040)
Previous samples ASB-104.1-3



V0000 (None), Floor, Vinyl Floor Tile and Mastic, 12"x12" light brown with dark brown and white smears, installed post 2017, 204 (Location #: 2040)



V0002(Lead, Low), Wall, Concrete (Precast), Various colours, 204 (Location #: 2040)



L0009(Lead, None), Ceiling, Drywall (no compound), Off-white, 204 (Location #: 2040)



L0010(Lead, High), Wall, Metal, Red/white on door and frame, 204 (Location #: 2040)



Building Photo