



FACILITIES MAINTENANCE - WORKS DEPARTMENT

2019 ASBESTOS-CONTAINING MATERIAL CONDITION REVIEW FORM

Facility Name: Whitby Child Care Center
Facility Address: 501 Dunlop Street, Whitby, Ontario

Region Inspector: Nathan Forrester
Date Inspected: 20-Feb-19

Building/Floor	Location of the Asbestos-Containing Materials	Material Description	Type of Asbestos	Pervious Condition	Current Condition
Exterior	Roof	Roof Materials	Assumed	Good	Good
Exterior	Walls	Caulking	Assumed	Good	Good
First Floor	Walls and Ceilings: Foyer, main play room, supervisor's office, quite room, washroom, mechanical room, closet, kitchen, yellow room, green room, blue room, and hallway	Drywall Joint Compound	Chrysotile	Good	Good

Nathan Forrester
Work Technician