

DESIGNATED SUBSTANCES SPREADSHEET OF FINDINGS  
FOR PAINTING OPERATIONS  
20 Perry Street, Uxbridge, Ontario



ASBESTOS-CONTAINING MATERIALS

Area	Level	Location	Material & Description	Est. Qty*	Units	Condition	Friable Yes/No	Accessibility	Sample #	% Asbestos and Type	Photographs	Recommended Procedures For Painting Operations
Storage Room (within Main Floor Common Room). Also observed in the Second Floor Laundry/Air Handling Room.	All	Floor	300 mm x 300 mm cream vinyl floor tile with black streaks	28	Square meters	Good	No	High	S01 A - C	0.75% Chrysotile		Do not disturb the material. If disturbance is required or the material is damaged, remove following Type 1 Asbestos Procedures.
Throughout	All	Ceiling	Texture finish	2,800	Square meters	Good (overall - refer to report for details)	Yes	High	S02 A - C	0.5% Chrysotile		Do not disturb the material. If disturbance is required or the material is damaged (i.e. less than 1 square metre only), repair following Type 2 Asbestos Procedures. If greater than 1 square metre of damage is present, removal and repair will require Type 3 Asbestos Procedures. Painting asbestos-containing texture coat in good condition requires Type 2 asbestos procedures.
Throughout	All	Walls & Ceilings	Drywall Joint Compound	5,100	Square meters	Good (overall - refer to report for details)	No	High	S04 A - C	1.4% Chrysotile		Remove or repair damaged asbestos-containing joint compound following Type 2 Asbestos Procedures. Painting produces no disturbance to the asbestos-containing joint compound present in good condition. Asbestos Awareness Procedures are recommended.
East Stairwell - may also be present as a secondary layer of flooring in additional areas as well (i.e. West and Central Stairwells, etc.).	Main Floor	Floor	Beige vinyl floor tile (Secondary layer, concealed beneath non-asbestos (S03) vinyl floor tiles)	Unknown	N/A	Presumed to be Good (in-accessible)	No	Low	S05 A - C	0.5% Chrysotile		Do not disturb the material. If disturbance is required or the material is damaged, remove following Type 1 Asbestos Procedures.
Throughout	All	Floor	300 mm x 300 mm off-white vinyl floor tiles with black spots	2,500	Square meters	Good (overall, refer to report for details)	No	High	S08 A - B	Presumed asbestos containing since identified to be 1.4% chrysotile in Previous Limited DSS. Samples 08 A and B found None Detected, refer to report for details.		Do not disturb the material. If disturbance is required or the material is damaged, remove following Type 1 Asbestos Procedures.

DESIGNATED SUBSTANCES SPREADSHEET OF FINDINGS  
FOR PAINTING OPERATIONS  
20 Perry Street, Uxbridge, Ontario



LEAD-CONTAINING MATERIALS										
Area	Level	Location / Substrate	Colour & Description	Estimated Quantity	Condition	Accessibility	Sample #	% Lead	Photographs	Recommended Procedures For Painting Operations
All	Throughout	Walls and Ceilings	Paint	N/A	Good	High	LP-1 to LP-7	All paint samples collected were found to contain low levels of lead ranging from 0.0078% to 0.053%		Light sanding of surfaces containing low levels of lead is classified as a Type 1 Lead Operation, provided the airborne concentration of lead is maintained below <math>0.05 \text{ mg/m}^3</math> of air. Applying paint causes no disturbance to the lead-containing paint that is present in good condition. Lead Awareness Procedures are recommended.
Stairwells/ Exit Corridors	Throughout	Battery in Exit Lights		N/A	Good	Moderate		N/A		Disturbance of this lead-containing product is not anticipated during painting operations. However, if this material is to be disturbed or is present in damaged condition, follow the appropriate procedures outlined in the Lead Guideline.
OTHER DESIGNATED SUBSTANCES										
Substance	Level	Location	Estimated Quantity	Condition	Accessibility	Sample #	Photographs	Recommended Procedures For Painting Operations		
Mercury - vapour	All	Fluorescent light fixtures	N/A	Good	Moderate	Not sampled - presumed	Photograph Unavailable	Disturbance of this mercury-containing product is not anticipated during painting operations.		
Mercury - liquid	First Floor	Elevator Room / Garbage Room	1	Good	Moderate	Not sampled - presumed		Disturbance of this mercury-containing product is not anticipated during painting operations.		

DESIGNATED SUBSTANCES SPREADSHEET OF FINDINGS  
 FOR PAINTING OPERATIONS  
 20 Perry Street, Uxbridge, Ontario



Silica	ALL	Bricks and mortar	N/A	Good	High	Not Sampled - presumed		<p>Disturbance of this silica-containing product is not anticipated during painting operations. However, if this material is to be disturbed or is present in damaged condition, follow the appropriate procedures outlined in the Silica Guideline.</p>
--------	-----	-------------------	-----	------	------	------------------------	---	--

This table is to be used for the purposes of painting operations only and is not intended for any other purpose.

For detailed information on the designated substances present at this Site, refer to the full report.

Inputted by: AHD  
 Checked by: Original to be signed