



November 17, 2025

Hastings and Prince Edward District School Board
224 Palmer Road
Belleville, ON K8P 4E1

Re: Asbestos Reassessment

Eastside Secondary School, 275 Farley Avenue, Belleville, ON
Pinchin File: 200584.099

Hastings and Prince Edward District School Board (Client) retained Pinchin Ltd. (Pinchin) to conduct an asbestos-containing materials (ACM) reassessment of Eastside Secondary School located at 275 Farley Avenue, Belleville, ON.

Pinchin performed the assessment on June 9, 2025. The assessor was unaccompanied during the assessment. The assessed area was unoccupied at the time of the assessment.

The objective of the reassessment was to evaluate the condition and quantity of previously reported ACM and develop corrective action plans as required. This assessment is only to be used for the purposes of long-term management and routine maintenance. The results of this assessment are not to be used for construction, renovation, demolition, or project tendering purposes.

The **assessed area** consisted of all accessible portions of the building where ACM were previously identified.

The scope included the following:

- Assessment of any rooms/areas that were inaccessible during the previous assessment (where access could be obtained).
- Documentation of any asbestos abatement that was performed since the last reassessment.

Building materials outside the defined **assessed area** are not discussed in this report.



1.0 RECOMMENDATIONS

1.1 Remedial Work

The following remedial work is recommended due to the condition and location of the material. The work must be completed in compliance with procedures defined in applicable regulations:

| System | Material Description | Quantities per Condition | | Location Name, (Location No.) | Recommended Procedure |
|--------|----------------------------|--------------------------|--------|-------------------------------|---|
| | | Fair | Poor | | |
| Wall | Paint on Concrete Block | | 5 SF | Change Room (135) | Remove/repair in accordance with Type 1 asbestos abatement procedures |
| Wall | Paint on Concrete Block | | 300 SF | Storage Room (139) | Remove/repair in accordance with Type 1 asbestos abatement procedures |
| Piping | Parging Cement | | 2 EA | Gym (142) | Remove in accordance with Type 2 or Glove Bag asbestos abatement procedures |
| Piping | Sweatwrap | | 2 LF | Classroom (150) | Remove in accordance with Type 2 or Glove Bag asbestos abatement procedures |
| Piping | Sweatwrap | | 1 LF | Classroom (151) | Remove in accordance with Type 2 or Glove Bag asbestos abatement procedures |
| Piping | Parging Cement | 1 EA | 1 EA | Classroom (151) | Remove in accordance with Type 2 or Glove Bag asbestos abatement procedures |
| Piping | Parging Cement | | 1 EA | Autoshop (153) | Remove in accordance with Type 2 or Glove Bag asbestos abatement procedures |
| Wall | Paint on Concrete Block | | 5 SF | Classroom (187) | Remove/repair in accordance with Type 1 asbestos abatement procedures |
| Wall | Paint on Concrete Block | | 15 SF | Corridor (191) | Remove/repair in accordance with Type 1 asbestos abatement procedures |
| Wall | Drywall and Joint Compound | | 5 SF | Classroom (212) | Remove/repair in accordance with Type 1 asbestos abatement procedures |



1.2 On-going Management and Maintenance

The following recommendations are provided regarding on-going management and maintenance work involving the ACM identified:

- Inspect all confirmed and presumed ACM at reasonable intervals and update the written documentation annually.
- Update the asbestos inventory report for all new information obtained (i.e., new materials, change of condition, abatement performed).
- Remove ACM before alteration or maintenance work if ACM may be disturbed. Follow appropriate asbestos precautions for the classification of work as per applicable regulations and guidelines.

1.3 Construction and Demolition

This assessment report does not provide sufficient detail to support renovation and demolition work. Therefore, perform a detailed intrusive assessment before building renovation or demolition operations. The assessment should include; destructive testing (e.g., coring, removal of building finishes and components), sampling of other hazardous materials (e.g., lead, mercury, PCBs, mould, etc.), and any other materials not tested (e.g. roofing materials, caulking, mastics).

1.3.1 Texture Finish, Texture Coat and Plaster Coating

If texture finish, texture coat or plaster coating is to be disturbed use Type 3 procedures as outlined within Ontario Regulation 278/05 (for quantities greater than 1 square metre). If only minor amounts of texture finish are to be disturbed (less than 1 square metre), Type 2 procedures would be applicable.

1.3.2 Pipe Insulation

If pipe insulation is to be removed, remove minor amounts (less than 1 square metre (10.8 square feet)) of asbestos-containing pipe insulations using Type 2 procedures as outlined within Ontario Regulation 278/05. If larger amounts of pipe insulation (greater than 1 square metre) are to be removed, use Type 3 procedures as outlined within Ontario Regulation 278/05. Alternately use Glove Bag Procedures as outlined within Ontario Regulation 278/05.

If friable paring cement pipe insulation is to be removed, remove minor amounts (less than 1 square metre) of asbestos-containing pipe insulations using Type 2 procedures as outlined within Ontario Regulation 278/05. If larger amounts of pipe insulation (greater than 1 square metre) are to be removed, use Type 3 procedures as outlined within Ontario Regulation 278/05. Alternately use Glove Bag Procedures as outlined within Ontario Regulation 278/05.



If jacketing over friable asbestos paring cement insulation is to be repaired (e.g. canvas and lagging), use Type 2 procedures as outlined within Ontario Regulation 278/05.

1.3.3 Drywall Compound

If the drywall with drywall joint compound must be removed as a result of planned demolition, renovation, etc. use Type 1 procedures as outlined within Ontario Regulation 278/05 to remove less than 1 square metre of drywall with asbestos-containing drywall joint compound, or Type 2 procedures for larger quantities.

1.3.4 Asbestos-Cement (Transite)

If asbestos cement (Transite) materials must be removed as a result of planned demolition, renovation, etc. use Type 1 procedures as outlined within Ontario Regulation 278/05 if the work is done using wet methods and using hand-held non-powered tools.

1.3.5 Vinyl Floor Tiles

If vinyl floor tiles must be removed as a result of planned demolition, renovation, etc., use Type 1 procedures as outlined within Ontario Regulation 278/05 if the work is done using wet methods and using hand-held non-powered tools.

1.3.6 Floor Tile Mastic

Mastic is considered a non-friable material and removal of mastic requires the use of Type 1 asbestos procedures as outlined within Ontario Regulation 278/05 if the work is done using wet methods and using hand-held non-powered tools. If the mastic is to be removed using hand-held non-powered tools, Pinchin recommends that any adhering asbestos-containing mastic be removed to a thin film (considered a trivial amount or surface staining).

1.3.6.1 Caulking, Putty and Sealants

If caulking, putties and sealants must be removed as a result of planned demolition, renovation, etc., use Type 1 procedures as outlined within Ontario Regulation 278/05 if the work is done using wet methods and using hand-held non-powered tools.

1.3.6.2 Paper Heat Shields

If the paper heat shields must be removed as a result of planned demolition, renovation, etc., use Type 1 procedures as outlined within Ontario Regulation 278/05 if the work is done using wet methods and using hand-held non-powered tools.

1.3.7 Paint

If the paint on concrete block and brick walls must be removed as a result of planned renovations, use Type 1 procedures as outlined within Ontario Regulation 278/05 if the work is done using wet methods and using hand-held non-powered tools. If power tools equipped with an effective HEPA filtered dust



collection system is used, Type 2 procedures would be required. If power tools without a HEPA filtered dust collection system are used, Type 3 procedures would be required.

1.3.7.1 Thinset

If thinset must be removed as a result of planned demolition, renovation, etc., use Type 1 procedures as outlined within Ontario Regulation 278/05 if the work is done using hand-held non-powered tools. If power tools equipped with an effective HEPA filtered dust collection system is used, Type 2 procedures would be required. If power tools without a HEPA filtered dust collection system are used, Type 3 procedures would be required.

1.3.7.2 Insulation within Core of Fire Rated Door

If the fire rated door must be removed as a result of planned demolition, renovation, etc., use Type 1 procedures as outlined within Ontario Regulation 278/05 if the door is removed and disposed of fully intact. If the insulation is to be removed from the door, follow Type 3 procedures.

1.3.7.3 Vermiculite

Although vermiculite contains only minor amounts of asbestos when expressed as a percentage of total weight or volume, unlike other ACM, the asbestos is not contained within a binder. Upon removal of vermiculite, elevated levels of airborne asbestos may be generated. Therefore, if vermiculite is to be removed use Type 2 or 3 procedures in accordance with O.Reg. 278/05; dependent on the method and quantity of disturbance.

1.3.7.4 Textile Vibration Dampener

Vibration dampeners are considered a non-friable material and removal of vibration dampeners follows the use of Type 1 asbestos procedures in accordance with O.Reg. 278/05, if the work is done using wet methods and using hand-held non-powered tools.

2.0 FINDINGS

2.1 Assessed Area Description Summary

| Description Item | Details |
|-------------------------|--|
| Use | Institutional |
| Number of Floors | Two storeys with a partial basement |
| Total Area | 130,000 square feet |
| Year of Construction | 1959 with additions completed in 1961 and 1975 |
| Structure | Structural steel and concrete |
| Exterior Cladding | Brick and pre-cast concrete |



| Description Item | Details |
|------------------|--|
| HVAC | Rooftop AC, boiler with hot water heating to radiators and suspended unit heaters |
| Roof | Flat (not assessed) |
| Flooring | Vinyl floor tiles, vinyl sheet flooring, wood, ceramic tiles, carpet, terrazzo and poured concrete |
| Interior Walls | Drywall, plaster, concrete block and ceramic tiles |
| Ceilings | Drywall, plaster, texture finish and acoustic ceiling tiles |

2.2 Existing Reports

2.2.1 Review of Previous Reports

Pinchin prepared the following reports and included relevant results as appropriate:

- *“Asbestos Reassessment, Eastside Secondary School, 275 Farley Avenue, Belleville, Ontario”* dated November 25, 2022, Pinchin Project Number 200584.074.
- *“Hazardous Building Materials Assessment (Pre-construction), Eastside Secondary School, 275 Farley Avenue, Belleville, Ontario”* dated April 29, 2024, Pinchin Project Number 200584.087.
- *“Site Review Report 01, Eastside Secondary School, 275 Farley Avenue, Belleville, Ontario”* dated July 3, 2024, Pinchin Project Number 200584.090.
- *“Asbestos Test Results, Eastside Secondary School, 275 Farley Avenue, Belleville, Ontario”* dated July 19, 2025, Pinchin Project Number 200584.092.
- *“Asbestos Test Results, Eastside Secondary School, 275 Farley Avenue, Belleville, Ontario”* dated July 29, 2025, Pinchin Project Number 200584.092.
- *“Hazardous Building Materials Assessment (Preconstruction), Greenhouse and Windows/Doors in 1961 Addition, Eastside Secondary School, 275 Farley Avenue, Belleville, ON”* dated May 7, 2025, Pinchin Project Number 200584.098.

2.2.2 Summary of New Information since the Previous Assessment

Based on a review of the above-noted reports, and observations made during the reassessment, the following is new information:

- 5 square feet of drywall joint compound previously reported to be in poor condition on the bulkhead in Room 128 has been repaired.
- 300 square feet of paint on concrete block walls previously reported to be in poor condition in Room 139 has been repaired.



Asbestos Reassessment

Eastside Secondary School, 275 Farley Avenue, Belleville, ON
Hastings and Prince Edward District School Board

November 17, 2025
Pinchin File: 200584.099

- Parging cement insulation previously reported to be in poor condition has been repaired in Room 149.
- 15 square feet of paint on concrete block walls previously reported to be in poor condition in Room 182 has been repaired.
- 10 square feet of paint on concrete block walls previously reported to be in poor condition in Room 184 has been repaired.
- 5 square feet of drywall joint compound on the wall previously reported to be in poor condition in Room 215 has been repaired.
- Approximately 8,000 square feet of Siporex roof deck panels with asbestos-containing skim coat has been abated from the 1961 southeast addition of the school.
- The Greenhouse has been demolished and the asbestos-containing materials previously identified (grey/light green caulking, grey and black window liner sealant, black/grey brittle fibrous tar, Transite panels, and masonry mortar) have been abated.
- All exterior windows have been replaced in the school since the last reassessment and all asbestos-containing caulking and sealants identified on the exterior and interior of the windows have been abated. Asbestos-containing caulking and sealants remain present on exterior doors.

2.3 Summary of Building Materials

The following table summarizes the materials evaluated for asbestos in the assessed area. For details on locations, condition and approximate quantities of asbestos materials, refer to the Confirmed/Presumed ACM Report in Appendix V.

The Client room numbering systems have changed in some locations, only the current room numbers are referenced in this report. To determine which room numbers correspond with the former room numbers and Pinchin Location numbers, Refer to the HMIS Location Report in Appendix IV.

| Sample Number | Material Description | Type of Asbestos | Confirmed Hazard | Total Quantity Present | Material Specific Notes |
|------------------------------|----------------------|------------------|------------------|------------------------|-------------------------|
| S0001 ABC S0014 ABC | Piping Aircell | Chrysotile | Yes | 1,498 LF | |



Asbestos Reassessment

Eastside Secondary School, 275 Farley Avenue, Belleville, ON
 Hastings and Prince Edward District School Board

November 17, 2025
 Pinchin File: 200584.099

| Sample Number | Material Description | Type of Asbestos | Confirmed Hazard | Total Quantity Present | Material Specific Notes |
|--|---|------------------|------------------|------------------------|-------------------------|
| S0002 ABC S0035 ABC | Piping Sweatwrap | Chrysotile | Yes | 744 LF | |
| S0003 ABCDE | Floor Vinyl Floor Tile and Mastic 9" x 9" Various Colours | Chrysotile | Yes | 6,050 SF | Note 1 |
| S0005 ABCDE FG | Wall Drywall and Joint Compound | Chrysotile | Yes | 2,100 SF | Note 2 |
| S0006 ABC S0008 ABC S0025 ABC | Piping Parging Cement | Chrysotile | Yes | 289 EA 265 LF | |
| S0012 ABC | Ceiling Texture Coat | Chrysotile | Yes | 500 SF | Note 3 |
| S0015 ABC | Floor Vinyl Floor Tile 12" x 12" Beige with Brown Streaks | Chrysotile | Yes | 100 SF | |
| S0017 ABC | Structure Paper Covering Paper Heat Shield | Chrysotile | Yes | 1 EA | |
| S0024 ABC | Floor Vinyl Floor Tile 12" x 12" Beige with Sparse White and Brown Flecks | Chrysotile | Yes | 2,200 SF | |
| S0026 ABC | Floor Vinyl Floor Tile 12" x 12" Off-White with Black and Grey Streaks | Chrysotile | Yes | 900 SF | |
| S0027 ABC | Ceiling, Wall Drywall and Joint Compound | Chrysotile | Yes | 400 SF | Note 2 |
| S0030 ABC | Ceiling Bulkhead Texture Coat | Chrysotile | Yes | 300 SF | |
| S0031 ABC | Wall Exterior Door Frames Caulking Beige | Chrysotile | Yes | 20 EA | |



Asbestos Reassessment

Eastside Secondary School, 275 Farley Avenue, Belleville, ON
 Hastings and Prince Edward District School Board

November 17, 2025
 Pinchin File: 200584.099

| Sample Number | Material Description | Type of Asbestos | Confirmed Hazard | Total Quantity Present | Material Specific Notes |
|----------------------|--|------------------|------------------|------------------------|--|
| S0033 ABC | Wall Door Frames Caulking Brown and Grey | Chrysotile | Yes | 20 EA | |
| S0053 ABCDE FG | Ceiling, Wall Drywall and joint compound | Chrysotile | Yes | 5,655 SF | Note 2 |
| S0054 ADG | Ceiling, Wall Drywall and joint compound | Chrysotile | Yes | 6,400 SF | Note 2 |
| S0059 ABCDE | Wall Paint On poured concrete | Chrysotile | Yes | 1,100 SF | |
| S0060 ABCDE | Wall Paint On brick | Chrysotile | Yes | 1,650 SF | Note 4 In addition to sample S0042C |
| S0061 ABCDE FG | Wall Paint On concrete block | Chrysotile | Yes | 12,000 SF | Note 4 1961 addition – 2nd Floor |
| S0062 ABCDE F | Wall Paint On concrete block, | Chrysotile | Yes | 17,800 SF | Note 4 1961 addition - 1st Floor (in addition to sample S0042D) |
| S0063 ABCDE F | Wall Paint On concrete block | Chrysotile | Yes | 35,900 SF | Note 4 original building - 1st Floor (in addition to sample S0042A) |
| S0064 ABCDE F | Wall Paint On concrete block | Chrysotile | Yes | 15,700 SF | Note 4 original building - 2nd Floor (in addition to sample S0042B) |
| S0065 ABCDE | Wall Paint On concrete block | Chrysotile | Yes | 1,500 SF | Note 4 1975 addition - Stage Area |



Asbestos Reassessment

Eastside Secondary School, 275 Farley Avenue, Belleville, ON
Hastings and Prince Edward District School Board

November 17, 2025
Pinchin File: 200584.099

| Sample Number | Material Description | Type of Asbestos | Confirmed Hazard | Total Quantity Present | Material Specific Notes |
|----------------------|--|--------------------------------|------------------|------------------------|--|
| S0066 ABCDE FG | Wall Paint On Concrete Block | Chrysotile | Yes | 8,800 SF | Note 4 1975 addition - Area adjacent to Stage |
| S0067 ABCDE F | Wall Paint On Concrete Block | Chrysotile | Yes | 13,715 SF | Note 4 1975 addition - 1st Floor (in addition to sample S0042F) |
| S0068 ABCD | Wall Paint On Concrete Block | Chrysotile | Yes | 4,000 SF | Note 4 1975 addition - 2nd Floor (in addition to sample S0042E) |
| S0071 ABC | Column Plaster Coating material on plaster | Chrysotile | Yes | 200 SF | Auto Shop |
| S0087 ABC | Structure Texture Coat | Chrysotile | Yes | 30 SF | Exterior Canopy |
| S0090 ABC | Structure Cement Product Transite | Chrysotile | Yes | 90 SF | Exterior Canopy |
| S0092 ABC | Wall Insulation Vermiculite | Libby Amphibole Asbestos | Yes | 100% | Note 6 |
| V9500 | Duct Textile Vibration Dampers | Presumed Asbestos | Yes | 1 EA | Auto Shop |
| V9500 | Floor Mortar Behind ceramic tiles | Presumed Asbestos | Yes | 3,325 SF | |
| V9500 | Piping Cement Product Transite | Presumed Asbestos | Yes | 183 LF | Note 5 |
| V9500 | Ceiling, Wall, Other Cement Product Transite Panels Radiator Heat Shields, Ceiling Finishes, Countertops and Drying Racks | Presumed Asbestos | Yes | 1,668 SF | |



| Sample Number | Material Description | Type of Asbestos | Confirmed Hazard | Total Quantity Present | Material Specific Notes |
|---------------|---|-------------------|------------------|------------------------|-------------------------|
| V9500 | Wall Mortar Behind ceramic tiles | Presumed Asbestos | Yes | 4,000 SF | |
| V9500 | Wall Thermal Insulation within Fire Rated Doors | Presumed Asbestos | Yes | 1 EA | |
| V9500 | Roof Caulking | Presumed Asbestos | Yes | 100 % | |
| V9500 | Other Roofing Material | Presumed Asbestos | Yes | 100 % | |

Any quantities listed in this report or data tables are estimated based on visual approximations only and are subject to variation.

Site Specific Notes:

- Where 9"x9" vinyl floor tiles have been abated, replacement tiles must be treated as asbestos-containing for removal/disposal purposes due to contamination from asbestos-containing mastic.
- Drywall joint compound, containing chrysotile asbestos, is present on wall and ceiling finishes throughout the 1975 addition and a portion of the original building (samples 0005D-G,0027A-C, S0053A-G and S0054A,D,G).

Drywall joint compound present on wall and ceiling finishes throughout the remainder of the building does not contain asbestos (samples S0055A-E and S0058A-G).
- Due to the nature of construction, it was not possible to delineate all occurrences of texture finish and any associated overspray without extensive intrusive demolition. As such, asbestos-containing texture finish and associated overspray may be present within concealed areas, including, but not limited to cavities, walls, behind finishes, structural components, ducts, pipes, electrical equipment, etc.
- Various colours of paint, containing chrysotile asbestos, is present on concrete block and brick walls throughout the building (samples S0042A-G, S0060D, V0061, S0062A-F, S0063 ABD). The asbestos-positive results indicate that at a minimum, a portion of paint on concrete block and brick walls contains asbestos and all paint on concrete block and brick walls is presumed to contain asbestos. Further sampling may be considered in an attempt to delineate asbestos-containing paint from non-asbestos paint.
- Additional Transite pipe is presumed to be concealed above solid ceilings and in vertical chases, walls and columns.



6. Vermiculite insulation, containing Libby Amphibole asbestos, was identified behind the window lintel in Classroom 111 (HMIS samples S0092A-C; Original samples were S0072 A-C; Lab Report b318710). It is presumed that asbestos-containing vermiculite is present behind the window lintels of other windows throughout the original 1959 building, Asbestos-containing vermiculite may be present in other concealed areas of the building, including, but not limited to cavities, walls, behind finishes, structural components etc.

General Notes:

Pipes insulated with asbestos-containing insulations may be present in inaccessible spaces such as above solid ceilings, in chases, in column enclosures and within shafts.

Materials identified as Sample Number V9500 were either observed to be present or based on the construction of the building/equipment are likely present in concealed locations. These materials have not been sampled and are presumed to contain asbestos based on historical known use of asbestos. Sampling of these materials may be completed prior to disturbance.

2.3.1 Excluded Asbestos Materials

The following is a list of materials which may contain asbestos and was excluded from the assessment. These materials are presumed to contain asbestos until otherwise proven to be non-asbestos by sampling and analysis:

- Roofing felts and tar, mastics.
- Electrical components.
- Mechanical packing, ropes and gaskets.
- Caulking/sealants on roof.
- Vibration dampers on HVAC equipment.
- Ropes and gaskets in cast-iron bell and spigot joints.
- Insulation within the core of fire-rated doors.
- Sealants on pipe threads.
- Inaccessible/concealed materials.

3.0 METHODOLOGY

Pinchin conducted an assessment to evaluate the current condition of all accessible ACM identified in the most recent assessment. The assessor made reference to any existing assessment or abatement reports (as provided by the Client).



As per the original scope of work, concealed locations such as ceiling spaces above solid ceilings, shafts and chases were accessed via existing access panels. Our investigation did not include demolition of drywall or plaster walls to view concealed conditions. Structural items or exterior building finishes were not removed to determine the presence of concealed materials.

Sampling, assessment, or verification of materials listed as exclusions in previous reports was not conducted unless otherwise indicated.

For further details on the methodology including test methods, refer to Appendix III.

4.0 REFERENCES

The following legislation and documents were referenced in completing the assessment and this report:

1. Asbestos on Construction Projects and in Buildings and Repair Operations, Ontario Regulation 278/05.
2. Designated Substances, Ontario Regulation 490/09.
3. Ministry of the Environment Regulation, R.R.O. 1990 Reg. 347 as amended.

5.0 TERMS AND LIMITATIONS

This work was performed subject to the Terms and Limitations presented or referenced in the proposal for this project.

Information provided by Pinchin is intended for Client use only. Pinchin will not provide results or information to any party unless disclosure by Pinchin is required by law. Any use by a third party of reports or documents authored by Pinchin or any reliance by a third party on or decisions made by a third party based on the findings described in said documents, is the sole responsibility of such third parties. Pinchin accepts no responsibility for damages suffered by any third party as a result of decisions made or actions conducted. No other warranties are implied or expressed.



6.0 CLOSURE

The data presented in the appendices is prepared by Pinchin's Hazardous Materials Inventory System (HMIS). The information can be made available for your real-time access through our secure web-based platform. Please contact your Pinchin representative to discuss HMIS solutions for management of your asbestos (and other hazardous materials) inventory.

Should you have any questions or concerns regarding the contents of this letter, please contact the Project Manager, Halie MacKillican at 613.541.1013 or hmackillican@pinchin.com.

Sincerely,

Pinchin Ltd.

Prepared by:

Reviewed by:


Nic Page, M.A.Sc
Project Technologist

Halie MacKillican
Team Leader, Hazardous Materials

- | | | |
|-------|--------------|----------------------------------|
| Encl: | APPENDIX I | Drawings |
| | APPENDIX II | Asbestos Analytical Certificates |
| | APPENDIX III | Methodology |
| | APPENDIX IV | Location Summary Report |
| | APPENDIX V | Confirmed / Presumed ACM Report |
| | APPENDIX VI | Photographs |

\\pinchin.com\kgn\Job\200000s\0200584.000 HPEDSB, various, BellevilleON, HAZ, DSS\0200584.099 HPEDSB, VariousLocations, HAZ, REASMT\Deliverables\ESS School Group\Eastside SS\200584.099 AsbestosReassessment EastsideSS HPEDSB.docx
Template: Master Template Asbestos Reassessment, HMIS, HAZ, March 13, 2024

APPENDIX I
Drawings



- LEGEND**
- (X) PINCHIN LOCATION NUMBER
 - XXX ROOM NUMBER
 - ⊗ INTRUSIVE INSPECTION
 - ASBESTOS-CONTAINING MATERIALS:
 - PIPE INSULATION
 - NUMBER OF FITTINGS WITH PARGING CEMENT
 - VINYL FLOOR TILES & MASTIC
 - MASTIC UNDER VINYL FLOOR TILE
 - VINYL FLOOR TILES
 - TEXTURE FINISH
 - HEAT SHIELD
 - TRANSITE PANELS (PRESUMED)
 - TRANSITE PIPE (PRESUMED)
 - AREA OF DRYWALL JOINT COMPOUND
 - FIRE-RATED DOOR (PRESUMED)
 - TEXTILE VIBRATION DAMPENER (PRESUMED)

- FOR CLARITY THE FOLLOWING ASBESTOS CONTAINING MATERIALS ARE PRESENT IN THE ASSESSED AREA BUT HAVE NOT BEEN HATCHED ON THE DRAWING:
- PAINT ON CONCRETE BLOCK AND BRICK WALLS.
 - VARIOUS COLOURS OF CAULKING ON EXTERIOR DOOR FRAMES.
 - VERMICULITE INSULATION WITHIN PERIMETRE WALLS BEHIND THE STEEL BEAM ABOVE WINDOWS.
 - THINSET BEHIND CERAMIC TILES (PRESUMED).
 - COATING ON PLASTER COLUMNS IN THE AUTO SHOP.
 - ROOFING MATERIALS AND CAULKING/SEALANTS ON THE ROOF (PRESUMED).



| | |
|--|--------------------------|
| PROJECT NAME: ASBESTOS REASSESSMENT | |
| CLIENT NAME: HASTINGS AND PRINCE EDWARD DISTRICT SCHOOL BOARD | |
| PROJECT LOCATION: EASTSIDE SECONDARY SCHOOL 275 FARLEY AVENUE BELLEVILLE, ONTARIO | |
| FIGURE NAME: GROUND FLOOR | |
| PROJECT NUMBER: 200584.099 | SCALE: NOT TO SCALE |
| DRAWN BY: JW | REVIEWED BY: HM |
| DATE: SEPTEMBER 2025 | FIGURE NUMBER: 1 OF 3 |

NOT ALL KNOWN OR SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS ASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.



- LEGEND**
- (X) PINCHIN LOCATION NUMBER
 - XXX ROOM NUMBER
 - ⊗ INTRUSIVE INSPECTION
 - ASBESTOS-CONTAINING MATERIALS:
 - PIPE INSULATION
 - NUMBER OF FITTINGS WITH PARGING CEMENT
 - VINYL FLOOR TILES & MASTIC
 - MASTIC UNDER VINYL FLOOR TILE
 - VINYL FLOOR TILES
 - TEXTURE FINISH
 - HEAT SHIELD
 - TRANSITE PANELS (PRESUMED)
 - TRANSITE PIPE (PRESUMED)
 - AREA OF DRYWALL JOINT COMPOUND
 - FIRE-RATED DOOR (PRESUMED)
 - TEXTILE VIBRATION DAMPENER (PRESUMED)

FOR CLARITY THE FOLLOWING ASBESTOS CONTAINING MATERIALS ARE PRESENT IN THE ASSESSED AREA BUT HAVE NOT BEEN HATCHED ON THE DRAWING:

- PAINT ON CONCRETE BLOCK AND BRICK WALLS.
- VARIOUS COLOURS OF CAULKING ON EXTERIOR DOOR FRAMES.
- VERMICULITE INSULATION WITHIN PERIMETRE WALLS BEHIND THE STEEL BEAM ABOVE WINDOWS.
- THINSET BEHIND CERAMIC TILES (PRESUMED).
- COATING ON PLASTER COLUMNS IN THE AUTO SHOP.
- ROOFING MATERIALS AND CAULKING/SEALANTS ON THE ROOF (PRESUMED).



PROJECT NAME:
ASBESTOS REASSESSMENT

CLIENT NAME:
HASTINGS AND PRINCE EDWARD DISTRICT SCHOOL BOARD

PROJECT LOCATION:
EASTSIDE SECONDARY SCHOOL
275 FARLEY AVENUE
BELLEVILLE, ONTARIO

FIGURE NAME:
SECOND FLOOR

PROJECT NUMBER:
200584.099

SCALE:
NOT TO SCALE

DRAWN BY:
JW

REVIEWED BY:
HM


DATE:
SEPTEMBER 2025

FIGURE NUMBER:
2 OF 3

NOT ALL KNOWN OR SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS ASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.



NOT ALL KNOWN OR SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS MAY BE DEPICTED ON THE DRAWING. REFER TO THE ASBESTOS ASSESSMENT REPORT FOR A COMPLETE LIST OF KNOWN AND SUSPECTED ASBESTOS-CONTAINING BUILDING MATERIALS.

LEGEND IS COLOUR DEPENDENT. NON-COLOUR COPIES MAY ALTER INTERPRETATION.

BASE PLAN PROVIDED BY CLIENT.

LEGEND

- PINCHIN LOCATION NUMBER
- XXX ROOM NUMBER
- INTRUSIVE INSPECTION
- ASBESTOS-CONTAINING MATERIALS:
- PIPE INSULATION
- NUMBER OF FITTINGS WITH PARGING CEMENT
- VINYL FLOOR TILES & MASTIC
- MASTIC UNDER VINYL FLOOR TILE
- VINYL FLOOR TILES
- TEXTURE FINISH
- HEAT SHIELD
- TRANSITE PANELS (PRESUMED)
- TRANSITE PIPE (PRESUMED)
- AREA OF DRYWALL JOINT COMPOUND
- FIRE-RATED DOOR (PRESUMED)
- TEXTILE VIBRATION DAMPENER (PRESUMED)

FOR CLARITY THE FOLLOWING ASBESTOS CONTAINING MATERIALS ARE PRESENT IN THE ASSESSED AREA BUT HAVE NOT BEEN HATCHED ON THE DRAWING:

- PAINT ON CONCRETE BLOCK AND BRICK WALLS.
- VARIOUS COLOURS OF CAULKING ON EXTERIOR DOOR FRAMES.
- VERMICULITE INSULATION WITHIN PERIMETRE WALLS BEHIND THE STEEL BEAM ABOVE WINDOWS.
- THINSET BEHIND CERAMIC TILES (PRESUMED).
- COATING ON PLASTER COLUMNS IN THE AUTO SHOP.
- ROOFING MATERIALS AND CAULKING/SEALANTS ON THE ROOF (PRESUMED).



PROJECT NAME:
ASBESTOS REASSESSMENT

CLIENT NAME:
HASTINGS AND PRINCE EDWARD DISTRICT SCHOOL BOARD

PROJECT LOCATION:
EASTSIDE SECONDARY SCHOOL
275 FARLEY AVENUE
BELLEVILLE, ONTARIO

FIGURE NAME:
ROOF

PROJECT NUMBER:
200584.099

SCALE:
NOT TO SCALE

DRAWN BY:
JW

REVIEWED BY:
HM

DATE:
SEPTEMBER 2025

FIGURE NUMBER:
3 OF 3

APPENDIX II
Asbestos Analytical Certificates



Your Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Your C.O.C. #: n/a

Attention: Glenn Hendry

Pinchin Ltd
 1456 Centennial Drive
 Suite 2
 Kingston, ON
 CANADA K7P 0K4

Report Date: 2021/10/18
 Report #: R6857108
 Version: 2 - Revision

CERTIFICATE OF ANALYSIS – REVISED REPORT

BV LABS JOB #: C1Q2918
Received: 2021/09/13, 09:41

Sample Matrix: Solid
 # Samples Received: 98

| Analyses | Date | | Laboratory Method | Analytical Method |
|-------------------------------|----------|-----------|--------------------------|-------------------|
| | Quantity | Extracted | | |
| Asbestos by PLM - 0.5 RDL (1) | 55 | N/A | 2021/09/20 COR3SOP-00002 | EPA 600R-93/116 |
| Asbestos by PLM - 0.5 RDL (1) | 43 | N/A | N/A COR3SOP-00002 | EPA 600R-93/116 |

Remarks:

Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, MELCC, EPA, APHA.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested. This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

Bureau Veritas Laboratories' Asbestos Laboratory is accredited by NVLAP for bulk asbestos analysis by polarized light microscopy, NVLAP Code 600136-0.

This report may not be reproduced, except in full, without the written approval of Bureau Veritas Canada. This report may not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any other agency of the U.S. Government.

Bureau Veritas Laboratories' scope of accreditation includes EPA-600/M4-82-020: "Interim Method for the Determination of Asbestos in Bulk Insulation Samples" and EPA-600/R-93/116: "Method for the Determination of Asbestos in Bulk Building Materials".

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.



Your Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Your C.O.C. #: n/a

Attention: Glenn Hendry

Pinchin Ltd
1456 Centennial Drive
Suite 2
Kingston, ON
CANADA K7P 0K4

Report Date: 2021/10/18
Report #: R6857108
Version: 2 - Revision

CERTIFICATE OF ANALYSIS – REVISED REPORT

BV LABS JOB #: C1Q2918

Received: 2021/09/13, 09:41

(1) P.O.B. - Percent of Bulk

When Asbestos data is reported with other data, this report contains data that are not covered by the NVLAP accreditation.

Encryption Key

Antonella Brasil
Senior Project Manager
18 Oct 2021 10:50:12

Please direct all questions regarding this Certificate of Analysis to your Project Manager.

Antonella Brasil, Senior Project Manager
Email: Antonella.Brasil@bureauveritas.com
Phone# (905)817-5817

=====

BV Labs has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation please refer to the Validation Signature Page.



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0036 A BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 101 | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE930 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous dark yellow mastic | Not Detected | | Non-Fibrous |
| Comment: Another layer is present but not analyzed as requested. | | | | | |

| S 0036 B BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 223 | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE931 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous dark yellow mastic | Not Detected | | Non-Fibrous |
| Comment: Another layer is present but not analyzed as requested. | | | | | |

| S 0036 C BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 225 | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE932 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous dark yellow mastic | Not Detected | | Non-Fibrous |
| Comment: Another layer is present but not analyzed as requested | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0037 A TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161 | | | | | |
|--|--------------|-----------------------------------|--------------------------|---------------------|--------------------|
| Bureau Veritas ID: QQE933 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Chrysotile <0.50% | | Non-Fibrous |

| S 0037 B TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161 | | | | | |
|--|--------------|-----------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE934 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Not Detected | | Non-Fibrous |

| S 0037 C TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161 | | | | | |
|--|--------------|-----------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE935 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0038 A TEXTURED PLASTER ON WALL, RESOURCE CENTRE 129 | | | | | |
|---|--------------|-----------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE936 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Not Detected | | Non-Fibrous |

| S 0038 B TEXTURED PLASTER ON WALL, STAIRWELL TO RESOURCE CENTRE 129 | | | | | |
|--|--------------|-----------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE937 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Not Detected | | Non-Fibrous |

| S 0038 C TEXTURED PLASTER ON WALL, STAIRWELL TO RESOURCE CENTRE 129 | | | | | |
|--|--------------|-----------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE938 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0039 A PLASTER ON STEEL BEAM, LOBBY 192 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE939 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0039 B PLASTER ON STEEL BEAM, LOBBY 192 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE940 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0039 C PLASTER ON STEEL BEAM, LOBBY 192 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE941 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0040 A FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 187 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE942 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| S 0040 B FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, WEIGHT ROOM 182 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE943 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| S 0040 C FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, OFFICE 180 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE944 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0041 A SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 103 | | | | | | | |
|--|--------------|---------------------------|-------------------|----|---------------------|-----|--------------------|
| Bureau Veritas ID: QQE945 | | Date Analyzed: 2021/09/20 | | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Chrysotile | 2% | Cellulose | 10% | Non-Fibrous |

| S 0041 B SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, WOOD SHOP 152 | | | | | | | |
|--|--------------|---------------------------|-----------------|--|---------------------|--|--------------------|
| Bureau Veritas ID: QQE946 | | Date Analyzed: 2021/09/20 | | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | | | N/A | | | | |
| Comment: Not Analyzed - Positive Stop | | | | | | | |

| S 0041 C SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 250 | | | | | | | |
|--|--------------|---------------------------|-----------------|--|---------------------|--|--------------------|
| Bureau Veritas ID: QQE947 | | Date Analyzed: 2021/09/20 | | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | | | N/A | | | | |
| Comment: Not Analyzed - Positive Stop | | | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0042 A YELLOW PAINT ON CONCRETE BLOCK WALL, CLASSROOM 101 | | | | | | |
|--|--------------|--|-------------------|--------|---------------------|--------------------|
| Bureau Veritas ID: QQE948 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 90 | Non-homogeneous yellow/white paint/plaster | Chrysotile | <0.50% | | Non-Fibrous |
| Layer 2 | 10 | Homogeneous grey concrete | Not Detected | | | Non-Fibrous |

| S 0042 B YELLOW PAINT ON CONCRETE BLOCK WALL, CLASSROOM 217 | | | | | | |
|--|--------------|---|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: QQE949 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 20 | Non-homogeneous white/white paint/plaster | Not Detected | | | Non-Fibrous |
| Layer 2 | 80 | Homogeneous grey concrete | Not Detected | | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0042 C YELLOW PAINT ON BRICK WALL, CORRIDOR 193 | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE950 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 40 | Homogeneous white paint | Not Detected | | Non-Fibrous |
| Layer 2 | 60 | Homogeneous red/brown brick | Not Detected | | Non-Fibrous |

| S 0042 D YELLOW PAINT ON CONCRETE BLOCK WALL, CUSTODIAL ROOM 160 | | | | | |
|---|--------------|---|--------------------------|---------------------|--------------------|
| Bureau Veritas ID: QQE951 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous white/off-white/grey paint/plaster/concrete | Chrysotile <0.50% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0042 E YELLOW PAINT ON CONCRETE BLOCK WALL, MECHANICAL ROOM 282 | | | | | | |
|--|--------------|---|-------------------|--------|---------------------|--------------------|
| Bureau Veritas ID: QQE952 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Non-homogeneous white/off-white paint/plaster | Chrysotile | <0.50% | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey concrete | Not Detected | | | Non-Fibrous |

| S 0042 F YELLOW PAINT ON CONCRETE BLOCK WALL, OFFICE 180 | | | | | | |
|---|--------------|---|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: QQE953 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous white/off-white/grey paint/plaster/concrete | Not Detected | | | Non-Fibrous |

| S 0042 G BLACK PAINT ON CONCRETE BLOCK WALL, STAGE 140 | | | | | | |
|---|--------------|---|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: QQE954 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous black/off-white paint/plaster | Chrysotile | 1% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0043 A ADHESIVE BEHIND BASEBOARD, OFFICE 151 | | | | | |
|---|--------------|----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE955 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous brown adhesive | Not Detected | | Non-Fibrous |

| S 0043 B ADHESIVE BEHIND BASEBOARD, CLASSROOM 158 | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE956 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous yellow adhesive | Not Detected | | Non-Fibrous |

| S 0043 C ADHESIVE BEHIND BASEBOARD, CLASSROOM 187 | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE957 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous yellow adhesive | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0043 D ADHESIVE BEHIND BASEBOARD, OFFICE 181 | | | | | |
|---|--------------|----------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE958 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous dark yellow adhesive | Not Detected | | Non-Fibrous |

| S 0043 E ADHESIVE BEHIND BASEBOARD, CLASSROOM 115 | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE959 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous yellow adhesive | Not Detected | | Non-Fibrous |

| S 0043 F ADHESIVE BEHIND BASEBOARD, CLASSROOM 111 | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE960 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous yellow adhesive | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0043 G ADHESIVE BEHIND BASEBOARD, CLASSROOM 217 | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE961 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous yellow adhesive | Not Detected | | Non-Fibrous |

| S 0044 A TERRAZZO FLOOR, CORRIDOR 190, WEST STAIRWELL | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE962 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white terrazzo floor | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey cementitious material | Not Detected | | Non-Fibrous |

| S 0044 B TERRAZZO FLOOR, CORRIDOR 190 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE963 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white terrazzo floor | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey cementitious material | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0044 C TERRAZZO FLOOR, CORRIDOR 194, STAIRWELL | | | | | |
|---|--------------|---|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE964 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous white/grey terrazzo floor/cementitious material | Not Detected | | Non-Fibrous |

| S 0044 D TERRAZZO FLOOR, CORRIDOR 260 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE965 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 90 | Homogeneous white terrazzo floor | Not Detected | | Non-Fibrous |
| Layer 2 | 10 | Homogeneous grey cementitious material | Not Detected | | Non-Fibrous |

| S 0044 E TERRAZZO FLOOR, CORRIDOR 195 | | | | | |
|--|--------------|---|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE966 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous white/grey terrazzo floor/cementitious material | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0044 F TERRAZZO FLOOR, CORRIDOR 261, WEST STAIRWELL | | | | | |
|--|--------------|---|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE967 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous white/grey terrazzo floor/cementitious material | Not Detected | | Non-Fibrous |

| S 0044 G TERRAZZO FLOOR, CORRIDOR 262 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE968 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 60 | Homogeneous white terrazzo floor | Not Detected | | Non-Fibrous |
| Layer 2 | 40 | Homogeneous grey cementitious material | Not Detected | | Non-Fibrous |

| S 0045 A OFF-WHITE PAINT ON CONCRETE STRUCTURE, CUSTODIAL ROOM 146 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE969 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white paint | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0045 B OFF-WHITE PAINT ON CONCRETE STRUCTURE, CUSTODIAL ROOM 146 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE970 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white paint | Not Detected | | Non-Fibrous |

| S 0045 C OFF-WHITE PAINT ON CONCRETE STRUCTURE, OFFICE 145 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE971 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white paint | Not Detected | | Non-Fibrous |

| S 0045 D OFF-WHITE PAINT ON CONCRETE STRUCTURE, WOOD SHOP 152 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE972 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white paint | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0045 E OFF-WHITE PAINT ON CONCRETE STRUCTURE, CORRIDOR 168 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE973 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white paint | Not Detected | | Non-Fibrous |

| S 0046 A LIGHT GREY DUCT MASTIC, CLASSROOM 125 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE974 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| S 0046 B LIGHT GREY DUCT MASTIC, MUSIC ROOM 188 | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE975 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white caulking | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0046 C LIGHT GREY DUCT MASTIC, CLASSROOM 186 | | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--|--------------------|
| Bureau Veritas ID: QQE976 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | | Non-Fibrous |

| S 0047 A 1'X1' ACOUSTIC CEILING TILE, RADIO ROOM 156D | | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|-----|--------------------|
| Bureau Veritas ID: QQE977 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous brown ceiling tile | Not Detected | Cellulose | 90% | Non-Fibrous |

| S 0047 B 1'X1' ACOUSTIC CEILING TILE, RADIO ROOM 156D | | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|-----|--------------------|
| Bureau Veritas ID: QQE978 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous brown ceiling tile | Not Detected | Cellulose | 90% | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0047 C 1'X1' ACOUSTIC CEILING TILE, COMPUTER LAB 156C | | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|-----|--------------------|
| Bureau Veritas ID: QQE979 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous brown ceiling tile | Not Detected | Cellulose | 90% | Non-Fibrous |

| S 0048 A 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 223 | | | | | | |
|---|--------------|-------------------------------|-----------------|---------------------|-----|--------------------|
| Bureau Veritas ID: QQE980 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey ceiling tile | Not Detected | Fibrous Glass | 70% | Non-Fibrous |

| S 0048 B 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 224 | | | | | | |
|---|--------------|-------------------------------|-----------------|---------------------|-----|--------------------|
| Bureau Veritas ID: QQE981 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey ceiling tile | Not Detected | Fibrous Glass | 70% | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0048 C 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 102 | | | | | | |
|---|--------------|-------------------------------|-----------------|---------------------|--------------------|--|
| Bureau Veritas ID: QQE982 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Homogeneous grey ceiling tile | Not Detected | Fibrous Glass 70% | Non-Fibrous | |

| S 0049 A BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CORRIDOR 191 | | | | | | |
|---|--------------|--------------------------------------|----------------------|---------------------|--------------------|--|
| Bureau Veritas ID: QQE983 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Homogeneous grey/black butyl sealant | Chrysotile 1% | | Non-Fibrous | |

| S 0049 B BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CLASSROOM 187 | | | | | | |
|--|--|---------------------------|-----------------|---------------------|--------------------|--|
| Bureau Veritas ID: QQE984 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | | | N/A | | | |
| | Comment: Not Analyzed - Positive Stop | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| S 0049 C BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF WEIGHT ROM 182 | | | | | |
| Bureau Veritas ID: QQE985 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | |
|---|--------------|--------------------------------------|----------------------|---------------------|--------------------|
| S 0050 A GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CLASSROOM 104 | | | | | |
| Bureau Veritas ID: QQE986 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey/black butyl sealant | Chrysotile 3% | | Non-Fibrous |

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S 0050 B GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF OFFICE 124 | | | | | |
| Bureau Veritas ID: QQE987 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0050 C GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF OFFICE 124A | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE988 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| S 0051 A GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE989 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| S 0051 B GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE990 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0051 C GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE991 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| S 0052 A MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CAFETERIA 167 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE992 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

| S 0052 B MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF MANUFACTURING SHOP 153 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE993 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0052 C MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 151B | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE994 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

| S 0052 D MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF GYM 142 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE995 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

| S 0052 E MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF MUSIC ROOM 188 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE996 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0052 F MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 115 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE997 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

| S 0052 G MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 111 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE998 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

| S 0053 A DRYWALL JOINT COMPOUND ON CEILING, CHANGE ROOM 131, SHOWER | | | | | |
|--|--------------|--|----------------------|---------------------|--------------------|
| Bureau Veritas ID: QQE999 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile 1% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0053 B DRYWALL JOINT COMPOUND ON CEILING, OFFICE 180, SHOWER | | | | | |
|---|--------------|--|-------------------|----|--------------------|
| Bureau Veritas ID: QQF000 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | Non-Fibrous |

| S 0053 C DRYWALL JOINT COMPOUND ON INTERIOR WALL, RESOURCE CENTRE 129 | | | | | |
|--|--------------|--|-------------------|----|--------------------|
| Bureau Veritas ID: QQF001 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | Non-Fibrous |

| S 0053 D DRYWALL JOINT COMPOUND ON INTERIOR WALL, OFFICE 129B | | | | | |
|--|--------------|--|-------------------|----|--------------------|
| Bureau Veritas ID: QQF002 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous beige drywall joint compound | Chrysotile | 1% | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0053 E DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 187 | | | | | | |
|--|--------------|--|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: QQF003 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | | Non-Fibrous |

| S 0053 F DRYWALL JOINT COMPOUND ON INTERIOR WALL, MECHANICAL ROOM 280 | | | | | | |
|--|--------------|--|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: QQF004 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | | Non-Fibrous |

| S 0053 G DRYWALL JOINT COMPOUND ON CEILING, CHANGE ROOM 135, SHOWER | | | | | | |
|--|--------------|--|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: QQF005 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0054 A DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 126 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF006 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey drywall joint compound | Not Detected | | Non-Fibrous |

| S 0054 B DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 151B | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF007 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

| S 0054 C DRYWALL JOINT COMPOUND ON INTERIOR WALL, RADIO ROOM 156D | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF008 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0054 D DRYWALL JOINT COMPOUND ON INTERIOR WALL, OFFICE 123 | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF009 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

| S 0054 E DRYWALL JOINT COMPOUND ON INTERIOR WALL, MANUFACTURING SHOP 154 | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF010 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

| S 0054 F DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 251 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF011 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0054 G DRYWALL JOINT COMPOUND ON INTERIOR WALL, STORAGE 216 | | | | | | |
|--|--------------|--|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: QQF012 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | | Non-Fibrous |

| S 0055 A DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 226 | | | | | | |
|---|--------------|--|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: QQF013 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | | Non-Fibrous |

| S 0055 B DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 220 | | | | | | |
|--|--------------|--|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: QQF014 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0055 D DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 111 | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF015 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

| S 0055 E DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 112 | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF016 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

| S 0056 A SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 157 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF017 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0056 B SMOOTH PLASTER CEILING, STORAGE 160 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF018 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0056 C SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 251 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF019 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0056 D SMOOTH PLASTER CEILING, STORAGE 203 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF020 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0056 E SMOOTH PLASTER ON EXTERIOR WALL BELOW RADIATOR, CLASSROOM 202 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF021 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0057 A SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 104 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF022 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0057 B SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 112 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF023 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0057 C SMOOTH PLASTER ON BULKHEAD, ABOVE LOCKER, CORRIDOR 190 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF024 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0057 D SMOOTH PLASTER ON BULKHEAD, ABOVE LOCKER, CORRIDOR 261 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF025 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0057 E SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 217 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF026 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0055 C DRYWALL JOINT COMPOUND, INTERIOR WALL, CLASSROOM 219 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF027 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |
| Comment: This is sample 55C, but bag is labelled 22C | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE930
Sample ID: S 0036 A BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 101
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE931
Sample ID: S 0036 B BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 223
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE932
Sample ID: S 0036 C BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 225
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE933
Sample ID: S 0037 A TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE933 Dup
Sample ID: S 0037 A TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE934
Sample ID: S 0037 B TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE935
Sample ID: S 0037 C TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



TEST SUMMARY

Bureau Veritas ID: QQE936
Sample ID: S 0038 A TEXTURED PLASTER ON WALL, RESOURCE CENTRE 129
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE937
Sample ID: S 0038 B TEXTURED PLASTER ON WALL, STAIRWELL TO RESOURCE CENTRE 129
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE938
Sample ID: S 0038 C TEXTURED PLASTER ON WALL, STAIRWELL TO RESOURCE CENTRE 129
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE939
Sample ID: S 0039 A PLASTER ON STEEL BEAM, LOBBY 192
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE940
Sample ID: S 0039 B PLASTER ON STEEL BEAM, LOBBY 192
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE941
Sample ID: S 0039 C PLASTER ON STEEL BEAM, LOBBY 192
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE942
Sample ID: S 0040 A FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 187
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



TEST SUMMARY

Bureau Veritas ID: QQE942 Dup
Sample ID: S 0040 A FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 187
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE943
Sample ID: S 0040 B FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, WEIGHT ROOM 182
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE944
Sample ID: S 0040 C FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, OFFICE 180
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE945
Sample ID: S 0041 A SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 103
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE946
Sample ID: S 0041 B SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, WOOD SHOP 152
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE947
Sample ID: S 0041 C SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 250
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE948
Sample ID: S 0042 A YELLOW PAINT ON CONCRETE BLOCK WALL, CLASSROOM 101
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE949
Sample ID: S 0042 B YELLOW PAINT ON CONCRETE BLOCK WALL, CLASSROOM 217
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE950
Sample ID: S 0042 C YELLOW PAINT ON BRICK WALL, CORRIDOR 193
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE951
Sample ID: S 0042 D YELLOW PAINT ON CONCRETE BLOCK WALL, CUSTODIAL ROOM 160
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE952
Sample ID: S 0042 E YELLOW PAINT ON CONCRETE BLOCK WALL, MECHANICAL ROOM 282
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE952 Dup
Sample ID: S 0042 E YELLOW PAINT ON CONCRETE BLOCK WALL, MECHANICAL ROOM 282
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE953
Sample ID: S 0042 F YELLOW PAINT ON CONCRETE BLOCK WALL, OFFICE 180
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE954
Sample ID: S 0042 G BLACK PAINT ON CONCRETE BLOCK WALL, STAGE 140
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



TEST SUMMARY

Bureau Veritas ID: QQE955
Sample ID: S 0043 A ADHESIVE BEHIND BASEBOARD, OFFICE 151
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE956
Sample ID: S 0043 B ADHESIVE BEHIND BASEBOARD, CLASSROOM 158
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE957
Sample ID: S 0043 C ADHESIVE BEHIND BASEBOARD, CLASSROOM 187
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE958
Sample ID: S 0043 D ADHESIVE BEHIND BASEBOARD, OFFICE 181
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE959
Sample ID: S 0043 E ADHESIVE BEHIND BASEBOARD, CLASSROOM 115
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE960
Sample ID: S 0043 F ADHESIVE BEHIND BASEBOARD, CLASSROOM 111
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE961
Sample ID: S 0043 G ADHESIVE BEHIND BASEBOARD, CLASSROOM 217
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE962
Sample ID: S 0044 A TERRAZZO FLOOR, CORRIDOR 190, WEST STAIRWELL
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE962 Dup
Sample ID: S 0044 A TERRAZZO FLOOR, CORRIDOR 190, WEST STAIRWELL
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE963
Sample ID: S 0044 B TERRAZZO FLOOR, CORRIDOR 190
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE964
Sample ID: S 0044 C TERRAZZO FLOOR, CORRIDOR 194, STAIRWELL
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE965
Sample ID: S 0044 D TERRAZZO FLOOR, CORRIDOR 260
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE966
Sample ID: S 0044 E TERRAZZO FLOOR, CORRIDOR 195
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE967
Sample ID: S 0044 F TERRAZZO FLOOR, CORRIDOR 261, WEST STAIRWELL
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE968
Sample ID: S 0044 G TERRAZZO FLOOR, CORRIDOR 262
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE969
Sample ID: S 0045 A OFF-WHITE PAINT ON CONCRETE STRUCTURE, CUSTODIAL ROOM 146
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE970
Sample ID: S 0045 B OFF-WHITE PAINT ON CONCRETE STRUCTURE, CUSTODIAL ROOM 146
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE971
Sample ID: S 0045 C OFF-WHITE PAINT ON CONCRETE STRUCTURE, OFFICE 145
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE972
Sample ID: S 0045 D OFF-WHITE PAINT ON CONCRETE STRUCTURE, WOOD SHOP 152
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE972 Dup
Sample ID: S 0045 D OFF-WHITE PAINT ON CONCRETE STRUCTURE, WOOD SHOP 152
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE973
Sample ID: S 0045 E OFF-WHITE PAINT ON CONCRETE STRUCTURE, CORRIDOR 168
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE974
Sample ID: S 0046 A LIGHT GREY DUCT MASTIC, CLASSROOM 125
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE975
Sample ID: S 0046 B LIGHT GREY DUCT MASTIC, MUSIC ROOM 188
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE976
Sample ID: S 0046 C LIGHT GREY DUCT MASTIC, CLASSROOM 186
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE977
Sample ID: S 0047 A 1'X1' ACOUSTIC CEILING TILE, RADIO ROOM 156D
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE978
Sample ID: S 0047 B 1'X1' ACOUSTIC CEILING TILE, RADIO ROOM 156D
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE979
Sample ID: S 0047 C 1'X1' ACOUSTIC CEILING TILE, COMPUTER LAB 156C
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE980
Sample ID: S 0048 A 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 223
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE981
Sample ID: S 0048 B 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 102
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE982
Sample ID: S 0048 C 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 102
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE982 Dup
Sample ID: S 0048 C 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 102
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE983
Sample ID: S 0049 A BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CORRIDOR 191
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE984
Sample ID: S 0049 B BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CLASSROOM 187
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE985
Sample ID: S 0049 C BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF WEIGHT ROM 182
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE986
Sample ID: S 0050 A GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CLASSROOM 104
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE987
Sample ID: S 0050 B GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF OFFICE 124
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE988
Sample ID: S 0050 C GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF OFFICE 124A
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE989
Sample ID: S 0051 A GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE990
Sample ID: S 0051 B GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE991
Sample ID: S 0051 C GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE992
Sample ID: S 0052 A MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CAFETERIA
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE992 Dup
Sample ID: S 0052 A MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CAFETERIA
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE993
Sample ID: S 0052 B MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF MANUFACTURING SHOP 153
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE994
Sample ID: S 0052 C MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 118
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE995
Sample ID: S 0052 D MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF GYM 115
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE996
Sample ID: S 0052 E MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF MUSIC ROOM 118
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE997
Sample ID: S 0052 F MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 115
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE998
Sample ID: S 0052 G MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 115
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE999
Sample ID: S 0053 A DRYWALL JOINT COMPOUND ON CEILING, CHANGE ROOM 131, SHOWER
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



TEST SUMMARY

Bureau Veritas ID: QQF000
Sample ID: S 0053 B DRYWALL JOINT COMPOUND ON CEILING, OFFICE 180, SHOWER
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF001
Sample ID: S 0053 C DRYWALL JOINT COMPOUND ON INTERIOR WALL, RESOURCE CENTRE 129
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF002
Sample ID: S 0053 D DRYWALL JOINT COMPOUND ON INTERIOR WALL, OFFICE 129B
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF002 Dup
Sample ID: S 0053 D DRYWALL JOINT COMPOUND ON INTERIOR WALL, OFFICE 129B
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF003
Sample ID: S 0053 E DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 187
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF004
Sample ID: S 0053 F DRYWALL JOINT COMPOUND ON INTERIOR WALL, MECHANICAL ROOM 280
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF005
Sample ID: S 0053 G DRYWALL JOINT COMPOUND ON CEILING, CHANGE ROOM 135, SHOWER
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQF006
Sample ID: S 0054 A DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 126
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF007
Sample ID: S 0054 B DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 151B
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF008
Sample ID: S 0054 C DRYWALL JOINT COMPOUND ON INTERIOR WALL, RADIO ROOM 156D
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF009
Sample ID: S 0054 D DRYWALL JOINT COMPOUND ON INTERIOR WALL, OFFICE 123
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF010
Sample ID: S 0054 E DRYWALL JOINT COMPOUND ON INTERIOR WALL, MANUFACTURING SHOP 154
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF011
Sample ID: S 0054 F DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 251
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF012
Sample ID: S 0054 G DRYWALL JOINT COMPOUND ON INTERIOR WALL, STORAGE 216
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQF012 Dup
Sample ID: S 0054 G DRYWALL JOINT COMPOUND ON INTERIOR WALL, STORAGE 216
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF013
Sample ID: S 0055 A DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 226
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF014
Sample ID: S 0055 B DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 220
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF015
Sample ID: S 0055 D DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 111
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF016
Sample ID: S 0055 E DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 112
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF017
Sample ID: S 0056 A SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 157
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF018
Sample ID: S 0056 B SMOOTH PLASTER CEILING, STORAGE 160
Matrix: Solid

Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQF019
Sample ID: S 0056 C SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 251
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF020
Sample ID: S 0056 D SMOOTH PLASTER CEILING, STORAGE 203
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF021
Sample ID: S 0056 E SMOOTH PLASTER ON EXTERIOR WALL BELOW RADIATOR, CLASSROOM 202
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF021 Dup
Sample ID: S 0056 E SMOOTH PLASTER ON EXTERIOR WALL BELOW RADIATOR, CLASSROOM 202
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF022
Sample ID: S 0057 A SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 104
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF023
Sample ID: S 0057 B SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 112
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF024
Sample ID: S 0057 C SMOOTH PLASTER ON BULKHEAD, ABOVE LOCKER, CORRIDOR 190
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |



TEST SUMMARY

Bureau Veritas ID: QQF025
Sample ID: S 0057 D SMOOTH PLASTER ON BULKHEAD, ABOVE LOCKER, CORRIDOR 261
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF026
Sample ID: S 0057 E SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 217
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF027
Sample ID: S 0055 C DRYWALL JOINT COMPOUND, INTERIOR WALL, CLASSROOM 219
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

GENERAL COMMENTS

Samples can contain very fine asbestos fibres that are below the resolution limits of the PLM. Transmission Electron Microscopy (TEM) is recommended for confirmation of None Detected results.

Revised Report (2021/10/18): ID changed for S0022C to S 0055 C as per client request .

Results relate only to the items tested.



**BUREAU
VERITAS**

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

Jon Delos Santos, Laboratory Supervisor

BV Labs has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation please refer to the Validation Signature Page.



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|----------------|--------------------|------------------------|---------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 001A | Aircell pipe insulation, Location 150 | 55% Chrysotile | 30% Cellulose | 15% Other | Tan, White Fibrous Heterogeneous |
| 1717806PLM_1 | | | | | Teased |
| 001B | Aircell pipe insulation, Location 230 | Not Analyzed | | | |
| 1717806PLM_2 | | | | | |
| 001C | Aircell pipe insulation, Location 002 | Not Analyzed | | | |
| 1717806PLM_3 | | | | | |
| 002A - A | Brown pressed paper insulation, Location 150 | None Detected | 80% Cellulose | 20% Other | Black Fibrous Heterogeneous |
| 1717806PLM_4 | felt | | | | Dissolved, Teased |
| 002A - B | Brown pressed paper insulation, Location 150 | 2% Chrysotile | 90% Cellulose | 8% Other | Tan Fibrous Heterogeneous |
| 1717806PLM_173 | paper | | | | Teased |
| 002B | Brown pressed paper insulation, Custodial Office | Not Analyzed | | | |
| 1717806PLM_5 | paper only | | | | |
| 002C | Brown pressed paper insulation, Location 109 | Not Analyzed | | | |
| 1717806PLM_6 | paper only | | | | |
| 003A - A | 9" vinyl floor tiles, various patterns and colours, IT Room at Resource Centre | 4% Chrysotile | | 96% Other | Gray, White Non Fibrous Heterogeneous |
| 1717806PLM_7 | tile | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|---------------|--------------------|------------------------|-------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 003A - B | 9" vinyl floor tiles, various patterns and colours, IT Room at Resource Centre | 5% Chrysotile | 5% Cellulose | 90% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_119 | mastic | | | | Dissolved |
| 003B - A | 9" vinyl floor tiles, various patterns and colours, Location 115 | Not Analyzed | | | |
| 1717806PLM_8 | tile | | | | |
| 003B - B | 9" vinyl floor tiles, various patterns and colours, Location 115 | Not Analyzed | | | |
| 1717806PLM_120 | mastic | | | | |
| 003C - A | 9" vinyl floor tiles, various patterns and colours, Location 157 | Not Analyzed | | | |
| 1717806PLM_9 | tile | | | | |
| 003C - B | 9" vinyl floor tiles, various patterns and colours, Location 157 | Not Analyzed | | | |
| 1717806PLM_121 | mastic | | | | |
| 003D - A | 9" vinyl floor tiles, various patterns and colours, Location 150 | Not Analyzed | | | |
| 1717806PLM_10 | tile | | | | |
| 003D - B | 9" vinyl floor tiles, various patterns and colours, Location 150 | Not Analyzed | | | |
| 1717806PLM_122 | mastic | | | | |
| 003E - A | 9" vinyl floor tiles, various patterns and colours, Custodial at Location 161 | Not Analyzed | | | |
| 1717806PLM_11 | tile | | | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|---------------|--------------------|------------------------|---------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 003E - B | 9" vinyl floor tiles, various patterns and colours, Custodial at Location 161 | Not Analyzed | | | |
| 1717806PLM_123 | mastic | | | | |
| 004A - A | 12" beige vinyl floor tiles, Location 151A | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous |
| 1717806PLM_12 | tile | | | | Dissolved |
| 004A - B | 12" beige vinyl floor tiles, Location 151A | None Detected | 3% Cellulose | 97% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_124 | mastic | | | | Dissolved |
| 004B - A | 12" beige vinyl floor tiles, Location 151A | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous |
| 1717806PLM_13 | tile | | | | Dissolved |
| 004B - B | 12" beige vinyl floor tiles, Location 151A | None Detected | 3% Cellulose | 97% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_174 | mastic | | | | Dissolved |
| 004C - A | 12" beige vinyl floor tiles, Location 151A | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_14 | tile - ashed | | | | Ashed |
| 004C - B | 12" beige vinyl floor tiles, Location 151A | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_126 | mastic | | | | Dissolved |
| 005A | Drywall joint compound, Location 151 | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1717806PLM_15 | | | | | Crushed |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|---------------|--|----------------|--------------------|------------------------|-------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 005B | Drywall joint compound, Location 154A | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1717806PLM_16 | | | | | Crushed |
| 005C | Drywall joint compound, Location 156C | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1717806PLM_17 | | | | | Crushed |
| 005D | Drywall joint compound, Location 125 | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1717806PLM_18 | | | | | Crushed |
| 005E | Drywall joint compound, Location 212 | 3% Chrysotile | | 97% Other | White Non Fibrous Homogeneous |
| 1717806PLM_19 | | | | | Crushed |
| 005F | Drywall joint compound, Location 129 | Not Analyzed | | | |
| 1717806PLM_20 | | | | | |
| 005G | Drywall joint compound, Location 215 | Not Analyzed | | | |
| 1717806PLM_21 | | | | | |
| 006A | Parging Cement, 1959 Portion, Location 152 | 30% Chrysotile | | 70% Other | Gray Fibrous Heterogeneous |
| 1717806PLM_22 | | | | | Teased |
| 006B | Parging Cement, 1959 Portion, Location 230 | Not Analyzed | | | |
| 1717806PLM_23 | | | | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|---------------|--|----------------|--------------------|------------------------|-----------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 006C | Parging Cement, 1959 Portion, Location 002 | Not Analyzed | | | |
| 1717806PLM_24 | | | | | |
| 007A | Brown duct mastic, Location 152 | None Detected | 10% Wollastonite | 90% Other | Brown Non Fibrous Homogeneous |
| 1717806PLM_25 | | | | | Ashed |
| 007B | Brown duct mastic, Location 152 | None Detected | 10% Wollastonite | 90% Other | Brown Non Fibrous Homogeneous |
| 1717806PLM_26 | | | | | Ashed |
| 007C | Brown duct mastic, Location 152 | None Detected | 10% Wollastonite | 90% Other | Brown Non Fibrous Homogeneous |
| 1717806PLM_27 | | | | | Ashed |
| 008A | Parging cement, 1961 portion, Location 153 | 30% Chrysotile | 10% Cellulose | 60% Other | Gray, White Fibrous Heterogeneous |
| 1717806PLM_28 | | | | | Teased |
| 008B | Parging cement, 1961 portion, Location 153 | Not Analyzed | | | |
| 1717806PLM_29 | | | | | |
| 008C | Parging cement, 1961 portion, Location 153 | Not Analyzed | | | |
| 1717806PLM_30 | | | | | |
| 009A - A | Smooth plaster, 1959 portion, Location 155 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_31 | finish | | | | Crushed |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|---------------|--------------------|--------------------------|---------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 009A - B | Smooth plaster, 1959 portion, Location 155 | None Detected | | 70% Other 30% Perlite | Gray Non Fibrous Heterogeneous |
| 1717806PLM_127 | base | | | | Crushed |
| 009B - A | Smooth plaster, 1959 portion, Location 160 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_32 | finish | | | | Crushed |
| 009B - B | Smooth plaster, 1959 portion, Location 160 | None Detected | | 70% Other 30% Perlite | Gray Non Fibrous Heterogeneous |
| 1717806PLM_128 | base | | | | Crushed |
| 009C - A | Smooth plaster, 1959 portion, Location 195 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_33 | finish | | | | Ashed |
| 009C - B | Smooth plaster, 1959 portion, Location 195 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_129 | base | | | | Crushed |
| 009D - A | Smooth plaster, 1959 portion, Location 196 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_34 | finish | | | | Crushed |
| 009D - B | Smooth plaster, 1959 portion, Location 196 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_130 | base | | | | Crushed |
| 009E - A | Smooth plaster, 1959 portion, Location 195 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_35 | finish | | | | Crushed |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|---------------|-----------------------------------|--------------------------|---|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 009E - B | Smooth plaster, 1959 portion, Location 195 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_131 | base | | | | Crushed |
| 009F - A | Smooth plaster, 1959 portion, Location 261 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_36 | finish | | | | Crushed |
| 009F - B | Smooth plaster, 1959 portion, Location 261 | None Detected | | 70% Other 30% Perlite | Gray Non Fibrous Heterogeneous |
| 1717806PLM_132 | base | | | | Crushed |
| 009G - A | Smooth plaster, 1959 portion, Location 261 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_37 | finish | | | | Crushed |
| 009G - B | Smooth plaster, 1959 portion, Location 261 | None Detected | | 70% Other 30% Perlite | Gray Non Fibrous Heterogeneous |
| 1717806PLM_133 | base | | | | Crushed |
| 0010A | 2 x 4 acoustic ceiling tile, dense small and medium pinhole pattern, Location 154 | None Detected | 50% Cellulose 30% Mineral Wool | 10% Perlite 10% Other | Gray, White Fibrous Heterogeneous |
| 1717806PLM_38 | | | | | Teased |
| 0010B | 2 x 4 acoustic ceiling tile, dense small and medium pinhole pattern, Location 154 | None Detected | 50% Cellulose 30% Mineral Wool | 10% Perlite 10% Other | Gray, White Fibrous Heterogeneous |
| 1717806PLM_39 | | | | | Teased |
| 0010C | 2 x 4 acoustic ceiling tile, dense small and medium pinhole pattern, Location 154 | None Detected | 50% Cellulose 30% Mineral Wool | 10% Perlite 10% Other | Gray, White Fibrous Heterogeneous |
| 1717806PLM_40 | | | | | Teased |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|---------------|---|----------------------|--------------------|--------------------------|----------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0011A | 1' x 1; Acoustic ceiling tile, large and medium uniform pinhole, Location 156 | None Detected | 85% Cellulose | 15% Other | Tan, White Fibrous Heterogeneous |
| 1717806PLM_41 | | | | | Teased |
| 0011B | 1' x 1; Acoustic ceiling tile, large and medium uniform pinhole, Location 157 | None Detected | 85% Cellulose | 15% Other | Tan, White Fibrous Heterogeneous |
| 1717806PLM_42 | | | | | Teased |
| 0011C | 1' x 1; Acoustic ceiling tile, large and medium uniform pinhole, Location 156 | None Detected | 85% Cellulose | 15% Other | Tan, White Fibrous Heterogeneous |
| 1717806PLM_43 | | | | | Teased |
| 0012A | Ceiling texture, Location 159 | 5% Chrysotile | | 50% Perlite 45% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_44 | | | | | Teased |
| 0012B | Ceiling texture, Location 257 | Not Analyzed | | | |
| 1717806PLM_45 | | | | | |
| 0012C | Ceiling texture, Location 257 | Not Analyzed | | | |
| 1717806PLM_46 | | | | | |
| 0013A | 12" vinyl floor tile, red and black checkered pattern, Location 160 | None Detected | | 100% Other | Red Non Fibrous Heterogeneous |
| 1717806PLM_47 | tile only | | | | Dissolved |
| 0013B | 12" vinyl floor tile, red and black checkered pattern, Location 160 | None Detected | | 100% Other | Red Non Fibrous Heterogeneous |
| 1717806PLM_48 | tile only | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|----------------|--------------------|------------------------|--|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0013C - A | 12" vinyl floor tile, red and black checkered pattern, Location 160 | None Detected | | 100% Other | Black Non Fibrous Heterogeneous |
| 1717806PLM_49 | tile - ashed | | | | Ashed |
| 0013C - B | 12" vinyl floor tile, red and black checkered pattern, Location 160 | None Detected | | 100% Other | Yellow Non Fibrous Homogeneous |
| 1717806PLM_134 | mastic | | | | Dissolved |
| 0014A | Aircell, 1961 portion, Custodial office | 40% Chrysotile | 50% Cellulose | 10% Other | Tan, White Fibrous Heterogeneous |
| 1717806PLM_50 | | | | | Teased |
| 0014B | Aircell, 1961 portion, Custodial office | Not Analyzed | | | |
| 1717806PLM_51 | | | | | |
| 0014C | Aircell, 1961 portion, Custodial office | Not Analyzed | | | |
| 1717806PLM_52 | | | | | |
| 0015A - A | 12" vinyl floor tile, beige with brown streaks, Location 163 | 3% Chrysotile | | 97% Other | Brown, Cream Non Fibrous Heterogeneous |
| 1717806PLM_53 | tile | | | | Dissolved |
| 0015A - B | 12" vinyl floor tile, beige with brown streaks, Location 163 | None Detected | | 100% Other | Gray, Yellow Non Fibrous Heterogeneous |
| 1717806PLM_135 | mastic/ leveling | | | | Crushed, Dissolved |
| 0015B - A | 12" vinyl floor tile, beige with brown streaks, Location 163 | Not Analyzed | | | |
| 1717806PLM_54 | tile | | | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|---------------|--------------------|------------------------|--|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0015B - B | 12" vinyl floor tile, beige with brown streaks, Location 163 | None Detected | 3% Cellulose | 97% Other | Gray, Yellow Non Fibrous Heterogeneous |
| 1717806PLM_136 | mastic/ leveling | | | | Crushed, Dissolved |
| 0015C - A | 12" vinyl floor tile, beige with brown streaks, Location 163 | Not Analyzed | | | |
| 1717806PLM_55 | tile | | | | |
| 0015C - B | 12" vinyl floor tile, beige with brown streaks, Location 163 | None Detected | 5% Cellulose | 95% Other | Gray, Yellow Non Fibrous Heterogeneous |
| 1717806PLM_137 | mastic/ leveling | | | | Crushed, Dissolved |
| 0016A - A | Plaster above lockers, Location 194 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_56 | finish | | | | Crushed |
| 0016A - B | Plaster above lockers, Location 194 | None Detected | 1% Hair | 99% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_138 | base | | | | Crushed |
| 0016B - A | Plaster above lockers, Location 194 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_57 | finish | | | | Crushed |
| 0016B - B | Plaster above lockers, Location 194 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_139 | base | | | | Crushed |
| 0016C - A | Plaster above lockers, Location 194 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_58 | finish | | | | Crushed |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|-------------------------------------|----------------|--------------------|------------------------|---|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0016C - B | Plaster above lockers, Location 194 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_140 | base | | | | Crushed |
| 0016D - A | Plaster above lockers, Location 194 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_59 | finish | | | | Crushed |
| 0016D - B | Plaster above lockers, Location 194 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_141 | base | | | | Crushed |
| 0016E - A | Plaster above lockers, Location 194 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_60 | finish | | | | Crushed |
| 0016E - B | Plaster above lockers, Location 194 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_142 | base | | | | Crushed |
| 0017A | Light heat shield, Location 002 | 70% Chrysotile | | 30% Other | White, Silver Fibrous Heterogeneous |
| 1717806PLM_61 | | | | | Teased |
| 0017B | Light heat shield, Location 002 | Not Analyzed | | | |
| 1717806PLM_62 | | | | | |
| 0017C | Light heat shield, Location 002 | Not Analyzed | | | |
| 1717806PLM_63 | | | | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|---------------|--------------------|------------------------|---|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0018A - A | 12" vinyl floor tile, off-white with grey fleck, Location 125 | None Detected | | 100% Other | Gray, White Non Fibrous Heterogeneous |
| 1717806PLM_64 | tile | | | | Dissolved |
| 0018A - B | 12" vinyl floor tile, off-white with grey fleck, Location 125 | None Detected | 3% Cellulose | 97% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_143 | mastic | | | | Dissolved |
| 0018B - A | 12" vinyl floor tile, off-white with grey fleck, Location 125 | None Detected | | 100% Other | Gray, White Non Fibrous Heterogeneous |
| 1717806PLM_65 | tile | | | | Dissolved |
| 0018B - B | 12" vinyl floor tile, off-white with grey fleck, Location 125 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_144 | mastic | | | | Dissolved |
| 0018C - A | 12" vinyl floor tile, off-white with grey fleck, Location 125 | None Detected | | 100% Other | Gray, White Non Fibrous Heterogeneous |
| 1717806PLM_66 | tile - ashed | | | | Dissolved |
| 0018C - B | 12" vinyl floor tile, off-white with grey fleck, Location 125 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_145 | mastic | | | | Dissolved |
| 0019A | 1' acoustic ceiling tile, random pinhole pattern, Principals Office | None Detected | 90% Mineral Wool | 10% Other | White Fibrous Heterogeneous |
| 1717806PLM_67 | ceiling tile only | | | | Teased |
| 0019B - A | 1' acoustic ceiling tile, random pinhole pattern, Location 123 | None Detected | 90% Mineral Wool | 10% Other | White Fibrous Heterogeneous |
| 1717806PLM_68 | ceiling tile | | | | Teased |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|---------------|--------------------|------------------------|--|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0019B - B | 1' acoustic ceiling tile, random pinhole pattern, Location 123 | None Detected | | 100% Other | Brown Non Fibrous Homogeneous |
| 1717806PLM_146 | mastic | | | | Dissolved |
| 0019C - A | 1' acoustic ceiling tile, random pinhole pattern, Location 225 | None Detected | 90% Mineral Wool | 10% Other | White Fibrous Heterogeneous |
| 1717806PLM_69 | ceiling tile | | | | Teased |
| 0019C - B | 1' acoustic ceiling tile, random pinhole pattern, Location 225 | None Detected | | 100% Other | Brown Non Fibrous Homogeneous |
| 1717806PLM_147 | mastic | | | | Dissolved |
| 0020A - A | 12" red vinyl floor tiles, Location 124 | None Detected | | 100% Other | Red Non Fibrous Heterogeneous |
| 1717806PLM_70 | tile | | | | Dissolved |
| 0020A - B | 12" red vinyl floor tiles, Location 124 | None Detected | | 100% Other | White, Black Non Fibrous Heterogeneous |
| 1717806PLM_148 | mastic/ leveling | | | | Crushed, Dissolved |
| 0020B - A | 12" red vinyl floor tiles, Location 124 | None Detected | | 100% Other | Red Non Fibrous Heterogeneous |
| 1717806PLM_71 | tile | | | | Dissolved |
| 0020B - B | 12" red vinyl floor tiles, Location 124 | None Detected | | 100% Other | White, Black Non Fibrous Heterogeneous |
| 1717806PLM_149 | mastic/ leveling | | | | Crushed, Dissolved |
| 0020C - A | 12" red vinyl floor tiles, Location 124 | None Detected | | 100% Other | Red Non Fibrous Heterogeneous |
| 1717806PLM_72 | tile - ashed | | | | Ashed |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|---------------|--------------------|------------------------|--|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0020C - B | 12" red vinyl floor tiles, Location 124 | None Detected | | 100% Other | White, Black Non Fibrous Heterogeneous |
| 1717806PLM_150 | mastic/ leveling | | | | Crushed, Dissolved |
| 0021A - A | 12" vinyl floor tiles, grey with white and grey fleck, Location 129 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_73 | tile | | | | Dissolved |
| 0021A - B | 12" vinyl floor tiles, grey with white and grey fleck, Location 129 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_151 | mastic | | | | Dissolved |
| 0021B - A | 12" vinyl floor tiles, grey with white and grey fleck, Location 129 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_74 | tile | | | | Dissolved |
| 0021B - B | 12" vinyl floor tiles, grey with white and grey fleck, Location 129 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_152 | mastic | | | | Dissolved |
| 0021C - A | 12" vinyl floor tiles, grey with white and grey fleck, Location 129 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_75 | tile - ashed | | | | Ashed |
| 0021C - B | 12" vinyl floor tiles, grey with white and grey fleck, Location 129 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_153 | mastic | | | | Dissolved |
| 0022A - A | 12" vinyl floor tiles, beige with white and beige blotches, Location 111 | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous |
| 1717806PLM_76 | tile | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|---------------|--------------------|------------------------|---------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0022A - B | 12" vinyl floor tiles, beige with white and beige blotches, Location 111 | None Detected | 2% Cellulose | 98% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_154 | mastic | | | | Dissolved |
| 0022B - A | 12" vinyl floor tiles, beige with white and beige blotches, Location 114 | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous |
| 1717806PLM_77 | tile | | | | Dissolved |
| 0022B - B | 12" vinyl floor tiles, beige with white and beige blotches, Location 114 | None Detected | 2% Cellulose | 98% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_155 | mastic | | | | Dissolved |
| 0022C - A | 12" vinyl floor tiles, beige with white and beige blotches, Location 207 | None Detected | | 100% Other | Beige Non Fibrous Heterogeneous |
| 1717806PLM_78 | tile - ashed | | | | Ashed |
| 0022C - B | 12" vinyl floor tiles, beige with white and beige blotches, Location 207 | None Detected | 2% Cellulose | 98% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_156 | mastic | | | | Dissolved |
| 0023A - A | 12" vinyl floor tiles, turquoise with white fleck, Location 116 | None Detected | | 100% Other | Aqua Non Fibrous Heterogeneous |
| 1717806PLM_79 | tile | | | | Dissolved |
| 0023A - B | 12" vinyl floor tiles, turquoise with white fleck, Location 116 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_157 | mastic | | | | Dissolved |
| 0023B - A | 12" vinyl floor tiles, turquoise with white fleck, Location 228 | None Detected | | 100% Other | Aqua Non Fibrous Heterogeneous |
| 1717806PLM_80 | tile | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|---------------|--------------------|------------------------|---------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0023B - B | 12" vinyl floor tiles, tourquise with white fleck, Location 228 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_158 | mastic | | | | Dissolved |
| 0023C - A | 12" vinyl floor tiles, tourquise with white fleck, Location 116 | None Detected | | 100% Other | Aqua Non Fibrous Heterogeneous |
| 1717806PLM_81 | tile - ashed | | | | Ashed |
| 0023C - B | 12" vinyl floor tiles, tourquise with white fleck, Location 116 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_159 | mastic | | | | Dissolved |
| 0024A - A | 12" vinyl floor ties, beige with a few white and brown flecks, Location 139 | 3% Chrysotile | | 97% Other | Beige Non Fibrous Heterogeneous |
| 1717806PLM_82 | tile | | | | Dissolved |
| 0024A - B | 12" vinyl floor ties, beige with a few white and brown flecks, Location 139 | None Detected | 2% Cellulose | 98% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_160 | mastic | | | | Dissolved |
| 0024B - A | 12" vinyl floor ties, beige with a few white and brown flecks, Location 182 | Not Analyzed | | | |
| 1717806PLM_83 | tile | | | | |
| 0024B - B | 12" vinyl floor ties, beige with a few white and brown flecks, Location 182 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_161 | mastic | | | | Dissolved |
| 0024C - A | 12" vinyl floor ties, beige with a few white and brown flecks, Location 182 | Not Analyzed | | | |
| 1717806PLM_84 | tile | | | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|----------------|--------------------|------------------------|--|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0024C - B | 12" vinyl floor ties, beige with a few white and brown flecks, Location 182 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_162 | mastic | | | | Dissolved |
| 0025A | Parging cement, Location 139, 1974 portion | 30% Chrysotile | 10% Cellulose | 60% Other | White Fibrous Heterogeneous |
| 1717806PLM_85 | | | | | Teased |
| 0025B | Parging cement, Location 139, 1974 portion | Not Analyzed | | | |
| 1717806PLM_86 | | | | | |
| 0025C | Parging cement, Location 139, 1974 portion | Not Analyzed | | | |
| 1717806PLM_87 | | | | | |
| 0026A - A | 12" vinyl floor tiles, off-white black and grey streaks, Location 187 | 3% Chrysotile | | 97% Other | White, Black Non Fibrous Heterogeneous |
| 1717806PLM_88 | tile | | | | Dissolved |
| 0026A - B | 12" vinyl floor tiles, off-white black and grey streaks, Location 187 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_163 | mastic | | | | Dissolved |
| 0026B - A | 12" vinyl floor tiles, off-white black and grey streaks, Location 187 | Not Analyzed | | | |
| 1717806PLM_89 | tile | | | | |
| 0026B - B | 12" vinyl floor tiles, off-white black and grey streaks, Location 187 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_164 | mastic small sample | | | | Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|---------------|----------------------|------------------------|-----------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0026C - A | 12" vinyl floor tiles, off-white black and grey streaks, Location 135 | Not Analyzed | | | |
| 1717806PLM_90 | tile | | | | |
| 0026C - B | 12" vinyl floor tiles, off-white black and grey streaks, Location 135 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_165 | mastic | | | | Dissolved |
| 0027A | Drywall joint compound, Location 185 | None Detected | | 100% Other | White Non Fibrous Homogeneous |
| 1717806PLM_91 | | | | | Crushed |
| 0027B | Drywall joint compound, Corridor 131 | 2% Chrysotile | | 98% Other | White Non Fibrous Homogeneous |
| 1717806PLM_92 | | | | | Crushed |
| 0027C | Drywall joint compound, Corridor 184 | Not Analyzed | | | |
| 1717806PLM_93 | | | | | |
| 0028A | Vinyl sheet flooring, beige/grey pebbled pattern, Location 131 | None Detected | 60% Synthetic Fibers | 40% Other | Gray Fibrous Heterogeneous |
| 1717806PLM_94 | backing only | | | | Teased |
| 0028B | Vinyl sheet flooring, beige/grey pebbled pattern, Location 131 | None Detected | 30% Synthetic Fibers | 70% Other | Gray, Beige Fibrous Heterogeneous |
| 1717806PLM_95 | | | | | Teased, Dissolved |
| 0028C | Vinyl sheet flooring, beige/grey pebbled pattern, Location 131 | None Detected | 30% Synthetic Fibers | 70% Other | Gray, Beige Fibrous Heterogeneous |
| 1717806PLM_96 | | | | | Teased, Dissolved |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|---------------|--------------------|--------------------------|---------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0029A - A | 12" vinyl floor tile, white with grey fleck, Location 219 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_97 | tile | | | | Dissolved |
| 0029A - B | 12" vinyl floor tile, white with grey fleck, Location 219 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_166 | mastic | | | | Dissolved |
| 0029B - A | 12" vinyl floor tile, white with grey fleck, Location 219 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_98 | tile | | | | Dissolved |
| 0029B - B | 12" vinyl floor tile, white with grey fleck, Location 219 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_167 | mastic | | | | Dissolved |
| 0029C - A | 12" vinyl floor tile, white with grey fleck, Location 219 | None Detected | | 100% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_99 | tile - ashed | | | | Ashed |
| 0029C - B | 12" vinyl floor tile, white with grey fleck, Location 219 | None Detected | | 100% Other | Black Non Fibrous Homogeneous |
| 1717806PLM_168 | mastic | | | | Dissolved |
| 0030A | Ceiling texture, Location 214 | 5% Chrysotile | | 60% Perlite 35% Other | White Non Fibrous Heterogeneous |
| 1717806PLM_100 | | | | | Teased |
| 0030B | Ceiling texture, Location 214 | Not Analyzed | | | |
| 1717806PLM_101 | | | | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|----------------------|--------------------|------------------------|-------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0030C | Ceiling texture, Location 214 | Not Analyzed | | | |
| 1717806PLM_102 | | | | | |
| 0031A | Beige caulking, central portion | 4% Chrysotile | | 96% Other | Gray Non Fibrous Homogeneous |
| 1717806PLM_103 | | | | | Dissolved |
| 0031B | Beige caulking, east elevation | Not Analyzed | | | |
| 1717806PLM_104 | | | | | |
| 0031C | Beige caulking, south elevation | Not Analyzed | | | |
| 1717806PLM_105 | | | | | |
| 0032A | Grey expansion joint sealant, central portion | None Detected | | 100% Other | Gray Non Fibrous Homogeneous |
| 1717806PLM_106 | | | | | Ashed |
| 0032B | Grey expansion joint sealant, east portion | None Detected | | 100% Other | Gray Non Fibrous Homogeneous |
| 1717806PLM_107 | | | | | Ashed |
| 0032C | Grey expansion joint sealant, south portion | None Detected | | 100% Other | Gray Non Fibrous Homogeneous |
| 1717806PLM_108 | | | | | Ashed |
| 0033A - A | Brown door caulking, central portion | None Detected | | 100% Other | Brown Non Fibrous Homogeneous |
| 1717806PLM_109 | <i>brown layer</i> | | | | Ashed |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|--|---------------|--------------------|------------------------|--------------------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0033A - B | Brown door caulking, central portion | None Detected | | 100% Other | Gray Non Fibrous Homogeneous |
| 1717806PLM_169 | gray layer | | | | Ashed |
| 0033B - A | Brown door caulking, north portion | None Detected | | 100% Other | Brown Non Fibrous Homogeneous |
| 1717806PLM_110 | brown layer | | | | Ashed |
| 0033B - B | Brown door caulking, north portion | 2% Chrysotile | | 98% Other | Gray Non Fibrous Homogeneous |
| 1717806PLM_170 | gray layer | | | | Crushed |
| 0033C | Brown door caulking, central portion | Not Analyzed | | | |
| 1717806PLM_111 | | | | | |
| 0034A | Grey exterior canopy texture, west portion at Location 101 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_112 | | | | | Crushed |
| 0034B | Grey exterior canopy texture, west portion at Location 101 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_113 | | | | | Crushed |
| 0034C | Grey exterior canopy texture, west portion at Location 101 | None Detected | | 100% Other | Gray Non Fibrous Heterogeneous |
| 1717806PLM_114 | | | | | Crushed |
| 0035A - A | Black paper in sweatwrap insulation, Location 150 | None Detected | 70% Cellulose | 30% Other | Black Fibrous Heterogeneous |
| 1717806PLM_115 | felt | | | | Teased |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: Pinchin Ltd.
1456 Centennial Drive Suite 2
Kingston, ON K7L 0A5

Attn: Glenn Hendry
Sarah Young

Lab Order ID: 1717806
Analysis ID: 1717806_PLM
Date Received: 8/18/2017
Date Reported: 8/23/2017

Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS

| Sample ID | Description | Asbestos | Fibrous Components | Non-Fibrous Components | Attributes |
|----------------|---|---------------|--------------------|------------------------|-----------------------------|
| Lab Sample ID | Lab Notes | | | | Treatment |
| 0035A - B | Black paper in sweatwrap insulation, Location 150 | 1% Chrysotile | 95% Cellulose | 4% Other | Tan Fibrous Heterogeneous |
| 1717806PLM_171 | paper | | | | Teased |
| 0035B - A | Black paper in sweatwrap insulation, Location 150 | None Detected | 70% Cellulose | 30% Other | Black Fibrous Heterogeneous |
| 1717806PLM_116 | felt | | | | Teased, Dissolved |
| 0035B - B | Black paper in sweatwrap insulation, Location 150 | Not Analyzed | | | |
| 1717806PLM_172 | paper | | | | |
| 0035C - A | Black paper in sweatwrap insulation, Location 150 | None Detected | 70% Cellulose | 30% Other | Black Fibrous Heterogeneous |
| 1717806PLM_117 | felt | | | | Teased, Dissolved |
| 0035C - B | Black paper in sweatwrap insulation, Location 150 | Not Analyzed | | | |
| 1717806PLM_118 | paper | | | | |

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAL. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Sharon Donald (173)

Analyst

Approved Signatory

1717 806

Version 1-15-2012

| | | |
|---|--|--|
| Client: Pinchin Ltd. Contact: Glenn Hendry 135 Ontario Street, Unit# 1 Kingston, ON K7L 0A5 Phone: 613-541-1013 Fax: Email: ghendry@pinchin.com syoung@pinchin.com Project: 200584.017, Farley Ave, Belleville, ON, HPEDSB, Moira SS Client Notes: P.O. #: 200584.017 Date Submitted: 17 August, 2017 Analysis: PLM - Stop Positive TurnAroundTime: 4days | *Instructions: Use Column "B" for your contact info To See an Example Click the bottom Example Tab. Enter samples between "<<" and ">>" Begin Samples with a "<<" "above the first sample and end with a ">>" below the last sample. Only Enter your data on the first sheet "Sheet1" Note: Data 1 and Data 2 are optional fields that do not show up on the official report, however they will be included in the electronic data returned to you to facilitate your reintegration of the report data. | Invoice to: Contact name here Email address here |
| | | Scientific Analytical Institute  4604 Dundas Dr. Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313 Email: lab@sailab.com |

| Sample Number | Data 1 (Lab use only) | Sample Description | Data 2 (Lab use only) |
|---------------|-----------------------|--------------------|-----------------------|
|---------------|-----------------------|--------------------|-----------------------|

| | | | |
|-------|--|--|--|
| << | | | |
| 0001A | | Aircell pipe insulation, Location 150 | |
| 0001B | | Aircell pipe insulation, Location 230 | |
| 0001C | | Aircell pipe insulation, Location 002 | |
| 0002A | | Brown pressed paper insulation, Location 150 | |
| 0002B | | Brown pressed paper insulation, Custodial Office | |
| 0002C | | Brown pressed paper insulation, Location 109 | |
| 0003A | | 9" vinyl floor tiles, various patterns and colours, IT Room at Resource Centre | |
| 0003B | | 9" vinyl floor tiles, various patterns and colours, Location 115 | |
| 0003C | | 9" vinyl floor tiles, various patterns and colours, Location 157 | |
| 0003D | | 9" vinyl floor tiles, various patterns and colours, Location 150 | |
| 0003E | | 9" vinyl floor tiles, various patterns and colours, Custodial at Location 161 | |
| 0004A | | 12" beige vinyl floor tiles, Location 151A | |
| 0004B | | 12" beige vinyl floor tiles, Location 151A | |
| 0004C | | 12" beige vinyl floor tiles, Location 151A | |
| 0005A | | Drywall joint compound, Location 151 | |
| 0005B | | Drywall joint compound, Location 154A | |
| 0005C | | Drywall joint compound, Location 156C | |
| 0005D | | Drywall joint compound, Location 125 | |

Accepted

Rejected

Sheelston 8/18 10A

1717806

| | |
|-------|--|
| 0005E | Drywall joint compound, Location 212 |
| 0005F | Drywall joint compound, Location 129 |
| 0005G | Drywall joint compound, Location 215 |
| 0006A | Parging Cement, 1959 Portion, Location 152 |
| 0006B | Parging Cement, 1959 Portion, Location 230 |
| 0006C | Parging Cement, 1959 Portion, Location 002 |
| 0007A | Brown duct mastic, Location 152 |
| 0007B | Brown duct mastic, Location 152 |
| 0007C | Brown duct mastic, Location 152 |
| 0008A | Parging cement, 1961 portion, Location 153 |
| 0008B | Parging cement, 1961 portion, Location 153 |
| 0008C | Parging cement, 1961 portion, Location 153 |
| 0009A | Smooth plaster, 1959 portion, Location 155 |
| 0009B | Smooth plaster, 1959 portion, Location 160 |
| 0009C | Smooth plaster, 1959 portion, Location 195 |
| 0009D | Smooth plaster, 1959 portion, Location 196 |
| 0009E | Smooth plaster, 1959 portion, Location 195 |
| 0009F | Smooth plaster, 1959 portion, Location 261 |
| 0009G | Smooth plaster, 1959 portion, Location 261 |
| 0010A | 2 x 4 acoustic ceiling tile, dense small and medium pinhole pattern, Location 154A |
| 0010B | 2 x 4 acoustic ceiling tile, dense small and medium pinhole pattern, Location 154A |
| 0010C | 2 x 4 acoustic ceiling tile, dense small and medium pinhole pattern, Location 154A |
| 0011A | 1' x 1; Acoustic ceiling tile, large and medium uniform pinhole, Location 156 |
| 0011B | 1' x 1; Acoustic ceiling tile, large and medium uniform pinhole, Location 157 |
| 0011C | 1' x 1; Acoustic ceiling tile, large and medium uniform pinhole, Location 156 |
| 0012A | Ceiling texture, Location 159 |
| 0012B | Ceiling texture, Location 257 |
| 0012C | Ceiling texture, Location 257 |
| 0013A | 12" vinyl floor tile, red and black checkered pattern, Location 160 |
| 0013B | 12" vinyl floor tile, red and black checkered pattern, Location 160 |
| 0013C | 12" vinyl floor tile, red and black checkered pattern, Location 160 |
| 0014A | Aircell, 1961 portion, Custodial office |
| 0014B | Aircell, 1961 portion, Custodial office |
| 0014C | Aircell, 1961 portion, Custodial office |
| 0015A | 12" vinyl floor tile, beige with brown streaks, Location 163 |
| 0015B | 12" vinyl floor tile, beige with brown streaks, Location 163 |
| 0015C | 12" vinyl floor tile, beige with brown streaks, Location 163 |
| 0016A | Plaster above lockers, Location 194 |
| 0016B | Plaster above lockers, Location 194 |
| 0016C | Plaster above lockers, Location 194 |

1717806

| | |
|-------|--|
| 0016D | Plaster above lockers, Location 194 |
| 0016E | Plaster above lockers, Location 194 |
| 0017A | Light heat shield, Location 002 |
| 0017B | Light heat shield, Location 002 |
| 0017C | Light heat shield, Location 002 |
| 0018A | 12" vinyl floor tile, off-white with grey fleck, Location 125 |
| 0018B | 12" vinyl floor tile, off-white with grey fleck, Location 125 |
| 0018C | 12" vinyl floor tile, off-white with grey fleck, Location 125 |
| 0019A | 1' acoustic ceiling tile, random pinhole pattern, Principals Office |
| 0019B | 1' acoustic ceiling tile, random pinhole pattern, Location 123 |
| 0019C | 1' acoustic ceiling tile, random pinhole pattern, Location 225 |
| 0020A | 12" red vinyl floor tiles, Location 124 |
| 0020B | 12" red vinyl floor tiles, Location 124 |
| 0020C | 12" red vinyl floor tiles, Location 124 |
| 0021A | 12" vinyl floor tiles, grey with white and grey fleck, Location 129 |
| 0021B | 12" vinyl floor tiles, grey with white and grey fleck, Location 129 |
| 0021C | 12" vinyl floor tiles, grey with white and grey fleck, Location 129 |
| 0022A | 12" vinyl floor tiles, beige with white and beige blotches, Location 111 |
| 0022B | 12" vinyl floor tiles, beige with white and beige blotches, Location 114 |
| 0022C | 12" vinyl floor tiles, beige with white and beige blotches, Location 207 |
| 0023A | 12" vinyl floor tiles, turquoise with white fleck, Location 116 |
| 0023B | 12" vinyl floor tiles, turquoise with white fleck, Location 228 |
| 0023C | 12" vinyl floor tiles, turquoise with white fleck, Location 116 |
| 0024A | 12" vinyl floor tiles, beige with a few white and brown flecks, Location 139 |
| 0024B | 12" vinyl floor tiles, beige with a few white and brown flecks, Location 182 |
| 0024C | 12" vinyl floor tiles, beige with a few white and brown flecks, Location 182 |
| 0025A | Parging cement, Location 139, 1974 portion |
| 0025B | Parging cement, Location 139, 1974 portion |
| 0025C | Parging cement, Location 139, 1974 portion |
| 0026A | 12" vinyl floor tiles, off-white black and grey streaks, Location 187 |
| 0026B | 12" vinyl floor tiles, off-white black and grey streaks, Location 187 |
| 0026C | 12" vinyl floor tiles, off-white black and grey streaks, Location 135 |
| 0027A | Drywall joint compound, Location 185 |
| 0027B | Drywall joint compound, Corridor 131 |
| 0027C | Drywall joint compound, Corridor 184 |
| 0028A | Vinyl sheet flooring, beige/grey pebbled pattern, Location 131 |
| 0028B | Vinyl sheet flooring, beige/grey pebbled pattern, Location 131 |
| 0028C | Vinyl sheet flooring, beige/grey pebbled pattern, Location 131 |
| 0029A | 12" vinyl floor tile, white with grey fleck, Location 219 |
| 0029B | 12" vinyl floor tile, white with grey fleck, Location 219 |

1717806

| | |
|-------|--|
| 0029C | 12" vinyl floor tile, white with grey fleck, Location 219 |
| 0030A | Ceiling texture, Location 214 |
| 0030B | Ceiling texture, Location 214 |
| 0030C | Ceiling texture, Location 214 |
| 0031A | Beige caulking, central portion |
| 0031B | Beige caulking, east elevation |
| 0031C | Beige caulking, south elevation |
| 0032A | Grey expansion joint sealant, central portion |
| 0032B | Grey expansion joint sealant, east portion |
| 0032C | Grey expansion joint sealant, south portion |
| 0033A | Brown door caulking, central portion |
| 0033B | Brown door caulking, north portion |
| 0033C | Brown door caulking, central portion |
| 0034A | Grey exterior canopy texture, west portion at Location 101 |
| 0034B | Grey exterior canopy texture, west portion at Location 101 |
| 0034C | Grey exterior canopy texture, west portion at Location 101 |
| 0035A | Black paper in sweatwrap insulation, Location 150 |
| 0035B | Black paper in sweatwrap insulation, Location 150 |
| 0035C | Black paper in sweatwrap insulation, Location 150 |

>>



Your Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Your C.O.C. #: n/a

Attention: Glenn Hendry

Pinchin Ltd
 1456 Centennial Drive
 Suite 2
 Kingston, ON
 CANADA K7P 0K4

Report Date: 2021/10/18
 Report #: R6857108
 Version: 2 - Revision

CERTIFICATE OF ANALYSIS – REVISED REPORT

BV LABS JOB #: C1Q2918
Received: 2021/09/13, 09:41

Sample Matrix: Solid
 # Samples Received: 98

| Analyses | Date | | Laboratory Method | Analytical Method |
|-------------------------------|----------|-----------|-------------------|-------------------|
| | Quantity | Extracted | | |
| Asbestos by PLM - 0.5 RDL (1) | 55 | N/A | 2021/09/20 | EPA 600R-93/116 |
| Asbestos by PLM - 0.5 RDL (1) | 43 | N/A | N/A | EPA 600R-93/116 |

Remarks:
 Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, MELCC, EPA, APHA.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested. This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

Bureau Veritas Laboratories' Asbestos Laboratory is accredited by NVLAP for bulk asbestos analysis by polarized light microscopy, NVLAP Code 600136-0.

This report may not be reproduced, except in full, without the written approval of Bureau Veritas Canada. This report may not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any other agency of the U.S. Government.

Bureau Veritas Laboratories' scope of accreditation includes EPA-600/M4-82-020: "Interim Method for the Determination of Asbestos in Bulk Insulation Samples" and EPA-600/R-93/116: "Method for the Determination of Asbestos in Bulk Building Materials".

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.



Your Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Your C.O.C. #: n/a

Attention: Glenn Hendry

Pinchin Ltd
1456 Centennial Drive
Suite 2
Kingston, ON
CANADA K7P 0K4

Report Date: 2021/10/18
Report #: R6857108
Version: 2 - Revision

CERTIFICATE OF ANALYSIS – REVISED REPORT

BV LABS JOB #: C1Q2918

Received: 2021/09/13, 09:41

(1) P.O.B. - Percent of Bulk

When Asbestos data is reported with other data, this report contains data that are not covered by the NVLAP accreditation.

Encryption Key

Please direct all questions regarding this Certificate of Analysis to your Project Manager.

Antonella Brasil, Senior Project Manager

Email: Antonella.Brasil@bureauveritas.com

Phone# (905)817-5817

=====

BV Labs has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation please refer to the Validation Signature Page.



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0036 A BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 101 | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE930 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous dark yellow mastic | Not Detected | | Non-Fibrous |
| Comment: Another layer is present but not analyzed as requested. | | | | | |

| S 0036 B BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 223 | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE931 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous dark yellow mastic | Not Detected | | Non-Fibrous |
| Comment: Another layer is present but not analyzed as requested. | | | | | |

| S 0036 C BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 225 | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE932 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous dark yellow mastic | Not Detected | | Non-Fibrous |
| Comment: Another layer is present but not analyzed as requested | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0037 A TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161 | | | | | | |
|--|--------------|-----------------------------------|-------------------|--------|---------------------|--------------------|
| Bureau Veritas ID: QQE933 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Chrysotile | <0.50% | | Non-Fibrous |

| S 0037 B TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161 | | | | | | |
|--|--------------|-----------------------------------|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: QQE934 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Not Detected | | | Non-Fibrous |

| S 0037 C TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161 | | | | | | |
|--|--------------|-----------------------------------|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: QQE935 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Not Detected | | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0038 A TEXTURED PLASTER ON WALL, RESOURCE CENTRE 129 | | | | | |
|---|--------------|-----------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE936 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Not Detected | | Non-Fibrous |

| S 0038 B TEXTURED PLASTER ON WALL, STAIRWELL TO RESOURCE CENTRE 129 | | | | | |
|--|--------------|-----------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE937 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Not Detected | | Non-Fibrous |

| S 0038 C TEXTURED PLASTER ON WALL, STAIRWELL TO RESOURCE CENTRE 129 | | | | | |
|--|--------------|-----------------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE938 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey textured plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0039 A PLASTER ON STEEL BEAM, LOBBY 192 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE939 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0039 B PLASTER ON STEEL BEAM, LOBBY 192 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE940 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0039 C PLASTER ON STEEL BEAM, LOBBY 192 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE941 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0040 A FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 187 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE942 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| S 0040 B FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, WEIGHT ROOM 182 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE943 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| S 0040 C FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, OFFICE 180 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE944 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | | | |
|--|--------------|---------------------------|-------------------|----|---------------------|-----|--------------------|
| S 0041 A SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 103 | | | | | | | |
| Bureau Veritas ID: QQE945 | | Date Analyzed: 2021/09/20 | | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Chrysotile | 2% | Cellulose | 10% | Non-Fibrous |

| | | | | | | | |
|--|--|---------------------------|-----------------|--|---------------------|--|--------------------|
| S 0041 B SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, WOOD SHOP 152 | | | | | | | |
| Bureau Veritas ID: QQE946 | | Date Analyzed: 2021/09/20 | | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | | | N/A | | | | |
| | Comment: Not Analyzed - Positive Stop | | | | | | |

| | | | | | | | |
|--|--|---------------------------|-----------------|--|---------------------|--|--------------------|
| S 0041 C SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 250 | | | | | | | |
| Bureau Veritas ID: QQE947 | | Date Analyzed: 2021/09/20 | | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | | | N/A | | | | |
| | Comment: Not Analyzed - Positive Stop | | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0042 A YELLOW PAINT ON CONCRETE BLOCK WALL, CLASSROOM 101 | | | | | | |
|--|--------------|--|-------------------|--------|---------------------|--------------------|
| Bureau Veritas ID: QQE948 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 90 | Non-homogeneous yellow/white paint/plaster | Chrysotile | <0.50% | | Non-Fibrous |
| Layer 2 | 10 | Homogeneous grey concrete | Not Detected | | | Non-Fibrous |

| S 0042 B YELLOW PAINT ON CONCRETE BLOCK WALL, CLASSROOM 217 | | | | | | |
|--|--------------|---|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: QQE949 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 20 | Non-homogeneous white/white paint/plaster | Not Detected | | | Non-Fibrous |
| Layer 2 | 80 | Homogeneous grey concrete | Not Detected | | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0042 C YELLOW PAINT ON BRICK WALL, CORRIDOR 193 | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE950 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 40 | Homogeneous white paint | Not Detected | | Non-Fibrous |
| Layer 2 | 60 | Homogeneous red/brown brick | Not Detected | | Non-Fibrous |

| S 0042 D YELLOW PAINT ON CONCRETE BLOCK WALL, CUSTODIAL ROOM 160 | | | | | |
|---|--------------|---|--------------------------|---------------------|--------------------|
| Bureau Veritas ID: QQE951 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous white/off-white/grey paint/plaster/concrete | Chrysotile <0.50% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0042 E YELLOW PAINT ON CONCRETE BLOCK WALL, MECHANICAL ROOM 282 | | | | | | |
|--|--------------|---|-------------------|--------|---------------------|--------------------|
| Bureau Veritas ID: QQE952 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Non-homogeneous white/off-white paint/plaster | Chrysotile | <0.50% | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey concrete | Not Detected | | | Non-Fibrous |

| S 0042 F YELLOW PAINT ON CONCRETE BLOCK WALL, OFFICE 180 | | | | | | |
|---|--------------|---|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: QQE953 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous white/off-white/grey paint/plaster/concrete | Not Detected | | | Non-Fibrous |

| S 0042 G BLACK PAINT ON CONCRETE BLOCK WALL, STAGE 140 | | | | | | |
|---|--------------|---|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: QQE954 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous black/off-white paint/plaster | Chrysotile | 1% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0043 A ADHESIVE BEHIND BASEBOARD, OFFICE 151 | | | | | |
|---|--------------|----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE955 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous brown adhesive | Not Detected | | Non-Fibrous |

| S 0043 B ADHESIVE BEHIND BASEBOARD, CLASSROOM 158 | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE956 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous yellow adhesive | Not Detected | | Non-Fibrous |

| S 0043 C ADHESIVE BEHIND BASEBOARD, CLASSROOM 187 | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE957 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous yellow adhesive | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|---|--------------|----------------------------------|-----------------|---------------------|--------------------|
| S 0043 D ADHESIVE BEHIND BASEBOARD, OFFICE 181 | | | | | |
| Bureau Veritas ID: QQE958 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous dark yellow adhesive | Not Detected | | Non-Fibrous |

| | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| S 0043 E ADHESIVE BEHIND BASEBOARD, CLASSROOM 115 | | | | | |
| Bureau Veritas ID: QQE959 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous yellow adhesive | Not Detected | | Non-Fibrous |

| | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| S 0043 F ADHESIVE BEHIND BASEBOARD, CLASSROOM 111 | | | | | |
| Bureau Veritas ID: QQE960 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous yellow adhesive | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0043 G ADHESIVE BEHIND BASEBOARD, CLASSROOM 217 | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE961 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous yellow adhesive | Not Detected | | Non-Fibrous |

| S 0044 A TERRAZZO FLOOR, CORRIDOR 190, WEST STAIRWELL | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE962 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white terrazzo floor | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey cementitious material | Not Detected | | Non-Fibrous |

| S 0044 B TERRAZZO FLOOR, CORRIDOR 190 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE963 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white terrazzo floor | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey cementitious material | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0044 C TERRAZZO FLOOR, CORRIDOR 194, STAIRWELL | | | | | |
|---|--------------|---|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE964 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous white/grey terrazzo floor/cementitious material | Not Detected | | Non-Fibrous |

| S 0044 D TERRAZZO FLOOR, CORRIDOR 260 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE965 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 90 | Homogeneous white terrazzo floor | Not Detected | | Non-Fibrous |
| Layer 2 | 10 | Homogeneous grey cementitious material | Not Detected | | Non-Fibrous |

| S 0044 E TERRAZZO FLOOR, CORRIDOR 195 | | | | | |
|--|--------------|---|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE966 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous white/grey terrazzo floor/cementitious material | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0044 F TERRAZZO FLOOR, CORRIDOR 261, WEST STAIRWELL | | | | | |
|--|--------------|---|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE967 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous white/grey terrazzo floor/cementitious material | Not Detected | | Non-Fibrous |

| S 0044 G TERRAZZO FLOOR, CORRIDOR 262 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE968 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 60 | Homogeneous white terrazzo floor | Not Detected | | Non-Fibrous |
| Layer 2 | 40 | Homogeneous grey cementitious material | Not Detected | | Non-Fibrous |

| S 0045 A OFF-WHITE PAINT ON CONCRETE STRUCTURE, CUSTODIAL ROOM 146 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE969 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white paint | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0045 B OFF-WHITE PAINT ON CONCRETE STRUCTURE, CUSTODIAL ROOM 146 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE970 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white paint | Not Detected | | Non-Fibrous |

| S 0045 C OFF-WHITE PAINT ON CONCRETE STRUCTURE, OFFICE 145 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE971 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white paint | Not Detected | | Non-Fibrous |

| S 0045 D OFF-WHITE PAINT ON CONCRETE STRUCTURE, WOOD SHOP 152 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE972 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white paint | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| S 0045 E OFF-WHITE PAINT ON CONCRETE STRUCTURE, CORRIDOR 168 | | | | | |
| Bureau Veritas ID: QQE973 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white paint | Not Detected | | Non-Fibrous |

| | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| S 0046 A LIGHT GREY DUCT MASTIC, CLASSROOM 125 | | | | | |
| Bureau Veritas ID: QQE974 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|--------------------|
| S 0046 B LIGHT GREY DUCT MASTIC, MUSIC ROOM 188 | | | | | |
| Bureau Veritas ID: QQE975 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white caulking | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--|--------------------|
| S 0046 C LIGHT GREY DUCT MASTIC, CLASSROOM 186 | | | | | | |
| Bureau Veritas ID: QQE976 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | | Non-Fibrous |

| | | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|-----|--------------------|
| S 0047 A 1'X1' ACOUSTIC CEILING TILE, RADIO ROOM 156D | | | | | | |
| Bureau Veritas ID: QQE977 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous brown ceiling tile | Not Detected | Cellulose | 90% | Non-Fibrous |

| | | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|-----|--------------------|
| S 0047 B 1'X1' ACOUSTIC CEILING TILE, RADIO ROOM 156D | | | | | | |
| Bureau Veritas ID: QQE978 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous brown ceiling tile | Not Detected | Cellulose | 90% | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | | |
|--|--------------|--------------------------------|-----------------|---------------------|-----|--------------------|
| S 0047 C 1'X1' ACOUSTIC CEILING TILE, COMPUTER LAB 156C | | | | | | |
| Bureau Veritas ID: QQE979 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous brown ceiling tile | Not Detected | Cellulose | 90% | Non-Fibrous |

| | | | | | | |
|---|--------------|-------------------------------|-----------------|---------------------|-----|--------------------|
| S 0048 A 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 223 | | | | | | |
| Bureau Veritas ID: QQE980 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey ceiling tile | Not Detected | Fibrous Glass | 70% | Non-Fibrous |

| | | | | | | |
|---|--------------|-------------------------------|-----------------|---------------------|-----|--------------------|
| S 0048 B 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 224 | | | | | | |
| Bureau Veritas ID: QQE981 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey ceiling tile | Not Detected | Fibrous Glass | 70% | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0048 C 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 102 | | | | | | |
|---|--------------|-------------------------------|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: QQE982 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey ceiling tile | Not Detected | | Fibrous Glass 70% | Non-Fibrous |

| S 0049 A BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CORRIDOR 191 | | | | | | |
|---|--------------|--------------------------------------|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: QQE983 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey/black butyl sealant | Chrysotile | 1% | | Non-Fibrous |

| S 0049 B BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CLASSROOM 187 | | | | | | |
|--|--|---------------------------|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: QQE984 | | Date Analyzed: 2021/09/20 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | | |
| | Comment: Not Analyzed - Positive Stop | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| S 0049 C BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF WEIGHT ROM 182 | | | | | |
| Bureau Veritas ID: QQE985 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | |
|---|--------------|--------------------------------------|----------------------|---------------------|--------------------|
| S 0050 A GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CLASSROOM 104 | | | | | |
| Bureau Veritas ID: QQE986 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey/black butyl sealant | Chrysotile 3% | | Non-Fibrous |

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S 0050 B GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF OFFICE 124 | | | | | |
| Bureau Veritas ID: QQE987 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| S 0050 C GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF OFFICE 124A | | | | | |
| Bureau Veritas ID: QQE988 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S 0051 A GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE | | | | | |
| Bureau Veritas ID: QQE989 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S 0051 B GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE | | | | | |
| Bureau Veritas ID: QQE990 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0051 C GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE991 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| S 0052 A MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CAFETERIA 167 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE992 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

| S 0052 B MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF MANUFACTURING SHOP 153 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE993 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0052 C MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 151B | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE994 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

| S 0052 D MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF GYM 142 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE995 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

| S 0052 E MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF MUSIC ROOM 188 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQE996 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S 0052 F MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 115 | | | | | |
| Bureau Veritas ID: QQE997 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S 0052 G MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 111 | | | | | |
| Bureau Veritas ID: QQE998 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey mortar | Not Detected | | Non-Fibrous |

| | | | | | |
|--|--------------|--|----------------------|---------------------|--------------------|
| S 0053 A DRYWALL JOINT COMPOUND ON CEILING, CHANGE ROOM 131, SHOWER | | | | | |
| Bureau Veritas ID: QQE999 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile 1% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0053 B DRYWALL JOINT COMPOUND ON CEILING, OFFICE 180, SHOWER | | | | | | |
|---|--------------|--|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: | | QQF000 | | | Date Analyzed: | 2021/09/20 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | | Non-Fibrous |

| S 0053 C DRYWALL JOINT COMPOUND ON INTERIOR WALL, RESOURCE CENTRE 129 | | | | | | |
|--|--------------|--|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: | | QQF001 | | | Date Analyzed: | 2021/09/20 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | | Non-Fibrous |

| S 0053 D DRYWALL JOINT COMPOUND ON INTERIOR WALL, OFFICE 129B | | | | | | |
|--|--------------|--|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: | | QQF002 | | | Date Analyzed: | 2021/09/20 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous beige drywall joint compound | Chrysotile | 1% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0053 E DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 187 | | | | | | |
|--|--------------|--|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: | | QQF003 | | | Date Analyzed: | 2021/09/20 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | | Non-Fibrous |

| S 0053 F DRYWALL JOINT COMPOUND ON INTERIOR WALL, MECHANICAL ROOM 280 | | | | | | |
|--|--------------|--|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: | | QQF004 | | | Date Analyzed: | 2021/09/20 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | | Non-Fibrous |

| S 0053 G DRYWALL JOINT COMPOUND ON CEILING, CHANGE ROOM 135, SHOWER | | | | | | |
|--|--------------|--|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: | | QQF005 | | | Date Analyzed: | 2021/09/20 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0054 A DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 126 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF006 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey drywall joint compound | Not Detected | | Non-Fibrous |

| S 0054 B DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 151B | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF007 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

| S 0054 C DRYWALL JOINT COMPOUND ON INTERIOR WALL, RADIO ROOM 156D | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF008 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0054 D DRYWALL JOINT COMPOUND ON INTERIOR WALL, OFFICE 123 | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF009 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

| S 0054 E DRYWALL JOINT COMPOUND ON INTERIOR WALL, MANUFACTURING SHOP 154 | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF010 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

| S 0054 F DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 251 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF011 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0054 G DRYWALL JOINT COMPOUND ON INTERIOR WALL, STORAGE 216 | | | | | | |
|--|--------------|--|-------------------|----|---------------------|--------------------|
| Bureau Veritas ID: | | QQF012 | | | Date Analyzed: | 2021/09/20 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white drywall joint compound | Chrysotile | 1% | | Non-Fibrous |

| S 0055 A DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 226 | | | | | | |
|---|--------------|--|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: | | QQF013 | | | Date Analyzed: | 2021/09/20 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | | Non-Fibrous |

| S 0055 B DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 220 | | | | | | |
|--|--------------|--|-----------------|--|---------------------|--------------------|
| Bureau Veritas ID: | | QQF014 | | | Date Analyzed: | 2021/09/20 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0055 D DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 111 | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF015 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

| S 0055 E DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 112 | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF016 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |

| S 0056 A SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 157 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF017 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0056 B SMOOTH PLASTER CEILING, STORAGE 160 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF018 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0056 C SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 251 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF019 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0056 D SMOOTH PLASTER CEILING, STORAGE 203 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF020 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0056 E SMOOTH PLASTER ON EXTERIOR WALL BELOW RADIATOR, CLASSROOM 202 | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF021 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0057 A SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 104 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF022 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0057 B SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 112 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF023 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0057 C SMOOTH PLASTER ON BULKHEAD, ABOVE LOCKER, CORRIDOR 190 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF024 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0057 D SMOOTH PLASTER ON BULKHEAD, ABOVE LOCKER, CORRIDOR 261 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF025 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C1Q2918
 Report Date: 2021/10/18

Pinchin Ltd
 Client Project #: 200584.061
 Site Location: 275 FARLEY AVENUE, BELLEVILLE
 Sampler Initials: H.M

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S 0057 E SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 217 | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF026 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 50 | Homogeneous white plaster | Not Detected | | Non-Fibrous |
| Layer 2 | 50 | Homogeneous grey plaster | Not Detected | | Non-Fibrous |

| S 0055 C DRYWALL JOINT COMPOUND, INTERIOR WALL, CLASSROOM 219 | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| Bureau Veritas ID: QQF027 | | Date Analyzed: 2021/09/20 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white drywall joint compound | Not Detected | | Non-Fibrous |
| Comment: This is sample 55C, but bag is labelled 22C | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE930
Sample ID: S 0036 A BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 101
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE931
Sample ID: S 0036 B BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 223
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE932
Sample ID: S 0036 C BROWN MASTIC BEHIND 1'X1' ACOUSTIC CEILING TILE, CLASSROOM 225
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE933
Sample ID: S 0037 A TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE933 Dup
Sample ID: S 0037 A TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE934
Sample ID: S 0037 B TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE935
Sample ID: S 0037 C TEXTURED PLASTER ON CEILING, MECHANICAL ROOM 161
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE936
Sample ID: S 0038 A TEXTURED PLASTER ON WALL, RESOURCE CENTRE 129
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE937
Sample ID: S 0038 B TEXTURED PLASTER ON WALL, STAIRWELL TO RESOURCE CENTRE 129
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE938
Sample ID: S 0038 C TEXTURED PLASTER ON WALL, STAIRWELL TO RESOURCE CENTRE 129
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE939
Sample ID: S 0039 A PLASTER ON STEEL BEAM, LOBBY 192
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE940
Sample ID: S 0039 B PLASTER ON STEEL BEAM, LOBBY 192
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE941
Sample ID: S 0039 C PLASTER ON STEEL BEAM, LOBBY 192
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE942
Sample ID: S 0040 A FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 187
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE942 Dup
Sample ID: S 0040 A FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 187
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE943
Sample ID: S 0040 B FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, WEIGHT ROOM 182
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE944
Sample ID: S 0040 C FIRM GREY CAULKING ON INTERIOR WINDOW FRAME, OFFICE 180
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE945
Sample ID: S 0041 A SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 103
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE946
Sample ID: S 0041 B SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, WOOD SHOP 152
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE947
Sample ID: S 0041 C SOFT GREY CAULKING ON INTERIOR WINDOW FRAME, CLASSROOM 250
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE948
Sample ID: S 0042 A YELLOW PAINT ON CONCRETE BLOCK WALL, CLASSROOM 101
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE949
Sample ID: S 0042 B YELLOW PAINT ON CONCRETE BLOCK WALL, CLASSROOM 217
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE950
Sample ID: S 0042 C YELLOW PAINT ON BRICK WALL, CORRIDOR 193
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE951
Sample ID: S 0042 D YELLOW PAINT ON CONCRETE BLOCK WALL, CUSTODIAL ROOM 160
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE952
Sample ID: S 0042 E YELLOW PAINT ON CONCRETE BLOCK WALL, MECHANICAL ROOM 282
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE952 Dup
Sample ID: S 0042 E YELLOW PAINT ON CONCRETE BLOCK WALL, MECHANICAL ROOM 282
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE953
Sample ID: S 0042 F YELLOW PAINT ON CONCRETE BLOCK WALL, OFFICE 180
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE954
Sample ID: S 0042 G BLACK PAINT ON CONCRETE BLOCK WALL, STAGE 140
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE955
Sample ID: S 0043 A ADHESIVE BEHIND BASEBOARD, OFFICE 151
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE956
Sample ID: S 0043 B ADHESIVE BEHIND BASEBOARD, CLASSROOM 158
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE957
Sample ID: S 0043 C ADHESIVE BEHIND BASEBOARD, CLASSROOM 187
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE958
Sample ID: S 0043 D ADHESIVE BEHIND BASEBOARD, OFFICE 181
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE959
Sample ID: S 0043 E ADHESIVE BEHIND BASEBOARD, CLASSROOM 115
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE960
Sample ID: S 0043 F ADHESIVE BEHIND BASEBOARD, CLASSROOM 111
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE961
Sample ID: S 0043 G ADHESIVE BEHIND BASEBOARD, CLASSROOM 217
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE962
Sample ID: S 0044 A TERRAZZO FLOOR, CORRIDOR 190, WEST STAIRWELL
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE962 Dup
Sample ID: S 0044 A TERRAZZO FLOOR, CORRIDOR 190, WEST STAIRWELL
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE963
Sample ID: S 0044 B TERRAZZO FLOOR, CORRIDOR 190
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE964
Sample ID: S 0044 C TERRAZZO FLOOR, CORRIDOR 194, STAIRWELL
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE965
Sample ID: S 0044 D TERRAZZO FLOOR, CORRIDOR 260
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE966
Sample ID: S 0044 E TERRAZZO FLOOR, CORRIDOR 195
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE967
Sample ID: S 0044 F TERRAZZO FLOOR, CORRIDOR 261, WEST STAIRWELL
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE968
Sample ID: S 0044 G TERRAZZO FLOOR, CORRIDOR 262
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE969
Sample ID: S 0045 A OFF-WHITE PAINT ON CONCRETE STRUCTURE, CUSTODIAL ROOM 146
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE970
Sample ID: S 0045 B OFF-WHITE PAINT ON CONCRETE STRUCTURE, CUSTODIAL ROOM 146
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE971
Sample ID: S 0045 C OFF-WHITE PAINT ON CONCRETE STRUCTURE, OFFICE 145
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE972
Sample ID: S 0045 D OFF-WHITE PAINT ON CONCRETE STRUCTURE, WOOD SHOP 152
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE972 Dup
Sample ID: S 0045 D OFF-WHITE PAINT ON CONCRETE STRUCTURE, WOOD SHOP 152
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587253 | N/A | | Monika Vogt |

Bureau Veritas ID: QQE973
Sample ID: S 0045 E OFF-WHITE PAINT ON CONCRETE STRUCTURE, CORRIDOR 168
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE974
Sample ID: S 0046 A LIGHT GREY DUCT MASTIC, CLASSROOM 125
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE975
Sample ID: S 0046 B LIGHT GREY DUCT MASTIC, MUSIC ROOM 188
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE976
Sample ID: S 0046 C LIGHT GREY DUCT MASTIC, CLASSROOM 186
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE977
Sample ID: S 0047 A 1'X1' ACOUSTIC CEILING TILE, RADIO ROOM 156D
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE978
Sample ID: S 0047 B 1'X1' ACOUSTIC CEILING TILE, RADIO ROOM 156D
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE979
Sample ID: S 0047 C 1'X1' ACOUSTIC CEILING TILE, COMPUTER LAB 156C
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE980
Sample ID: S 0048 A 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 223
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE981
Sample ID: S 0048 B 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 224
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE982
Sample ID: S 0048 C 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 102
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE982 Dup
Sample ID: S 0048 C 1'X1' ACOUSTIC CEILING TILE, MEDIUM AND LARGE PINHOLES WITH FLECKS, CLASSROOM 102
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE983
Sample ID: S 0049 A BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CORRIDOR 191
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE984
Sample ID: S 0049 B BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CLASSROOM 187
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE985
Sample ID: S 0049 C BLACK BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF WEIGHT ROM 182
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE986
Sample ID: S 0050 A GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF CLASSROOM 104
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



TEST SUMMARY

Bureau Veritas ID: QQE987
Sample ID: S 0050 B GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF OFFICE 124
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE988
Sample ID: S 0050 C GREY BUTYL SEALANT ON EXTERIOR WINDOW, OUTSIDE OF OFFICE 124A
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE989
Sample ID: S 0051 A GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE990
Sample ID: S 0051 B GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE991
Sample ID: S 0051 C GREY CAULKING BETWEEN METAL PANELS BELOW WINDOW, MAIN ENTRANCE
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE992
Sample ID: S 0052 A MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CAFETERIA
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE992 Dup
Sample ID: S 0052 A MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CAFETERIA
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQE993
Sample ID: S 0052 B MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF MANUFACTURING SHOP 153
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE994
Sample ID: S 0052 C MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 115
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE995
Sample ID: S 0052 D MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF GYM 118
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE996
Sample ID: S 0052 E MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF MUSIC ROOM 118
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE997
Sample ID: S 0052 F MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 115
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE998
Sample ID: S 0052 G MORTAR BETWEEN JOINTS OF EXTERIOR BRICK CLADDING, OUTSIDE OF CLASSROOM 115
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQE999
Sample ID: S 0053 A DRYWALL JOINT COMPOUND ON CEILING, CHANGE ROOM 131, SHOWER
Matrix: Solid
Collected: 2021/09/09
Shipped: 2021/09/13
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQF000
Sample ID: S 0053 B DRYWALL JOINT COMPOUND ON CEILING, OFFICE 180, SHOWER
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF001
Sample ID: S 0053 C DRYWALL JOINT COMPOUND ON INTERIOR WALL, RESOURCE CENTRE 129
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF002
Sample ID: S 0053 D DRYWALL JOINT COMPOUND ON INTERIOR WALL, OFFICE 129B
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF002 Dup
Sample ID: S 0053 D DRYWALL JOINT COMPOUND ON INTERIOR WALL, OFFICE 129B
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF003
Sample ID: S 0053 E DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 187
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF004
Sample ID: S 0053 F DRYWALL JOINT COMPOUND ON INTERIOR WALL, MECHANICAL ROOM 280
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF005
Sample ID: S 0053 G DRYWALL JOINT COMPOUND ON CEILING, CHANGE ROOM 135, SHOWER
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQF006
Sample ID: S 0054 A DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 126
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF007
Sample ID: S 0054 B DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 151B
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF008
Sample ID: S 0054 C DRYWALL JOINT COMPOUND ON INTERIOR WALL, RADIO ROOM 156D
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF009
Sample ID: S 0054 D DRYWALL JOINT COMPOUND ON INTERIOR WALL, OFFICE 123
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF010
Sample ID: S 0054 E DRYWALL JOINT COMPOUND ON INTERIOR WALL, MANUFACTURING SHOP 154
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF011
Sample ID: S 0054 F DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 251
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF012
Sample ID: S 0054 G DRYWALL JOINT COMPOUND ON INTERIOR WALL, STORAGE 216
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQF012 Dup
Sample ID: S 0054 G DRYWALL JOINT COMPOUND ON INTERIOR WALL, STORAGE 216
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF013
Sample ID: S 0055 A DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 226
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF014
Sample ID: S 0055 B DRYWALL JOINT COMPOUND ON INTERIOR WALL, CLASSROOM 220
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF015
Sample ID: S 0055 D DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 111
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF016
Sample ID: S 0055 E DRYWALL JOINT COMPOUND ON BULKHEAD, CLASSROOM 112
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587274 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF017
Sample ID: S 0056 A SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 157
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF018
Sample ID: S 0056 B SMOOTH PLASTER CEILING, STORAGE 160
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |



TEST SUMMARY

Bureau Veritas ID: QQF019
Sample ID: S 0056 C SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 251
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF020
Sample ID: S 0056 D SMOOTH PLASTER CEILING, STORAGE 203
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF021
Sample ID: S 0056 E SMOOTH PLASTER ON EXTERIOR WALL BELOW RADIATOR, CLASSROOM 202
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF021 Dup
Sample ID: S 0056 E SMOOTH PLASTER ON EXTERIOR WALL BELOW RADIATOR, CLASSROOM 202
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF022
Sample ID: S 0057 A SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 104
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF023
Sample ID: S 0057 B SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 112
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF024
Sample ID: S 0057 C SMOOTH PLASTER ON BULKHEAD, ABOVE LOCKER, CORRIDOR 190
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

TEST SUMMARY

Bureau Veritas ID: QQF025
Sample ID: S 0057 D SMOOTH PLASTER ON BULKHEAD, ABOVE LOCKER, CORRIDOR 261
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF026
Sample ID: S 0057 E SMOOTH PLASTER ON COLUMN AT WINDOW, EXTERIOR WALL, CLASSROOM 217
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |

Bureau Veritas ID: QQF027
Sample ID: S 0055 C DRYWALL JOINT COMPOUND, INTERIOR WALL, CLASSROOM 219
Matrix: Solid
Collected: 2021/09/09
Shipped:
Received: 2021/09/13

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 7587284 | N/A | 2021/09/20 | Monika Vogt |



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

GENERAL COMMENTS

Samples can contain very fine asbestos fibres that are below the resolution limits of the PLM. Transmission Electron Microscopy (TEM) is recommended for confirmation of None Detected results.

Revised Report (2021/10/18): ID changed for S0022C to S 0055 C as per client request .

Results relate only to the items tested.



BUREAU
VERITAS

Bureau Veritas Job #: C1Q2918
Report Date: 2021/10/18

Pinchin Ltd
Client Project #: 200584.061
Site Location: 275 FARLEY AVENUE, BELLEVILLE
Sampler Initials: H.M

VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

A handwritten signature in black ink, appearing to read 'J Santos', written over a horizontal line.

Jon Delos Santos, Laboratory Supervisor

BV Labs has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation please refer to the Validation Signature Page.



Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

March 21, 2024

HPEDSB

Attention: **Melanie Morrish**

Lab Reference No.: **b310536**

Client Project Name: **Eastside Secondary School**

Client Project No.: **N/A**

Date Received: **March 21, 2024**

Date Analyzed: **March 21, 2024**

Analyst(s): **C. Luong**

Samples submitted: **1**

Phases analyzed: **1**

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared with representative portions of material and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold (see chart below) indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with all provincial regulatory requirements (NIOSH 9002, I.R.S.S.T. MA-244). Multiple phases within a sample are analyzed and reported separately.

| Provincial Jurisdiction | Regulatory Threshold | Provincial Jurisdiction | Regulatory Threshold |
|--|----------------------|--|-----------------------------|
| Ontario, British Columbia, Nova Scotia | 0.5% | PEI, NWT, Yukon, Nunavut, Newfoundland and Labrador, and New Brunswick | 1% |
| Quebec | 0.1% | Saskatchewan | 0.5% friable 1% non-friable |
| Alberta | Undefined | Manitoba | 0.1% friable 1% non-friable |

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested. If you have any questions, please feel free to contact me.

Yours truly,

NOTE: This test report may not be reproduced, except in full, without the written approval of the laboratory. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. This report is valid only when signed in blue ink by the analyst and the laboratory manager. Vinyl asbestos floor tiles contain very fine fibres of asbestos and may be missed by some laboratories using the PLM method. Internal verification studies performed by Pinchin indicate that the chance of missing asbestos in floor tiles is no higher than about 2%. The vinyl tile study and laboratory documentation on measurement uncertainty are available upon request. The analysis of dust samples by PLM cannot be used as an indicator of past or present airborne asbestos fibre levels.



Pinchin Ltd. Asbestos Laboratory
Certificate of Analysis

Client Project Name: Eastside Secondary School
Client Project No.: N/A
Prepared For: Melanie Morrish

Lab Reference No.: b310536
Date Analyzed: March 21, 2024

BULK SAMPLE ANALYSIS

| SAMPLE IDENTIFICATION | SAMPLE DESCRIPTION | % COMPOSITION (VISUAL ESTIMATE) | |
|--|--|---------------------------------|-------------------------------|
| | | ASBESTOS | OTHER |
| 1 Cement transite board - Greenhouse | Homogeneous, grey, hard, cementitious transite material. | Chrysotile 10-25% | Non-Fibrous Material > 75% |

Reviewed by:


Digitally signed by
Pinchin Ltd.
Date: 2024.03.21
14:06:39-04'00'

Reporting Analyst:


Digitally signed by
Pinchin Ltd.
Date: 2024.03.21
14:06:52-04'00'



Pinchin Ltd. Asbestos Laboratory *Certificate of Analysis*

Project No.: 0200584.087
Prepared For: C. Wright / L. Skoblenick

Lab Reference No.: b311687
Analyst(s): E. Cianni / K. Cockburn

Date Received: April 11, 2024 **Samples Submitted:** 6
Date Analyzed: April 18, 2024 **Phases Analyzed:** 8

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project No.: 0200584.087
Prepared For: C. Wright / L. Skoblenick

Lab Reference No.: b311687
Date Analyzed: April 18, 2024

BULK SAMPLE ANALYSIS

| SAMPLE IDENTIFICATION | SAMPLE DESCRIPTION | % COMPOSITION (VISUAL ESTIMATE) | |
|---|--|---------------------------------|--|
| | | ASBESTOS | OTHER |
| S0070A Ceiling, Cement Product, Siporex, Loc: 153, Autoshop | 2 Phases: a) Homogeneous, off-white, porous, cementitious material. | None Detected | |
| | b) Homogeneous, green, coating material under white paint. | Chrysotile | 0.5-5% Non-Fibrous Material > 75% |
| S0070B Ceiling, Cement Product, Siporex, Loc: 153, Autoshop | 2 Phases: a) Homogeneous, off-white, porous, cementitious material. | None Detected | |
| | b) Homogeneous, green, coating material under white paint. | Not Analyzed | |
| Comments: | Analysis of phase b) was stopped due to a previous positive result. | | |
| S0070C Ceiling, Cement Product, Siporex, Loc: 153, Autoshop | 2 Phases: a) Homogeneous, off-white, porous, cementitious material. | None Detected | |
| | b) Homogeneous, green, coating material under white paint. | Not Analyzed | |
| Comments: | Analysis of phase b) was stopped due to a previous positive result. | | |
| S0071A Column, Plaster, Loc: 153, Autoshop | 2 Phases: a) Homogeneous, beige, plaster material. | None Detected | |
| | b) Homogeneous, green, yellow, black, and white, coating material. | Chrysotile | 0.5-5% Vermiculite 10-25% Other Non-Fibrous > 75% |
| | | | Non-Fibrous Material > 75% |



**Pinchin Ltd. Asbestos Laboratory
Certificate of Analysis**

Project No.: 0200584.087
Prepared For: C. Wright / L. Skoblenick

Lab Reference No.: b311687
Date Analyzed: April 18, 2024

BULK SAMPLE ANALYSIS

| SAMPLE IDENTIFICATION | SAMPLE DESCRIPTION | % COMPOSITION (VISUAL ESTIMATE) | |
|---|--|---------------------------------|---|
| | | ASBESTOS | OTHER |
| S0071B Column,Plaster,Loc:153, Autoshop | 2 Phases: a) Homogeneous, beige, plaster material. b) Homogeneous, green, yellow, black, and white, coating material. | None Detected | Vermiculite 10-25% Other Non-Fibrous > 75% Not Analyzed |
| Comments: | Analysis of phase b) was stopped due to a previous positive result. | | |
| S0071C Column,Plaster,Loc:153, Autoshop | 2 Phases: a) Homogeneous, beige, plaster material. b) Homogeneous, green, yellow, black, and white, coating material. | None Detected | Vermiculite 10-25% Other Non-Fibrous > 75% Not Analyzed |
| Comments: | Analysis of phase b) was stopped due to a previous positive result. | | |

Reviewed by:

Digitally signed by
Elizabeth DeCurtis
Date: 2024.04.18
12:04:33-04'00'

Reporting Analyst:

Digitally signed by
Elizabeth DeCurtis
Date: 2024.04.18
12:04:12-04'00'

Analyzed by: EC
 Reviewed by: [Signature]
 Report Sent by: [Signature]

**Pinchin Ltd. - Asbestos Laboratory
Internal Asbestos Bulk Sample Chain of Custody**

| | | | |
|--|-----------------------------|------------------|-------------------------|
| Client Name: | | Project Address: | ON |
| Portfolio/Building No: | | Pinchin File: | 200584.087 |
| Submitted by: | Chris Wright | Email: | cwright@pinchin.com |
| CC Results to: | Laura Skoblenick | CC Email: | lskoblenick@pinchin.com |
| Date Submitted: | April 10 2024 | Required by: | April 17 2024 |
| # of Samples: | 6 | Priority: | 5 Day Turnaround |
| Year of Building Construction (Mandatory, Years ONLY): | 1961 | | |
| Do NOT Stop on Positive (Sample Numbers): | | | |
| Pinchin Group Company (Mandatory Field): | Pinchin | | |
| HMIS2 Building Reference #: | 125643/20231003031841580022 | | |

To be Completed by Lab Personnel Only:

| | | | |
|------------------------|-------------------|-------|------------------------------------|
| Lab Reference #: | <u>6311687 CA</u> | Time: | 24 hour clock |
| Received by: | <u>EC/K.C</u> | Date: | <u>Apr 18, 2024</u> Month Day Year |
| Name(s) of Analyst(s): | <u>EC/K.C</u> | | |

| Sample Prefix | Sample No. | Sample Suffix | Sample Description/Location (Mandatory) |
|---------------|------------|---------------|---|
| S | 0070 | A | Ceiling, Cement Product, Siporex, Loc: 153, Autoshop <u>a) ND b) CH 0.5-5%</u> |
| S | 0070 | B | Ceiling, Cement Product, Siporex, Loc: 153, Autoshop <u>a) ND b) NA</u> |
| S | 0070 | C | Ceiling, Cement Product, Siporex, Loc: 153, Autoshop <u>a) ND b) NA</u> |
| S | 0071 | A | Column, Plaster, Loc: 153, Autoshop <u>a) ND b) CH 0.5-5%</u> |
| S | 0071 | B | Column, Plaster, Loc: 153, Autoshop <u>a) ND b) NA</u> |
| S | 0071 | C | Column, Plaster, Loc: 153, Autoshop <u>a) ND b) NA</u> |



Pinchin Ltd. Asbestos Laboratory *Certificate of Analysis*

Project No.: 0200584.092
Prepared For: H. MacKillican

Lab Reference No.: b318710
Analyst(s): C. Luong

Date Received: July 18, 2024 **Samples Submitted:** 3
Date Analyzed: July 18, 2024 **Phases Analyzed:** 1

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis for all bulk materials. Please be advised that bulk materials do not include debris, dust, and tape-lift samples, and the analysis and reporting of these materials does not conform with Pinchin Ltd.'s NVLAP accreditation.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project No.: 0200584.092
Prepared For: H. MacKillican
Lab Reference No.: b318710
Date Analyzed: July 18, 2024

BULK SAMPLE ANALYSIS

| SAMPLE IDENTIFICATION | SAMPLE DESCRIPTION | % COMPOSITION (VISUAL ESTIMATE) | |
|---|--|---------------------------------------|---|
| | | ASBESTOS | OTHER |
| S0072A Vermiculite Insulation, Behind Lintel, CLR 111 | Homogeneous, grey, beige, and brown, loose particulate, micaceous material. | Libby Amphibole Confirmed Asbestos | Vermiculite > 75% Other Non-Fibrous 0.5-5% |
| Comments: | This sample originated from Libby Montana (a mine known to be contaminated with amphibole asbestos and is sold under the brand name Zonolite) and was confirmed in our laboratory to contain asbestos fibres. The laboratory does not report a percentage due to the variable asbestos content of the vermiculite from bag to bag or even between sampling locations in the same installation. The overall percentage of asbestos in Libby Vermiculite has been shown to range up to 6% (Atkinson et al. 1982; Amandus et al. 1987). Pinchin recommends that once the material is confirmed to be Libby Zonolite, it be treated as an asbestos containing material (>0.5% asbestos). | | |
| S0072B Vermiculite Insulation, Behind Lintel, CLR 111 | | | Not Analyzed |
| Comments: | Analysis was stopped due to a previous positive result. | | |
| S0072C Vermiculite Insulation, Behind Lintel, CLR 111 | | | Not Analyzed |
| Comments: | Analysis was stopped due to a previous positive result. | | |

Reviewed by:

Digitally signed by
Pinchin Ltd.
Date: 2024.07.18
10:15:49-04'00'

Reporting Analyst:

Digitally signed by
Pinchin Ltd.
Date: 2024.07.18
10:16:06-04'00'



Analyzed by: C.L
 Reviewed by: OK
 Report Sent by: OK

Special Instructions: Stop Work Order in Place at the Site. Please call Halie MacKillican (Project Manager) at 613.483.0691 with verbal results ASAP.

- left message. CL

**Pinchin Ltd. - Asbestos Laboratory
 Internal Asbestos Bulk Sample Chain of Custody**

| | | | |
|--|-------------------|------------------|--------------------------|
| Client Name: | | Project Address: | |
| Portfolio/Building No: | | Pinchin File: | 200584.092 |
| Submitted by: | Halie MacKillican | Email: | hmackillican@pinchin.com |
| CC Results to: | Laura Skoblenick | CC Email: | lskoblenick@pinchin.com |
| Invoice to: | | Invoice Email: | |
| Date Submitted: | July 17 2024 | Required by: | July 18 2024 |
| # of Samples: | 3 | Priority: | Rush Turnaround |
| Year of Building Construction (Mandatory Field): | | | |
| Do NOT Stop on Positive (Sample Numbers): | | | |
| Pinchin Group Company (Mandatory Field): | | Pinchin | |

To be Completed by Lab Personnel Only:

| Lab Reference #: | <u>6318710</u> | Time: | 24 hour clock | | |
|------------------------|----------------|---------------|--|-----------|-------------|
| Received by: | <u>OK</u> | Date: | Month | Day | 2021 |
| Name(s) of Analyst(s): | <u>C.L</u> | | <u>July</u> | <u>18</u> | <u>2024</u> |
| Sample Prefix | Sample No. | Sample Suffix | Sample Description/Location (Mandatory) | | |
| S | 0072 | A | Vermiculite Insulation, Behind Lintel, CLR 111 <i>libby - confirmed</i> | | |
| S | 0072 | B | Vermiculite Insulation, Behind Lintel, CLR 111 <i>- NA -</i> | | |
| S | 0072 | C | Vermiculite Insulation, Behind Lintel, CLR 111 <i>- NA -</i> | | |



Pinchin Ltd. Asbestos Laboratory *Certificate of Analysis*

Project No.: 0200584.092
Prepared For: H. Mackillican

Lab Reference No.: b319411
Analyst(s): A. Wells

Date Received: July 26, 2024 **Samples Submitted:** 6
Date Analyzed: July 26, 2024 **Phases Analyzed:** 3

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis for all bulk materials. Please be advised that bulk materials do not include debris, dust, and tape-lift samples, and the analysis and reporting of these materials does not conform with Pinchin Ltd.'s NVLAP accreditation.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project No.: 0200584.092
Prepared For: H. Mackillican

Lab Reference No.: b319411
Date Analyzed: July 26, 2024

BULK SAMPLE ANALYSIS

| SAMPLE IDENTIFICATION | SAMPLE DESCRIPTION | % COMPOSITION (VISUAL ESTIMATE) | | | |
|--|---|---------------------------------|--------|----------------------------------|-----------------|
| | | ASBESTOS | | OTHER | |
| S0073A Off-white putty between glass panel and window frame, Outdoor Staging Area | 2 Phases: a) Homogeneous, beige, caulking material. | Chrysotile | 0.5-5% | Man-Made Vitreous Fibres | 0.5-5% |
| | b) Homogeneous, beige, adhesive material. | Chrysotile | 0.5-5% | Non-Fibrous Material | > 75% |
| S0073B Off-white putty between glass panel and window frame, Outdoor Staging Area | | | | Not Analyzed | |
| Comments: | Analysis was stopped due to a previous positive result. | | | | |
| S0073C Off-white putty between glass panel and window frame, Outdoor Staging Area | | | | Not Analyzed | |
| Comments: | Analysis was stopped due to a previous positive result. | | | | |
| S0074A Grey cementitious material on metal window frame, Outdoor Staging Area | Homogeneous, beige, hard, cementitious material. | Actinolite/Tremolite | 0.5-5% | Vermiculite Other Non-Fibrous | 10-25% > 75% |
| S0074B Grey cementitious material on metal window frame, Outdoor Staging Area | | | | Not Analyzed | |
| Comments: | Analysis was stopped due to a previous positive result. | | | | |



**Pinchin Ltd. Asbestos Laboratory
Certificate of Analysis**

Project No.: 0200584.092
Prepared For: H. Mackillican
Lab Reference No.: b319411
Date Analyzed: July 26, 2024

BULK SAMPLE ANALYSIS

| SAMPLE IDENTIFICATION | SAMPLE DESCRIPTION | % COMPOSITION (VISUAL ESTIMATE) | |
|--|---|---------------------------------|--------------|
| | | ASBESTOS | OTHER |
| S0074C Grey cementitious material on metal window frame, Outdoor Staging Area | | | Not Analyzed |
| Comments: | Analysis was stopped due to a previous positive result. | | |

Reviewed by:

Digitally signed
by Pinchin Ltd.
Date: 2024.07.26
13:17:35-04'00'

Reporting Analyst:

Digitally signed
by Pinchin Ltd.
Date: 2024.07.26
13:17:57-04'00'



Analyzed by: *AE*
 Reviewed by: *[Signature]*
 Report Sent by: *[Signature]*

Special Instructions:

**Pinchin Ltd. - Asbestos Laboratory
 Internal Asbestos Bulk Sample Chain of Custody**

| | | | |
|--|-------------------|------------------|--|
| Client Name: | | Project Address: | |
| Portfolio/Building No: | | Pinchin File: | 200584.092 |
| Submitted by: | Halie MacKillican | Email: | hmackillican@pinchin.com |
| CC Results to: | Laura Skoblenick | CC Email: | lskoblenick@pinchin.com |
| Invoice to: | | Invoice Email: | |
| Date Submitted: | July 25 2024 | Required by: | July 26 2024 |
| # of Samples: | 6 | Priority: | Rush Turnaround |
| Year of Building Construction (Mandatory Field): | | | |
| Do NOT Stop on Positive (Sample Numbers): | | | |
| Pinchin Group Company (Mandatory Field): Pinchin | | | |

| | | | |
|---|--------------------|-------|--------------------|
| To be Completed by Lab Personnel Only: | | | |
| Lab Reference #: | 6319411 <i>cu.</i> | Time: | 24 hour clock |
| Received by: | JUL 26 2024 | Date: | Month Day 2021 |
| Name(s) of Analyst(s): | <i>AW 2007-26</i> | | |

| Sample Prefix | Sample No. | Sample Suffix | Sample Description/Location (Mandatory) |
|---------------|------------|---------------|--|
| S | 0073 | A | Off-white putty between glass panel and window frame, Outdoor Staging Area <i>at CHO-S-51. b) CHO-S-51.</i> |
| S | 0073 | B | Off-white putty between glass panel and window frame, Outdoor Staging Area <i>na</i> |
| S | 0073 | C | Off-white putty between glass panel and window frame, Outdoor Staging Area <i>na</i> |
| S | 0074 | A | Grey cementitious material on metal window frame, Outdoor Staging Area <i>at AC17R a.5-51.</i> |
| S | 0074 | B | Grey cementitious material on metal window frame, Outdoor Staging Area <i>na</i> |

| Sample Prefix | Sample No. | Sample Suffix | Sample Description/Location (Mandatory) |
|---------------|------------|---------------|---|
| S | 0074 | C | Grey cementitious material on metal window frame, Outdoor Staging Area <i>nd</i> |



Pinchin Ltd. Asbestos Laboratory *Certificate of Analysis*

Project No.: 0200584.092
Prepared For: H. Mackillican

Lab Reference No.: b319411
Analyst(s): A. Wells

Date Received: July 26, 2024 **Samples Submitted:** 6
Date Analyzed: July 26, 2024 **Phases Analyzed:** 3

The Pinchin Ltd. Mississauga asbestos laboratory is accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program (NVLAP Lab Code 101270-0) for the 'EPA – 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples,' and the 'EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials'; and meets all requirements of ISO/IEC 17025:2017. The Pinchin asbestos laboratory uses the aforementioned methods of analysis for all bulk materials. Please be advised that bulk materials do not include debris, dust, and tape-lift samples, and the analysis and reporting of these materials does not conform with Pinchin Ltd.'s NVLAP accreditation.

Bulk samples are checked visually and scanned under a stereomicroscope. Slides are prepared and observed under a Polarized Light Microscope (PLM) at magnifications of 40X, 100X or 400X as appropriate. Asbestos fibres are identified by a combination of morphology, colour, refractive index, extinction, sign of elongation, birefringence and dispersion staining colours. A visual estimate is made of the percentage of asbestos present. A reported concentration of less than (<) the regulatory threshold indicates the presence of confirmed asbestos in trace quantities, limited to only a few fibres or fibre bundles in an entire sample. This method complies with provincial regulatory requirements where applicable. Multiple phases within a sample are analyzed and reported separately.

All bulk samples submitted to this laboratory for asbestos analysis are retained for a minimum of three months. Samples may be retrieved, upon request, for re-examination at any time during that period.

This report relates only to the items tested.

This report relates only to the items tested and is valid only when signed with a protected, authorized, electronic signature. This report may not be reproduced, except in full, without the written approval of Pinchin Ltd. The client may not use this report to claim product endorsement by NVLAP or any agency of the U.S. Government. Internal verification studies, quality assurance / control data and laboratory documentation on measurement uncertainty are available upon request.



Pinchin Ltd. Asbestos Laboratory Certificate of Analysis

Project No.: 0200584.092
Prepared For: H. Mackillican

Lab Reference No.: b319411
Date Analyzed: July 26, 2024

BULK SAMPLE ANALYSIS

| SAMPLE IDENTIFICATION | SAMPLE DESCRIPTION | % COMPOSITION (VISUAL ESTIMATE) | | | |
|--|---|---------------------------------|--------|--------------------------|--------|
| | | ASBESTOS | | OTHER | |
| S0073A Off-white putty between glass panel and window frame, Outdoor Staging Area | 2 Phases: a) Homogeneous, beige, caulking material. | Chrysotile | 0.5-5% | Man-Made Vitreous Fibres | 0.5-5% |
| | b) Homogeneous, beige, adhesive material. | Chrysotile | 0.5-5% | Non-Fibrous Material | > 75% |
| S0073B Off-white putty between glass panel and window frame, Outdoor Staging Area | | | | Not Analyzed | |
| Comments: | Analysis was stopped due to a previous positive result. | | | | |
| S0073C Off-white putty between glass panel and window frame, Outdoor Staging Area | | | | Not Analyzed | |
| Comments: | Analysis was stopped due to a previous positive result. | | | | |
| S0074A Grey cementitious material on metal window frame, Outdoor Staging Area | Homogeneous, beige, hard, cementitious material. | Actinolite/Tremolite | 0.5-5% | Vermiculite | 10-25% |
| | | | | Other Non-Fibrous | > 75% |
| S0074B Grey cementitious material on metal window frame, Outdoor Staging Area | | | | Not Analyzed | |
| Comments: | Analysis was stopped due to a previous positive result. | | | | |



**Pinchin Ltd. Asbestos Laboratory
Certificate of Analysis**

Project No.: 0200584.092
Prepared For: H. Mackillican
Lab Reference No.: b319411
Date Analyzed: July 26, 2024

BULK SAMPLE ANALYSIS

| SAMPLE IDENTIFICATION | SAMPLE DESCRIPTION | % COMPOSITION (VISUAL ESTIMATE) | |
|--|---|---------------------------------|--------------|
| | | ASBESTOS | OTHER |
| S0074C Grey cementitious material on metal window frame, Outdoor Staging Area | | | Not Analyzed |
| Comments: | Analysis was stopped due to a previous positive result. | | |

Reviewed by:

Digitally signed
by Pinchin Ltd.
Date: 2024.07.26
13:17:35-04'00'

Reporting Analyst:

Digitally signed
by Pinchin Ltd.
Date: 2024.07.26
13:17:57-04'00'



Analyzed by: *AE*
 Reviewed by: *[Signature]*
 Report Sent by: *[Signature]*

Special Instructions:

**Pinchin Ltd. - Asbestos Laboratory
 Internal Asbestos Bulk Sample Chain of Custody**

| | | | |
|--|-------------------|------------------|--|
| Client Name: | | Project Address: | |
| Portfolio/Building No: | | Pinchin File: | 200584.092 |
| Submitted by: | Halie MacKillican | Email: | hmackillican@pinchin.com |
| CC Results to: | Laura Skoblenick | CC Email: | lskoblenick@pinchin.com |
| Invoice to: | | Invoice Email: | |
| Date Submitted: | July 25 2024 | Required by: | July 26 2024 |
| # of Samples: | 6 | Priority: | Rush Turnaround |
| Year of Building Construction (Mandatory Field): | | | |
| Do NOT Stop on Positive (Sample Numbers): | | | |
| Pinchin Group Company (Mandatory Field): Pinchin | | | |

| | | | |
|---|--------------------|-------|--------------------|
| To be Completed by Lab Personnel Only: | | | |
| Lab Reference #: | 6319411 <i>ai.</i> | Time: | 24 hour clock |
| Received by: | JUL 26 2024 | Date: | Month Day 2021 |
| Name(s) of Analyst(s): | <i>AW 2007-26</i> | | |

| Sample Prefix | Sample No. | Sample Suffix | Sample Description/Location (Mandatory) |
|---------------|------------|---------------|--|
| S | 0073 | A | Off-white putty between glass panel and window frame, Outdoor Staging Area <i>at CHO-S-51. b) CHO-S-51.</i> |
| S | 0073 | B | Off-white putty between glass panel and window frame, Outdoor Staging Area <i>na</i> |
| S | 0073 | C | Off-white putty between glass panel and window frame, Outdoor Staging Area <i>na</i> |
| S | 0074 | A | Grey cementitious material on metal window frame, Outdoor Staging Area <i>at AC17R a.5-51.</i> |
| S | 0074 | B | Grey cementitious material on metal window frame, Outdoor Staging Area <i>na</i> |

| Sample Prefix | Sample No. | Sample Suffix | Sample Description/Location (Mandatory) |
|---------------|------------|---------------|---|
| S | 0074 | C | Grey cementitious material on metal window frame, Outdoor Staging Area <i>nd</i> |



Your Project #: 200584.098
 Site Location: ON
 Your C.O.C. #: 1026639

Attention: Pinchin Asbestos Lab

Pinchin Ltd
 2360 Meadowpine Blvd
 Unit # 2
 Mississauga, ON
 CANADA L5N 6S2

Report Date: 2025/05/07
 Report #: R8533370
 Version: 2 - Revision

CERTIFICATE OF ANALYSIS – REVISED REPORT

BUREAU VERITAS JOB #: C544581

Received: 2025/04/22, 14:25

Sample Matrix: Solid
 # Samples Received: 49

| Analyses | Quantity | Date Extracted | Date Analyzed | Laboratory Method | Analytical Method |
|-------------------------------|-----------------|-----------------------|----------------------|--------------------------|--------------------------|
| Asbestos by PLM - 0.5 RDL (1) | 49 | N/A | 2025/04/29 | COR3SOP-00002 | EPA 600R-93/116 |

Remarks:

Bureau Veritas is accredited to ISO/IEC 17025 for specific parameters on scopes of accreditation. Unless otherwise noted, procedures used by Bureau Veritas are based upon recognized Provincial, Federal or US method compendia such as CCME, EPA, APHA or the Quebec Ministry of Environment.

All work recorded herein has been done in accordance with procedures and practices ordinarily exercised by professionals in Bureau Veritas' profession using accepted testing methodologies, quality assurance and quality control procedures (except where otherwise agreed by the client and Bureau Veritas in writing). All data is in statistical control and has met quality control and method performance criteria unless otherwise noted. All method blanks are reported; unless indicated otherwise, associated sample data are not blank corrected. Where applicable, unless otherwise noted, Measurement Uncertainty has not been accounted for when stating conformity to the referenced standard.

Bureau Veritas liability is limited to the actual cost of the requested analyses, unless otherwise agreed in writing. There is no other warranty expressed or implied. Bureau Veritas has been retained to provide analysis of samples provided by the Client using the testing methodology referenced in this report. Interpretation and use of test results are the sole responsibility of the Client and are not within the scope of services provided by Bureau Veritas, unless otherwise agreed in writing. Bureau Veritas is not responsible for the accuracy or any data impacts, that result from the information provided by the customer or their agent.

Solid sample results, except biota, are based on dry weight unless otherwise indicated. Organic analyses are not recovery corrected except for isotope dilution methods.

Results relate to samples tested. When sampling is not conducted by Bureau Veritas, results relate to the supplied samples tested. This Certificate shall not be reproduced except in full, without the written approval of the laboratory.

Bureau Veritas' Asbestos Laboratory is accredited by NVLAP for bulk asbestos analysis by polarized light microscopy, NVLAP Code 600136-0.

This report may not be reproduced, except in full, without the written approval of Bureau Veritas. This report may not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any other agency of the U.S. Government.

Bureau Veritas' scope of accreditation includes EPA -- 40 CFR Appendix E to Subpart E of Part 763, "Interim Method for the Determination of Asbestos in Bulk Insulation Samples" and EPA-600/R-93/116: "Method for the Determination of Asbestos in Bulk Building Materials".

Reference Method suffix "m" indicates test methods incorporate validated modifications from specific reference methods to improve performance.

* RPDs calculated using raw data. The rounding of final results may result in the apparent difference.

(1) P.O.B. - Percent of Bulk



Your Project #: 200584.098
Site Location: ON
Your C.O.C. #: 1026639

Attention: Pinchin Asbestos Lab

Pinchin Ltd
2360 Meadowpine Blvd
Unit # 2
Mississauga, ON
CANADA L5N 6S2

Report Date: 2025/05/07
Report #: R8533370
Version: 2 - Revision

CERTIFICATE OF ANALYSIS – REVISED REPORT

BUREAU VERITAS JOB #: C544581

Received: 2025/04/22, 14:25

When Asbestos data is reported with other data, this report contains data that are not covered by the NVLAP accreditation.

Encryption Key

Nilushi Mahathantila
Project Manager
07 May 2025 10:36:47

Please direct all questions regarding this Certificate of Analysis to:

Nilushi Mahathantila, Project Manager
Email: Nilushi.Mahathantila@bureauveritas.com
Phone# (905) 817-5700

=====

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S0072A,Wall,Window | | | | | | |
|---|--------------|---------------------------------------|------------------------|---------------------|--------------------|-------------|
| Frame,Caulking,Grey,Loc:1000,Greenhouse Exterior | | | | | | |
| Bureau Veritas ID: | AQDC79 | | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 60 | Homogeneous light grey caulking | Not Detected | Glass Fibres | 0.5% | Non-Fibrous |
| Layer 2 | 40 | Homogeneous grey/light green caulking | Chrysotile 0.5% | | | Non-Fibrous |

| S0072B,Wall,Window | | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|-------------|
| Frame,Caulking,Grey,Loc:1000,Greenhouse Exterior | | | | | | |
| Bureau Veritas ID: | AQDC80 | | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 75 | Homogeneous light grey caulking | Not Detected | Glass Fibres | 0.5% | Non-Fibrous |
| Layer 2 | 25 | Homogeneous grey/light green caulking | N/A | | | |
| | | Comment: Not Analyzed - Positive Stop | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S0072C,Wall,Window Frame,Caulking,Grey,Loc:1000,Greenhouse Exterior | | | | | | |
|--|--------------|---------------------------------------|-----------------|---------------------|--------------------|-------------|
| Bureau Veritas ID: AQDC81 | | Date Analyzed: 2025/04/29 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 90 | Homogeneous light grey caulking | Not Detected | Glass Fibres | 0.5% | Non-Fibrous |
| Layer 2 | 10 | Homogeneous grey/light green caulking | N/A | | | |
| Comment: Not Analyzed - Positive Stop | | | | | | |

| S0073A,Wall,Window Liner,Sealant,Grey, Soft,Loc:1000,Greenhouse Exterior | | | | | | |
|---|--------------|---------------------------------|----------------------|---------------------|--------------------|-------------|
| Bureau Veritas ID: AQDC82 | | Date Analyzed: 2025/04/29 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Homogeneous light grey caulking | Chrysotile 4% | | | Non-Fibrous |

| S0073B,Wall,Window Liner,Sealant,Grey, Soft,Loc:1000,Greenhouse Exterior | | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|--|
| Bureau Veritas ID: AQDC83 | | Date Analyzed: 2025/04/29 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | | | N/A | | | |
| Comment: Not Analyzed - Positive Stop | | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|---|--|--------------------------|-----------------|---------------------|--------------------|
| S0073C,Wall,Window Liner,Sealant,Grey, Soft,Loc:183,Greenhouse | | | | | |
| Bureau Veritas ID: | AQDC84 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| | Comment: Not Analyzed - Positive Stop | | | | |

| | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| S0074A,Wall,Door Frame,Caulking,Grey, Malleable,Loc:1000,Greenhouse Exterior | | | | | |
| Bureau Veritas ID: | AQDC85 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| | | | | | |
|--|--------------|--|-----------------------|---------------------|--------------------|
| S0075A,Wall,Unidentified Material,Brittle, Fibrous, Grey,Loc:1000,Greenhouse Exterior | | | | | |
| Bureau Veritas ID: | AQDC86 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous black/grey tar with fibres | Chrysotile 10% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S0075B,Wall,Unidentified Material,Brittle, Fibrous, Grey,Loc:1000,Greenhouse Exterior | | | | | |
| Bureau Veritas ID: AQDC87 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S0075C,Wall,Unidentified Material,Brittle, Fibrous, Grey,Loc:1000,Greenhouse Exterior | | | | | |
| Bureau Veritas ID: AQDC88 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|
| S0076A,Wall,Tar Paper,Loc:1000,Greenhouse Exterior | | | | | |
| Bureau Veritas ID: AQDC89 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Non-homogeneous brown/black paper with tar | Not Detected | Cellulose 50% | Non-Fibrous |
| Comment: Inseparable layers | | | | | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S0076B,Wall,Tar Paper,Loc:1000,Greenhouse Exterior | | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|-------------|
| Bureau Veritas ID: AQDC90 | | Date Analyzed: 2025/04/29 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Non-homogeneous brown/black paper with tar | Not Detected | Cellulose | 50% | Non-Fibrous |
| Comment: Inseparable layers | | | | | | |

| S0076C,Wall,Tar Paper,Loc:1000,Greenhouse Exterior | | | | | | |
|---|--------------|--|-----------------|---------------------|--------------------|-------------|
| Bureau Veritas ID: AQDC91 | | Date Analyzed: 2025/04/29 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Non-homogeneous brown/black paper with tar | Not Detected | Cellulose | 50% | Non-Fibrous |
| Comment: Inseparable layers | | | | | | |

| S0077A,Flashing,Caulking,Black,Loc:1000,Greenhouse Exterior | | | | | | |
|--|--------------|----------------------------|-----------------|---------------------|--------------------|-------------|
| Bureau Veritas ID: AQDC92 | | Date Analyzed: 2025/04/29 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Homogeneous black caulking | Not Detected | Glass Fibres | 0.5% | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S0077B,Flashing,Caulking,Black,Loc:1000,Greenhouse Exterior | | | | | | |
|--|--------------|----------------------------|-----------------|---------------------|--------------------|-------------|
| Bureau Veritas ID: AQDC93 | | Date Analyzed: 2025/04/29 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Homogeneous black caulking | Not Detected | Glass Fibres | 0.5% | Non-Fibrous |

| S0077C,Flashing,Caulking,Black,Loc:1000,Greenhouse Exterior | | | | | | |
|--|--------------|----------------------------|-----------------|---------------------|--------------------|-------------|
| Bureau Veritas ID: AQDC94 | | Date Analyzed: 2025/04/29 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Homogeneous black caulking | Not Detected | Glass Fibres | 0.5% | Non-Fibrous |

| S0079A,Wall,Window Liner,Sealant,Black,Loc:183,Greenhouse | | | | | | |
|--|--------------|---------------------------------|----------------------|---------------------|--------------------|-------------|
| Bureau Veritas ID: AQDC95 | | Date Analyzed: 2025/04/29 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Homogeneous black/grey caulking | Chrysotile 3% | | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S0079B,Wall,Window Liner,Sealant,Black,Loc:183,Greenhouse | | | | | |
| Bureau Veritas ID: AQDC96 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S0079C,Wall,Window Liner,Sealant,Black,Loc:183,Greenhouse | | | | | |
| Bureau Veritas ID: AQDC97 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S0080A,Wall,Window Liner,Sealant,Grey In Door Window Liner,Loc:194,Corridor | | | | | |
| Bureau Veritas ID: AQDC98 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S0080B,Wall,Window | | | | | |
| Liner,Sealant,Grey,Loc:194,Corridor | | | | | |
| Bureau Veritas ID: | AQDC99 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S0080C,Wall,Window | | | | | |
| Liner,Sealant,Grey,Loc:194,Corridor | | | | | |
| Bureau Veritas ID: | AQDD00 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | | Non-Fibrous |

| | | | | | |
|---|--------------|----------------------------|------------------------|---------------------|--------------------|
| S0081A,Wall,Window,Putty,Beige,Loc:165,Kitchen | | | | | |
| Bureau Veritas ID: | AQDD01 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous beige caulking | Chrysotile 0.5% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S0081B, Wall, Window, Putty, Beige, Loc:165, Kitchen | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: AQDD02 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| S0081C, Wall, Window, Putty, Beige, Loc:165, Kitchen | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|
| Bureau Veritas ID: AQDD03 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| S0082A, Wall, Window, Putty, Off White, Loc:161, Mechanical Room | | | | | |
|---|--------------|--------------------------------|----------------------|---------------------|--------------------|
| Bureau Veritas ID: AQDD04 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous off-white caulking | Chrysotile 1% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | | |
|--------------------------------------|--|--------------------------|-----------------|---------------------|--------------------|------------|
| S0082B,Wall,Window,Putty,Off | | | | | | |
| White,Loc:161,Mechanical Room | | | | | | |
| Bureau Veritas ID: | AQDD05 | | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | | | N/A | | | |
| | Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | | |
|--------------------------------------|--|--------------------------|-----------------|---------------------|--------------------|------------|
| S0082C,Wall,Window,Putty,Off | | | | | | |
| White,Loc:161,Mechanical Room | | | | | | |
| Bureau Veritas ID: | AQDD06 | | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | | | N/A | | | |
| | Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|------------|
| S0083A,Wall,Window | | | | | | |
| Frame,Putty,Grey,Loc:154,Manufacturing Shop | | | | | | |
| Bureau Veritas ID: | AQDD07 | | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Homogeneous grey cementitious material | Not Detected | | Non-Fibrous | |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|--|--------------|--|-----------------|---------------------|--------------------|
| S0083B,Wall,Window | | | | | |
| Frame,Putty,Grey,Loc:154,Manufacturing Shop | | | | | |
| Bureau Veritas ID: | AQDD08 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey cementitious material | Not Detected | | Non-Fibrous |

| | | | | | |
|--|--------------|---------------------------|----------------------|---------------------|--------------------|
| S0083C,Wall,Window,Putty,Grey,Loc:164,Staff Room (Exterior) | | | | | |
| Bureau Veritas ID: | AQDD09 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey caulking | Chrysotile 2% | | Non-Fibrous |

| | | | | | |
|--|--------------|----------------------------|----------------------|---------------------|--------------------|
| S0084A,Wall,Window Liner,Sealant,Black Butyl,Loc:159,Washroom | | | | | |
| Bureau Veritas ID: | AQDD10 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous black caulking | Chrysotile 3% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S0084B,Wall,Window Liner,Sealant,Black Butyl,Loc:159,Washroom | | | | | |
| Bureau Veritas ID: AQDD11 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|
| S0084C,Wall,Window Liner,Sealant,Black Butyl,Loc:159,Washroom | | | | | |
| Bureau Veritas ID: AQDD12 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | |
|---|--------------|-----------------------------|-----------------|---------------------|--------------------|
| S0086A,Wall,Window Frame,Caulking,Silver,Loc:161,Mechanical Room | | | | | |
| Bureau Veritas ID: AQDD13 | | Date Analyzed: 2025/04/29 | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous silver caulking | Not Detected | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|--|--------------|-----------------------------|-----------------|---------------------|--------------------|
| S0086B,Wall,Window | | | | | |
| Frame,Caulking,Silver,Loc:161,Mechanical Room | | | | | |
| Bureau Veritas ID: | AQDD14 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous silver caulking | Not Detected | | Non-Fibrous |

| | | | | | |
|---|--------------|-----------------------------|-----------------|---------------------|--------------------|
| S0086C,Wall,Window | | | | | |
| Frame,Caulking,Silver,Loc:158,Classroom (Exterior) | | | | | |
| Bureau Veritas ID: | AQDD15 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous silver caulking | Not Detected | | Non-Fibrous |

| | | | | | |
|--|--------------|--------------------------------|----------------------|---------------------|--------------------|
| S0087A,Structure,Texture Coat,Loc:195,Corridor (Exterior) | | | | | |
| Bureau Veritas ID: | AQDD16 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous white texture coat | Chrysotile 1% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | |
|--|--|--------------------------|-----------------|---------------------|--------------------|
| S0087B, Structure, Texture Coat, Loc:195, Corridor (Exterior) | | | | | |
| Bureau Veritas ID: | AQDD17 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| | Comment: Not Analyzed - Positive Stop | | | | |

| | | | | | |
|--|--|--------------------------|-----------------|---------------------|--------------------|
| S0087C, Structure, Texture Coat, Loc:195, Corridor (Exterior) | | | | | |
| Bureau Veritas ID: | AQDD18 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | | N/A | | |
| | Comment: Not Analyzed - Positive Stop | | | | |

| | | | | | |
|--|--------------|--|------------------------|---------------------|--------------------|
| S0089A, Wall, Mortar, Loc:1000, Greenhouse Exterior | | | | | |
| Bureau Veritas ID: | AQDD19 | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey cementitious material | Chrysotile 0.5% | | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| S0089B, Wall, Mortar, Loc:1000, Greenhouse Exterior | | | | | |
|--|--------------------------|---------------------------|--|---------------------|--------------------|
| Bureau Veritas ID: AQDD20 | | Date Analyzed: 2025/04/29 | | | |
| <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | N/A | | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| S0089C, Wall, Mortar, Loc:1000, Greenhouse Exterior | | | | | |
|--|--------------------------|---------------------------|--|---------------------|--------------------|
| Bureau Veritas ID: AQDD21 | | Date Analyzed: 2025/04/29 | | | |
| <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | | N/A | | | |
| Comment: Not Analyzed - Positive Stop | | | | | |

| S0090A, Structure, Canopy, Cement Product, Transite, Loc:194, Corridor (Exterior) | | | | | |
|--|--------------------------|---------------------------|--|-----------------------|--------------------|
| Bureau Veritas ID: AQDD22 | | Date Analyzed: 2025/04/29 | | | |
| <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | | <u>Other Fibres</u> | <u>Particulate</u> |
| Layer 1 | 100 | Homogeneous grey transite | | Chrysotile 12% | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | | |
|---|--|--------------------------|-----------------|---------------------|--------------------|------------|
| S0090B,Structure,Canopy,Cement | | | | | | |
| Product,Transite,Loc:194,Corridor (Exterior) | | | | | | |
| Bureau Veritas ID: | AQDD23 | | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | | | N/A | | | |
| | Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | | |
|---|--|--------------------------|-----------------|---------------------|--------------------|------------|
| S0090C,Structure,Canopy,Cement | | | | | | |
| Product,Transite,Loc:194,Corridor (Exterior) | | | | | | |
| Bureau Veritas ID: | AQDD24 | | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | | | N/A | | | |
| | Comment: Not Analyzed - Positive Stop | | | | | |

| | | | | | | |
|--|--------------|---------------------------|-----------------|---------------------|--------------------|-------------|
| S0091A,Wall,Door Frame,Caulking,Grey,Hard,Loc:155,Manufacturing Shop (Exterior) | | | | | | |
| Bureau Veritas ID: | AQDD25 | | | | Date Analyzed: | 2025/04/29 |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | Glass Fibres | <0.50% | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



Bureau Veritas Job #: C544581
 Report Date: 2025/05/07

Pinchin Ltd
 Client Project #: 200584.098
 Site Location: ON
 Sampler Initials: KG

Asbestos Analytical Results

EPA/600R-93/116 by Polarized Light Microscopy

| | | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|-------------|
| S0091B,Wall,Door Frame,Caulking,Grey, Hard,Loc:155,Manufacturing Shop (Exterior) | | | | | | |
| Bureau Veritas ID: AQDD26 | | Date Analyzed: 2025/04/29 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | Glass Fibres | <0.50% | Non-Fibrous |

| | | | | | | |
|---|--------------|---------------------------|-----------------|---------------------|--------------------|-------------|
| S0091C,Wall,Door Frame,Caulking,Grey, Hard,Loc:155,Manufacturing Shop (Exterior) | | | | | | |
| Bureau Veritas ID: AQDD27 | | Date Analyzed: 2025/04/29 | | | | |
| | <u>P.O.B</u> | <u>Sample Morphology</u> | <u>Asbestos</u> | <u>Other Fibres</u> | <u>Particulate</u> | |
| Layer 1 | 100 | Homogeneous grey caulking | Not Detected | Glass Fibres | <0.50% | Non-Fibrous |

The limit of quantitation is 0.50%, although asbestos may be qualitatively detected at concentrations less than 0.50%. Samples for which asbestos is detected at <0.50% are reported as trace, "<0.50%". "Not Detected" indicates that no asbestos fibres were observed.

Calibrated Visual Estimate (%)
 Date Format : yyyy/mm/dd



BUREAU VERITAS

Bureau Veritas Job #: C544581
Report Date: 2025/05/07

Pinchin Ltd
Client Project #: 200584.098
Site Location: ON
Sampler Initials: KG

TEST SUMMARY

Bureau Veritas ID: AQDC79
Sample ID: S0072A,Wall,Window Frame,Caulking,Grey,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC80
Sample ID: S0072B,Wall,Window Frame,Caulking,Grey,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC81
Sample ID: S0072C,Wall,Window Frame,Caulking,Grey,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC82
Sample ID: S0073A,Wall,Window Liner,Sealant,Grey, Soft,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC82 Dup
Sample ID: S0073A,Wall,Window Liner,Sealant,Grey, Soft,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC83
Sample ID: S0073B,Wall,Window Liner,Sealant,Grey, Soft,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC84
Sample ID: S0073C,Wall,Window Liner,Sealant,Grey, Soft,Loc:183,Greenhouse
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |



BUREAU VERITAS

Bureau Veritas Job #: C544581
Report Date: 2025/05/07

Pinchin Ltd
Client Project #: 200584.098
Site Location: ON
Sampler Initials: KG

TEST SUMMARY

Bureau Veritas ID: AQDC85
Sample ID: S0074A,Wall,Door Frame,Caulking,Grey, Malleable,Loc:1000,Greenhouse Exterior
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC86
Sample ID: S0075A,Wall,Unidentified Material,Brittle, Fibrous, Grey,Loc:1000,Greenhouse Exterior
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC87
Sample ID: S0075B,Wall,Unidentified Material,Brittle, Fibrous, Grey,Loc:1000,Greenhouse Exterior
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC88
Sample ID: S0075C,Wall,Unidentified Material,Brittle, Fibrous, Grey,Loc:1000,Greenhouse Exterior
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC89
Sample ID: S0076A,Wall,Tar Paper,Loc:1000,Greenhouse Exterior
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC89 Dup
Sample ID: S0076A,Wall,Tar Paper,Loc:1000,Greenhouse Exterior
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC90
Sample ID: S0076B,Wall,Tar Paper,Loc:1000,Greenhouse Exterior
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |



BUREAU VERITAS

Bureau Veritas Job #: C544581
Report Date: 2025/05/07

Pinchin Ltd
Client Project #: 200584.098
Site Location: ON
Sampler Initials: KG

TEST SUMMARY

Bureau Veritas ID: AQDC91
Sample ID: S0076C,Wall,Tar Paper,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC92
Sample ID: S0077A,Flashing,Caulking,Black,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC93
Sample ID: S0077B,Flashing,Caulking,Black,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC94
Sample ID: S0077C,Flashing,Caulking,Black,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC95
Sample ID: S0079A,Wall,Window Liner,Sealant,Black,Loc:183,Greenhouse
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC96
Sample ID: S0079B,Wall,Window Liner,Sealant,Black,Loc:183,Greenhouse
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC97
Sample ID: S0079C,Wall,Window Liner,Sealant,Black,Loc:183,Greenhouse
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |



BUREAU VERITAS

Bureau Veritas Job #: C544581
Report Date: 2025/05/07

Pinchin Ltd
Client Project #: 200584.098
Site Location: ON
Sampler Initials: KG

TEST SUMMARY

Bureau Veritas ID: AQDC98
Sample ID: S0080A,Wall,Window Liner,Sealant,Grey In Door Window Liner,Loc:194,Corridor
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC99
Sample ID: S0080B,Wall,Window Liner,Sealant,Grey,Loc:194,Corridor
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDC99 Dup
Sample ID: S0080B,Wall,Window Liner,Sealant,Grey,Loc:194,Corridor
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD00
Sample ID: S0080C,Wall,Window Liner,Sealant,Grey,Loc:194,Corridor
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD01
Sample ID: S0081A,Wall,Window,Putty,Beige,Loc:165,Kitchen
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD02
Sample ID: S0081B,Wall,Window,Putty,Beige,Loc:165,Kitchen
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD03
Sample ID: S0081C,Wall,Window,Putty,Beige,Loc:165,Kitchen
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |



BUREAU VERITAS

Bureau Veritas Job #: C544581
Report Date: 2025/05/07

Pinchin Ltd
Client Project #: 200584.098
Site Location: ON
Sampler Initials: KG

TEST SUMMARY

Bureau Veritas ID: AQDD04
Sample ID: S0082A,Wall,Window,Putty,Off White,Loc:161,Mechanical Room
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD05
Sample ID: S0082B,Wall,Window,Putty,Off White,Loc:161,Mechanical Room
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD06
Sample ID: S0082C,Wall,Window,Putty,Off White,Loc:161,Mechanical Room
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD07
Sample ID: S0083A,Wall,Window Frame,Putty,Grey,Loc:154,Manufacturing Shop
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD08
Sample ID: S0083B,Wall,Window Frame,Putty,Grey,Loc:154,Manufacturing Shop
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD09
Sample ID: S0083C,Wall,Window,Putty,Grey,Loc:164,Staff Room (Exterior)
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD09 Dup
Sample ID: S0083C,Wall,Window,Putty,Grey,Loc:164,Staff Room (Exterior)
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |



BUREAU VERITAS

Bureau Veritas Job #: C544581
Report Date: 2025/05/07

Pinchin Ltd
Client Project #: 200584.098
Site Location: ON
Sampler Initials: KG

TEST SUMMARY

Bureau Veritas ID: AQDD10
Sample ID: S0084A,Wall,Window Liner,Sealant,Black Butyl,Loc:159,Washroom
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD11
Sample ID: S0084B,Wall,Window Liner,Sealant,Black Butyl,Loc:159,Washroom
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD12
Sample ID: S0084C,Wall,Window Liner,Sealant,Black Butyl,Loc:159,Washroom
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD13
Sample ID: S0086A,Wall,Window Frame,Caulking,Silver,Loc:161,Mechanical Room
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD14
Sample ID: S0086B,Wall,Window Frame,Caulking,Silver,Loc:161,Mechanical Room
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD15
Sample ID: S0086C,Wall,Window Frame,Caulking,Silver,Loc:158,Classroom (Exterior)
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD16
Sample ID: S0087A,Structure,Texture Coat,Loc:195,Corridor (Exterior)
Matrix: Solid
Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |



TEST SUMMARY

Bureau Veritas ID: AQDD17
Sample ID: S0087B,Structure,Texture Coat,Loc:195,Corridor (Exterior)
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD18
Sample ID: S0087C,Structure,Texture Coat,Loc:195,Corridor (Exterior)
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD19
Sample ID: S0089A,Wall,Mortar,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD19 Dup
Sample ID: S0089A,Wall,Mortar,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD20
Sample ID: S0089B,Wall,Mortar,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD21
Sample ID: S0089C,Wall,Mortar,Loc:1000,Greenhouse Exterior
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9917649 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD22
Sample ID: S0090A,Structure,Canopy,Cement Product,Transite,Loc:194,Corridor (Exterior)
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9918262 | N/A | 2025/04/29 | Dina Yousif |



TEST SUMMARY

Bureau Veritas ID: AQDD23
Sample ID: S0090B,Structure,Canopy,Cement Product,Transite,Loc:194,Corridor (Exterior)
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9918262 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD24
Sample ID: S0090C,Structure,Canopy,Cement Product,Transite,Loc:194,Corridor (Exterior)
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9918262 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD25
Sample ID: S0091A,Wall,Door Frame,Caulking,Grey, Hard,Loc:155,Manufacturing Shop (Exterior)
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9918262 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD26
Sample ID: S0091B,Wall,Door Frame,Caulking,Grey, Hard,Loc:155,Manufacturing Shop (Exterior)
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9918262 | N/A | 2025/04/29 | Dina Yousif |

Bureau Veritas ID: AQDD27
Sample ID: S0091C,Wall,Door Frame,Caulking,Grey, Hard,Loc:155,Manufacturing Shop (Exterior)
Matrix: Solid

Collected: 2025/04/21
Shipped:
Received: 2025/04/22

| Test Description | Instrumentation | Batch | Extracted | Date Analyzed | Analyst |
|---------------------------|-----------------|---------|-----------|---------------|-------------|
| Asbestos by PLM - 0.5 RDL | MIC | 9918262 | N/A | 2025/04/29 | Dina Yousif |



**BUREAU
VERITAS**

Bureau Veritas Job #: C544581
Report Date: 2025/05/07

Pinchin Ltd
Client Project #: 200584.098
Site Location: ON
Sampler Initials: KG

GENERAL COMMENTS

Revised Report (2025/05/07): Client sample ID and morphology for samples S0087A-C changed as per client request.

Results relate only to the items tested.



BUREAU
VERITAS

Bureau Veritas Job #: C544581
Report Date: 2025/05/07

Pinchin Ltd
Client Project #: 200584.098
Site Location: ON
Sampler Initials: KG

VALIDATION SIGNATURE PAGE

The analytical data and all QC contained in this report were reviewed and validated by:

Dina Yousif, Analyst 2

Bureau Veritas has procedures in place to guard against improper use of the electronic signature and have the required "signatories", as per ISO/IEC 17025, signing the reports. For Service Group specific validation, please refer to the Validation Signatures page if included, otherwise available by request. For Department specific Analyst/Supervisor validation names, please refer to the Test Summary section if included, otherwise available by request. This report is authorized by Rodney Major, General Manager responsible for Ontario Environmental laboratory operations.

C544581
2025/04/22 14:25

71026639



NONT-2025-04-4779

Analyzed by: _____

Reviewed by: _____

Report Sent by: _____

**Pinchin Ltd. - Asbestos Laboratory
Internal Asbestos Bulk Sample Chain of Custody**

Special Instructions:

| | | | |
|--|-----------------------------------|-------------------------|-------------------------------|
| Client Name: | | Project Address: | ON |
| Portfolio/Building No: | | Pinchin File: | 200584.098 |
| Submitted by: | Kuzey Gunesli | Email: | kgunesli@pinchin.com |
| CC Email: | _____ Leona Skoblenick | CC Email: | lskoblenick@pinchin.com |
| Date Submitted: | April 21 2025 | Required by: | April 28 2025 |
| # of Samples: | 49 | Priority: | 5 Day Turnaround |
| Year of Building Construction (Mandatory, Years ONLY): | 1961 | | |
| Do NOT Stop on Positive (Sample Numbers): | | | |
| Pinchin Group Company (Mandatory Field): | Pinchin | | |
| HMIS2 Building Reference #: | 148682/202531698235185 | | |
| To be Completed by Lab Personnel Only: <i>Addie Sublime</i> | | | |
| Lab Reference #: | | Time: | 24 hour clock |
| Received by: | <i>APR 22 2025</i> | Date: | <i>2024/04/22</i> |
| Name(s) of Analyst(s): | <i>NSH: JIM SUKUNZ</i> | Date: | <i>14, '24</i> Month Day Year |

| Sample Prefix | Sample No. | Sample Suffix | Sample Description/Location (Mandatory) |
|---------------|------------|---------------|--|
| S | 0072 | A | Wall, Window Frame, Caulking, Grey, Loc:1000, Greenhouse Exterior |
| S | 0072 | B | Wall, Window Frame, Caulking, Grey, Loc:1000, Greenhouse Exterior |
| S | 0072 | C | Wall, Window Frame, Caulking, Grey, Loc:1000, Greenhouse Exterior |
| S | 0073 | A | Wall, Window Liner, Sealant, Grey, Soft, Loc:1000, Greenhouse Exterior |
| S | 0073 | B | Wall, Window Liner, Sealant, Grey, Soft, Loc:1000, Greenhouse Exterior |
| S | 0073 | C | Wall, Window Liner, Sealant, Grey, Soft, Loc:183, Greenhouse |
| S | 0074 | A | Wall, Door Frame, Caulking, Grey, Malleable, Loc:1000, Greenhouse Exterior |

| Sample Prefix | Sample No. | Sample Suffix | Sample Description/Location (Mandatory) |
|---------------|------------|---------------|--|
| S | 0075 | A | Wall, Unidentified Material, Brittle, Fibrous, Grey, Loc:1000, Greenhouse Exterior |
| S | 0075 | B | Wall, Unidentified Material, Brittle, Fibrous, Grey, Loc:1000, Greenhouse Exterior |
| S | 0075 | C | Wall, Unidentified Material, Brittle, Fibrous, Grey, Loc:1000, Greenhouse Exterior |
| S | 0076 | A | Wall, Tar Paper, Loc:1000, Greenhouse Exterior |
| S | 0076 | B | Wall, Tar Paper, Loc:1000, Greenhouse Exterior |
| S | 0076 | C | Wall, Tar Paper, Loc:1000, Greenhouse Exterior |
| S | 0077 | A | Flashing, Caulking, Black, Loc:1000, Greenhouse Exterior |
| S | 0077 | B | Flashing, Caulking, Black, Loc:1000, Greenhouse Exterior |
| S | 0077 | C | Flashing, Caulking, Black, Loc:1000, Greenhouse Exterior |
| S | 0079 | A | Wall, Window Liner, Sealant, Black, Loc:183, Greenhouse |
| S | 0079 | B | Wall, Window Liner, Sealant, Black, Loc:183, Greenhouse |
| S | 0079 | C | Wall, Window Liner, Sealant, Black, Loc:183, Greenhouse |
| S | 0080 | A | Wall, Window Liner, Sealant, Grey In Door Window Liner, Loc:194, Corridor |
| S | 0080 | B | Wall, Window Liner, Sealant, Grey, Loc:194, Corridor |
| S | 0080 | C | Wall, Window Liner, Sealant, Grey, Loc:194, Corridor |
| S | 0081 | A | Wall, Window, Putty, Beige, Loc:165, Kitchen |

| Sample Prefix | Sample No. | Sample Suffix | Sample Description/Location (Mandatory) |
|---------------|------------|---------------|--|
| S | 0081 | B | Wall,Window,Putty,Beige,Loc:165,Kitchen |
| S | 0081 | C | Wall,Window,Putty,Beige,Loc:165,Kitchen |
| S | 0082 | A | Wall,Window,Putty,Off White,Loc:161,Mechanical Room |
| S | 0082 | B | Wall,Window,Putty,Off White,Loc:161,Mechanical Room |
| S | 0082 | C | Wall,Window,Putty,Off White,Loc:161,Mechanical Room |
| S | 0083 | A | Wall,Window Frame,Putty,Grey,Loc:154,Manufacturing Shop |
| S | 0083 | B | Wall,Window Frame,Putty,Grey,Loc:154,Manufacturing Shop |
| S | 0083 | C | Wall,Window,Putty,Grey,Loc:164,Staff Room (Exterior) |
| S | 0084 | A | Wall,Window Liner,Sealant,Black Butyl,Loc:159,Washroom |
| S | 0084 | B | Wall,Window Liner,Sealant,Black Butyl,Loc:159,Washroom |
| S | 0084 | C | Wall,Window Liner,Sealant,Black Butyl,Loc:159,Washroom |
| S | 0086 | A | Wall,Window Frame,Caulking,Silver,Loc:161,Mechanical Room (Exterior) |
| S | 0086 | B | Wall,Window Frame,Caulking,Silver,Loc:161,Mechanical Room (Exterior) |
| S | 0086 | C | Wall,Window Frame,Caulking,Silver,Loc:158,Classroom (Exterior) |
| S | 0087 | A | Structure,Texture Finish - Non Friable,Loc:195,Corridor (Exterior) |
| S | 0087 | B | Structure,Texture Finish - Non Friable,Loc:195,Corridor (Exterior) |

| Sample Prefix | Sample No. | Sample Suffix | Sample Description/Location (Mandatory) |
|---------------|------------|---------------|---|
| S | 0087 | C | Structure,Texture Finish - Non Friable,Loc:195,Corridor (Exterior) |
| S | 0089 | A | Wall,Mortar,Loc:1000,Greenhouse Exterior |
| S | 0089 | B | Wall,Mortar,Loc:1000,Greenhouse Exterior |
| S | 0089 | C | Wall,Mortar,Loc:1000,Greenhouse Exterior |
| S | 0090 | A | Structure,Canopy,Cement Product,Transite,Loc:194,Corridor (Exterior) |
| S | 0090 | B | Structure,Canopy,Cement Product,Transite,Loc:194,Corridor (Exterior) |
| S | 0090 | C | Structure,Canopy,Cement Product,Transite,Loc:194,Corridor (Exterior) |
| S | 0091 | A | Wall,Door Frame,Caulking,Grey, Hard,Loc:155,Manufacturing Shop (Exterior) |
| S | 0091 | B | Wall,Door Frame,Caulking,Grey, Hard,Loc:155,Manufacturing Shop (Exterior) |
| S | 0091 | C | Wall,Door Frame,Caulking,Grey, Hard,Loc:155,Manufacturing Shop (Exterior) |

APPENDIX III
Methodology



1.0 GENERAL

Pinchin conducted an investigation of previously identified asbestos-containing materials (ACM) to evaluate the current condition of all accessible ACM identified in the most recent assessment.

The surveyor made reference to any existing assessment or abatement reports (as provided by the Client).

Materials listed as exclusions in the previous reports have remained as exclusions. Sampling, assessment or verification of excluded materials was not conducted.

Existing sampling data, where available, was reviewed and relied upon.

Where sampling was conducted, sample collection was conducted in accordance with our Standard Operating Procedures.

Analytical results were compared to the following criteria:

| Jurisdiction | Friable | Non-Friable |
|--------------|---------|-------------|
| Ontario | 0.5% | 0.5% |

Where building materials are described in the report as “non-asbestos” or “does not contain asbestos”, this means that either no asbestos was detected by the analytical method utilized in any of the multiple samples or, if detected, it is below the lower limit of an asbestos-containing material in the applicable regulation. Additionally, these terms are used for materials which historically are known to not include asbestos in their manufacturing.

Asbestos materials are evaluated in order to make recommendations regarding remedial work. The priority for remedial action is based on several factors:

- Friability (friable or non-friable)
- Condition (good, fair, poor, debris)
- Accessibility (ranking from accessible to all building users to inaccessible)
- Visibility (whether the material is obscured by other building components)
- Efficiency of the work (for example, if damaged ACM is being removed in an area, it may be most practical to remove all ACM in the area even if it is in good condition)

For a complete description of the Evaluation Criteria and Basis of Recommendations, refer to Annex A.

METHODOLOGY ANNEX A EVALUATION CRITERIA

1.0 EVALUATION CRITERIA AND BASIS OF RECOMMENDATIONS

The detailed asbestos assessment provides information regarding the location, condition, accessibility and friability of the asbestos-containing materials (ACM). In order to make recommendations for compliance with current regulations, Pinchin developed the following criteria.

2.0 EVALUATION OF CONDITION

2.1 Friable Sprayed or Trowelled Fireproofing, Thermal Insulation and Texture Finishes (Surfacing Materials)

To evaluate the condition of ACM sprayed or trowelled on fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes, the following criteria are applied:

| | |
|-------------|---|
| Good | Surface of material shows no significant signs of damage, deterioration or delamination. Good condition includes unencapsulated or unpainted fireproofing or texture finishes, where no or limited delamination or damage is observed, or encapsulated fireproofing or texture finishes where the encapsulant or paint has been applied after the damage or fallout occurred. |
| Poor | A sprayed material that shows signs of significant damage or is significantly delaminating or deteriorating. This may be limited to surface delamination or some portion of the substrate may be exposed. |

In Locations where damage exists in isolated areas, both good and poor condition may be applicable. The extent of each condition will be recorded. Fair condition is not utilized in the evaluation of ACM sprayed or trowelled fireproofing, sprayed or trowelled thermal insulation (non-mechanical), or texture, decorative or acoustic finishes.

The evaluation of the above products above ceilings may be limited by the number of observations and by building components such as ducts or full height walls that obstruct the above ceiling observations.

2.2 Friable Mechanical or Thermal System Insulation (TSI)

To evaluate the condition of mechanical insulation on vessels, boilers, breeching, ducts, pipes, fan units, equipment etc. the following criteria are applied:

| | |
|-------------|---|
| Good | Insulation is completely covered in jacketing and exhibits no evidence of damage or deterioration. No insulation is exposed. Includes conditions where the jacketing has minor damage (i.e. scuffs or stains), but the jacketing is not penetrated. |
|-------------|---|

| | |
|-------------|---|
| Fair | Minor penetrating damage to jacketed insulation (cuts, tears, nicks, deterioration or delamination) or undamaged insulation that has never been jacketed. Insulation is exposed but not showing surface disintegration. The extent of missing insulation ranges from minor to none. Damage can be repaired. |
| Poor | Original insulation jacket is missing, damaged, deteriorated or delaminated. Insulation is exposed and significant areas have been dislodged. Damage cannot be readily repaired. Includes components where insulation may have been removed incompletely. |

The evaluation of mechanical insulation may be limited by the number of observations made and building components such as ducts or full height walls that obstruct observations. It is often not possible to observe each foot of mechanical insulation from all angles.

2.3 Potentially Friable Materials and Miscellaneous Friable Materials

Potentially friable ACM are products that are basically non-friable while in place but have the potential to generate friable dust upon removal or if significantly disturbed without appropriate procedures. These products may become friable if damaged. Potentially friable materials include materials such as acoustic ceiling tiles and plaster. To evaluate the condition of potentially friable materials, the following criteria are applied:

| | |
|-------------|--|
| Good | No significant damage or deterioration. Still serving its intended use as a building material or finish. |
| Fair | Showing signs of some cracking or breakage, but is not deteriorating (e.g. cracked plaster, broken but in place ceiling tile, missing tile or section of plaster etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes. |
| Poor | Significant deterioration or breaking apart of the material. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material has deteriorated to a point it has become friable. Normally potentially friable ACM in Poor condition is not repairable and requires at least localized removal and replacement. |

2.4 Non-Friable Materials

Non-friable ACM cover a wide range of products with a wide variation in their tendency to release dust or asbestos fibres to the air. Many of these materials, (particularly where the matrix is an unweathered bitumen, asphalt or tar material) do not release fibres except in very unusual circumstances or during significant disturbance (e.g. use of abrasive power tools). Others with a cementitious matrix (asbestos-cement products) can more readily release dust due to abrasion, demolition, weathering, etc. The

potential for asbestos release from non-friable ACM is always lower than from friable ACM. To evaluate the condition of non-friable Materials, the following criteria are applied:

| | |
|-------------|---|
| Good | No significant damage or deterioration. Still serving its intended use as a building material or finish. |
| Fair | Showing signs of some cracking or breakage but is not deteriorating (e.g. cracked vinyl floor tile, missing piece of tile or transite, etc.). The condition is such that it is still serving its intended use as a building material or finish but may require repair for mainly cosmetic purposes. |
| Poor | Significant deterioration or breaking apart of the material to the point at which it cannot be repaired, and it will require at least local removal. Material has deteriorated to the point it is not serving its intended use as building material or finish. Material may have deteriorated to a point where traffic or disturbance may cause it to become friable. |

2.5 Evaluation of ACM Debris

The identification of the exact location or presence of debris on the top of ceiling tiles is limited by the number of observations made and the presence of building components such as ducts or full height walls that obstruct observations.

The presence of fallen or dislodged ACM is noted separately from the ACM source and is referred to as Debris. Debris may be friable if from a friable ACM source or a badly deteriorated non-friable ACM source. Debris may also be non-friable (such as fallen pieces of transite sheet or mastic fittings, or broken, dislodged floor tiles).

| | |
|---------------|--|
| Debris | Debris may be friable or non-friable but is always identified as “debris” as the component of an observation and quantified as Poor condition. |
|---------------|--|

2.6 Evaluation of Presumed Asbestos-Containing Material (PACM)

Presumed asbestos-containing materials (PACM), are building materials that may contain asbestos but were not sampled or analyzed due to inaccessibility or the need to perform destructive testing to obtain a reasonable sample set. Evaluation of these materials is based on the assumption that these PACM are asbestos-containing.

A list of PACM is provided in the report and they are generally not included in the detailed room by room reports. Typically, they are excluded because they are inaccessible or present in very small quantities. If PACM are evaluated, Pinchin uses the criteria that correspond with the type (and friability) of the material listed above.

3.0 EVALUATION OF ACCESSIBILITY

The accessibility of building materials known or suspected of being ACM is rated according to the following criteria:

| | |
|--|---|
| Access (A) | Common areas of the building within reach of all building users (approximately 8' - 9' from floor or standard ceiling height). Includes other areas where occupant activities may result in disturbance of material that is not normally within reach from floor level, but may be disturbed by common activities (e.g. gymnasiums, workshops, warehouses.) |
| Access (B) | Areas of the building accessed primarily by Maintenance/Caretaking/Janitorial Staff and within reach without use of a ladder. Includes areas within reach in Boiler Rooms, Electrical Rooms, Janitors Closets, Elevator Rooms, Mechanical Rooms, etc. Includes materials within reach from fixed ladders or catwalks, mezzanines, and accessible pipe chases. |
| Access (C) and Visible | Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Only includes ACM that are visible to view without the removal or opening of other building components such as ceiling tiles or service access panels. |
| Access (C) and not Visible / Limited Visibility | Areas of the building above 8' - 9' where use of a ladder or scaffold is required to reach the ACM. Includes ACM that are not visible or partially visible to view and require the removal of a building component to see, such as ceilings tiles or access panels to view and access. Includes rarely entered crawl spaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. |
| Access (D) | Areas of the building behind inaccessible solid ceiling systems, walls or equipment etc. where demolition of the ceiling, wall or equipment etc. is required to reach the ACM. Material inaccessible due to height or location or is only accessed under unusual situations. Evaluation of condition and extent of ACM is limited or impossible, depending on the surveyor's ability to visually examine materials in Access D. |

4.0 ACTION MATRIX AND DEFINITIONS

Pinchin's evaluation of the viability of a specific asbestos control option is based on the consideration of the friability, condition, accessibility and visibility of a material. The logic used is that damaged ACM located in an area frequently accessed by all building occupants is of a higher priority than damaged ACM located in an infrequently accessed service area. The action matrix considers the potential for fibre release (primarily from friable ACM) and the possible concerns from regulatory bodies and many building occupants to all damaged ACM (including non-friable).

In any building with asbestos, many current regulations require an Asbestos Management Program be implemented. Depending on the condition and the accessibility, more active measures such as repair or removal may be recommended. The following matrix provides guidance for recommended Actions in the absence of renovation or demolition. In the event of construction or maintenance activity which will disturb ACM more aggressive control or removal will be required.

4.1 Action Matrix

The following tables outline the action decisions based on the relationship of assessed factors. Table I applies to friable ACM. Table II applies to non-friable ACM.

Table I Decision Matrix for Friable ACM

| Access | Condition | | | Debris |
|--------------------------------------|-----------------------|-----------------------|----------|----------|
| | Good | Fair | Poor | |
| (A) | Action 5 ¹ | Action 5 ² | Action 3 | Action 1 |
| (B) | Action 7 | Action 6 ³ | Action 3 | Action 1 |
| (C) Visible | Action 7 | Action 6 | Action 3 | Action 2 |
| (C) Not Visible / Limited Visibility | Action 7 | Action 7 | Action 4 | Action 2 |
| (D) | Action 7 | Action 7 | Action 7 | Action 7 |

Table II Decision Matrix for Potentially Friable and Non-Friable ACM

| Access | Condition | | | Debris |
|--------------------------------------|-----------|-----------------------|----------|----------|
| | Good | Fair | Poor | |
| (A) | Action 7 | Action 7 ⁴ | Action 3 | Action 1 |
| (B) | Action 7 | Action 7 | Action 3 | Action 1 |
| (C) Visible | Action 7 | Action 7 | Action 4 | Action 2 |
| (C) Not Visible / Limited Visibility | Action 7 | Action 7 | Action 4 | Action 2 |
| (D) | Action 7 | Action 7 | Action 7 | Action 7 |

¹ If friable ACM in access (A)/Good condition is not proactively removed Action 7 (Manage) is recommended.

² If friable ACM in access (A)/Fair condition is not proactively removed repair is recommended.

³ If friable ACM in access (B)/Fair condition is likely to be disturbed after repair proactive removal is recommended.

⁴ Action 7 is recommended for all non-friable ACM in Fair condition however some clients may wish to repair or take some action primarily for cosmetic reasons

4.2 Action Definitions

The following are the definitions in the Action Matrix Table presented above:

| Action Definitions | |
|---------------------------|---|
| Action 1 | Clean-Up of ACM Debris Restrict access that is likely to cause a disturbance of the ACM Debris and clean up ACM Debris. Utilize appropriate asbestos precautions. |
| Action 2 | Precautions for Access Which may Disturb ACM Debris Use appropriate means to isolate the debris or to limit entry to the area which may disturb the material. At locations where ACM Debris can remain in place in lieu of removal or clean-up (e.g. Debris on top of ceiling tiles or behind lockable door), Utilize appropriate asbestos precautions to enter the area if this will disturb debris. The precautions will be required until the ACM Debris has been cleaned up. |
| Action 3 | ACM Removal Remove ACM. Utilize asbestos procedures appropriate to the scope of the removal work. Until it is removed, restrict access to the material so it is not disturbed. |
| Action 4 | Precautions for Work Which may Disturb ACM in Poor Condition. Utilize appropriate asbestos precautions if ACM may be disturbed by work on or near ACM. This does not require restricting access to the area, only control of work which may contact or disturb the ACM. Removal is the only viable option if work will disturb ACM. |
| Action 5 | Proactive ACM Removal Remove friable ACM where the presence of friable asbestos in Good condition is not desirable. If friable ACM in Fair condition is not removed, then Repair friable ACM. |
| Action 6 | ACM Repair Repair friable ACM in Fair condition which is not likely to be damaged again or disturbed by normal use of the area or room. Pinchin recommends proactive removal if friable ACM is likely to be damaged or disturbed during normal use of the area or room. |
| Action 7 | Asbestos Management Program with Routine Surveillance Implement an Asbestos Management Program, including routine surveillance of ACM. Reassess materials regularly (typically once per year). |

Master Template: Methodology Annex A to Appendix I Evaluation Criteria, HAZ, April 3, 2024

APPENDIX IV
Location Summary Report

Client:Hastings and Prince Edward District School Board
Building Name: Eastside Secondary School
Survey Date:
Building Phases: A: 1959 , B: 1961 , C: 1975

Site: 275 Farley Avenue, Belleville, ON
Last Re-Assessment: 2025-06-09

| Location No. | Name or Description | Area ft ² | Floor No. | Bldg. Phase | Notes |
|--------------|-----------------------------------|----------------------|-----------|-------------|--|
| 0 | Roof | 6000 | ROOF | A | Includes Portion of Phase B addition |
| 1 | Basement, room no. 001 | 150 | 0 | A | |
| 2 | Basement, room no. 002 | 500 | 0 | A | |
| 3 | Exterior | 0 | | A | |
| 4 | Roof B | 0 | Roof | B | |
| 100 | Offices, room no. 124-3 | 400 | 1 | A | Formerly Room 100, Includes Rooms 124E-F and 125A-C |
| 101 | Classroom, room no. 101 | 500 | 1 | A | |
| 102 | Classroom, room no. 102 | 500 | 1 | A | |
| 103 | Classroom, room no. 103 | 500 | 1 | A | |
| 104 | Classroom, room no. 104 | 500 | 1 | A | |
| 105 | Resource Room, room no. 104 | 500 | 1 | A | Formerly Room 105 |
| 106 | Classroom, room no. 106 | 500 | 1 | A | |
| 108 | Guidance, room no. 120 | 600 | 1 | A | Formerly Room 108, Includes Rooms 120A-E |
| 109 | Storage, room no. 121 | 200 | 1 | A | Formerly Room 109, Includes Room 121A |
| 110 | Staff Room, room no. 110 | 300 | 1 | A | Includes Rooms 110A-C |
| 111 | Classroom, room no. 111 | 500 | 1 | A | |
| 112 | Classroom, room no. 112 | 500 | 1 | A | |
| 113 | Classroom, room no. 113 | 500 | 1 | A | |
| 114 | Classroom, room no. 114 | 500 | 1 | A | |
| 115 | Classroom, room no. 115 | 500 | 1 | A | |
| 116 | Custodial Room, room no. 105 | 50 | 1 | A | Formerly Room 116 |
| 122 | Office, room no. 122 | 100 | 1 | A | |
| 123 | Office, room no. 123 | 200 | 1 | A | Includes Rooms 123A-B |
| 124 | Office, room no. 124-1 | 700 | 1 | A | Includes Room 124-2 and 124A-D |
| 125 | Classroom, room no. 125 | 400 | 1 | A | |
| 126 | Classroom/IT Office, room no. 126 | 500 | 1 | A | Includes Rooms 129J-K |
| 127 | Staff Room, room no. 127 | 500 | 1 | A | Includes Rooms 127A-B |
| 128 | Washroom, room no. 128 | 300 | 1 | A | |
| 129 | Resource Centre, room no. 129 | 9000 | 1 | A | Includes Rooms 129A-H and 129L-N |
| 130 | Custodial Room, room no. 130 | 25 | 1 | C | |
| 131 | Change Room, room no. 131 | 400 | 1 | C | Includes Rooms 131A-C |
| 132 | Washroom, room no. 132 | 50 | 1 | C | |
| 133 | Washroom, room no. 133 | 50 | 1 | C | |
| 134 | Change Room, room no. 134 | 400 | 1 | C | |
| 135 | Change Room, room no. 135 | 400 | 1 | C | Includes Rooms 135A-B |
| 136 | Washroom, room no. 136 | 200 | 1 | C | |
| 137 | Washroom, room no. 137 | 200 | 1 | C | Includes Room 137A |
| 139 | Storage Room, room no. 139 | 300 | 1 | C | |
| 140 | Stage, room no. 140 | 200 | 1 | C | |
| 141 | Equipment Storage, room no. 142A | 400 | 1 | C | Formerly Rooms 141 and 141A-C, Includes Rooms 142B-F |
| 142 | Gym, room no. 142 | 9000 | 1 | C | Includes Room 191A |
| 143 | Custodial Office, room no. 143 | 100 | 1 | A | Includes Rooms 143A |
| 144 | Office, room no. 144 | 150 | 1 | A | |
| 145 | Washroom, room no. 146 | 300 | 1 | A | Formerly Room 145 |
| 146 | Custodial Room, room no. 145 | 100 | 1 | A | Formerly Room 146 |
| 150 | Classroom, room no. 148 | 300 | 1 | A | Formerly Room 150 |
| 151 | Classroom, room no. 149 | 300 | 1 | A | Formerly Room 151, Includes Rooms 149A-C |
| 152 | Wood Shop, room no. 151 | 1000 | 1 | A | Formerly Room 152, Includes Room 151A |
| 153 | Autoshop, room no. 153 | 4000 | 1 | B | |
| 154 | Manufacturing Shop, room no. 154 | 1500 | 1 | B | Includes 154A |
| 155 | Manufacturing Shop, room no. 155 | 2000 | 1 | B | |
| 156 | Tech Area, room no. 156 | 500 | 1 | B | Includes rooms 156A-C |
| 157 | Classroom, room no. 157 | 400 | 1 | B | |
| 158 | Classroom, room no. 158 | 400 | 1 | B | |
| 159 | Washroom, room no. 159 | 300 | 1 | B | |
| 160 | Custodial Room, room no. 160 | 50 | 1 | B | |
| 161 | Mechanical Room, room no. 161 | 250 | 1 | B | Includes Rooms 161A-B |

| Location No. | Name or Description | Area ft ² | Floor No. | Bldg. Phase | Notes |
|--------------|--------------------------------|----------------------|-----------|-------------|--|
| 162 | Storage, room no. 152 | 100 | 1 | A | Formerly Room 162 |
| 163 | Boiler Room, room no. 163 | 600 | 1 | A | Includes Room 162 |
| 164 | Staff Room, room no. 164 | 200 | 1 | A | |
| 165 | Kitchen, room no. 165 | 600 | 1 | A | Includes Rooms 165A-D |
| 166 | Kitchen, room no. 194B | 150 | 1 | A | Formerly Room 166 |
| 167 | Cafeteria, room no. 167 | 1000 | 1 | A | |
| 168 | Corridor, room no. 168 | 200 | 1 | A | |
| 169 | Classroom, room no. 150 | 400 | 1 | A | Formerly Room 169, Includes Room 150A |
| 180 | Staff Room, room no. 180 | 400 | 1 | C | Includes Rooms 180A-B |
| 181 | Staff Room, room no. 181 | 500 | 1 | C | |
| 182 | Weight Room, room no. 182 | 500 | 1 | C | Includes Room 183A |
| 183 | Greenhouse, room no. 183 | 500 | 1 | C | Greenhouse is no longer present |
| 184 | Classroom, room no. 184 | 300 | 1 | C | Includes Room 184A |
| 185 | Classroom, room no. 185 | 500 | 1 | C | |
| 186 | Classroom, room no. 186 | 300 | 1 | C | |
| 187 | Classroom, room no. 187 | 500 | 1 | C | Includes Room 188 |
| 188 | Music Room, room no. 189 | 500 | 1 | C | Formerly Room 188, Includes Rooms 189A-E |
| 190 | Corridor, room no. 190 | 2000 | 1 | A | Includes Room 190A |
| 191 | Corridor, room no. 191 | 3000 | 1 | C | |
| 192 | Corridor, room no. 192 | 4000 | 1 | A | |
| 193 | Corridor, room no. 193 | 200 | 1 | A | Includes Rooms 193A-B |
| 194 | Corridor, room no. 194 | 2000 | 1 | A | Includes Rooms 194A and 194C |
| 195 | Corridor, room no. 195 | 2000 | 1 | B | Includes Rooms 195A |
| 202 | Classroom, room no. 204 | 400 | 2 | A | Formerly Room 202, Includes Room 205 |
| 203 | Storage, room no. 216 | 100 | 2 | A | Formerly Room 203 |
| 204 | Custodial Room, room no. 217-2 | 100 | 2 | A | Formerly Room 204 |
| 205 | Washroom, room no. 217-1 | 200 | 2 | A | Formerly Room 205 |
| 206 | Washroom, room no. 217-3 | 200 | 2 | A | Formerly Room 206 |
| 207 | Classroom, room no. 201 | 500 | 2 | A | Formerly Room 207 |
| 208 | Storage, room no. 201A | 100 | 2 | A | Formerly Room 208 |
| 209 | Storage, room no. 202 | 50 | 2 | A | Formerly Room 209 |
| 210 | Staff Room, room no. 210 | 300 | 2 | A | |
| 211 | Classroom, room no. 208 | 400 | 2 | A | Formerly Room 211 |
| 212 | Classroom, room no. 212 | 400 | 2 | A | Includes Rooms 212A |
| 214 | Theatre, room no. 214 | 500 | 2 | A | |
| 215 | Classroom, room no. 215 | 400 | 2 | A | Includes Room 215A |
| 216 | Storage, room no. 213 | 200 | 2 | A | Formerly Room 216 |
| 217 | Classroom, room no. 218 | 500 | 2 | A | Formerly Room 217 |
| 218 | Resource Room, room no. 218A | 150 | 2 | A | Formerly Room 218 |
| 219 | Classroom, room no. 219 | 500 | 2 | A | |
| 220 | Classroom, room no. 220 | 500 | 2 | A | Includes Room 220A |
| 223 | Classroom, room no. 223 | 500 | 2 | A | |
| 224 | Classroom, room no. 224 | 500 | 2 | A | |
| 225 | Classroom, room no. 225 | 500 | 2 | A | |
| 226 | Classroom, room no. 226 | 500 | 2 | A | |
| 227 | Resource Room, room no. 227 | 150 | 2 | A | Includes Room 227A |
| 228 | Classroom, room no. 228 | 500 | 2 | A | |
| 229 | Storage, room no. 211 | 100 | 2 | A | Formerly Room 229 |
| 230 | Mechanical Room, room no. 207 | 400 | 2 | A | Formerly Room 230 |
| 231 | Electrical Room, room no. 209 | 200 | 2 | A | Formerly Room 231, Includes Room 209A |
| 250 | Classroom, room no. 249 | 500 | 2 | B | Formerly Room 250, Includes Rooms 249A-B |
| 251 | Classroom, room no. 251 | 400 | 2 | B | |
| 252 | Classroom, room no. 252 | 300 | 2 | B | |
| 253 | Classroom, room no. 253 | 300 | 2 | B | |
| 254 | Classroom, room no. 254 | 300 | 2 | B | |
| 255 | Classroom, room no. 258 | 300 | 2 | B | Formerly Room 255 |
| 257 | Washroom, room no. 257 | 200 | 2 | B | |
| 258 | Custodial Closet, room no. 256 | 50 | 2 | B | Formerly Room 258 |
| 259 | Washroom, room no. 255 | 200 | 2 | B | Formerly Room 259 |
| 260 | Corridor, room no. 295 | 2000 | 2 | B | Formerly Room 260 |
| 261 | Corridor, room no. 290 | 2000 | 2 | A | Formerly Room 261 |
| 262 | Corridor, room no. 292 | 2000 | 2 | A | Formerly Room 262 |
| 263 | Washroom, room no. 203 | 50 | 2 | A | Formerly Room 263 |

| Location No. | Name or Description | Area ft ² | Floor No. | Bldg. Phase | Notes |
|--------------|-------------------------|----------------------|-----------|-------------|---------------------------------------|
| 264 | Washroom, room no. 206 | 50 | 2 | A | Formerly Room 264 |
| 265 | Office, room no. 259 | 200 | 2 | B | Formerly Room 265, Includes Room 295A |
| 266 | Offices, room no. 250 | 300 | 2 | B | Formerly Room 266 |
| 267 | Stairwell, room no. ST8 | 200 | 1-2 | A | |
| 268 | Stairwell, room no. ST9 | 200 | 1-2 | A | |
| 280 | Penthouse, room no. 280 | 2000 | 2 | C | Includes 281 and 282 |
| 294 | Corridor, room no. 294 | 0 | | A | |
| 1000 | Greenhouse Exterior | 0 | | A | Greenhouse is no longer present |

APPENDIX V
Confirmed / Presumed ACM Report

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #0 : Roof

Floor: ROOF

Room #:

Area (sqft): 6000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|------------------|------|----------|----|----|-----|--------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Other | | Roofing material | | | C | Y | | 100(7) | | | % | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |

Includes Portion of Phase B addition

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #1 : Basement

Floor: 0

Room #: 001

Area (sqft): 150

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|---------------------------|------|----------|----|----|-----|--------|------|------|------|---------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Aircell | | | A | Y | | 80(5) | | | LF | V0014 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | A | Y | | 15(5) | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | All | Paint, On poured concrete | | | A | Y | | 100(7) | | | SF | S0059DE | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #2 : Basement

Floor: 0

Room #: 002

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|-----------|---------------|---------------------------|------|----------|----|----|-----|---------|------|------|------|----------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Parging Cement | | | A | Y | | 5(5) | | | EA | S0006C | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | All | Aircell | | | A | Y | | 50(5) | | | LF | S0001C | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Structure | Light Fixture | Paper | | | A | Y | | 1(7) | | | EA | S0017ABC | Chrysotile | 50-75% | Confirmed Asbestos | NF |
| Wall | All | Paint, On poured concrete | | | B | Y | | 1000(7) | | | SF | S0059ABC | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #3 : Exterior

Floor:

Room #:

Area (sqft): 0

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|-----------|-----------|---------------------------------|------|----------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Structure | Canopy | Cement Product, Transite panels | | | C | Y | | 200(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | Door | Caulking, Brown and grey | | | A | Y | | 20(7) | | | EA | S0033B | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | Door | Caulking, Beige | | | A | Y | | 20(7) | | | EA | S0031B | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #100 : Offices
Survey Date: 2025-06-09
Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 124-3
Last Re-Assessment: 2025-06-09
Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|---------------------------------|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | All | Cement Product, Transite panels | | | C | N | | 400(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |
| Wall | All | Drywall and joint compound | | | A | Y | | 500(7) | | | SF | V0054 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 100, Includes Rooms 124E-F and 125A-C

Client: Hastings and Prince Edward District School Board
Location: #101 : Classroom
Survey Date: 2025-06-09
Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 101
Last Re-Assessment: 2025-06-09
Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------------|----------|----|----|-----|---------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 500(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |
| Wall | All | Paint, On concrete block | | | A | Y | | 1200(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #102 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 102
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 500(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Client: Hastings and Prince Edward District School Board
Location: #103 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 103
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 500(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0063F | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Site: 275 Farley Avenue, Belleville, ON
Location: #104 : Classroom
Floor: 1
Survey Date: 2025-06-09

Building Name: Eastside Secondary School
Room #: 104
Area (sqft): 500
Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-------------------|--|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 500(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Piping | Hot Water Heating | Aircell | | | C | N | | 60(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Client: Hastings and Prince Edward District School Board
Site: 275 Farley Avenue, Belleville, ON
Location: #105 : Resource Room
Floor: 1
Survey Date: 2025-06-09

Building Name: Eastside Secondary School
Room #: 104
Area (sqft): 500
Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 100(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 400(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Formerly Room 105

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #106 : Classroom

Floor: 1

Room #: 106

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-------------------|--------------------------|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | Hot Water Heating | Aircell | | | C | N | | 60(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #108 : Guidance

Floor: 1

Room #: 120

Area (sqft): 600

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |
| Wall | All | Drywall and joint compound | | | A | Y | | 500(7) | | | SF | V0054 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 108, Includes Rooms 120A-E

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #109 : Storage

Floor: 1

Room #: 121

Area (sqft): 200

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Aircell | | | C | Y | | 70(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Piping | | Sweatwrap | | | C | Y | | 30(7) | | | LF | S0002C | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | C | Y | | 3(7) | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 109, Includes Room 121A

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #110 : Staff Room

Floor: 1

Room #: 110

Area (sqft): 300

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------------|------------------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | | Mastic | ALL | Vinyl Floor Tile | D | N | | 300(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Includes Rooms 110A-C

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #111 : Classroom

Floor: 1

Room #: 111

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------------|----------|----|----|-----|--------|------|------|------|----------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0063E | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite, Libby Amphibole Asbestos Behind steel beam above windows | Insulation | | D | N | | 100(7) | | | % | S0092ABC | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #112 : Classroom

Floor: 1

Room #: 112

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #113 : Classroom

Floor: 1

Room #: 113

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #114 : Classroom

Floor: 1

Room #: 114

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #115 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 115
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 500(7) | | | SF | S0003B | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Client: Hastings and Prince Edward District School Board
Location: #116 : Custodial Room
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 105
Last Re-Assessment: 2025-06-09

Area (sqft): 50

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 200(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 116

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #122 : Office

Floor: 1

Room #: 122

Area (sqft): 100

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Sweatwrap | | | C | N | | 15(7) | | | LF | V0035 | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Piping | All | Aircell | | | C | N | | 15(7) | | | LF | V0014 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 300(7) | | | SF | S0063C | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #123 : Office

Floor: 1

Room #: 123

Area (sqft): 200

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|------------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | All | Aircell | | | C | Y | | 30(7) | | | LF | V0014 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Drywall and joint compound | | | A | Y | | 500(7) | | | SF | S0054D | [Asbestos] | [Asbestos] | [Asbestos] | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Includes Rooms 123A-B

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #124 : Office
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 124-1
Last Re-Assessment: 2025-06-09

Area (sqft): 700

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|-----------------------------|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic | | | A | Y | | 200(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Piping | All | Parging Cement | | | C | Y | | 4(7) | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | All | Aircell | | | C | Y | | 8(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |
| Wall | All | Drywall and joint compound | | | A | Y | | 500(7) | | | SF | V0054 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Room 124-2 and 124A-D

Client: Hastings and Prince Edward District School Board
Location: #125 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 125
Last Re-Assessment: 2025-06-09

Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|---------------------------------|------------|----------|----|----|-----|--------|------|------|------|--------|--------------------------|------------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | All | Cement Product, Transite panels | | | C | N | | 100(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Piping | All | Aircell, Under radiator | | | A | Y | | 3(5) | | | LF | V0025 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Cement Product, Transite panels | | | D | N | | 8(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |
| Wall | All | Drywall and joint compound | | | A | Y | | 500(7) | | | SF | S0005D | [Asbestos] | [Asbestos] | [Asbestos] | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #126 : Classroom/IT Office
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 126
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|------------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | | Mastic, Under new 12x12 beige tile with brown and white flecks | | | D | N | | 150(7) | | | SF | S0003A | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Piping | All | Aircell | | | A | Y | | 2(5) | | | LF | V0025 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 300(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Drywall and joint compound | | | A | Y | | 800(7) | | | SF | S0054A | [Asbestos] | [Asbestos] | [Asbestos] | NF |

Includes Rooms 129J-K

Client: Hastings and Prince Edward District School Board
Location: #127 : Staff Room
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 127
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 200(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Drywall and joint compound | | | A | Y | | 800(7) | | | SF | V0054 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Rooms 127A-B

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #128 : Washroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 128
Last Re-Assessment: 2025-06-09

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|-------------------------------------|------|---------------|----|----|-----|---------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Bulkhead | Drywall and joint compound | | | C | Y | | 200(7) | | | SF | V0054 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Floor | All | Mortar, 12x12 brown and beige tiles | ALL | Ceramic Tiles | D | N | | 300(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | All | Mortar, 12x12 brown and beige tiles | ALL | Ceramic Tiles | D | N | | 1000(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |

Client: Hastings and Prince Edward District School Board
Location: #129 : Resource Centre
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 129
Last Re-Assessment: 2025-06-09

Area (sqft): 9000

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------|----------|----|----|-----|---------|------|------|------|---------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Parging Cement | | | C | N | | 10(7) | | | EA | V0008 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | | Aircell | | | C | N | | 90(7) | | | LF | V0025 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | All | Sweatwrap | | | D | N | | 160(7) | | | LF | V0035 | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 3000(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Drywall and joint compound | | | A | Y | | 3500(7) | | | SF | S0053CD | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Rooms 129A-H and 129L-N

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #130 : Custodial Room
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 130
Last Re-Assessment: 2025-06-09

Area (sqft): 25

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------|---------------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | All | Drywall and joint compound | | | C | Y | | 25(7) | | | SF | V0053 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Floor | | Mortar, 1"x1" grey tiles | ALL | Ceramic Tiles | D | N | | 25(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 100(7) | | | SF | V0067 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board
Location: #131 : Change Room
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 131
Last Re-Assessment: 2025-06-09

Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|---|------|---------------|----|----|-----|--------|------|------|------|--------|-------------------|------------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Drywall and joint compound | | | C | Y | | 200(7) | | | SF | S0027B | [Asbestos] | [Asbestos] | [Asbestos] | NF |
| Ceiling | | Drywall and joint compound | | | C | Y | | | | | | S0053A | [Asbestos] | [Asbestos] | [Asbestos] | NF |
| Floor | | Mortar, 1"x1" grey tiles | ALL | Ceramic Tiles | D | N | | 150(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Floor | All | Vinyl Floor Tile, 12x12 off-white with black and grey streaks | | | A | Y | | 200(7) | | | SF | V0026 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 600(7) | | | SF | V0067 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Rooms 131A-C

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #132 : Washroom

Floor: 1

Room #: 132

Area (sqft): 50

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|---------------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Mortar, 1"x1" grey tiles | ALL | Ceramic Tiles | D | N | | 50(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | All | Paint, On concrete block | | | A | Y | | 200(7) | | | SF | V0067 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #133 : Washroom

Floor: 1

Room #: 133

Area (sqft): 50

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|---------------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Mortar, 1"x1" grey tiles | ALL | Ceramic Tiles | D | N | | 50(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | All | Paint, On concrete block | | | A | Y | | 200(7) | | | SF | V0067 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #134 : Change Room
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 134
Last Re-Assessment: 2025-06-09

Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------|---------------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Drywall and joint compound | | | C | Y | | 200(7) | | | SF | V0053 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Floor | | Mortar, 1"x1" grey tiles | ALL | Ceramic Tiles | D | N | | 200(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 600(7) | | | SF | S0067D | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board
Location: #135 : Change Room
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 135
Last Re-Assessment: 2025-06-09

Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|-------------------|-----------|---|------|---------------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Drywall and joint compound | | | C | Y | | 200(7) | | | SF | S0053G | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Floor | | Mortar, 1"x1" grey tiles | ALL | Ceramic Tiles | D | N | | 200(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Floor | All | Vinyl Floor Tile, 12x12 off-white with black and grey streaks | | | A | Y | | 200(7) | | | SF | S0026C | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall ¹ | | Paint, On concrete block | | | A | Y | | 800(7) | | 5(3) | SF | V0067 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Rooms 135A-B
 1 - Room 135b

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #136 : Washroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 136
Last Re-Assessment: 2025-06-09

Area (sqft): 200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|-------------------------------------|------|---------------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Mortar, 12x12 brown and beige tiles | ALL | Ceramic Tiles | D | N | | 200(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0066D | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board
Location: #137 : Washroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 137
Last Re-Assessment: 2025-06-09

Area (sqft): 200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|-------------------------------------|------|---------------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Mortar, 12x12 brown and beige tiles | ALL | Ceramic Tiles | D | N | | 200(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0066 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Room 137A

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #139 : Storage Room
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 139
Last Re-Assessment: 2025-06-09

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|--------|------|----------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile, 12x12 beige with sparse white and brown flecks | | | A | Y | | 300(7) | | | SF | S0024A | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Piping | All | Parging Cement | | | C | Y | | 4(7) | | | EA | S0025ABC | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 400(7) | | 300(3) | SF | S0066AB | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board
Location: #140 : Stage
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 140
Last Re-Assessment: 2025-06-09

Area (sqft): 200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-------------------|--------------------------|------|----------|----|----|-----|---------|------|------|------|-----------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | Rain Water Leader | Cement Product, Transite | | | C | Y | | 15(7) | | | LF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Piping | Rain Water Leader | Parging Cement | | | C | Y | | 2(7) | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | | | | | S0042G | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Paint, On concrete block | | | A | Y | | 1000(7) | | | SF | S0065ABCD | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #141 : Equipment Storage
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 142A
Last Re-Assessment: 2025-06-09

Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-------------------|--|------|----------|----|----|-----|---------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile, 12x12 beige with sparse white and brown flecks | | | A | Y | | 200(7) | | | SF | V0024 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Piping | All | Parging Cement | | | C | Y | | 30(7) | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | Rain Water Leader | Cement Product, Transite | | | C | Y | | 40(7) | | | LF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 2010(7) | | | SF | S0067F | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | S0066E | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Rooms 141 and 141A-C, Includes Rooms 142B-F

Client: Hastings and Prince Edward District School Board
Location: #142 : Gym
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 142
Last Re-Assessment: 2025-06-09

Area (sqft): 9000

| ASBESTOS | | | | | | | | | | | | | | | | |
|--------------------|-------------------|--|------|----------|----|----|-----|---------|------|------|------|---------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor ¹ | | Vinyl Floor Tile, 12x12 beige with sparse white and brown flecks | | | A | Y | | 200(7) | | | SF | V0024 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Piping | All | Cement Product, Transite | | | D | Y | | 46(7) | | | LF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Piping | Rain Water Leader | Parging Cement | | | D | Y | | | | 2(7) | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | S0065E | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Paint, On concrete block | | | A | Y | | 5000(7) | | | SF | S0066FG | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Room 191A
 1 - 191A

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #143 : Custodial Office

Floor: 1

Room #: 143

Area (sqft): 100

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Drywall and joint compound | | | A | Y | | 200(7) | | | SF | V0054 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 200(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Rooms 143A

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #144 : Office

Floor: 1

Room #: 144

Area (sqft): 150

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Site: 275 Farley Avenue, Belleville, ON
Location: #145 : Washroom
Floor: 1
Survey Date: 2025-06-09

Building Name: Eastside Secondary School
Room #: 146
Area (sqft): 300
Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|-------------------------------------|------|---------------|----|----|-----|---------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Bulkhead | Drywall and joint compound | | | C | Y | | 200(7) | | | SF | V0054 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Floor | All | Mortar, 12x12 brown and beige tiles | ALL | Ceramic Tiles | D | N | | 300(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | All | Mortar, 12x12 brown and beige tiles | ALL | Ceramic Tiles | D | N | | 1000(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |

Formerly Room 145

Client: Hastings and Prince Edward District School Board
Site: 275 Farley Avenue, Belleville, ON
Location: #146 : Custodial Room
Floor: 1
Survey Date: 2025-06-09

Building Name: Eastside Secondary School
Room #: 145
Area (sqft): 100
Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 400(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 146

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #150 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 148
Last Re-Assessment: 2025-06-09

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------------|----------|----|----|-----|---------|------|------|------|----------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 300(7) | | | SF | S0003D | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Piping | | Aircell | | | C | Y | | 100(7) | | | LF | S0001A | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Piping | | Sweatwrap | | | A | Y | | 110(5) | | | LF | S0002A | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Piping | | Sweatwrap | | | A | Y | | | | 2(3) | LF | S0035ABC | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | C | Y | | 12(7) | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 1000(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Formerly Room 150

Client: Hastings and Prince Edward District School Board
Location: #151 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 149
Last Re-Assessment: 2025-06-09

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------------|----------|----|----|-----|---------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Aircell | | | C | Y | | 60(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Piping | | Sweatwrap | | | C | Y | | 60(7) | | 1(3) | LF | V0035 | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | C | Y | | 8(7) | 1(6) | 1(3) | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 1000(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Formerly Room 151, Includes Rooms 149A-C

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #152 : Wood Shop

Floor: 1

Room #: 151

Area (sqft): 1000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Parging Cement | | | C | Y | | 25(7) | | | EA | S0006A | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | | Sweatwrap | | | C | Y | | 170(7) | | | LF | V0002 | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Piping | All | Aircell | | | C | Y | | 170(7) | | | LF | V0025 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 4000(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 152, Includes Room 151A

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #153 : Autoshop

Floor: 1

Room #: 153

Area (sqft): 4000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|-------------------|-----------|---------------------------|------|----------|----|----|-----|---------|------|------|------|----------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Duct | | Textile, Vibration damper | | | D | Y | | 1(7) | | | EA | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Other | Column | Plaster, Coating material | | Paint | A | Y | | 200(7) | | | SF | S0071ABC | Chrysotile | 0.5-5% | Confirmed Asbestos | [NF]* |
| Piping | | Aircell | | | C | Y | | 150(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Piping | | Sweatwrap | | | C | Y | | 150(7) | | | LF | V0002 | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | C | Y | | 29(7) | | 1(3) | EA | S0008ABC | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 4000(7) | | | SF | V0062 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall ¹ | Door | Caulking, Soft, grey | | | A | Y | | 8(7) | | | LF | V0041 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

1 - Exterior garage door

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #154 : Manufacturing Shop

Floor: 1

Room #: 154

Area (sqft): 1500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Aircell | | | C | Y | | 200(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | A | Y | | 20(5) | | | EA | V0008 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 3000(7) | | | SF | V0062 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes 154A

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #155 : Manufacturing Shop

Floor: 1

Room #: 155

Area (sqft): 2000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|-------------------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Aircell | | | C | Y | | 100(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | C | Y | | 15(7) | | | EA | V0008 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 4000(7) | | | SF | S0062C | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall ¹ | Door | Caulking, Soft, grey | | | A | Y | | 8(7) | | | LF | V0041 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

1 - Exterior garage door

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #156 : Tech Area

Floor: 1

Room #: 156

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | | Paint, On concrete block | | | A | Y | | 2000(7) | | | SF | S0062B | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes rooms 156A-C

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #157 : Classroom

Floor: 1

Room #: 157

Area (sqft): 400

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 400(7) | | | SF | S0003C | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0062A | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #158 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 158
Last Re-Assessment: 2025-06-09

Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 400(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0062 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board
Location: #159 : Washroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 159
Last Re-Assessment: 2025-06-09

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | All | Texture Coat | | | C | Y | | 300(7) | | | SF | S0012A | Chrysotile | 5-10% | Confirmed Asbestos | F |
| Wall | All | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | S0062D | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Site: 275 Farley Avenue, Belleville, ON
Location: #161 : Mechanical Room
Floor: 1
Survey Date: 2025-06-09

Building Name: Eastside Secondary School
Room #: 161
Area (sqft): 250
Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 50(7) | | | SF | S0003E | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Piping | | Aircell | | | C | Y | | 25(7) | | | LF | V0014 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | C | Y | | 5(7) | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | S0062E | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Paint, On brick | | | A | Y | | 100(7) | | | SF | S0060D | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Rooms 161A-B

Client: Hastings and Prince Edward District School Board
Site: 275 Farley Avenue, Belleville, ON
Location: #163 : Boiler Room
Floor: 1
Survey Date: 2025-06-09

Building Name: Eastside Secondary School
Room #: 163
Area (sqft): 600
Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|---------|------|------|------|----------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | | Vinyl Floor Tile, 12x12 beige with brown streaks | | | A | Y | | 100(7) | | | SF | S0015ABC | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Piping | | Aircell | | | C | Y | | 30(7) | | | LF | S0014ABC | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | | Sweatwrap | | | C | Y | | 30(7) | | | LF | S0002B | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | C | Y | | 4(7) | | | EA | V0008 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 1200(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | Door | Thermal Insulation | | Metal | A | Y | | 1(5) | | | EA | V9500 | Presumed Asbestos | | Presumed Asbestos | F |

Includes Room 162

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #164 : Staff Room
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 164
Last Re-Assessment: 2025-06-09

Area (sqft): 200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 200(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Piping | | Aircell | | | C | N | | 60(7) | | | LF | V0014 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | C | N | | 6(7) | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0063A | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board
Location: #165 : Kitchen
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 165
Last Re-Assessment: 2025-06-09

Area (sqft): 600

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | All | Parging Cement | | | C | N | | 25(7) | | | EA | V0008 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 1000(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Rooms 165A-D

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #166 : Kitchen

Floor: 1

Room #: 194B

Area (sqft): 150

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | All | Parging Cement | | | C | N | | 25(7) | | | EA | V0008 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 166

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #167 : Cafeteria

Floor: 1

Room #: 167

Area (sqft): 1000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Aircell | | | C | Y | | 30(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | C | Y | | 2(7) | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 2500(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #168 : Corridor
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 168
Last Re-Assessment: 2025-06-09

Area (sqft): 200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 200(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Piping | All | Aircell | | | C | Y | | 60(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 400(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board
Location: #169 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 150
Last Re-Assessment: 2025-06-09

Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------------|----------|----|----|-----|---------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Aircell | | | C | N | | 10(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Piping | | Sweatwrap | | | C | N | | 10(7) | | | LF | V0035 | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | C | N | | 11(7) | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 1000(7) | | | SF | S0063B | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |

Formerly Room 169, Includes Room 150A

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #180 : Staff Room

Floor: 1

Room #: 180

Area (sqft): 400

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|---------------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | | Drywall and joint compound | | | C | Y | | 200(7) | | | SF | S0053B | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Floor | | Mortar, 1"x1" grey tiles | ALL | Ceramic Tiles | D | N | | 200(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Floor | All | Vinyl Floor Tile, 12x12 beige with sparse white and brown flecks | | | A | Y | | 200(7) | | | SF | V0024 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 600(7) | | | SF | V0067 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Rooms 180A-B

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #181 : Staff Room

Floor: 1

Room #: 181

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile, 12x12 beige with sparse white and brown flecks | | | A | Y | | 500(7) | | | SF | V0024 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 600(7) | | | SF | S0067E | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Drywall and joint compound | | | A | Y | | 30(7) | | | SF | V0053 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Site: 275 Farley Avenue, Belleville, ON
Location: #182 : Weight Room
Floor: 1
Survey Date: 2025-06-09

Building Name: Eastside Secondary School
Room #: 182
Last Re-Assessment: 2025-06-09
Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|---|------|----------|----|----|-----|---------|------|------|------|---------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 12x12 beige with sparse white and brown flecks | | | A | Y | | 500(7) | | | SF | S0024BC | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Piping | All | Parging Cement | | | C | N | | 10(7) | | | EA | V0006 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 1000(7) | | | SF | V0067 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Room 183A

Client: Hastings and Prince Edward District School Board
Site: 275 Farley Avenue, Belleville, ON
Location: #184 : Classroom
Floor: 1
Survey Date: 2025-06-09

Building Name: Eastside Secondary School
Room #: 184
Last Re-Assessment: 2025-06-09
Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|------------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Drywall and joint compound | | | A | Y | | 100(7) | | | SF | S0027C | [Asbestos] | [Asbestos] | [Asbestos] | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0067 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Room 184A

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #185 : Classroom

Floor: 1

Room #: 185

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Drywall and joint compound | | | A | Y | | 100(7) | | | SF | S0027A | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 1000(7) | | | SF | V0067 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #186 : Classroom

Floor: 1

Room #: 186

Area (sqft): 300

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0067C | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #187 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 187
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-------------------|---|------|----------|----|----|-----|--------|------|------|------|---------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile, 12x12 off-white with black and grey streaks | | | A | Y | | 500(7) | | | SF | S0026AB | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Piping | Rain Water Leader | Cement Product, Transite | | | C | N | | 10(7) | | | LF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 595(7) | | 5(3) | SF | V0067 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Drywall and joint compound | | | A | Y | | 200(7) | | | SF | S0053E | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Room 188

Client: Hastings and Prince Edward District School Board
Location: #188 : Music Room
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 1

Building Name: Eastside Secondary School
Room #: 189
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-------------------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | Rain Water Leader | Cement Product, Transite | | | A | Y | | 12(7) | | | LF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0067A | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 188, Includes Rooms 189A-E

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #190 : Corridor

Floor: 1

Room #: 190

Area (sqft): 2000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-------------------|--------------------------|------------|----------|----|----|-----|---------|------|------|------|--------|--------------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | All | Parging Cement | | | C | N | | 1(7) | | | EA | V0008 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | Rain Water Leader | Sweatwrap | | | C | N | | 6(7) | | | LF | V0002 | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 2000(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Vermiculite | Insulation | | D | N | | 100(7) | | | % | V0092 | Libby Amphibole Detected | >75% | Confirmed Asbestos | F |
| Wall | Stairs | Paint, On brick | | | A | Y | | 500(7) | | | SF | S0060B | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Room 190A

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #191 : Corridor

Floor: 1

Room #: 191

Area (sqft): 3000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|---------------------|-------------------|-------------------------------|------|---------------|----|----|-----|---------|------|-------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor ¹ | | Mortar, 1"x1" grey tiles | ALL | Ceramic Tiles | A | Y | | 50(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Floor | All | Mortar, 4"x8" red quarry tile | ALL | Ceramic Tiles | D | N | | 1000(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Piping ² | Rain Water Leader | Cement Product, Transite | | | A | Y | | 10(7) | | | LF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Drywall and joint compound | | | A | Y | | 800(7) | | | SF | V0053 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 2985(7) | | 15(3) | SF | S0067B | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Paint, On concrete block | | | A | Y | | 1000(7) | | | SF | S0066C | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

1 - Custodial closet

2 - Custodial closet

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #192 : Corridor

Floor: 1

Room #: 192

Area (sqft): 4000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Parging Cement | | | C | N | | 2(7) | | | EA | V0008 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | | Aircell | | | C | N | | 100(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 1000(7) | | | SF | V0063 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #193 : Corridor

Floor: 1

Room #: 193

Area (sqft): 200

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|-----------------|-------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | All | Parging Cement | Elbow | | C | N | | 2(7) | | | EA | V0025 | Chrysotile | 25-50% | Confirmed Asbestos | F |
| Piping | All | Aircell | | | C | Y | | 50(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Wall | All | Paint, On brick | | | A | Y | | 800(7) | | | SF | S0060A | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Rooms 193A-B

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #194 : Corridor

Floor: 1

Room #: 194

Area (sqft): 2000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|------------------------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|----------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping ¹ | | Aircell | | | C | N | | 50(7) | | | LF | V0001 | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Structure ² | Canopy | Cement Product, Transite | | Paint | C | Y | | 90(7) | | | SF | S0090ABC | Chrysotile | 10-25% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 2000(7) | | | SF | S0063D | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Rooms 194A and 194C

1 - Outside of assessed area

2 - Exterior

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #195 : Corridor

Floor: 1

Room #: 195

Area (sqft): 2000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|------------------------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|----------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Structure ¹ | | Texture Coat | | Paint | C | Y | | 30(7) | | | SF | S0087ABC | Chrysotile | 0.5-5% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 2000(7) | | | SF | S0062F | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Rooms 195A

1 - Exterior canopy

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #202 : Classroom

Floor: 2

Room #: 204

Area (sqft): 400

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Drywall and joint compound | | | B | Y | | 400(7) | | | SF | V0054 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 202, Includes Room 205

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #203 : Storage

Floor: 2

Room #: 216

Area (sqft): 100

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 200(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 203

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #204 : Custodial Room

Floor: 2

Room #: 217-2

Area (sqft): 100

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | | Paint, On concrete block | | | A | Y | | 200(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 204

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #205 : Washroom

Floor: 2

Room #: 217-1

Area (sqft): 200

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|-------------------------------------|------|---------------|----|----|-----|---------|------|------|------|--------|-------------------|--------|-------------------|---------|
| Floor | All | Mortar, 12x12 brown and beige tiles | ALL | Ceramic Tiles | D | N | | 200(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | All | Mortar, 12x12 brown and beige tiles | ALL | Ceramic Tiles | D | N | | 1000(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |

Formerly Room 205

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #206 : Washroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 2

Building Name: Eastside Secondary School
Room #: 217-3
Last Re-Assessment: 2025-06-09

Area (sqft): 200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|-------------------------------------|------|---------------|----|----|-----|---------|------|------|------|--------|-------------------|--------|-------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Mortar, 12x12 brown and beige tiles | ALL | Ceramic Tiles | D | N | | 200(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | All | Mortar, 12x12 brown and beige tiles | ALL | Ceramic Tiles | D | N | | 1000(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |

Formerly Room 206

Client: Hastings and Prince Edward District School Board
Location: #207 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 2

Building Name: Eastside Secondary School
Room #: 201
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 207

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #208 : Storage

Floor: 2

Room #: 201A

Area (sqft): 100

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 400(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 208

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #209 : Storage

Floor: 2

Room #: 202

Area (sqft): 50

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 200(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 209

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #210 : Staff Room

Floor: 2

Room #: 210

Area (sqft): 300

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|----------|------|------------------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| Floor | | Mastic | ALL | Vinyl Floor Tile | D | N | | 300(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #211 : Classroom

Floor: 2

Room #: 208

Area (sqft): 400

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0064F | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 211

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #212 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 2

Building Name: Eastside Secondary School
Room #: 212
Last Re-Assessment: 2025-06-09

Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|------------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | | Vinyl Floor Tile, 12x12 beige with sparse white and brown flecks | | | A | Y | | 150(7) | | | SF | V0024 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Drywall and joint compound | | | A | Y | | 795(7) | | 5(3) | SF | S0005E | [Asbestos] | [Asbestos] | [Asbestos] | NF |

Includes Rooms 212A

Client: Hastings and Prince Edward District School Board
Location: #214 : Theatre
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 2

Building Name: Eastside Secondary School
Room #: 214
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------|----------|----|----|-----|---------|------|------|------|----------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | Bulkhead | Texture Coat | | | C | Y | | 300(7) | | | SF | S0030ABC | Chrysotile | 5-10% | Confirmed Asbestos | F |
| Wall | | Paint, On concrete block | | | A | Y | | 600(7) | | | SF | S0064E | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Drywall and joint compound | | | A | Y | | 1000(7) | | | SF | V0054 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Site: 275 Farley Avenue, Belleville, ON
Location: #215 : Classroom
Floor: 2
Survey Date: 2025-06-09

Building Name: Eastside Secondary School
Room #: 215
Last Re-Assessment: 2025-06-09
Area (sqft): 400

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | | Vinyl Floor Tile, 12x12 beige with sparse white and brown flecks | | | A | Y | | 150(7) | | | SF | V0024 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Drywall and joint compound | | | A | Y | | 795(7) | | 5(3) | SF | S0005G | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Room 215A

Client: Hastings and Prince Edward District School Board
Site: 275 Farley Avenue, Belleville, ON
Location: #216 : Storage
Floor: 2
Survey Date: 2025-06-09

Building Name: Eastside Secondary School
Room #: 213
Last Re-Assessment: 2025-06-09
Area (sqft): 200

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|------------|------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | All | Drywall and joint compound | | | A | Y | | 600(7) | | | SF | S0054G | [Asbestos] | [Asbestos] | [Asbestos] | NF |

Formerly Room 216

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #217 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 2

Building Name: Eastside Secondary School
Room #: 218
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|------------|--------------------------------------|------|----------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Other | | Cement Product, Transite drying rack | | | A | Y | | 10(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Other | Countertop | Cement Product, Transite | | | A | Y | | 160(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 217

Client: Hastings and Prince Edward District School Board
Location: #218 : Resource Room
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 2

Building Name: Eastside Secondary School
Room #: 218A
Last Re-Assessment: 2025-06-09

Area (sqft): 150

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|------------|--------------------------------------|------|----------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Other | | Cement Product, Transite drying rack | | | A | Y | | 10(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Other | Countertop | Cement Product, Transite | | | A | Y | | 100(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 500(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 218

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #219 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 2

Building Name: Eastside Secondary School
Room #: 219
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|------------|--------------------------------------|------|----------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Other | | Cement Product, Transite drying rack | | | A | Y | | 10(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Other | Countertop | Cement Product, Transite | | | A | Y | | 160(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0064C | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board
Location: #220 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 2

Building Name: Eastside Secondary School
Room #: 220
Last Re-Assessment: 2025-06-09

Area (sqft): 500

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|------------|--------------------------------------|------|----------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Other | | Cement Product, Transite drying rack | | | A | Y | | 10(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Other | Countertop | Cement Product, Transite | | | A | Y | | 160(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Room 220A

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #223 : Classroom

Floor: 2

Room #: 223

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0064A | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #224 : Classroom

Floor: 2

Room #: 224

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #225 : Classroom

Floor: 2

Room #: 225

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0064B | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #226 : Classroom

Floor: 2

Room #: 226

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|------------|--------------------------------------|------|----------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| Other | | Cement Product, Transite drying rack | | | A | Y | | 10(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Other | Countertop | Cement Product, Transite | | | A | Y | | 160(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #227 : Resource Room

Floor: 2

Room #: 227

Area (sqft): 150

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 400(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes Room 227A

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #228 : Classroom

Floor: 2

Room #: 228

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|------------|--------------------------------------|------|----------|----|----|-----|--------|------|------|------|--------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Other | | Cement Product, Transite drying rack | | | A | Y | | 10(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Other | Countertop | Cement Product, Transite | | | A | Y | | 160(7) | | | SF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #229 : Storage

Floor: 2

Room #: 211

Area (sqft): 100

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 200(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 229

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #230 : Mechanical Room

Floor: 2

Room #: 207

Area (sqft): 400

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|----------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | | Aircell | | | B | Y | | 100(7) | | | LF | S0001B | Chrysotile | 50-75% | Confirmed Asbestos | F |
| Piping | All | Parging Cement | | | B | Y | | 15(7) | | | EA | S0006B | Chrysotile | 25-50% | Confirmed Asbestos | F |

Formerly Room 230

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #250 : Classroom

Floor: 2

Room #: 249

Area (sqft): 500

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|---------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 2000(7) | | | SF | S0061BC | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 250, Includes Rooms 249A-B

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #251 : Classroom

Floor: 2

Room #: 251

Area (sqft): 400

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0061 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #252 : Classroom

Floor: 2

Room #: 252

Area (sqft): 300

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0061 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #253 : Classroom

Floor: 2

Room #: 253

Area (sqft): 300

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 300(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0061A | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board
Location: #254 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 2

Building Name: Eastside Secondary School
Room #: 254
Last Re-Assessment: 2025-06-09

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 300(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0061 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board
Location: #255 : Classroom
Survey Date: 2025-06-09

Site: 275 Farley Avenue, Belleville, ON
Floor: 2

Building Name: Eastside Secondary School
Room #: 258
Last Re-Assessment: 2025-06-09

Area (sqft): 300

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | | A | Y | | 300(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | S0061D | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 255

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #257 : Washroom

Floor: 2

Room #: 257

Area (sqft): 200

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------|------|----------|----|----|-----|--------|------|------|------|---------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Ceiling | All | Texture Coat | | | C | Y | | 200(7) | | | SF | S0012BC | Chrysotile | 5-10% | Confirmed Asbestos | F |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #258 : Custodial Closet

Floor: 2

Room #: 256

Area (sqft): 50

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 200(7) | | | SF | V0061 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 258

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #259 : Washroom

Floor: 2

Room #: 255

Area (sqft): 200

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | All | Paint, On concrete block | | | A | Y | | 400(7) | | | SF | S0061G | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 259

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #260 : Corridor

Floor: 2

Room #: 295

Area (sqft): 2000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | | Paint, On concrete block | | | A | Y | | 2000(7) | | | SF | S0061F | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | Stairs | Paint, On brick | | | A | Y | | 250(7) | | | SF | S0060C | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 260

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #261 : Corridor

Floor: 2

Room #: 290

Area (sqft): 2000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | | Paint, On concrete block | | | A | Y | | 2000(7) | | | SF | V0064 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 261

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #262 : Corridor

Floor: 2

Room #: 292

Area (sqft): 2000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|--------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | | Paint, On concrete block | | | A | Y | | 2000(7) | | | SF | S0064D | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 262

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #263 : Washroom

Floor: 2

Room #: 203

Area (sqft): 50

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|----------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | | Drywall and joint compound | | | A | Y | | 100(7) | | | SF | V0054 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 263

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #264 : Washroom

Floor: 2

Room #: 206

Area (sqft): 50

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

ASBESTOS

| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
|--------|-----------|----------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| Wall | | Drywall and joint compound | | | A | Y | | 100(7) | | | SF | V0054 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 264

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #265 : Office

Floor: 2

Room #: 259

Area (sqft): 200

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|--------------------|-----------|--|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Floor ¹ | All | Vinyl Floor Tile and Mastic, 9x9 various colours | | Paint | A | Y | | 50(7) | | | SF | V0003 | Chrysotile | 5-10% | Confirmed Asbestos | NF |
| Wall | | Paint, On concrete block | | | A | Y | | 600(7) | | | SF | S0061E | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 265, Includes Room 295A

1 - Vestibule

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #266 : Offices

Floor: 2

Room #: 250

Area (sqft): 300

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|--------------------------|------|----------|----|----|-----|--------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On concrete block | | | A | Y | | 800(7) | | | SF | V0061 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Formerly Room 266

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #267 : Stairwell

Floor: 1-2

Room #: ST8

Area (sqft): 200

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|------------------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On brick and concrete block | | | A | Y | | 1000(7) | | | SF | V0061 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #268 : Stairwell

Floor: 1-2

Room #: ST9

Area (sqft): 200

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-----------|------------------------------------|------|----------|----|----|-----|---------|------|------|------|--------|---------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Wall | | Paint, On brick and concrete block | | | A | Y | | 1000(7) | | | SF | V0061 | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

CONFIRMED AND PRESUMED HAZARDOUS MATERIALS REPORT

Client: Hastings and Prince Edward District School Board

Site: 275 Farley Avenue, Belleville, ON

Building Name: Eastside Secondary School

Location: #280 : Penthouse

Floor: 2

Room #: 280

Area (sqft): 2000

Survey Date: 2025-06-09

Last Re-Assessment: 2025-06-09

| ASBESTOS | | | | | | | | | | | | | | | | |
|----------|-------------------|----------------------------|------|----------|----|----|-----|---------|------|------|------|-----------|-------------------|--------|--------------------|---------|
| System | Component | Material | Item | Covering | A* | V* | AP* | Good | Fair | Poor | Unit | Sample | Asbestos Type | Amount | Hazard | Friable |
| Piping | Rain Water Leader | Cement Product, Transite | | | C | Y | | 50(7) | | | LF | V9500 | Presumed Asbestos | | Presumed Asbestos | NF |
| Wall | | Drywall and joint compound | | | B | Y | | 500(7) | | | SF | S0053F | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |
| Wall | All | Paint, On concrete block | | | B | Y | | 4000(7) | | | SF | S0068ABCD | Chrysotile | 0.5-5% | Confirmed Asbestos | NF |

Includes 281 and 282

Legend:

| Sample number | Units | Other |
|---------------|--|---------------------------------|
| S#### | Asbestos sample collected | SF Square feet |
| V#### | Material visually similar to numbered sample collected | LF Linear feet |
| V0000 | Known non-asbestos material | EA Each |
| V9000 | Visually identified as an asbestos material | % Percentage |
| V9500 | Material is presumed to be an asbestos material | |
| | | A Access |
| | | V Visible |
| | | AP Air Plenum |
| | | F Friable material |
| | | NF Non Friable material |
| | | PF Potentially Friable material |

| Access | |
|--------|---|
| A | Accessible to all building occupants |
| B | Accessible to maintenance and operations staff without a ladder |
| C | Accessible to maintenance and operations staff with a ladder. Also rarely entered, locked areas |
| D | Not normally accessible |

| Condition | |
|-----------|---|
| Good | No visible damage or deterioration |
| Fair | Minor, repairable damage, cracking, delamination or deterioration |
| Poor | Irreparable damage or deterioration with exposed and missing material |

| Visible | |
|---------|---|
| Y | The material is visible when standing on the floor of the room, without the removal or opening of other building components (e.g. ceiling tiles or access panels). |
| N | The material is not visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceilings tiles or access panels) to view and access. Includes rarely entered crawlspaces, attic spaces, etc. Observations will be limited to the extent visible from the access points. |
| L | The material is partially visible to view when standing on the floor of the room and requires the removal of a building component (e.g. ceiling system or access panels) to view completely and access. Includes partially viewed access points to crawlspaces, attic spaces, etc. without entering. Observations are limited to the extent visible from the access points. |

| Air Plenum | |
|------------|---|
| Yes or No | The material is in a return air plenum or in a direct airstream or there is evidence of air erosion (e.g. duct for heating or cooling blowing directly on or across an ACM). This field is only completed where Air Plenum consideration is required by regulation. |

| Colour Coding | |
|--|---|
|  | The material is a hazardous material, either by analytical results or by visible identification. |
|  | The material is presumed to be a hazardous material, based on visual appearance, and was not sampled due to limited access or the non-destructive nature of sampling. |

| Action | | | | |
|--------|--|-----|--|-----------------|
| (1) | Clean up of ACM Debris | (2) | Precautions for Access Which may Disturb ACM Debris | (3) ACM removal |
| (4) | Precautions for Work Which may Disturb ACM in Poor Condition | (5) | Proactive ACM removal (Minimum repair required for fair condition) | (6) ACM repair |
| (7) | Management program and surveillance | | | |

APPENDIX VI
Photographs



V0001 (Confirmed Asbestos), Piping, Aircell, Office (Location #: 124)



V0002 (Confirmed Asbestos), Piping, Rain Water Leader, Sweatwrap, Corridor (Location #: 190)




V0003 (Confirmed Asbestos), 9x9 various colours, Floor, All, Vinyl Floor Tile and Mastic, Classroom (Location #: 103)



V0003 (Confirmed Asbestos), , All, Vinyl Floor Tile and Mastic, 9x9 various colours, Floor Resource Room (Location #: 105)




S0003B (Confirmed Asbestos), , All, Vinyl Floor Tile and Mastic, 9x9 various colours, Floor Classroom (Location #: 115)



V0003 (Confirmed Asbestos), Floor, All, Vinyl Floor Tile and Mastic, 9x9 various colours, Classroom (Location #: 255)




V0006 (Confirmed Asbestos), Piping, Parging Cement, Storage (Location #: 109)



S0008A (Confirmed Asbestos), Piping, All, Parging Cement, Poor Condition, Autoshop (Location #: 153)



S0012A (Confirmed Asbestos), Ceiling, All, Texture Coat, Washroom (Location #: 159)



S0015A (Confirmed Asbestos), Floor, Vinyl Floor Tile, 12x12 beige with brown streaks, Boiler Room (Location #: 163)




V0001 (Confirmed Asbestos), Piping, Aircell, Corridor (Location #: 192)



S0026C (Confirmed Asbestos), Floor, All, Vinyl Floor Tile, 12x12 off-white with black and grey streaks, Change Room (Location #: 135)



S0035A (Confirmed Asbestos), Piping, Sweatwrap, Poor Condition, Classroom (Location #: 150)




V0035 and V0006 (Confirmed Asbestos), Piping, Sweatwrap, Parging Cement, Poor Condition, Classroom (Location #: 151)




V0054 (Confirmed Asbestos), Wall, All, Drywall and joint compound, Guidance (Location #: 108)



V0054 (Confirmed Asbestos), Ceiling, Bulkhead, Drywall and joint compound, Poor Condition, Classroom (Location #: 212)



V0063 (Confirmed Asbestos), Wall, Paint, On concrete block, Equipment Storage (Location #: 141)



S0066A (Confirmed Asbestos), Wall, Paint, On concrete block, Poor Condition, Storage Room (Location #: 139)




S0066A (Confirmed Asbestos), Wall, Paint, On concrete block, Poor Condition, Storage Room (Location #: 139)



S0066A (Confirmed Asbestos), Wall, Paint, On concrete block, Poor Condition, Storage Room (Location #: 139)




V0067 (Confirmed Asbestos), , Wall, Paint, On concrete block Poor Condition, Change Room (Location #: 135)
Room 135b



V0067 (Confirmed Asbestos), Wall, Paint, On concrete block, Poor Condition, Classroom (Location #: 187)



S0090C (Confirmed Asbestos), Transite, Structure, Canopy, Cement Product, Corridor (Location #: 194)
Exterior



V9500 (Presumed Asbestos), Transite, Piping, Rain Water Leader, Cement Product, Stage (Location #: 140)



V9500 (Confirmed Asbestos),, Piping, Rainwater Leader, Parging Cement, Poor Condition, Gym (Location #: 142)



V9500 (Presumed Asbestos), , Piping, Rain Water Leader, Parging Cement, Poor Condition, Gym (Location #: 142)



V9500 (Presumed Asbestos), Wall, Door, Thermal Insulation, Boiler Room (Location #: 163)



V9500 (Presumed Asbestos), Transite drying rack, Other, Cement Product, Resource Room (Location #: 218)



V9500 (Presumed Asbestos), Transite, Other, Countertop, Cement Product, Classroom (Location #: 219)




S0017A-C (Confirmed Asbestos), Structure, Paper Covering, Paper Heat Shield, Basement (Location #: 2)




S0024A-C (Confirmed Asbestos), Floor, Vinyl Floor Tile, 12"x12" Beige with Sparse White and Brown Flecks, Storage Room (Location #: 139)



S0030A-C (Confirmed Asbestos), Ceiling, Bulkhead, Texture Coat, Theatre (Location #: 214)



S0031A-C (Confirmed Asbestos), Wall, Exterior Door Frames, Beige Caulking, Exterior (Location #: 3)



S0033A-C (Confirmed Asbestos), Wall, Exterior Door Frames, Brown and Grey Caulking, Exterior (Location #: 3)



S0080C (None), Grey, Wall, Window Liner, Sealant, Corridor (Location #: 194)



S0087C (Confirmed Asbestos), Structure, Texture Coat, Corridor (Location #: 195)
Exterior canopy