



Corporation of the City of Kawartha Lakes
 Sample Survey Table
 6 Victoria Ave. N - Lindsay Police Station

Sample ID	Room Name/No. and Floor	Location of Sample	Type of Material	Location of Material	Condition of Material	Quantity of Material	Date	Fibrous Asbestos Content %		Friable/Non-Friable	Comments, Notes, and/or Recommendations
								% Asbestos	Asbestos Type		
Building constructed post 1986.											

Notes:

1. "NA" denotes not applicable.
2. "-" denotes not tested or information not required.